Maintenance Items

C-GOKO

Make & Model (Serial)	Operator	Reported Date	Hours	Landings
CESSNA 550 Bravo (550B-0814)	Kirkness Group	08-Aug-2022	8940.30	7013

- Major Components

Component	Model (Serial)	Hours	Cycles
Engine 1	PW530A (PCE-DA0054)	8540.30	6643.00
Engine 2	PW530A (PCE-DA0058)	8540.30	6643.00
Air Conditioner 1	UNKNOWN (SN-UNK)	1502.00	

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
00 PPPP1 Airframe INSPECTION #866	PAINT AIRCRAFT	22-MAY-2013 H: 7899.00 L: 5865					
05 12-01 Airframe INSPECTION #242	PHASE 1	15-JUL-2022 H: 8940.30 L: 7013	M: 24 H: 300.00			15-JUL-2024 H: 9240.30	M: 21 D: 21 H: 300.00
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-02 Airframe INSPECTION #376	PHASE 2	15-JUL-2022 H: 8940.30 L: 7013	M: 24 H: 300.00			15-JUL-2024 H: 9240.30	M: 21 D: 21 H: 300.00
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-03 Airframe INSPECTION #325	PHASE 3	15-JUL-2022 H: 8940.30 L: 7013	M: 24 H: 300.00			15-JUL-2024 H: 9240.30	M: 21 D: 21 H: 300.00
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-04 Airframe INSPECTION #193	PHASE 4	15-JUL-2022 H: 8940.30 L: 7013	M: 24 H: 300.00			15-JUL-2024 H: 9240.30	M: 21 D: 21 H: 300.00
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 12-05 Airframe INSPECTION #456	PHASE 5	22-JUN-2020 H: 8793.10 L: 6394	M: 36 H: 1200.00			22-JUN-2023 H: 9993.10	M: 8 D: 29 H: 1052.80
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-0B Airframe INSPECTION #87	PHASE B	15-JUL-2022 H: 8940.30 L: 7013	H: 150.00			H: 9090.30	H: 150.00
05 12-12 Airframe INSPECTION #161	PHASE 12	02-AUG-2018 H: 8577.20 L: 6283	H: 600.00			H: 9177.20	H: 236.90
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-14 Airframe INSPECTION #332	PHASE 14	18-JUN-1997 H: 0.00	H: 10000.00			H: 10000.00	H: 1059.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-15 Airframe INSPECTION #204	PHASE 15	18-JUN-1997 H: 0.00	H: 10000.00			H: 10000.00	H: 1059.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-16 Airframe INSPECTION #25	PHASE 16	18-JUN-1997 H: 0.00	H: 10000.00			H: 10000.00	H: 1059.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-17 Airframe INSPECTION #419	PHASE 17	18-JUN-1997 H: 0.00	H: 10000.00			H: 10000.00	H: 1059.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 12-18 Airframe INSPECTION #373	PHASE 18	15-JUL-2022 H: 8940.30 L: 7013	M: 12			15-JUL-2023	M: 9 D: 21
05 12-20 Airframe INSPECTION #486	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
05 12-21 Airframe INSPECTION #143	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
05 12-22 Airframe INSPECTION #353	PHASE 22 (NOT USED)	14-SEP-2011 H: 7562.70 L: 5681					
05 12-23 Airframe INSPECTION #124	PHASE 23 (NOT USED)	06-JUL-2012 H: 7724.30 L: 5770					
05 12-34 Airframe INSPECTION #131	PHASE 34 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	15-JUL-2022 H: 8940.30 L: 7013	M: 6			15-JAN-2023	M: 3 D: 22
05 12-35 Airframe INSPECTION #380	PHASE 35	15-JUL-2022 H: 8940.30 L: 7013	M: 6			15-JAN-2023	M: 3 D: 22
05 12-37 Airframe INSPECTION #292	PHASE 37	10-JUL-2005 H: 4950.00	H: 5000.00			H: 9950.00	H: 1009.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED						
05 12-47 Airframe INSPECTION #167	PHASE 47 (NOT USED)	21-DEC-2012 H: 7805.70 L: 5821					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 12-48 Airframe INSPECTION #261	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	21-DEC-2012 H: 7805.70 L: 5821					
05 12-49 Airframe INSPECTION #163	PHASE 49	22-JUN-2020 H: 8793.10 L: 6394	M: 36 H: 1200.00			22-JUN-2023 H: 9993.10	M: 8 D: 29 H: 1052.80
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-54 Airframe INSPECTION #397	PHASE 54 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	15-JUL-2022 H: 8940.30 L: 7013	M: 4 H: 200.00			15-NOV-2022 H: 9140.30	M: 1 D: 22 H: 200.00
05 12-57 Airframe INSPECTION #319	PHASE 57	15-JUL-2022 H: 8940.30 L: 7013	M: 12			15-JUL-2023	M: 9 D: 21
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-58 Airframe INSPECTION #469	PHASE 58	18-JUN-1997					
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-59 Airframe INSPECTION #491	PHASE 59	01-APR-2014 H: 8080.20 L: 5969					
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-60 Air Conditioner 1 INSPECTION #5	PHASE 60		H: 500.00			H: 1862.00	H: 360.00
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 12-61 Airframe INSPECTION #95	PHASE 61		H: 10000.00			H: 10000.00	H: 1059.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-62 Airframe INSPECTION #443	PHASE 62	06-NOV-2021 H: 8857.50 L: 6455	H: 300.00			H: 9157.50	H: 217.20
05 12-MA Airframe INSPECTION #351	PHASE MA	18-JUN-1997 H: 0.00	L: 10000			L: 10000	L: 2987
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-MD Airframe INSPECTION #129	PHASE MD	14-DEC-2019 H: 8729.10 L: 6366	H: 1456.00			H: 10185.10	H: 1244.80
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-ME Airframe INSPECTION #478	PHASE ME	05-FEB-2017 H: 8384.90 L: 6172	H: 2523.00			H: 10907.90	H: 1967.60
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-MF Airframe INSPECTION #306	PHASE MF	14-DEC-2019 H: 8729.10 L: 6366	H: 4450.00			H: 13179.10	H: 4238.80
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-MG Airframe INSPECTION #75	PHASE MG	22-MAR-2005 H: 4631.00	H: 5000.00			H: 9631.00	H: 690.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 12-MH Airframe INSPECTION #426	PHASE MH	15-SEP-2005 H: 5106.00	H: 5130.00			H: 10236.00	H: 1295.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-MI Airframe INSPECTION #467	PHASE MI	21-AUG-2006 H: 5870.00	H: 5900.00			H: 11770.00	H: 2829.70
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-MJ Airframe INSPECTION #21	PHASE MJ	19-JUN-2007 H: 6479.90 L: 4791	H: 6725.00			H: 13204.90	H: 4264.60
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 12-MK Airframe INSPECTION #251	PHASE MK	22-JUN-2020 H: 8793.10 L: 6394	H: 300.00			H: 9093.10	H: 152.80
	Notes THE SUBTASKS FOR THIS INSPECTION GROUP WERE NOT INCLUDED WITH THE ONBOARDING DATA. PLEASE CONFIRM IF THESE TASKS ARE TO BE TRACKED.						
05 1252 Engine 1 INSPECTION #14	ENGINE 1 OIL FILTER CHANGE	23-JUL-2021 H: 8438.50 C: 6064	M: 24 H: 900.00			23-JUL-2023 H: 9338.50	M: 9 D: 29 H: 798.20
05 1252 Engine 2 INSPECTION #15	ENGINE 2 OIL FILTER CHANGE	23-JUL-2021 H: 8438.50 C: 6064	M: 24 H: 900.00			23-JUL-2023 H: 9338.50	M: 9 D: 29 H: 798.20
05 1255 Engine 1 INSPECTION #47	ENGINE 1 MINOR INSPECTION	15-JUL-2022 H: 8540.30 C: 6643	M: 12 H: 600.00			15-JUL-2023 H: 9140.30	M: 9 D: 21 H: 600.00
05 1255 Engine 2 INSPECTION #41	ENGINE 2 MINOR INSPECTION	15-JUL-2022 H: 8540.30 C: 6643	M: 12 H: 600.00			15-JUL-2023 H: 9140.30	M: 9 D: 21 H: 600.00

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 2010B Airframe INSPECTION #47	INSPECT LEFT WINDSHIELD PRISM INSPECTION	06-NOV-2021 H: 8857.50 L: 6455	M: 24 H: 300.00			06-NOV-2023 H: 9157.50	M: 13 D: 13 H: 217.20
05 2010C Airframe INSPECTION #74	INSPECT LEFT SIDE WINDOW PRISM INSPECTION	06-NOV-2021 H: 8857.50 L: 6455	M: 24 H: 300.00			06-NOV-2023 H: 9157.50	M: 13 D: 13 H: 217.20
05 2103 Air Conditioner 1 INSPECTION #4	ENVIRO INSP 750 HOUR	17-MAR-2008 H: 1175.60	H: 750.00			H: 1925.60	H: 423.60
05 2104 Air Conditioner 1 INSPECTION #1	ENVIRO INSP 1500 HOUR	08-FEB-2006 H: 629.00	H: 1500.00			H: 2129.00	H: 627.00
05 2105 Air Conditioner 1 INSPECTION #3	ENVIRO INSP 3000 HOUR	08-FEB-2006 H: 629.00	H: 3000.00			H: 3629.00	H: 2127.00
05 3202 Airframe INSPECTION #398	INSPECT LEFT MAIN WHEEL NDT INSPECTION MAIN WHEEL	12-SEP-2019					
05 3202 Airframe INSPECTION #145	INSPECT RIGHT MAIN WHEEL NDT INSPECTION MAIN WHEEL						
05 3490 Airframe INSPECTION #436	RVSM GMU TEST FLIGHT	24-NOV-2003					
05 5075 Engine 1 INSPECTION #10	ENGINE 1 FUEL CONTAMINATION	18-JUN-1997					
05 5075 Engine 2 INSPECTION #48	ENGINE 2 FUEL CONTAMINATION	18-JUN-1997					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 5601 Airframe INSPECTION #76	IRRIDIUM SATELLITE ANTENNA EDDY CURRENT INSPECTION	18-APR-2011 H: 7498.10 L: 5628	H: 3941.00			H: 11439.10	H: 2498.80
05 7120 Engine 1 INSPECTION #3	ENGINE 1 INSPECTION LOW UTILIZATION	13-AUG-2019 H: 8669.40 C: 6334	M: 120			13-AUG-2029	M: 82 D: 20
05 7120 Engine 2 INSPECTION #42	ENGINE 2 INSPECTION LOW UTILIZATION	26-AUG-2019 H: 8669.40 C: 6334	M: 120			26-AUG-2029	M: 83 D: 2
08 2001 Airframe INSPECTION #431	CARS 625 AIRCRAFT REWEIGH	21-JUN-2021 H: 8836.80 L: 6432	M: 60			30-JUN-2026	M: 45 D: 6
21 1002 Airframe PART #334	EMERERGENCY PRESSURE VALVE Part Number: 27441482-06 Serial Number: 7AM52	18-JUN-1997 H: 0.00					
21 2004 Airframe PART - Life Limited #93	OVERHEAD CABIN FAN Part Number: BC61A901-2 Serial Number: 3331A	16-AUG-2013 H: 7979.80 L: 5914	H: 1000.00		M: 0 H: 0.00 L: 0	H: 9179.80	H: 239.50
21 2006 Airframe PART #473	COCKPIT DEFOGGER FAN Part Number: 5703-4 Serial Number: 307	18-JUN-1997 H: 0.00					
21 2009 Airframe PART #427	AIR FLOW ACTUATOR Part Number: NYLC50466 Serial Number: 1356	18-JUN-1997 H: 0.00					
21 2010 Airframe PART #290	DOOR ACTUATOR MOTOR Part Number: 9910059-3 Serial Number: SN-UNKNOWN	18-JUN-1997 H: 0.00					
21 3001 Airframe PART #383	CABIN PRESSURE INDICATOR Part Number: C668511-0106 Serial Number: 20395	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 3002 Airframe PART #107	CABIN RATE CONTROLLER	52770-112	K128	06-JUL-2008 H: 7207.88 L: 5395					
21 3007 Airframe PART #118	LEFT SECONDARY OUTFLOW VALVE	9912409-8	1383	18-JUN-1997 H: 0.00					
21 3007 Airframe PART #416	RIGHT PRIMARY OUTFLOW VALVE	9912409-7	800	16-DEC-2008 H: 7317.03 L: 5488					
21 3008 Airframe PART #282	TOGGLE MANUAL VALVE	9912409-4	SN- UNKNOWN	18-JUN-1997 H: 0.00					
21 3009 Airframe PART #54	LEFT FLOW CONTROL VALVE	5268-00-1	0141	25-JUL-2000 H: 917.00					
21 3009 Airframe PART #385	RIGHT FLOW CONTROL VALVE	5268-00-1	0646	14-DEC-2008 H: 7317.03 L: 5488					
21 5000 Airframe PART #241	ACM OVERHEAT SWITCH	1173T0635	SN- UNKNOWN	18-JUN-1997 H: 0.00					
21 5001 Airframe PART #109	REFRIGERATION PACKAGE ASSEMBLY	9912069-25	9702121	18-JUN-1997 H: 0.00					
21 5002 Airframe PART #184	ACM 450 DEGREE SWITCH	746833-1	SN- UNKNOWN	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5004 Airframe PART - Overhaul #103	AIR CYCLE MACHINE	738384-26	9610069	01-DEC-2005 H: 5242.00	H: 5000.00		M: 0 H: 0.00 L: 0	H: 10242.00	H: 1301.70
21 5005 Airframe PART #122	BYPASS VALVE	9912069-1	SN- UNKNOWN	18-JUN-1997 H: 0.00					
21 5007 Airframe PART #347	B/A PRESSURE VALVE	9912294-1	843	18-JUN-1997 H: 0.00					
21 5010 Airframe PART #215	HEAT EXCHANGER	9912041-4	937	18-JUN-1997 H: 0.00					
21 5012 Air Conditioner 1 PART - Life Limited #2	REPLACE COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS 1134104-1, -5 OR FWA1134104-1, -5)	FWA1134104-1	3758	16-AUG-2013 H: 1362.00	H: 500.00		M: 0 H: 0.00 C: 0	H: 1862.00	H: 360.00
21 5014 Airframe PART #117	AIR CONDITIONER PRESSURE SWITCH	FWA1250232-4	F715	21-AUG-2006 H: 5870.00					
21 5015 Airframe INSPECTION #867	COMPRESSOR DRIVE MOTOR			08-FEB-2006 H: 5393.00					
21 5016 Airframe PART #176	AIR CONDITIONER COMPRESSOR	FWA1134162	NSN	08-FEB-2006 H: 5393.00					
21 5017 Airframe PART #264	AIR CONDITIONER CONDENSER	1134400-9	234	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5022 Airframe PART #86	AFT EVAPORATOR ASSEMBLY	1134240-3	232	18-JUN-1997 H: 0.00					
21 5023 Airframe PART #13	FORWARD EVAPORATOR ASSEMBLY	1134240-2	231	18-JUN-1997 H: 0.00					
21 5025 Airframe PART #70	AIR CONDITIONER MONITOR-	C35020A	2561	22-JUL-2003 H: 3105.00					
21 6002 Airframe PART #330	TEMPERATURE CONTROL	9912069-22	97014893	18-JUN-1997 H: 0.00					
21 6003 Airframe PART #372	DUCT TEMPERATURE SENSOR	9912069-14	97026299	18-JUN-1997 H: 0.00					
21 6006 Airframe PART #199	CABIN TEMP INDICATOR	0221-007	85181	18-JUN-1997 H: 0.00					
21 6011 Airframe PART #68	OVERHEAT ACM SWITCH	1173T42-1	2585	18-JUN-1997 H: 0.00					
21 6013 Airframe PART #370	LEFT PRESSURE SWITCH	1103P240-1	899	18-JUN-1997 H: 0.00					
21 6013 Airframe PART #273	RIGHT PRESSURE SWITCH	1103P240-2	892	18-JUN-1997 H: 0.00					
21 6014 Airframe PART #438	CABIN TEMPERATURE SENSOR	1942T100-11	1457	05-NOV-2006 H: 6025.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 7001 Airframe PART #402	WATER SEPARATOR Part Number: 9912069-13 Serial Number: 9702120	18-JUN-1997 H: 0.00					
21 A216003 Airframe INSPECTION #869	VAPOR CYCLE COOLING SYSTEM HOUR METERCHECK (COMPRESSOR MOTORS 1134104-1,-5 or FWA1134104-1, -5) Notes PLEASE CONFIRM IF THIS TASK SHOULD BE TRACKING PER THE APPLICABLE PART NUMBER INSTALLED.						
21 FO-02(550/A) Airframe PART #45	COOLING-VAPOR CYCLE Part Number: NPN Serial Number: NSN	18-JUN-1997					
22 1009 Airframe PART #375	AUTOPILOT CONTROL Part Number: 7003897-923 Serial Number: 94020638	28-AUG-2004 H: 4209.00					
22 1010 Airframe PART #405	AFT AILERON SERVO Part Number: 4006719-906 Serial Number: 95087998	21-FEB-2007 H: 6199.00					
22 1010 Airframe PART #246	FORWARD ELEVATOR SERVO Part Number: 4006719-904 Serial Number: 01045446	08-APR-2014 H: 8080.20 L: 5969					
22 1010 Airframe PART #382	MIDDLE RUDDER SERVO Part Number: 4006719-906 Serial Number: 97019200	18-JUN-1997 H: 0.00					
23 1003 Airframe PART #237	HF RECEIVER-EXCITER Part Number: 064-01015-0001 Serial Number: 30238	03-SEP-1997 H: 84.00					
23 1004 Airframe PART #183	HF ANTENNA COUPLER Part Number: 064-01017-0001 Serial Number: 14893	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 1005 Airframe PART #85	HF CONTROL HEAD	071-01274-0002	3699	18-JUN-1997 H: 0.00					
23 2002 Airframe PART #357	NO.2 COMM ANTENNA	17-50-01	SN- UNKNOWN	18-JUN-1997 H: 0.00					
23 2003 Airframe PART #464	NO. 1 COMM ANTENNA	VFS10-90-7	0853	26-MAR-2002 H: 1838.00					
23 2004 Airframe PART #90	PHONE TRANSCEIVER	400-10680-001	1068010868	18-JUN-1997 H: 0.00					
23 2005 Airframe PART #52	CABIN PHONE HANDSET	400-0123-212	9776	18-JUN-1997 H: 0.00					
23 2006 Airframe PART #14	COCKPIT PHONE HANDSET	400-0123-212	10758	18-JUN-1997 H: 0.00					
23 2007 Airframe PART #309	TELEPHONE ANTENNA	CI5000-1	SN- UNKNOWN	04-JAN-2001 H: 1010.00					
23 2010 Airframe PART #384	NO. 1 COMM TRANSCEIVER	064-01054-0050	23933	18-FEB-2020 H: 8759.50 L: 6379					
23 2010 Airframe PART #169	NO. 2 COMM TRANSCEIVER	064-01054-0050	26198	18-FEB-2020 H: 8759.50 L: 6379					
23 2019 Airframe PART #10	LEFT HF ADAPTER	071-01268-0001	2944	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 2024 Airframe PART #333	SELCAL INDICATOR	1200006-010	110	04-JAN-2001 H: 1010.00					
23 5001 Airframe PART #234	LEFT AUDIO AMPLIFIER	5636-1	415	04-JUN-2008 H: 7148.07 L: 5349					
23 5001 Airframe PART #274	RIGHT AUDIO AMPLIFIER	5636-1	545	17-APR-2001 H: 1131.00					
23 7001 Airframe PART #305	COCKPIT VOICE RECORDER	S200-0012-00	1008	20-NOV-2008 H: 7302.60 L: 5472					
23 7002 Airframe PART #7	COCKPIT VOICE RECORDER CONTROLLER	S251-1120-00	542	18-JUN-1997 H: 0.00					
23 7004 Airframe PART #454	COCKPIT VOICE RECORDER BEACON	DK120	DU57901	21-FEB-2011 H: 7495.80 L: 5626					
23 7004A Airframe PART - Expiration #38	COCKPIT VOICE RECORDER BEACON BATTERY	PN-UNKNOWN	SN-UNKNOWN	16-MAY-2017 H: 8398.40 L: 6179	M: 72			01-JUN-2023	M: 8 D: 8
23 7017 Airframe PART #412	COCKPIT VOICE RECORDER GRAVITY SWITCH	6895D2-5-5	SN-UNKNOWN	18-JUN-1997 H: 0.00					
23 A237003 Airframe INSPECTION PHASE 21 #57	INSPECT UNDERWATER LOCATOR BEACON INSTALLED ON COCKPIT VOICE RECORDER (TASK 23-71-01-280)			23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 B237004 Airframe INSPECTION PHASE 21 #202	OPERATIONAL TEST UNDERWATER LOCATOR BEACON INSTALLED ON COCKPIT VOICE RECORDER (TASK 23-71-01-711)	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
24 2001 Airframe PART #62	LEFT AC NO 1 INVERTER Part Number: PC251-123E Serial Number: 8794	18-JUN-1997 H: 0.00					
24 2001 Airframe PART #231	RIGHT AC NO 2 INVERTER Part Number: PC251-123E Serial Number: 9070	29-NOV-2006 H: 6067.00					
24 3003 Airframe PART #37	LEFT DC GENERATOR CONTROL Part Number: 51525-001F Serial Number: 96411	14-DEC-2001 H: 1552.00					
24 3003 Airframe PART #4	RIGHT DC GENERATOR CONTROL Part Number: 51525-001F Serial Number: 99409	04-JAN-2007 H: 6160.00					
24 3004 Airframe PART #173	LEFT AMMETER Part Number: C662501-0106 Serial Number: H97657	04-JAN-2001 H: 1010.00					
24 3004 Airframe PART #83	RIGHT AMMETER Part Number: C662501-0106 Serial Number: 1033	18-JUN-1997 H: 0.00					
24 3005 Airframe PART #213	VOLTMETER Part Number: C662502-0101 Serial Number: 1237	18-JUN-1997 H: 0.00					
24 3007 Airframe PART #194	BATTERY Part Number: RG-380E/44LA5 Serial Number: 41163046	21-JUN-2021 H: 8836.80 L: 6432					
24 3008 Airframe PART #288	BATTERY TEMPERATURE MONITOR- Part Number: 1529-1-1 Serial Number: 2933	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 3009 Airframe PART #157	BATTERY TEMPERATURE GAGE	1229-1	988	20-APR-2006 H: 5553.00					
24 3010 Airframe PART #206	BATTERY TEMPERATURE SENSOR	29783-003	042406018	01-MAY-2009 H: 7442.10 L: 5585					
24 3014 Airframe PART #77	BATTERY DISCONNECT RELAY	A876K	CL86419	18-JUN-1997 H: 0.00					
24 5004 Airframe PART #162	OVERVOLTAGE MONITOR-	1645-1-3	1439	18-JUN-1997 H: 0.00					
24 D243003 Airframe INSPECTION PHASE 54 #150	LEAD ACID BATTERY CAPACITY CHECK: PHASE 54			15-JUL-2022 H: 8940.30 L: 7013	M: 4 H: 200.00			15-NOV-2022 H: 9140.30	M: 1 D: 22 H: 200.00
25 2004 Airframe PART #32	COMPUTER-TAS	90001-003	99047	28-MAR-2014 H: 8080.20 L: 5969					
25 2005 Airframe PART #40	CABIN DISPLAY	15000-003	104088	12-JAN-2008 H: 6920.43 L: 5171					
25 5014 Airframe PART #148	CONTROL MODULE	1052-1-1/54-1	SN- UNKNOWN	18-JUN-1997 H: 0.00					
25 6001 Airframe PART - Life Limited #16	NO. 1 LIFE JACKET	P01074-207	2010044004 6	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 6001 Airframe PART - Life Limited #219	NO. 10 LIFE JACKET	P01074-207	20100440116	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3
25 6001 Airframe PART - Life Limited #342	NO. 2 LIFE JACKET	P01074-207	20101094008	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3
25 6001 Airframe PART - Life Limited #465	NO. 3 LIFE JACKET	P01074-207	2010044012	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3
25 6001 Airframe PART - Life Limited #211	NO. 4 LIFE JACKET	P01074-207	20100440095	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3
25 6001 Airframe PART - Life Limited #113	NO. 5 LIFE JACKET	P01074-207	20100440024	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3
25 6001 Airframe PART - Life Limited #488	NO. 6 LIFE JACKET	P01074-207	20100440059	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3
25 6001 Airframe PART - Life Limited #335	NO. 7 LIFE JACKET	P01074-207	20100440100	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3
25 6001 Airframe PART - Life Limited #190	NO. 8 LIFE JACKET	P01074-207	20100440078	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3
25 6001 Airframe PART - Life Limited #421	NO. 9 LIFE JACKET	P01074-207	21010940005	27-APR-2021 H: 8836.80 L: 6432	M: 120		M: 0 H: 0.00 L: 0	27-APR-2031	M: 103 D: 3

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 6003 Airframe PART #336	TOILET PUMP	17200-382	SN-UNKNOWN	18-JUN-1997 H: 0.00					
25 6010 Airframe PART #275	EMERGENCY LOCATOR TRANSMITTER	453-0150	71371	01-JUL-2017 H: 8416.80 L: 6190					
25 6014 Airframe PART #293	EMERGENCY LOCATOR ANTENNA	DMQ18-3	6969	18-JUN-1997 H: 0.00					
25 6015 Airframe PART - Expiration #123	ELT LOCATOR BEACON BATTERY PACK	452-0130	387511-01	23-OCT-2020 H: 8822.40 L: 6424				30-APR-2023	M: 7 D: 6
26 1001 Airframe PART #226	LEFT FIRE DETECTOR SENSOR	9912036-3	SN-UNKNOWN						
26 1001 Airframe PART #221	RIGHT FIRE DETECTOR SENSOR	9912036-3	SN-UNKNOWN						
26 1002 Airframe PART #244	LEFT FIRE DETECTOR CONTROL	9912036-12	9651003						
26 1002 Airframe PART #191	RIGHT FIRE DETECTOR CONTROL	9912036-12	9648004						
26 2001 Airframe PART #323	AFT ENGINE FIRE EXTINGUISHER	9912048-2	38417B1	21-AUG-2006 H: 5870.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 2001 Airframe PART #254	FORWARD ENGINE FIRE EXTINGUISHER Part Number: 9912048-2 Serial Number: 38419B1	21-AUG-2006 H: 5870.00					
26 2002 Airframe PART #452	AFT HALON FIRE EXTINGUISHER Part Number: C352TS Serial Number: F49185840	14-JAN-2019 H: 8617.80 L: 6312					
26 2002 Airframe PART #260	FORWARD HALON FIRE EXTINGUISHER Part Number: C352TS Serial Number: F49185809	14-JAN-2019 H: 8617.80 L: 6312					
26 2003 Airframe INSPECTION AFT LH FEC #94	REPLACE AFT LEFT FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) Part Number: M13083-5 Serial Number: 29494 Notes PLEASE CONFIRM THE SERVICE LIFE OF THIS COMPONENT. THE MANUFACTURER RECOMMENDS A SERVICE LIFE OF 8 YEARS.	30-MAY-2014	M: 120			30-JAN-2024	M: 16 D: 6
26 2003 Airframe INSPECTION AFT RH FEC #236	REPLACE AFT RIGHT FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) Part Number: M13083-5 Serial Number: 29492 Notes PLEASE CONFIRM THE SERVICE LIFE OF THIS COMPONENT. THE MANUFACTURER RECOMMENDS A SERVICE LIFE OF 8 YEARS.	30-MAY-2014	M: 120			30-JAN-2024	M: 16 D: 6
26 2003 Airframe INSPECTION FWD LH FEC #340	REPLACE FORWARD LEFT FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) Part Number: M13083-5 Serial Number: 29583 Notes PLEASE CONFIRM THE SERVICE LIFE OF THIS COMPONENT. THE MANUFACTURER RECOMMENDS A SERVICE LIFE OF 8 YEARS.	30-MAY-2014	M: 120			30-JAN-2024	M: 16 D: 6
26 2003 Airframe INSPECTION FWD RH FEC #214	REPLACE FORWARD RIGHT FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) Part Number: M13083-5 Serial Number: 29575 Notes PLEASE CONFIRM THE SERVICE LIFE OF THIS COMPONENT. THE MANUFACTURER RECOMMENDS A SERVICE LIFE OF 8 YEARS.	30-MAY-2014	M: 120			30-JAN-2024	M: 16 D: 6

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 2101 Airframe PART - Life Limited #65	AFT LEFT FIRE EXTINGUISHER CARTRIDGE Part Number: M13083-5 Serial Number: 29494	30-MAY-2014 H: 8105.90 L: 5989	M: 120		M: 0 H: 0.00 L: 0	01-JAN-2024	M: 15 D: 8
26 2111 Airframe PART - Life Limited #218	AFT RIGHT FIRE EXTINGUISHER CARTRIDGE Part Number: M13083-5 Serial Number: 29492	30-MAY-2014 H: 8105.90 L: 5989	M: 120		M: 0 H: 0.00 L: 0	01-JAN-2024	M: 15 D: 8
26 2201 Airframe PART - Life Limited #404	FORWARD LEFT FIRE EXTINGUISHER CARTRIDGE Part Number: M13083-5 Serial Number: 29583	30-MAY-2014 H: 8105.90 L: 5989	M: 120		M: 0 H: 0.00 L: 0	01-JAN-2024	M: 15 D: 8
26 2211 Airframe PART - Life Limited #168	FORWARD RIGHT FIRE EXTINGUISHER CARTRIDGE Part Number: M13083-5 Serial Number: 29575	30-MAY-2014 H: 8105.90 L: 5989	M: 120		M: 0 H: 0.00 L: 0	01-JAN-2024	M: 15 D: 8
26 A262003 Airframe INSPECTION PHASE 34 #326	WEIGHT CHECK AFT HALON FIRE EXTINGUISHER : PHASE 34	15-JUL-2022 H: 8940.30 L: 7013	M: 6			15-JAN-2023	M: 3 D: 22
26 A262003 Airframe INSPECTION PHASE 34 #48	WEIGHT CHECK FORWARD HALON FIRE EXTINGUISHER : PHASE 34	15-JUL-2022 H: 8940.30 L: 7013	M: 6			15-JAN-2023	M: 3 D: 22
26 B262002 Airframe INSPECTION AEFE #88	HYDROSTATIC TEST AFT ENGINE FIRE EXTINGUISHER Part Number: 9912048-2 Serial Number: 38417B1	23-JUL-2021 H: 8838.50 L: 6434	M: 60			23-JUL-2026	M: 45 D: 29
26 B262002 Airframe INSPECTION FWD EFE #252	HYDROSTATIC TEST FORWARD ENGINE FIRE EXTINGUISHER Part Number: 9912048-2 Serial Number: 38419B1	23-JUL-2021 H: 8838.50 L: 6434	M: 60			23-JUL-2026	M: 45 D: 29
26 B262003 Airframe INSPECTION AHFE #349	HYDROSTATIC TEST AFT HALON FIRE EXTINGUISHER Part Number: C352TS Serial Number: F49185840	01-JAN-2019	M: 144			01-JAN-2031	M: 99 D: 8

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 B262003 Airframe INSPECTION FHFE #337	HYDROSTATIC TEST FORWARD HALON FIRE EXTINGUISHER Part Number: C352TS Serial Number: F49185809	01-JAN-2019	M: 144			01-JAN-2031	M: 99 D: 8
26 B262004 Airframe INSPECTION PHASE 48 #250	DETAILED INSPECTION HALON FIRE EXTINGUISHER : PHASE 48	14-JAN-2019 H: 8617.80 L: 6312	M: 72			14-JAN-2025	M: 27 D: 21
26 B262004 Airframe INSPECTION PHASE 48 #132	DETAILED INSPECTION HALON FIRE EXTINGUISHER : PHASE 48	14-JAN-2019 H: 8617.80 L: 6312	M: 72			14-JAN-2025	M: 27 D: 21
27 1001 Airframe PART #374	AILERON TRIM TAB ACTUATOR Part Number: 5565450-90 Serial Number: SN-UNKNOWN	18-JUN-1997 H: 0.00					
27 2001 Airframe PART #471	RUDDER TRIM TAB ACTUATOR Part Number: 5565450-102 Serial Number: N/A	29-JUN-2007 H: 6480.50 L: 4791					
27 3002 Airframe PART #390	ELECTRIC ELEVATOR TRIM ACTUATOR Part Number: 44430-3725 Serial Number: T401	21-FEB-2007 H: 6199.00					
27 3003 Airframe PART #321	LEFT ELEVATOR TRIM TAB ACTUATOR Part Number: 5565450-95 Serial Number: SN-UNKNOWN	18-JUN-1997 H: 0.00					
27 3003 Airframe PART #434	RIGHT ELEVATOR TRIM TAB ACTUATOR Part Number: 6565141-2 Serial Number: N/A	29-JUN-2007 H: 6480.50 L: 4791					
27 5001 Airframe PART #498	LEFT FLAP MOTOR Part Number: 9910055-4 Serial Number: 106	06-NOV-2008 H: 7302.60 L: 5472					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description			Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5001 Airframe PART #205	RIGHT FLAP MOTOR	Part Number 9910055-4	Serial Number 2567	12-SEP-2019 H: 8669.40 L: 6334					
27 5002 Airframe PART - Overhaul #71	LEFT FLAP GEARBOX	Part Number 5565175-38	Serial Number 050	29-JUN-2007 H: 6480.50 L: 4791	H: 3000.00		M: 0 H: 0.00 L: 0	H: 9480.50	H: 540.20
27 5002 Airframe PART - Overhaul #286	RIGHT FLAP GEARBOX	Part Number 5565175-38	Serial Number 061093-1	29-JUN-2007 H: 6480.50 L: 4791	H: 3000.00		M: 0 H: 0.00 L: 0	H: 9480.50	H: 540.20
27 6001 Airframe PART #283	LEFT SPEED BRAKES ACTUATOR	Part Number 9912344-1	Serial Number 631	18-JUN-1997 H: 0.00					
27 6001 Airframe PART #346	RIGHT SPEED BRAKES ACTUATOR	Part Number 9912344-1	Serial Number 627	18-JUN-1997 H: 0.00					
27 6002 Airframe PART #53	SPEEDBRAKE CONTROL VALVE	Part Number 66720	Serial Number 1402	18-JUN-1997 H: 0.00					
27 6003 Airframe PART #120	SAFETY VALVE	Part Number 68930	Serial Number 592	18-JUN-1997 H: 0.00					
27 6004 Airframe PART #294	THERMAL RELIEF VALVE	Part Number OAS5322-3-1700	Serial Number 507	18-JUN-1997 H: 0.00					
28 2001 Airframe PART #437	LEFT WING FUEL BOOST PUMP	Part Number 9912017-6	Serial Number 2AN8	18-JUN-1997 H: 0.00					
28 2001 Airframe PART #399	RIGHT WING FUEL BOOST PUMP	Part Number 9912017-6	Serial Number 2AN7	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 4001 Airframe PART #310	LEFT LOW FUEL SWITCH	L15H-3	5051	18-JUN-1997 H: 0.00					
28 4001 Airframe PART #195	RIGHT LOW FUEL SWITCH	L15H-3	6598	21-NOV-2003 H: 3401.00					
28 4002 Airframe PART #92	SIGNAL CONDITIONER	9912479-7	01090321	16-MAY-2006 H: 5648.00					
28 5001 Airframe PART #235	LEFT FUEL SHUTOFF VALVE	9912014-2	SN- UNKNOWN	18-JUN-1997 H: 0.00					
28 5001 Airframe PART #461	RIGHT FUEL SHUTOFF VALVE	9912014-2	SN- UNKNOWN	18-JUN-1997 H: 0.00					
28 5002 Airframe PART #207	LEFT FUEL CROSSFEED VALVE	9912014-1	SN- UNKNOWN	18-JUN-1997 H: 0.00					
28 5002 Airframe PART #418	RIGHT FUEL CROSSFEED VALVE	9912014-1	SN- UNKNOWN	18-JUN-1997 H: 0.00					
28 FO-01(550) Airframe PART #444	FUEL CAP LOCKING	NPN	NSN	18-JUN-1997					
29 1001 Airframe PART #300	HYDRAULIC RESERVOIR	9912506-1	25	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 1002 Airframe PART #435	LEFT ENGINE HYDRAULIC PUMP	9912062-4	2007	18-JUN-1997 H: 0.00					
29 1002 Airframe PART #149	RIGHT ENGINE HYDRAULIC PUMP	9912062-7	0376A	12-SEP-2019 H: 8669.40 L: 6334					
29 1004 Airframe PART #97	LEFT HYDRAULIC FIREWALL SHUTOFF VALVE	AV24B1325C5	P89163	18-JUN-1997 H: 0.00					
29 1004 Airframe PART #394	RIGHT HYDRAULIC FIREWALL SHUTOFF VALVE	AV24B1325C5	P89164	18-JUN-1997 H: 0.00					
29 1005 Airframe PART #127	LEFT CHECK VALVE FLOW SWITCH	9912194-3	3965	18-JUN-1997 H: 0.00					
29 1005 Airframe PART #263	RIGHT CHECK VALVE FLOW SWITCH	9912194-3	3961	18-JUN-1997 H: 0.00					
29 1006 Airframe PART #186	RELIEF VALVE	4614	1526A	18-JUN-1997 H: 0.00					
29 1010 Airframe PART #60	HYDRAULIC PRESSURE SWITCH	1106P59	4446	08-SEP-2006 H: 5903.00					
29 1012 Airframe PART #108	BYPASS VALVE	61510-1	1338A	08-SEP-2006 H: 5903.00					
29 1021 Airframe PART #291	SHUTTLE VALVE	98120	170	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 1001 Airframe PART #268	LEFT WING DE-ICE BOOT	P25S7D5059-09	MANG090	26-SEP-2008 H: 7244.55 L: 5424					
30 1002 Airframe PART #147	RIGHT WING DE-ICE BOOT	P25S-7D5059-10	MYF5CZ0	01-DEC-2005 H: 5242.00					
30 1003 Airframe PART #277	LEFT STABILIZER DE-ICE BOOT	P29S-7D5059-13	MYND160	21-AUG-2006 H: 5870.00					
30 1003 Airframe PART #217	RIGHT STABILIZER DE-ICE BOOT	P29S-7D5059-13	MAGT010	21-OCT-2008 H: 7279.08 L: 5453					
30 1004 Airframe PART #36	VERTICAL FIN BOOT	P25S-7D5059-05	MAMT180	09-OCT-2008 H: 7260.75 L: 5437					
30 1007 Airframe PART #331	AFT PRESSURE DE-ICE SWITCH	1106P55	7161A	22-MAR-2005 H: 4631.00					
30 1007 Airframe PART #11	FORWARD PRESSURE DE-ICE SWITCH	PN	SN- UNKNOWN	18-JUN-1997 H: 0.00					
30 1008 Airframe PART #20	AFT STABILIZER &FIN DE-ICE VALVE	3D2353-06	13981	18-JUN-1997 H: 0.00					
30 1008 Airframe PART #8	LEFT WING DE-ICE VALVE	3D2353-06	13977	18-JUN-1997 H: 0.00					
30 1008 Airframe PART #304	RIGHT WING DE-ICE VALVE	3D2353-06	13973	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description			Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 1010 Airframe PART #494	LEFT WING ANTI-ICE ASSEMBLY	Part Number 6528007-5	Serial Number MV68920	30-JAN-2002 H: 1662.00					
30 1010 Airframe PART #146	RIGHT WING ANTI-ICE ASSEMBLY	Part Number 6528007-11	Serial Number MYDHVSO	07-DEC-2004 H: 4471.00					
30 1013 Airframe PART #299	LEFT TEMPERATURE CONTROLLER	Part Number 3E1870-01	Serial Number UA637	21-DEC-2012 H: 7805.70 L: 5821					
30 1013 Airframe PART #476	RIGHT TEMPERATURE CONTROLLER	Part Number 9912106-1	Serial Number U4065	08-OCT-2006 H: 5959.00					
30 2003 Airframe PART #280	LEFT SOLENOID VALVE	Part Number 9912402-12	Serial Number 806C	18-JUN-1997 H: 0.00					
30 2003 Airframe PART #220	RIGHT SOLENOID VALVE	Part Number 9912402-12	Serial Number 3982C	07-MAY-2009 H: 7443.57 L: 5587					
30 2004 Airframe PART #411	LEFT TEMPERATURE SWITCH	Part Number 1173T0759	Serial Number 4769	25-NOV-2008 H: 7303.37 L: 5473					
30 2004 Airframe PART #259	RIGHT TEMPERATURE SWITCH	Part Number 1173T0759	Serial Number 0386	04-JUL-2002 H: 2113.00					
30 2005 Airframe PART #160	LEFT ANTI-ICE VALVE	Part Number 540-0406-6	Serial Number 2798	13-AUG-2019 H: 8669.40 L: 6334					
30 2005 Airframe PART #360	RIGHT ANTI-ICE VALVE	Part Number 540-0406-6	Serial Number 1698	26-AUG-2019 H: 8669.40 L: 6334					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 3001 Airframe PART #276	LEFT HEATED PITOT TUBE	PH502	694409	05-DEC-2007 H: 6823.80 L: 5093					
30 3001 Airframe PART #297	RIGHT HEATED PITOT TUBE	PH502	1094705	29-JUN-2009 H: 7467.67 L: 5607					
30 3001 Airframe PART #496	STANDBY HEATED PITOT TUBE	PH1100RW-RIGHT	1320701	22-FEB-2010 H: 7495.80 L: 5626					
30 4001 Airframe PART #2	HOT AIR TEMPERATURE MONITOR-	1169-1	2434	18-JUN-1997 H: 0.00					
30 4005 Airframe PART #73	TEMPERATURE CONTROL VALVE	9912085-1	2AN31	18-JUN-1997 H: 0.00					
30 4006 Airframe PART #451	TEMPERATURE CONTROLLER	9912085-6	1AN7	18-JUN-1997 H: 0.00					
30 4007 Airframe PART #114	CENTER TEMPERATURE SENSOR	9912085-3	2AN118	18-JUN-1997 H: 0.00					
30 4007 Airframe PART #55	LEFT TEMPERATURE SENSOR	9912085-3	SN- UNKNOWN	18-JUN-1997 H: 0.00					
30 4008 Airframe PART #257	PRESSURE SWITCH	1115P25	2168A	06-APR-2000 H: 803.00					
30 4009 Airframe PART #415	WINDSHIELD REGULATOR VALVE	9912086-4	3057	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 2001 Airframe PART #152	LEFT CLOCK	M877A5V	07540	29-JUN-2007 H: 6479.90 L: 4791					
31 2001 Airframe PART #387	RIGHT CLOCK	M877A5V	7690	18-JUN-1997 H: 0.00					
31 3001 Airframe PART #255	FLIGHT HOUR RECORDER	C664503-0104	SN- UNKNOWN	18-JUN-1997 H: 0.00					
31 3003 Airframe PART #422	LEFT ACCELEROMETER	7000992(SA-107RS)	9444	23-MAR-2008 H: 7023.38 L: 5247					
31 3003 Airframe PART #136	NO.1 GPWS ACCELEROMETER	979-0223-001	3543	14-APR-2009 H: 7432.50 L: 5578					
31 3003 Airframe PART #366	RIGHT ACCELEROMETER	7000992(SA-107RS)	9445	23-MAR-2008 H: 7023.38 L: 5247					
32 1001 Airframe PART #245	LEFT MAIN LANDING GEAR ASSEMBLY	6541410-1	15	18-JUN-1997 H: 0.00					
32 1002 Airframe PART #18	RIGHT MAIN LANDING GEAR ASSEMBLY	6541410-2	15	18-JUN-1997 H: 0.00					
32 1003 Airframe PART - Life Limited #181	LEFT OLEO ASSEMBLY	6541420-8	171	17-MAR-2008 H: 7010.70 L: 5238	L: 41600		M: 0 H: 0.00 L: 0	L: 46838	L: 39825
32 1004 Airframe PART - Life Limited #56	RIGHT OLEO ASSEMBLY	6541420-4	AC00019	04-JAN-2001 L: 790	L: 41600		M: 0 H: 0.00 L: 790	L: 41600	L: 34587

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 1005 Airframe PART - Life Limited #269	LEFT OLEO UPPER CAP	6541421-1	SN-UNKNOWN	04-JAN-2001 L: 790	L: 10400		M: 0 H: 0.00 L: 0	L: 11190	L: 4177
32 1005 Airframe PART - Life Limited #258	RIGHT OLEO UPPER CAP	6541421-1	SN-UNKNOWN	04-JAN-2001 L: 790	L: 10400		M: 0 H: 0.00 L: 0	L: 11190	L: 4177
32 1006 Airframe PART - Life Limited #364	LEFT OUTER BEARING ASSEMBLY	6541425-6	SN-UNKNOWN	04-JAN-2001 L: 790	L: 27600		M: 0 H: 0.00 L: 0	L: 28390	L: 21377
32 1006 Airframe PART - Life Limited #61	RIGHT OUTER BEARING ASSEMBLY	6541425-6	SN-UNKNOWN	04-JAN-2001 L: 790	L: 27600		M: 0 H: 0.00 L: 0	L: 28390	L: 21377
32 1007 Airframe PART - Life Limited #474	LEFT MAIN GEAR TRUNNION	6541460-1	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587
32 1007 Airframe PART - Life Limited #99	RIGHT MAIN GEAR TRUNNION	6541460-2	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587
32 1008 Airframe PART - Life Limited #212	LEFT TRAILING LINK ASSEMBLY	6541435-1	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587
32 1008 Airframe PART - Life Limited #81	RIGHT TRAILING LINK ASSEMBLY	6541435-2	814C	30-AUG-2014 H: 8134.10 L: 6019	L: 41600		M: 0 H: 0.00 L: 5969	L: 41650	L: 34637
32 2001 Airframe PART - Life Limited #50	NOSE LANDING GEAR ASSEMBLY	6642000-49	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 23900		M: 0 H: 0.00 L: 0	L: 23900	L: 16887

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 2002 Airframe PART #462	NOSE SHIMMY DAMPER	5543001-11	010-11X	28-FEB-2008 H: 7007.23 L: 5236					
32 2003 Airframe PART - Life Limited #128	NOSE LANDING GEAR FORK AND PISTON ASSEMBLY	6642000-3	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 13800		M: 0 H: 0.00 L: 0	L: 13800	L: 6787
32 2004 Airframe PART #180	NOSE LANDING GEAR FORK	5542300-2	SN-UNKNOWN	18-JUN-1997 H: 0.00					
32 3001 Airframe PART - Life Limited #450	LEFT MAIN LANDING GEAR ACTUATOR	9912465-5	0041	20-NOV-2008 H: 7302.60 L: 5472	L: 41600		M: 0 H: 0.00 L: 5443	L: 41629	L: 34616
32 3002 Airframe PART - Life Limited #407	RIGHT MAIN LANDING GEAR ACTUATOR	9912465-6	0568	01-DEC-2005 L: 3841	L: 41600		M: 0 H: 0.00 L: 1089	L: 44352	L: 37339
32 3003 Airframe PART - Life Limited #3	NOSE LANDING GEAR ACTUATOR	9912485-4	714	17-OCT-2004 L: 3157	L: 23900		M: 0 H: 0.00 L: 0	L: 27057	L: 20044
32 3004 Airframe PART #301	LEFT GEAR UPLOCK ACTUATOR	5527504-3	31	18-JUN-1997 H: 0.00					
32 3004 Airframe PART #392	NOSE GEAR UPLOCK ACTUATOR	5527504-2	WMP3324	21-AUG-2006 H: 4307.00					
32 3004 Airframe PART #155	RIGHT GEAR UPLOCK ACTUATOR	5527504-3	4051	17-MAR-2008 H: 7010.70 L: 5238					
32 3005 Airframe PART #125	EMERGENCY DUMP VALVE	OAS5319-1	525	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 3006 Airframe PART - Life Limited #483	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE	212940-2	9779	17-JAN-2019 H: 8618.00 L: 6313	M: 288		M: 0 H: 0.00 L: 0	30-NOV-2042	M: 242 D: 6
32 3007 Airframe PART #490	GEAR CONTROL VALVE	66710	786	18-JUN-1997 H: 0.00					
32 3008 Airframe PART #445	PISTON WELD ASSEMBLY	6642100-2	SN- UNKNOWN	18-JUN-1997 H: 0.00					
32 3019 Airframe PART #388	EMERGENCY AIR BOTTLE GAGE	2341128	62298A	18-JUN-1997 H: 0.00					
32 4001 Airframe PART #281	LEFT MAIN WHEEL	3-1562	0381	12-SEP-2019 H: 8669.40 L: 6334					
32 4001 Airframe PART #324	RIGHT MAIN WHEEL	3-1562	0537/0537	16-SEP-2020 H: 8817.30 L: 6418					
32 4002 Airframe PART #479	NOSE WHEEL	3-1418	4680	30-JUL-2014 H: 8121.50 L: 6009					
32 4003 Airframe PART #34	LEFT BRAKE	2-1588-1	0756	12-NOV-2016 H: 8370.00 L: 6166					
32 4004 Airframe PART #112	RIGHT BRAKE	9912469-7/2-1588-1	0291	12-NOV-2016 H: 8370.00 L: 6166					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4005 Airframe PART LEFT WHEEL #350	LEFT MAIN TIRE	229K48-2	91412705	12-SEP-2019 H: 8669.40 L: 6334					
32 4005 Airframe PART RIGHT WHEEL #312	RIGHT MAIN TIRE	229K48-2	91352699	12-SEP-2019 H: 8669.40 L: 6334					
32 4006 Airframe PART NOSE WHEEL #209	NOSE TIRE	031-613-8	2047T00398	08-AUG-2022 H: 8940.30 L: 7013					
32 4011 Airframe PART #216	INBOARD (CO-PILOT SIDE) MASTER BRAKE CYLINDER	9912050-18	1481	27-JUN-2008 H: 7194.40 L: 5381					
32 4011 Airframe PART #266	OUTBOARD (PILOT SIDE) MASTER BRAKE CYLINDER	9912050-17	1272	27-JUN-2008 H: 7194.42 L: 5381					
32 4012 Airframe PART #72	INBOARD (PILOT SIDE) MASTER BRAKE CYLINDER	9912050-11	1252	18-JUN-1997					
32 4012 Airframe PART #27	OUTBOARD (COPILOT SIDE) MASTER BRAKE CYLINDER	9912050-12	1671	18-JUN-1997					
32 4013 Airframe PART #256	PARKING BRAKE VALVE	9912388-2	0319A	17-JUN-2008 H: 7184.15 L: 5374					
32 4014 Airframe PART #201	EMERGENCY AIR BRAKE VALVE	895232-0875	V611	10-AUG-2008 H: 7220.55 L: 5408					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4019 Airframe PART #311	POWER BRAKE PUMP	9912166-3	5011	18-JUN-1997 H: 0.00					
32 4020 Airframe PART #499	BRAKE CONTROL BOX	9912305-14	113	18-JUN-1997 H: 0.00					
32 4021 Airframe PART #196	POWER BRAKE VALVE	9912305-12	SN- UNKNOWN	18-JUN-1997 H: 0.00					
32 4023 Airframe PART #230	HYDRAULIC ACCUMULATOR	57C57652	RH0298	26-DEC-2004 H: 4476.00					
32 4024 Airframe PART #489	LEFT WHEEL TRANSDUCER	9912305-2	3833	18-JUN-1997 H: 0.00					
32 4024 Airframe PART #460	RIGHT WHEEL TRANSDUCER	9912305-2	3810	18-JUN-1997 H: 0.00					
32 4025 Airframe PART #44	HIGH PRESSURE SWITCH	1206P27	3457	23-JUL-2004					
32 4025 Airframe PART #403	LOW PRESSURE SWITCH	9912163-1	3219	04-AUG-2008 H: 7216.70 L: 5403					
32 4026 Airframe PART #225	POWER BRAKE MOTOR ASSEMBLY	MP50B1	674	18-JUN-1997 H: 0.00					
32 4027 Airframe PART #368	FAULT DISPLAY UNIT	9912305-9	285A	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4028 Airframe PART #279	LEFT SHUTTLE VALVE	211-111	2164	15-JAN-2002					
32 4028 Airframe PART #448	RIGHT SHUTTLE VALVE	211-111	2164	22-FEB-2011 H: 7495.80 L: 5626					
32 5001 Airframe PART #228	NOSE STEERING BUNGEE	5565624-20	NSN	21-AUG-2006 H: 4307.00					
32 6002 Airframe PART #363	LEFT MAIN GEAR UP&LOCKED SWITCH	65-430087	SN- UNKNOWN	18-JUN-1997 H: 0.00					
32 6002 Airframe PART #447	RIGHT MAIN GEAR UP&LOCKED SWITCH	65-430087	SN- UNKNOWN	08-MAR-2006 H: 3977.00					
32 6003 Airframe PART #166	LEFT MAIN GEAR DOWN&LOCK SWITCH	1EN329R	SN- UNKNOWN	18-JUN-1997 H: 0.00					
32 6003 Airframe PART #224	RIGHT MAIN GEAR DOWN&LOCK SWITCH	1EN329R	SN- UNKNOWN	18-JUN-1997 H: 0.00					
32 6004 Airframe PART #466	NOSE GEAR DOWN&LOCK SWITCH	1EN329R	SN- UNKNOWN	18-JUN-1997 H: 0.00					
32 6005 Airframe PART #424	NOSE GEAR UP&LOCKED SWITCH	65-430087	SN- UNKNOWN	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 B326003 Airframe INSPECTION PBEBB #200	HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE	212940-2	9779	23-JUL-2021 H: 8838.50 L: 6434	M: 36			23-JUL-2024	M: 21 D: 29
33 1001 Airframe PART #270	ANNUNCIATOR PANEL	9912471-1	130	01-DEC-2006 H: 6067.00					
33 1002 Airframe PART #458	CENTER 5 VOLT DIMMER	273-1	4546	18-JUN-1997 H: 0.00					
33 1002 Airframe PART #391	LEFT 5 VOLT DIMMER	273-1	4545	18-JUN-1997 H: 0.00					
33 1002 Airframe PART #233	RIGHT 5 VOLT DIMMER	273-1	4547	18-JUN-1997 H: 0.00					
33 1011 Airframe PART #249	ELECTRICAL PANEL INVERTER	EM2044-1	2241A	18-JUN-1997 H: 0.00					
33 2001 Airframe PART #39	LEFT AFT POWER UNIT LIGHTING	AL-750PS	22623	29-JAN-2005 H: 4552.00					
33 2001 Airframe PART #429	LEFT CENTER AFT POWER UNIT LIGHTING	AL-750PS	24044	19-FEB-2009 H: 7375.68 L: 5529					
33 2001 Airframe PART #139	LEFT CENTER FORWARD POWER UNIT LIGHTING	AL-750PS	22949	31-AUG-2007 H: 6625.93 L: 4929					
33 2001 Airframe PART #26	LEFT FORWARD POWER UNIT LIGHTING	AL-750PS	22795	27-JUN-2005 H: 4920.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 2001 Airframe PART #33	RIGHT AFT POWER UNIT LIGHTING	AL-750PS	22661	29-JAN-2005 H: 4552.00					
33 2001 Airframe PART #315	RIGHT CENTER AFT POWER UNIT LIGHTING	AL-750PS	1129	18-JUN-1997 H: 0.00					
33 2001 Airframe PART #49	RIGHT CENTER FORWARD POWER UNIT LIGHTING	AL-750PS	417	18-JUN-1997 H: 0.00					
33 2001 Airframe PART #102	RIGHT FORWARD POWER UNIT LIGHTING	AL-750PS	368	18-JUN-1997 H: 0.00					
33 4002 Airframe PART #140	BEACON LIGHT ASSEMBLY	01-0790088-13	00209	31-JUL-2015 H: 8242.10 L: 6079					
33 4003 Airframe PART #377	LEFT STROBE POWER SUPPLY	01-0790101-04	00925	27-JUN-2004 H: 4011.00					
33 4003 Airframe PART #96	RIGHT STROBE POWER SUPPLY	01-0790101-04	00388	12-MAY-2007 H: 6388.10 L: 4715					
33 5001 Airframe PART #78	EMERGENCY BATTERY PACK	CBS28	1964	10-JUL-2005 H: 4950.00					
34 1005 Airframe PART #289	MACH WARNING SWITCH	D37C15	3057	10-MAY-2004 H: 3896.00					
34 1010 Airframe PART #178	ANGLE OF ATTACK INDICATOR	C12705-1	120	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 1013 Airframe PART #172	ANGLE OF ATTACK SENSOR	C12717-1	351	12-SEP-2019 H: 8669.40 L: 6334					
34 1014 Airframe PART #5	ANGLE OF ATTACK INDEXER	965-0113-008	114	18-JUN-1997 H: 0.00					
34 1024 Airframe PART #322	TEMPERATURE PROBE	102DB1AG	A13134	18-JUN-1997 H: 0.00					
34 1025 Airframe PART #442	ANGLE OF ATTACK COMPUTER	C12706-2	1173	21-FEB-2007 H: 6199.00					
34 1026 Airframe PART #59	STICK SHAKER CONTROL	PN	SN- UNKNOWN	18-JUN-1997 H: 0.00					
34 1036 Airframe PART #247	NO. 1 BAROMETRIC PRESS SWITCH	9910095-6	9706127	18-JUN-1997 H: 0.00					
34 1036 Airframe PART #371	NO. 2 BAROMETRIC PRESS SWITCH	GBC300-140	9633129	18-JUN-1997 H: 0.00					
34 1037 Airframe PART #58	PRESSURE SWITCH	99120575	1546	18-JUN-1997 H: 0.00					
34 1038 Airframe PART #9	OAT INDICATOR	C307FCL	A3078	18-JUN-1997 H: 0.00					
34 2001 Airframe PART #185	MAGNETIC COMPASS	C660501-0301	SN- UNKNOWN	17-JUN-2011 H: 7501.30 L: 5631					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 2042 Airframe PART #295	LEFT MODE SELECTOR	7018341-803	97010747	04-JAN-2001 H: 1010.00					
34 2042 Airframe PART #267	RIGHT MODE SELECTOR	7018341-803	03032311	15-OCT-2005 H: 5230.00					
34 2043 Airframe PART #395	LEFT VERTICAL GYRO	7000622-901	03109542	10-APR-2014 H: 8087.80 L: 5974					
34 2043 Airframe PART #345	RIGHT VERTICAL GYRO	7000622-901	98058588	30-AUG-2014 H: 8134.10 L: 6019					
34 2044 Airframe PART #417	RATE GYRO	7007453-903	96124220	18-JUN-1997 H: 0.00					
34 2048 Airframe PART #98	LEFT AIR DATA COMPUTER	7014700-920	97061256	07-FEB-2011 H: 7495.80 L: 5626					
34 2048 Airframe PART #296	RIGHT AIR DATA COMPUTER	7014700-920	99113270	06-NOV-2018 H: 8594.40 L: 6300					
34 2049 Airframe PART #262	LEFT DIRECTIONAL GYRO	4020577-3	98036417	01-DEC-2008 H: 7310.00 L: 5481					
34 2049 Airframe PART #41	RIGHT DIRECTIONAL GYRO	4020577-3	98046448	11-JUN-2009 H: 7454.70 L: 5599					
34 2050 Airframe PART #171	LEFT FLUX VALVE	2594484	97102470	05-AUG-2008 H: 7216.70 L: 5403					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 2050 Airframe PART #144	RIGHT FLUX VALVE	2594484	97012012	18-JUN-1997 H: 0.00					
34 2052 Airframe PART #210	REMOTE COMPENSATOR	2593379-1	96112212	18-JUN-1997 H: 0.00					
34 2054 Airframe PART #115	STANDBY HSI INDICATOR	520-3150-004	18224	26-FEB-2001 H: 1039.00					
34 2063 Airframe PART #84	REMOTE CONTROL HEADING INDICATOR	7016954-907	96120517	18-JUN-1997 H: 0.00					
34 2064 Airframe PART #35	STANDBY BATTERY PACK	501-1712-02	2360	20-APR-2015 H: 8201.80 L: 6057					
34 2076 Airframe PART #285	AFIS DATA TRANSFER UNIT	400-015655-0101	1320	04-JAN-2001 H: 1010.00					
34 2078 Airframe PART #482	LEFT AVIONICS COMPUTER	7017000-80130	00093714	28-JAN-2008 H: 6923.60 L: 5176					
34 2078 Airframe PART #91	RIGHT AVIONICS COMPUTER	7017000-80130	97020964	01-DEC-2005 H: 5242.00					
34 2079 Airframe PART #229	NO. 1 DISPLAY CONTROL	7016986-723	97030975	01-DEC-2005 H: 5242.00					
34 2079 Airframe PART #138	NO. 2 DISPLAY CONTROL	7016986-723	97121326	26-JUL-2007 H: 6523.43 L: 4840					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 2080 Airframe PART #303	MFD 1 FLIGHT DISPLAY BEZEL	7014332-841	96121107	18-JUN-1997 H: 0.00					
34 2080 Airframe PART #22	NO. 1 FLIGHT DISPLAY BEZEL	7014331-931	97010809	18-JUN-1997 H: 0.00					
34 2080 Airframe PART #480	NO. 2 FLIGHT DISPLAY BEZEL	7014331-931	97010808	18-JUN-1997 H: 0.00					
34 2081 Airframe PART #104	CENTER PRIMARY FLIGHT DISPLAY	7014300-901/DU-870	98083475	22-JUN-2020 H: 8793.10 L: 6394					
34 2081 Airframe PART #28	NO. 1 PRIMARY FLIGHT DISPLAY	7014300-901	01069676	15-JUL-2020 H: 8800.60 L: 6399					
34 2081 Airframe PART #497	NO. 2 PRIMARY FLIGHT DISPLAY	7014300-901/DU-870	00016016	21-AUG-2020 H: 8812.70 L: 6412					
34 2083 Airframe PART #15	SECONDARY ADU	27005-00-08	M005234	22-FEB-2011 H: 7495.80 L: 5626					
34 2084 Airframe PART #386	SECONDARY FLIGHT DISPLAY	26000-30-07	M001050	06-JUN-2014 H: 8108.70 L: 5992					
34 3001 Airframe PART #189	GLIDESLOPE COUPLER	PN	SN- UNKNOWN	18-JUN-1997 H: 0.00					
34 3002 Airframe PART #170	NAV ANTENNA COUPLER	CI-120-5	181168	29-JUN-2007 H: 6480.50 L: 4791					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 4004 Airframe PART #188	RADAR RECEIVER/TRANSMITTER	7012640-921	88060121	26-SEP-2008 H: 7244.55 L: 5424					
34 4022 Airframe PART #328	RADIO ALTIMETER RECEIVER/TRANSMITTER	622-2855-011	10836	18-JUN-1997 H: 0.00					
34 4023 Airframe PART #208	AFT RADIO ALTIMETER ANTENNA	622-0954-001	3V6LC	22-FEB-2011 H: 7495.80 L: 5626					
34 4023 Airframe PART #361	FORWARD RADIO ALTIMETER ANTENNA	622-0954-001	3V6LB	22-FEB-2011 H: 7495.80 L: 5626					
34 4024 Airframe PART #408	GPWS/EGPWS COMPUTER	965-1076-040-206-206	1653	30-OCT-2007 H: 6756.32 L: 5037					
34 4034 Airframe PART #356	RADAR CONTROLLER	7008471-803	97012703	18-JUN-1997 H: 0.00					
34 5004 Airframe PART #314	AFT BOTTOM TRANSPONDER ANTENNA	DMNI50-2-2	63740	18-JUN-1997 H: 0.00					
34 5004 Airframe PART #406	FORWARD BOTTOM TRANSPONDER ANTENNA	DMNI50-2-2	63748	18-JUN-1997 H: 0.00					
34 5007 Airframe PART #358	LEFT DME ANTENNA	DMNI50-2-2	64979	03-SEP-1997 H: 84.00					
34 5007 Airframe PART #365	RIGHT DME ANTENNA	DMNI50-2-2	63738	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 5010 Airframe PART #66	LEFT NAV ANTENNA	CI120-1-L	179416	29-JUN-2007 H: 6480.50 L: 4791					
34 5010 Airframe PART #156	RIGHT NAV ANTENNA	CI120-1-L	179417	29-JUN-2007 H: 6480.50 L: 4791					
34 5011 Airframe PART #298	LEFT ADF RECEIVER	PN	SN- UNKNOWN	18-JUN-1997 H: 0.00					
34 5011 Airframe PART #64	RIGHT ADF RECEIVER	066-01072-0006	68438	15-NOV-2012 H: 7777.30 L: 5809					
34 5014 Airframe PART #141	LEFT ADF LOOP ANTENNA	071-01234-02	KA44B- 01234-02	14-DEC-2017 H: 8483.20 L: 6232					
34 5017 Airframe PART #317	MARKER BEACON ANTENNA	31-10-01	SN- UNKNOWN	18-JUN-1997 H: 0.00					
34 5018 Airframe PART #307	GLIDE SLOPE ANTENNA	RGS1048	A4964	26-SEP-2008 H: 7244.55 L: 5424					
34 5031 Airframe PART #197	LEFT MARKER BEACON RECEIVER	066-01044-0000	5187	18-JUN-1997 H: 0.00					
34 5031 Airframe PART #79	RIGHT MARKER BEACON RECEIVER	066-01044-0000	5189	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 5032 Airframe PART #174	NO. 1 NAV RECEIVER	066-01067-0004	71086	18-APR-2008 H: 7080.02 L: 5289					
34 5032 Airframe PART #432	NO. 2 NAV RECEIVER	066-01067-0004	71193	08-SEP-2006 H: 5903.00					
34 5034 Airframe PART #381	LEFT TRANSPONDER	066-01141-1101	11234	17-FEB-2011 H: 7495.80 L: 5626					
34 5034 Airframe PART #142	RIGHT TRANSPONDER	066-01141-1101	14692	17-JUN-2011 H: 7501.30 L: 5631					
34 5035 Airframe PART #401	NO. 1 DME INDICATOR	066-01069-0015	1162	31-JUL-2003 H: 3124.00					
34 5035 Airframe PART #287	NO. 2 DME INDICATOR	066-01069-0015	1037	18-JUN-1997 H: 0.00					
34 5036 Airframe PART #409	NO. 2 DME INTERROGATOR	066-01107-0012	10124	11-JUN-1998 H: 285.00					
34 5036 Airframe PART #272	NO. 2 DME INTERROGATOR	066-01107-0012	30769	28-SEP-2002 H: 2248.00					
34 5053 Airframe PART #223	UNS FMS CONTROL DISPLAY UNIT	1117-1-106	5611	16-JUN-2011 H: 7501.30 L: 5629					
34 5083 Airframe PART #158	NAV FMS CONTROL	3116-42-1116	741	21-AUG-2018 H: 8580.20 L: 6287					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 5108 Airframe PART #248	VOR CONVERTER	066-01130-0701	10841	18-JUN-1997 H: 0.00					
34 5118 Airframe PART #23	LEFT GPS ANTENNA	10706	6649	16-JUN-2011 H: 7501.30 L: 5629					
34 5118 Airframe PART #459	RIGHT GPS ANTENNA	10706	6647	16-JUN-2011 H: 7501.30 L: 5629					
34 5129 Airframe PART #343	MULTIFUNCTION DISPLAY CONTROLLER	7007062-941	02112848	24-OCT-2006 H: 6002.00					
34 5131 Airframe PART #284	AFIS DATA MFT UNIT	400-045500-0003	2792	04-JAN-2001 H: 1010.00					
34 6011 Airframe PART #165	LEFT FMS 1 CONFIGURATION MODULE	31921	938	16-JUN-2011 H: 7501.30 L: 5631					
34 6014 Airframe PART #42	UNS DATA TRANSFER UNIT	1408-00-01	1330	16-JUN-2011 H: 7501.30 L: 5631					
34 6030 Airframe PART #362	CENTER TCAS CONTROL	071-01568-0901	2297	30-OCT-2002 H: 2344.00					
34 6030 Airframe PART #439	TCAS PROCESSOR	066-01145-0101	2765	10-JAN-2013 H: 7822.20 L: 5828					
34 6031 Airframe PART #177	LOWER TCS ANTENNA	071-01548-0100	6872	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 6031 Airframe PART #116	UPPER TCAS ANTENNA Part Number: 071-01548-0100 Serial Number: 6993	18-JUN-1997 H: 0.00					
34 A341005 Airframe INSPECTION PHASE 20 #80	PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
34 B341001 Airframe INSPECTION PHASE 20 #126	CALIBRATION TEST LEFT AIR DATA COMPUTER (FAR 91.411): PHASE 20	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
34 B341001 Airframe INSPECTION PHASE 20 #367	CALIBRATION TEST RIGHT AIR DATA COMPUTER (FAR 91.411): PHASE 20	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
34 B341001 Airframe INSPECTION PHASE 20 #101	CALIBRATION TEST SECONDARY ADU (FAR 91.411): PHASE 20	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
34 B345001 Airframe INSPECTION PHASE 21 #30	CALIBRATION CHECK LEFT TRANSPONDER (FAR 91.413): PHASE 21	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
34 B345001 Airframe INSPECTION PHASE 21 #46	CALIBRATION CHECK RIGHT TRANSPONDER (FAR 91.413): PHASE 21	23-JUL-2021 H: 8838.50 L: 6434	M: 24			23-JUL-2023	M: 9 D: 29
34 FO-04(550) Airframe INSPECTION #12	LOCATOR BEACON-EMERGENCY	18-JUN-1997					
35 1001 Airframe PART #1	OXYGEN PRESSURE GAGE Part Number: PN Serial Number: SN-UNKNOWN	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 1004 Airframe PART - Overhaul #187	COPILOT OXYGEN MASK	MC10-16-101	101461	02-AUG-2017 H: 8426.60 L: 6200	M: 72		M: 3 H: 0.00 L: 0	02-MAY-2023	M: 7 D: 8
35 1004 Airframe PART - Overhaul #243	PILOT OXYGEN MASK	9914067-41(MC10-16-101)	SE80332	23-JUL-2021 H: 8838.50 L: 6434	M: 72		M: 0	23-JUL-2027	M: 57 D: 29
35 1005 Airframe PART #495	OXYGEN REGULATOR	172170-01	4252	22-JUL-2009 H: 7495.30 L: 5625					
35 1006 Airframe PART - Life Limited #175	OXYGEN CYLINDER	176176-64	780367	22-JUL-2009 H: 7495.53 L: 5625	M: 288		M: 73 H: 0.00 L: 0	30-JUN-2027	M: 57 D: 6
35 B350005 Airframe INSPECTION OXY CYL #63	HYDROSTATIC TEST OXYGEN CYLINDER	176176-64	780367	23-JUL-2021 H: 8838.50 L: 6434	M: 36			23-JUL-2024	M: 21 D: 29
36 1000 Airframe PART #133	FLOW CONTROL PRESSURE REGULATOR VALVE	PN	SN-UNKNOWN	18-JUN-1997 H: 0.00					
36 1001 Airframe PART #308	DOOR SEAL VALVE	MJV3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
36 1003 Airframe PART #19	DEICE BOOT REGULATOR	9912043-2	217-U	17-MAR-2008 H: 7010.70 L: 5238					
36 1008 Airframe PART #203	LEFT PNEUMATIC B/A VALVE	PN	SN-UNKNOWN	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 1008 Airframe PART #106	RIGHT PNEUMATIC B/A VALVE	PN	SN-UNKNOWN	18-JUN-1997 H: 0.00					
52 1001 Airframe PART #24	CABIN DOOR SEAL	9912075-4	SN-UNKNOWN	14-AUG-2004 H: 4166.00					
53 1001 Airframe PART - Life Limited #154	LEFT TRUNNION SUPPORT FITTING	6613056-3	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 12200		M: 0 H: 0.00 L: 0	L: 12200	L: 5187
53 1001 Airframe PART - Life Limited #378	RIGHT TRUNNION SUPPORT FITTING	6613056-4	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 12200		M: 0 H: 0.00 L: 0	L: 12200	L: 5187
53 1002 Airframe PART - Life Limited #51	ACTUATOR SUPPORT FITTING	6511105-1	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 23900		M: 0 H: 0.00 L: 0	L: 23900	L: 16887
53 1201 Airframe PART #89	RADOME ASSEMBLY	6313101-846	147	12-NOV-2016 H: 8370.00 L: 6166					
55 4000 Airframe PART #428	RUDDER ASSEMBLY	5533000-93	0814	13-JUL-2012 H: 7723.70 L: 5772					
56 1001 Airframe PART #446	LEFT WINDSHIELD ASSY	93200-15/9912064-15	4199	29-JUN-2007 H: 6479.90 L: 4791					
56 1001 Airframe PART #232	RIGHT WINDSHIELD ASSY	93200-16/9912064-16	1332	29-JUN-2007 H: 6479.90 L: 4791					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 1003 Airframe PART #457	FOUL WEATHER WINDOW	5511275-17	2652	06-NOV-2008 H: 7302.60 L: 5472					
56 1005 Airframe PART #453	LEFT INBOARD FLIGHT COMPARTMENT WINDOW	5511285-5	SN-UNKNOWN	21-JUL-2005 H: 4955.00					
56 1005 Airframe PART #396	LEFT OUTBOARD FLIGHT COMPARTMENT WINDOW	5511285-47	05-14-2004	21-AUG-2006 H: 5870.00					
56 1005 Airframe PART #164	RIGHT INBOARD FLIGHT COMPARTMENT WINDOW	5511285-6	SN-UNKNOWN	21-NOV-2003 H: 3401.00					
56 1005 Airframe PART #339	RIGHT OUTBOARD FLIGHT COMPARTMENT WINDOW	5511285-200	NSN	22-FEB-2011 H: 7495.80 L: 5626					
56 2001 Airframe PART #82	LEFT NO. 1 MAIN DOOR WINDOW	9912207-8	SN-UNKNOWN	18-JUN-1997 H: 0.00					
56 2001 Airframe PART #441	LEFT NO. 2 CABIN WINDOW	6311123-201	5591	13-JUN-2006 H: 5706.00					
56 2001 Airframe PART #265	LEFT NO. 3 CABIN WINDOW	9912207-8	4175	22-FEB-2011 H: 7495.80 L: 5626					
56 2001 Airframe PART #153	LEFT NO. 4 CABIN WINDOW	9912207-8	SN-UNKNOWN	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 2001 Airframe PART #500	LEFT NO. 5 CABIN WINDOW	6311123-201	5588	13-JUN-2006 H: 5706.00					
56 2001 Airframe PART #352	LEFT NO. 6 CABIN WINDOW	5591005-5	SN- UNKNOWN	18-JUN-1997 H: 0.00					
56 2001 Airframe PART #355	RIGHT NO. 1 EMERGENCY DOOR WINDOW	9912207-8	SN- UNKNOWN	18-JUN-1997 H: 0.00					
56 2001 Airframe PART #67	RIGHT NO. 2 CABIN WINDOW	9912207-8	SN- UNKNOWN	18-JUN-1997 H: 0.00					
56 2001 Airframe PART #425	RIGHT NO. 3 CABIN WINDOW	161100-03	4175	22-FEB-2011 H: 7495.80 L: 5626					
56 2001 Airframe PART #493	RIGHT NO. 4 CABIN WINDOW	9912207-8	SN- UNKNOWN	18-JUN-1997 H: 0.00					
56 2001 Airframe PART #470	RIGHT NO. 5 CABIN WINDOW	9912207-8	SN- UNKNOWN	18-JUN-1997 H: 0.00					
56 2001 Airframe PART #440	RIGHT NO. 6 CABIN WINDOW	5591005-5	SN- UNKNOWN	18-JUN-1997 H: 0.00					
57 2001 Airframe PART - Life Limited #327	LEFT FORWARD TRUNNION ATTACH FITTING	6522460-5	SN- UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 2002 Airframe PART - Life Limited #240	RIGHT FORWARD TRUNNION ATTACH FITTING	6522460-6	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587
57 4001 Airframe PART - Life Limited #389	LEFT AFT TRUNNION ATTACH FITTING	6522465-1	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587
57 4002 Airframe PART - Life Limited #222	RIGHT AFT TRUNNION ATTACH FITTING	6522465-2	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587
57 4003 Airframe PART - Life Limited #485	LEFT SIDE BRACE FITTING	6521435-1	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587
57 4004 Airframe PART - Life Limited #227	RIGHT SIDE BRACE FITTING	6521435-2	SN-UNKNOWN	18-JUN-1997 H: 0.00	L: 41600		M: 0 H: 0.00 L: 0	L: 41600	L: 34587
71 0020 Engine 1 INSPECTION #5	ENGINE 1 PERFORMANCE RECOVERY WASH			18-JUN-1997					
71 0020 Engine 2 INSPECTION #7	ENGINE 2 PERFORMANCE RECOVERY WASH			02-AUG-2018 H: 8577.20 L: 6283					
71 2001 Airframe PART - Life Limited #492	LEFT ENGINE REAR (AFT) ISOLATOR MOUNT	9912477-2	LK0620	27-JUN-2004 H: 4011.00	H: 8000.00		M: 0 H: 0.00 L: 0	H: 12011.00	H: 3070.70
71 2001 Airframe PART - Life Limited #475	RIGHT ENGINE REAR (AFT) ISOLATOR MOUNT	9912477-2	LK0661	27-JUN-2004 H: 4011.00	H: 8000.00		M: 0 H: 0.00 L: 0	H: 12011.00	H: 3070.70

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 2002 Airframe PART - Life Limited #238	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT Part Number: 9912477-2 Serial Number: LK0637	27-JUN-2004 H: 4011.00	H: 8000.00		M: 0 H: 0.00 L: 0	H: 12011.00	H: 3070.70
71 2002 Airframe PART - Life Limited #487	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT Part Number: 9912477-2 Serial Number: LK0632	27-JUN-2004 H: 4011.00	H: 8000.00		M: 0 H: 0.00 L: 0	H: 12011.00	H: 3070.70
71 2002 Airframe PART - Life Limited #17	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT Part Number: 9912477-2 Serial Number: LK0615	27-JUN-2004 H: 4011.00	H: 8000.00		M: 0 H: 0.00 L: 0	H: 12011.00	H: 3070.70
71 2002 Airframe PART - Life Limited #472	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT Part Number: 9912477-2 Serial Number: LK0613	27-JUN-2004 H: 4011.00	H: 8000.00		M: 0 H: 0.00 L: 0	H: 12011.00	H: 3070.70
71 2005 Airframe PART #100	ENGINE VIBRATION MONITOR Part Number: 9912519-2 Serial Number: 119609	18-JUN-1997 H: 0.00					
71 EN1 Airframe PART #6	NO. 1 ENGINE Part Number: 31J1400-01 Serial Number: PCE-DA0054						
71 EN2 Airframe PART #179	NO. 2 ENGINE Part Number: 31J1400-01 Serial Number: PCE-DA0058						
72 0010 Engine 1 INSPECTION #32	ENGINE 1 OVERHAUL	13-AUG-2019 H: 8669.40 C: 6334	H: 4000.00	H: 100.00		H: 12669.40	H: 4129.10
72 0010 Engine 2 INSPECTION #6	ENGINE 2 OVERHAUL	26-AUG-2019 H: 8669.40 C: 6334	H: 4000.00	H: 100.00		H: 12669.40	H: 4129.10
72 0060 Engine 1 INSPECTION #42	ENGINE 1 BORESCOPE INSPECTION	13-AUG-2019 H: 8669.40 C: 6334	H: 2000.00			H: 10669.40	H: 2129.10

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0060 Engine 2 INSPECTION #44	ENGINE 2 BORESCOPE INSPECTION	26-AUG-2019 H: 8669.40 C: 6334	H: 2000.00			H: 10669.40	H: 2129.10
72 2001 Engine 1 PART #34	NO. 1 ENGINE - OIL PUMP Part Number: 30J2106-01 Serial Number: PWV04001 9P5	13-AUG-2019 H: 8669.40 C: 6334					
72 2001 Engine 2 PART #27	NO. 2 ENGINE - OIL PUMP Part Number: 30J2106-01 Serial Number: 23A225	26-AUG-2019 H: 8669.40 C: 6334					
72 3001 Engine 1 PART #15	NO. 1 ENGINE - FAN Part Number: 30J2142-01 Serial Number: 4K988	17-OCT-2004 H: 4318.00					
72 3001 Engine 2 PART #31	NO. 2 ENGINE - FAN Part Number: 30J2142-01 Serial Number: 2K089	17-OCT-2004 H: 4318.00					
72 3010 Engine 1 PART - Life Limited #247	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR Part Number: 30J1541-01 Serial Number: 42B749	17-OCT-2004	C: 15000		M: 0 H: 0.00 C: 0	C: 15000.00	C: 8357
72 3010 Engine 2 PART - Life Limited #25	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR Part Number: 30J1541-01 Serial Number: 42B770	17-OCT-2004	C: 15000		M: 0 H: 0.00 C: 0	C: 15000.00	C: 8357
72 3030 Engine 1 PART - Life Limited #7	NO. 1 ENGINE - 1ST-STAGE HP COMPRESSOR ROTOR Part Number: 30J1391 Serial Number: 37B568	17-OCT-2004	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 6857
72 3030 Engine 2 PART - Life Limited #46	NO. 2 ENGINE - 1ST-STAGE HP COMPRESSOR ROTOR Part Number: 30J1391 Serial Number: 41B930	18-JUN-1997	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 6857
72 3040 Engine 1 PART - Life Limited #35	NO. 1 ENGINE - 2ND-STAGE HP COMPRESSOR ROTOR Part Number: 30J2082-01 Serial Number: 41B941	13-AUG-2019	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 6857

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3040 Engine 2 PART - Life Limited #13	NO. 2 ENGINE - 2ND-STAGE HP COMPRESSOR ROTOR Part Number: 30J2082-01 Serial Number: 42B631	26-AUG-2019	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 6857
72 3060 Engine 1 PART - Life Limited #30	ENGINE 1 CENTRIFUGAL IMPELLER Part Number: 30J1280 Serial Number: 8F855	17-OCT-2004	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 6857
72 3060 Engine 2 PART - Life Limited #29	ENGINE 2 CENTRIFUGAL IMPELLER Part Number: 30J1280 Serial Number: 8F775	17-OCT-2004	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 6857
72 4001 Engine 1 PART #18	ENGINE 1 COMBUSTION LINER Part Number: 30J1663-01 Serial Number: 7L592	17-OCT-2004 H: 4318.00					
72 4001 Engine 1 PART #33	ENGINE 1 INNER COMBUSTION LINER Part Number: PN Serial Number: SN-UNKNOWN	18-JUN-1997					
72 4001 Engine 1 PART #6	ENGINE 1 OUTER COMBUSTION LINER Part Number: PN Serial Number: SN-UNKNOWN	18-JUN-1997					
72 4001 Engine 2 PART #35	ENGINE 2 COMBUSTION LINER Part Number: 30J1663-01 Serial Number: 7L552	17-OCT-2004 H: 4318.00					
72 4001 Engine 2 PART #24	ENGINE 2 INNER COMBUSTION LINER Part Number: PN Serial Number: SN-UNKNOWN	18-JUN-1997					
72 4001 Engine 2 PART #20	ENGINE 2 OUTER COMBUSTION LINER Part Number: PN Serial Number: SN-UNKNOWN	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 4707 Engine 1 PART #22	NO. 1 ENGINE - HIGH TURBINE BLADES Part Number: 31J2498-01 Serial Number: SN-UNKNOWN	17-OCT-2004 C: 3158					
72 4707 Engine 2 PART #38	NO. 2 ENGINE - HIGH TURBINE BLADES Part Number: 31J2498-01 Serial Number: SN-UNKNOWN	17-OCT-2004 C: 3158					
72 4710 Engine 1 PART #2	ENGINE 1 MAGNETIC CHIP COLLECTOR Part Number: 31J2558-01 Serial Number: LB0116	17-OCT-2004 H: 4318.00					
72 4710 Engine 2 PART #10	ENGINE 2 MAGNETIC CHIP COLLECTOR Part Number: 31J2558-01 Serial Number: LB0146	17-OCT-2004 H: 4318.00					
72 5000 Engine 1 INSPECTION #249	NO.1 ENG - DISCARD OF HP TURBINE NUT AND KEYWASHER Notes: AT OVERHAUL		H: 4000.00	H: 100.00		H: 12669.40	H: 4129.10
72 5000 Engine 2 INSPECTION #248	NO.2 ENG - DISCARD OF HP TURBINE NUT AND KEYWASHER Notes: AT OVERHAUL		H: 4000.00	H: 100.00		H: 12669.40	H: 4129.10
72 5010 Engine 1 PART - Life Limited #48	NO. 1 ENGINE - 1ST-STAGE TURBINE DISK Part Number: 30J1401 Serial Number: 41B261	17-OCT-2004	C: 12000		M: 0 H: 0.00 C: 0	C: 12000.00	C: 5357
72 5010 Engine 2 PART - Life Limited #17	NO. 2 ENGINE - 1ST-STAGE TURBINE DISK Part Number: 30J1401 Serial Number: 44B825	17-OCT-2004	C: 12000		M: 0 H: 0.00 C: 0	C: 12000.00	C: 5357
72 5020 Engine 1 PART - Life Limited #20	NO. 1 ENGINE - 2ND-STAGE TURBINE DISK Part Number: 30H1322 Serial Number: 59B022	13-AUG-2019 C: 2788	C: 13500		M: 0 H: 0.00 C: 0	C: 16288.00	C: 9645

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5020 Engine 2 PART - Life Limited #33	NO. 2 ENGINE - 2ND-STAGE TURBINE DISK	30H1322	59B006	26-AUG-2019 C: 2788	C: 13500		M: 0 H: 0.00 C: 0	C: 16288.00	C: 9645
72 5030 Engine 1 PART - Life Limited #8	NO. 1 ENGINE - 3RD-STAGE TURBINE DISK	30H1309	92A306	17-OCT-2004	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 6857
72 5030 Engine 2 PART - Life Limited #32	NO. 2 ENGINE - 3RD-STAGE TURBINE DISK	30H1309	92A303	17-OCT-2004	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 6857
72 6001 Engine 1 PART #40	ENGINE 1 MAIN GEARBOX ASSEMBLY	3033370	SN- UNKNOWN	17-OCT-2004 H: 4318.00					
72 6001 Engine 2 PART #9	ENGINE 2 MAIN GEARBOX ASSEMBLY	3033370	SN- UNKNOWN	17-OCT-2004 H: 4318.00					
73 1001 Airframe PART #354	LEFT LOW FUEL PRESSURE SWITCH	9912033-2	5888	14-NOV-2006 H: 6036.00					
73 1001 Airframe PART #121	RIGHT LOW FUEL PRESSURE SWITCH	9912033-2	7382	14-NOV-2006 H: 6036.00					
73 1002 Engine 1 PART #24	NO. 1 ENGINE - FLOW DIVIDER	814900-6	F37191	13-AUG-2019 H: 8669.40 C: 6334					
73 1002 Engine 2 PART #37	NO. 2 ENGINE - FLOW DIVIDER	814900-6	F36139	26-AUG-2019 H: 8669.40 C: 6334					
73 1005 Engine 1 PART #37	NO. 1 ENGINE - BLEED CONTROL VALVE	816950-4-005	97052431	13-AUG-2019 H: 8669.40 C: 6334					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1005 Engine 2 PART #8	NO. 2 ENGINE - BLEED CONTROL VALVE Part Number: 816950-4-005 Serial Number: 97064008	26-AUG-2019 H: 8669.40 C: 6334					
73 1030 Engine 1 INSPECTION #43	ENGINE 1 INSTALL NEW FUEL FILTER ELEMENT	23-JUL-2021 H: 8438.50 C: 6064	M: 24 H: 900.00	H: 50.00		23-JUL-2023 H: 9338.50	M: 9 D: 29 H: 798.20
73 1030 Engine 2 INSPECTION #39	ENGINE 2 INSTALL NEW FUEL FILTER ELEMENT	23-JUL-2021 H: 8438.50 C: 6064	M: 24 H: 900.00	H: 50.00		23-JUL-2023 H: 9338.50	M: 9 D: 29 H: 798.20
73 1050 Engine 1 INSPECTION #38	ENGINE 1 FUEL NOZZLE - OVERHAUL OR REFURBISH	13-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
73 1050 Engine 2 INSPECTION #23	ENGINE 2 FUEL NOZZLE - OVERHAUL OR REFURBISH	26-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
73 1055 Engine 1 INSPECTION #21	FLOW DIVIDER - OVERHAUL OR REFURBISH	13-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
73 1055 Engine 2 INSPECTION #18	FLOW DIVIDER - OVERHAUL OR REFURBISH	26-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
73 1100 Engine 1 INSPECTION #28	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	13-AUG-2019 H: 8669.40 C: 6334	H: 900.00	H: 50.00		H: 9569.40	H: 1029.10
73 1100 Engine 2 INSPECTION #26	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	26-AUG-2019 H: 8669.40 C: 6334	H: 900.00	H: 50.00		H: 9569.40	H: 1029.10
73 1110 Engine 1 INSPECTION #4	DIMENSIONAL CHECK EMERGENCY FUEL SHUTOFF PIN	13-AUG-2019 H: 8669.40 C: 6334					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1110 Engine 2 INSPECTION #11	DIMENSIONAL CHECK EMERGENCY FUEL SHUTOFF PIN	26-AUG-2019 H: 8669.40 C: 6334					
73 2001 Engine 1 PART #1	ENGINE 1 (FCU) FUEL CONTROL UNIT Part Number: 1012632-26 Serial Number: F54447	21-JUN-2021 H: 8836.80 L: 6432					
73 2001 Engine 2 PART #43	ENGINE 2 (FCU) FUEL CONTROL UNIT Part Number: 1012632-26 Serial Number: F55031	21-JUN-2021 H: 8836.80 L: 6432					
73 2002 Airframe PART #484	ENGINE SYNCRONIZATION CONTROL Part Number: 213693E Serial Number: 13992412	12-FEB-2005 H: 4590.00					
73 2003 Airframe PART #338	ENGINE SYNCRONIZATION ACTUATOR Part Number: 5485-066 Serial Number: 12291094	22-OCT-2002 H: 2320.00					
73 2005 Airframe PART #110	FUEL QUANTITY/FUEL FLOW INDICATOR Part Number: 10603N01M01 Serial Number: 01090713A	06-NOV-2018 H: 8594.40 L: 6300					
73 2010 Engine 1 INSPECTION #27	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT,RECONNECT AND PERFORM ENGINE CHECKS REQUIREDFOLLOWING WIRING HARNESS REPLACEMENT	13-AUG-2019 H: 8669.40 C: 6334	H: 900.00	H: 50.00		H: 9569.40	H: 1029.10
73 2010 Engine 2 INSPECTION #16	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT,RECONNECT AND PERFORM ENGINE CHECKS REQUIREDFOLLOWING WIRING HARNESS REPLACEMENT	26-AUG-2019 H: 8669.40 C: 6334	H: 900.00	H: 50.00		H: 9569.40	H: 1029.10
73 2050 Engine 1 INSPECTION #36	OVERHAUL - FUEL CONTROL UNIT AND PUMP	21-JUN-2021 H: 8836.80 C: 6432	H: 4000.00			H: 12836.80	H: 4296.50
73 2050 Engine 2 INSPECTION #19	OVERHAUL - FUEL CONTROL UNIT AND PUMP	21-JUN-2021 H: 8836.80 C: 6432	H: 4000.00			H: 12836.80	H: 4296.50

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 2051 Engine 1 INSPECTION #11	FUEL PUMP OVERHAUL	13-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
73 2051 Engine 2 INSPECTION #2	FUEL PUMP OVERHAUL	26-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
73 3003 Airframe PART #449	LEFT FUEL FLOW TRANSMITTER Part Number: 9-213-28 Serial Number: L8259	08-AUG-2022 H: 8940.30 L: 7013					
73 3003 Airframe PART #182	RIGHT FUEL FLOW TRANSMITTER Part Number: 9-231-28 Serial Number: L7766	15-JUL-2016 H: 8344.50 L: 6142					
74 1001 Engine 1 PART #26	ENGINE 1 IGNITION EXCITER Part Number: 31J2807-07 Serial Number: NNA04321170	17-OCT-2004 H: 4318.00					
74 1001 Engine 2 PART #47	ENGINE 2 IGNITION EXCITER Part Number: 31J2807-03 Serial Number: NN98070073	17-OCT-2004 H: 4318.00					
74 2001 Engine 1 PART #29	NO. 1 ENGINE - INNER IGNITOR Part Number: 30J2825-01 Serial Number: SN-UNKNOWN	14-AUG-2019 H: 8669.40 C: 6334					
74 2001 Engine 1 PART #46	NO. 1 ENGINE - OUTER IGNITOR Part Number: 30J2825-01 Serial Number: SN-UNKNOWN	14-AUG-2019 H: 8669.40 C: 6334					
74 2001 Engine 2 PART #12	NO. 2 ENGINE - INNER IGNITOR Part Number: PN-UNKNOWN Serial Number: SN-UNKNOWN	16-MAY-2017 H: 8398.40 C: 6179					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
74 2001 Engine 2 PART #5	NO. 2 ENGINE - OUTER IGNITOR Part Number: 30J2825-01 Serial Number: NNA09400060	11-MAY-2010 H: 7495.53 C: 5625					
74 2002 Engine 1 PART #9	NO. 1 ENGINE - LONG IGNITOR LEAD Part Number: 30J3124-02 Serial Number: NNA08094753	11-MAY-2010 H: 7495.53 C: 5625					
74 2002 Engine 2 PART #30	NO. 2 ENGINE - LONG IGNITOR LEAD Part Number: 30J3124-02 Serial Number: NNA07517024	11-MAY-2010 H: 7495.53 C: 5625					
74 2003 Engine 1 PART #39	NO. 1 ENGINE - SHORT IGNITOR LEAD Part Number: 30J3124-01 Serial Number: NNA07485140	11-MAY-2010 H: 7495.53 C: 5625					
74 2003 Engine 2 PART #28	NO. 2 ENGINE - SHORT IGNITOR LEAD Part Number: 30J3124-01 Serial Number: NNA08013706	11-MAY-2010 H: 7495.53 C: 5625					
75 0030 Engine 1 INSPECTION #23	REPLACE INTERCOMPRESSOR BLEED VALVE SERVO VALVE	13-AUG-2019 H: 8669.40 C: 6334					
75 0030 Engine 2 INSPECTION #1	REPLACE INTERCOMPRESSOR BLEED VALVE SERVO VALVE	26-AUG-2019 H: 8669.40 C: 6334					
75 0050 Engine 1 INSPECTION #19	ANTI-ICING VALVE - OVERHAUL OR REFURBISH	13-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
75 0050 Engine 2 INSPECTION #40	ANTI-ICING VALVE - OVERHAUL OR REFURBISH	26-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
75 1003 Engine 1 PART #12	NO. 1 ENGINE - BLEED VALVE	31J2547-01	25A105	13-AUG-2019 H: 8669.40 C: 6334					
75 1003 Engine 2 PART #34	NO. 2 ENGINE - BLEED VALVE	31J2547-01	24A893	26-AUG-2019 H: 8669.40 C: 6334					
75 1004 Engine 1 PART #31	NO. 1 ENGINE - INTERCOMPRESSOR BLEED VALVE SERVO VALVE	30J3490-01	TR7922	13-AUG-2019 H: 8669.40 C: 6334					
75 1004 Engine 2 PART #36	NO. 2 ENGINE - INTERCOMPRESSOR BLEED VALVE SERVO VALVE	30J3490-01	TRAXY0001 33	26-AUG-2019 H: 8669.40 C: 6334					
75 1005 Engine 1 PART #45	NO. 1 ENGINE - LINEAR VAR. DIFFERENTIAL TRANSFORMER	GM9237-2	2107	13-AUG-2019 H: 8669.40 C: 6334					
75 1005 Engine 2 PART #3	NO. 2 ENGINE - LINEAR VAR. DIFFERENTIAL TRANSFORMER	GM9237-2	1147	26-AUG-2019 H: 8669.40 C: 6334					
77 1003 Airframe PART #302	SAFELIGHT N1 COMPUTER	C12732-1	483	31-JAN-2009 H: 7363.27 L: 5519					
77 1004 Airframe PART #119	N1 SPEED/ITT TEMP INDICATOR	10601N02M00	0006647	06-NOV-2018 H: 8594.40 L: 6300					
77 1005 Engine 1 PART #16	NO. 1 ENGINE - N1 MONOPOLE	31J2614-01	CH160	13-AUG-2019 H: 8669.40 C: 6334					
77 1005 Engine 2 PART #45	NO. 2 ENGINE - N1 MONOPOLE	31J2614-01	CH220	26-AUG-2019 H: 8669.40 C: 6334					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
77 1006 Airframe PART #430	ENGINE (AMLCD) INDICATOR	PN	SN-UNKNOWN	18-JUN-1997 H: 0.00					
77 1006 Engine 1 PART #44	NO. 1 ENGINE - N2 MONOPOLE	31J1596-01	CH84	17-APR-2001 H: 1133.00					
77 1006 Engine 2 PART #4	NO. 2 ENGINE - N2 MONOPOLE	31J1596-01	CH140	17-APR-2001 H: 1133.00					
77 3001 Airframe PART #130	LEFT ENGINE ACCELEROMETER	6222SM15	10194	18-JUN-1997 H: 0.00					
77 3001 Airframe PART #344	RIGHT ENGINE ACCELEROMETER	6222SM15	10204	18-JUN-1997 H: 0.00					
78 3001 Airframe PART #455	LEFT THRUST REVERSER ASSEMBLY	53ND-78002-3	33	18-JUN-1997 H: 0.00					
78 3001 Airframe PART #379	RIGHT THRUST REVERSER ASSEMBLY	53ND-78002-4	34	18-JUN-1997 H: 0.00					
78 3002 Airframe PART #105	LEFT CONTROL VALVE	65680	3169	04-MAR-2006 H: 0.00					
78 3002 Airframe PART #393	RIGHT CONTROL VALVE	65680	2308	18-JUN-1997 H: 3976.00					
78 3003 Airframe PART #43	LEFT THREE WAY VALVE	13027-4	2949	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 3003 Airframe PART #477	RIGHT THREE WAY VALVE	13027-4	3059	18-JUN-1997 H: 0.00					
78 3005 Airframe PART #271	LEFT UPPER THRUST REVERSER DOOR ASSEMBLY	53ND-78003-3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3005 Airframe PART #329	RIGHT UPPER THRUST REVERSER DOOR ASSEMBLY	53ND-78003-3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3006 Airframe PART #341	LEFT LOWER THRUST REVERSER DOOR ASSEMBLY	53ND-78004-3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3006 Airframe PART #151	RIGHT LOWER THRUST REVERSER DOOR ASSEMBLY	53ND-78004-3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3007 Airframe PART #313	LEFT THRUST REVERSER MECH ASSEMBLY	53ND-78100-1	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3007 Airframe PART #69	RIGHT THRUST REVERSER MECH ASSEMBLY	53ND-78100-2	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3008 Airframe PART #400	LEFT THRUST REVERSER MECH ASSEMBLY	53ND-78100-3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3008 Airframe PART #348	RIGHT THRUST REVERSER MECH ASSEMBLY	53ND-78100-4	SN-UNKNOWN	18-JUN-1997 H: 0.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 3009 Airframe PART #318	LEFT THRUST REVERSER FAN DUCT	53ND-78200-5	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3009 Airframe PART #423	RIGHT THRUST REVERSER FAN DUCT	53ND-78200-7	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3010 Airframe PART #420	LEFT INBOARD THRUST REVERSER ACTUATOR	2563000-5	0538	12-SEP-2019 H: 8669.40 L: 6334					
78 3010 Airframe PART #316	LEFT OUTBOARD THRUST REVERSER ACTUATOR	53ND-78207-3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3010 Airframe PART #320	RIGHT INBOARD THRUST REVERSER ACTUATOR	53ND-78207-1	0634	31-AUG-2007 H: 6625.93 L: 4929					
78 3010 Airframe PART #463	RIGHT OUTBOARD THRUST REVERSER ACTUATOR	53ND-78207-3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3101 Airframe PART #159	LEFT INBOARD STOW LIMIT SWITCH	53ND78304-1	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3101 Airframe PART #111	LEFT OUTBOARD STOW LIMIT SWITCH	53ND78304-1	SN-UNKNOWN	18-JUN-1997 H: 0.00					
78 3101 Airframe PART #192	PRESSURE SWITCH THRUST REVERSER	6607A7-45	M012704	10-AUG-2011 H: 7545.50 L: 5660					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Part Number	Serial Number	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 3101 Airframe PART #369	RIGHT INBOARD STOW LIMIT SWITCH	53ND78304-1	SN-UNKNOWN	08-DEC-2005 H: 3841.00					
78 3101 Airframe PART #253	RIGHT OUTBOARD STOW LIMIT SWITCH	53ND78304-1	SN-UNKNOWN	08-DEC-2005 H: 3841.00					
78 3102 Airframe PART #413	LEFT DEPLOY LIMIT SWITCH	53ND78304-3	N/A	12-SEP-2019 H: 8669.40 L: 6334					
78 3102 Airframe PART #359	RIGHT DEPLOY LIMIT SWITCH	53ND78304-3	SN-UNKNOWN	18-JUN-1997 H: 0.00					
79 0001 Engine 2 INSPECTION #249	SOAP - OIL ANALYSIS			15-JUL-2022 H: 8540.30 C: 6643				15-JAN-2023 H: 8590.30	M: 3 D: 22 H: 50.00
79 0050 Engine 1 INSPECTION #13	CHANGE OIL INTERVAL			18-JUN-1997					
79 0050 Engine 2 INSPECTION #21	CHANGE OIL INTERVAL			18-JUN-1997					
79 2002 Engine 1 PART #17	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER	31J2955-02	JMPW051190	17-OCT-2004 H: 4318.00					
79 2002 Engine 2 PART #22	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER	D2552-600B	M50502	26-AUG-2019 H: 8669.40 C: 6334					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 2005 Engine 1 INSPECTION #25	OVERHAUL OR REFURBISH FUEL OIL HEAT EXCHANGER FUEL TO OIL HEAT EXCHANGER	13-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
79 2005 Engine 2 INSPECTION #14	OVERHAUL OR REFURBISH FUEL OIL HEAT EXCHANGER FUEL TO OIL HEAT EXCHANGER	26-AUG-2019 H: 8669.40 C: 6334	H: 4000.00			H: 12669.40	H: 4129.10
79 3002 Airframe PART #239	LEFT OIL TEMPERATURE TRANSMITTER Part Number: 102-00083 Serial Number: 2211	18-JUN-1997 H: 0.00					
79 3002 Airframe PART #29	RIGHT OIL TEMPERATURE TRANSMITTER Part Number: 102-00083 Serial Number: 2182	18-JUN-1997 H: 0.00					
79 3004 Airframe PART #31	LEFT OIL PRESSURE TRANSMITTER Part Number: 9912464-1 Serial Number: 604411121	21-NOV-1998 H: 388.00					
79 3004 Airframe PART #410	RIGHT OIL PRESSURE TRANSMITTER Part Number: 9912464-1 Serial Number: 64682665	12-MAR-2001 H: 1049.00					
79 3006 Airframe PART #468	LEFT LOW OIL PRESSURE SWITCH Part Number: 9912466-1 Serial Number: 32	18-JUN-1997					
79 3006 Airframe PART #501	RIGHT LOW OIL PRESSURE SWITCH Part Number: 9912466-1 Serial Number: 46	18-JUN-1997					
79 3007 Airframe PART #135	N2/OIL PRESSURE/OIL TEMPERATURE INDICATOR Part Number: 9912450-2 Serial Number: 9910613A	28-MAR-2007 H: 6279.67 L: 4625					
80 0010 Airframe PART - Overhaul #137	LEFT STARTER GENERATOR Part Number: 23080-025-1 Serial Number: P1083	18-FEB-2020 H: 8759.50 L: 6379	H: 1000.00		M: 0 H: 0.00 L: 0	H: 9759.50	H: 819.20

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
80 0010 Airframe PART - Overhaul #433	RIGHT STARTER GENERATOR Part Number: 23080-025-1 Serial Number: 98123	13-SEP-2013 H: 8000.40 L: 5925	H: 1000.00		M: 0 H: 0.00 L: 0	H: 9000.40	H: 60.10
ASB PW500-72-A30108 R03 Engine 1 ASB - Open #209	DECELERATION TEST FUEL CONTROL UNIT Notes CATEGORY 3						
ASB PW500-72-A30108 R03 Engine 2 SB - Open #217	DECELERATION TEST FUEL CONTROL UNIT Notes CATEGORY 3						
ASB PW500-72-A30421 Engine 1 ASB - N/A #87	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01) Notes NOT APPLICABLE	10-SEP-2010 H: 7495.80 C: 5626					
ASB PW500-72-A30421 Engine 2 ASB - N/A #142	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01) Notes NOT APPLICABLE	10-SEP-2010 H: 7495.80 C: 5626					
ASB PW500-72-A30421 R01 Engine 1 ASB - Complied With #240	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02) Notes COMPLIED WITH - PREVIOUSLY PREVIOUSLY COMPLIED WITH ORIGINAL BULLETIN						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB PW500-72-A30421 R01 Engine 2 ASB - Complied With #234	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02)						
	Notes COMPLIED WITH - PREVIOUSLY PREVIOUSLY COMPLIED WITH ORIGINAL BULLETIN						
ASB PW500-72-A30421 R2 Engine 1 ASB - Open #162	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE						
ASB PW500-72-A30421 R2 Engine 2 ASB - Complied With #87	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
ASL 550-26-02 Airframe SB - Complied With #748	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS	06-SEP-2007 H: 6639.60 L: 4941					
	Notes COMPLIED WITH - IAW THE SB N/A BY S/N						
ASL 550-29-11 R1 Airframe SB - Complied With #565	HYDRAULIC POWER - TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL550-29-11 R02)	19-JUL-2003 H: 3105.00					
	Notes COMPLIED WITH						
ASL 550-29-11 R2 Airframe SB - Complied With #517	HYDRAULIC POWER - TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL550-29-11 R03)	17-OCT-2004 H: 4316.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASL 550-29-11 R3 Airframe SB - Complied With #691	HYDRAULIC POWER - TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL550-29-11 R04)	22-MAR-2005 H: 4631.00					
	Notes COMPLIED WITH						
ASL 550-29-11 R4 Airframe SB - Complied With #535	HYDRAULIC POWER - TAILCONE HYDRAULIC TUBE INSPECTION	15-MAY-2005					
	Notes COMPLIED WITH						
ASL 550-32-85 Airframe SB - Complied With #677	LANDING GEAR-MAIN LANDING GEAR TIRE INSPECTION	01-AUG-2008 H: 7216.70 L: 5403					
	Notes COMPLIED WITH						
ASL 550-34-38 Airframe SB - N/A #597	FLAP PANEL CONTROL DISPLAY UNIT INVERTER CIRCUITRY INTEGRITY TEST	07-MAR-2002					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
ASL 550-52-04 Airframe SB - Complied With #769	DOORS - EMERGENCY DOOR INSPECTION						
	Notes COMPLIED WITH - PREVIOUSLY PREVIOUSLY C/W AFTER COMPLETION OF PHASE 5 INSPECTION						
ASL 550-52-05 R1 Airframe SB - Open #724	DOORS - EMERGENCY EXIT INSPECTION						
ASL 550-56-03 Airframe SB - Complied With #683	REQUIRED PRISM INSPECTION FOR COPILOT SIDE WINDOW	08-MAY-2001					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASL 550-72-29 Airframe SB #730	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO - VALVE - INSPECTION/REPLACEMENT OF	13-DEC-2011 H: 7605.00 L: 5710					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY WITH AT THIS TIME.						
ASL 550-72-29 Airframe SB #710	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-INSPECTION/REPLACEMENT OF	13-DEC-2011 H: 7605.00 L: 5710					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY WITH AT THIS TIME.						
CIL-34-09 Airframe SB - Open #868	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN FMZ-2000/2010 - FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 6.1 (FMS 6.1) UPGRADE AND CONSOLIDATION						
	Notes PLEASE CONFIRM THE APPLICABILITY OF THIS SERVICE LETTER						
SB 30554R2 Engine 1 SB - Open #248	TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF						
SB 30554R2 Engine 2 SB - Open #247	TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF						
SB 550-11-17 Airframe SB - Complied With #502	PLACARDS AND MARKINGS - ANTI-ICE FUEL ADDITIVE PLACARD REPLACEMENT	21-NOV-1998 H: 388.00					
SB 550-21-43 Airframe SB - Complied With #503	TRANSMITTAL OF FORT WORTH AIRWORKS, INC. SERVICE BULLETIN 98-101, EXHAUST SHUTOFF VALVE INSTALLATION	23-OCT-2000 H: 1010.00					
SB 550-21-45 Airframe SB - Complied With #504	ACM BYPASS VALVE RELOCATION	23-OCT-2000 H: 1010.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-21-46 Airframe SB - N/A #505	FLOOD COOLING DIODE REPLACEMENT	01-DEC-2000 H: 1010.00					
	Notes NOT APPLICABLE						
SB 550-21-47 Airframe SB - Open #624	COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION						
SB 550-21-49 Airframe SB - Open #580	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT						
	Notes MAY BE ACCOMPLISHED AT DISCRETION OF OWNER AT PHASE						
SB 550-21-50 Airframe SB - Complied With #506	RAM AIR DUCT IMPROVEMENT	15-MAY-2005 H: 4793.00					
	Notes COMPLIED WITH						
SB 550-21-51 Airframe SB - Complied With #507	AIR CONDITIONING - DEFOG BLOWER BONDING JUMPER	07-NOV-2007 H: 6766.82 L: 5043					
	Notes COMPLIED WITH						
SB 550-21-52 Airframe SB - Open #709	AIR CONDITIONING - CABIN ALTITUDE BAROMETRIC SWITCH IMPROVEMENT						
SB 550-21-57 Airframe SB - Open #676	AIR CONDITIONING - TEMPERATURE CONTROLLER IMPROVEMENT						
SB 550-21-58 Airframe SB - Complied With #509	AIR CONDITIONING - PRESSURIZATION SYSTEM PLUMBING IMPROVEMENT (SUPERSEDED BY 550-21-58 R01)	24-JAN-2013 H: 7822.20 L: 5828					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-21-58 R1 Airframe SB - Complied With #508	AIR CONDITIONING - PRESSURIZATION SYSTEM PLUMBING IMPROVEMENT	24-JAN-2013 H: 7822.20 L: 5828					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						
SB 550-23-22 Airframe SB - Open #647	ALLIEDSIGNAL 8.33 KHZ COMMUNICATION RADIO INSTALLATION						
SB 550-23-23 R2 Airframe SB - Open #706	COMMUNICATIONS - COCKPIT SPEAKER MUTE SWITCH						
SB 550-23-25 Airframe SB - Complied With #512	COM 1 COAX CABLE ROUTING INSPECTION	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-23-26 Airframe SB - Complied With #743	COMM 1 AND COMM2 WIRING MODIFICATION	08-MAY-2001 H: 1161.00					
	Notes COMPLIED WITH						
SB 550-23-29 Airframe SB - Complied With #673	HONEYWELL KY-196A/B DUAL VHF COMMUNICATION SYSTEM UPGRADE	21-NOV-2003 H: 3401.00					
	Notes COMPLIED WITH						
SB 550-23-32 Airframe SB - Open #799	COMMUNICATIONS - FIN TIP COMM ANTENNA IMPROVEMENT						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-24-30 Airframe SB - Complied With #534	CIRCUIT BREAKER TERMINAL SCREW LENGTH INSPECTION/REPLACEMENT (SUPERSEDED BY 550-24-30 R01)	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-24-30 R1 Airframe SB - Complied With #578	CIRCUIT BREAKER TERMINAL SCREW LENGTH INSPECTION/REPLACEMENT	12-MAR-2002 H: 1785.00					
	Notes COMPLIED WITH						
SB 550-24-31 Airframe SB - Complied With #719	MAIN LANDING GEAR TAXI LIGHT WIRE ROUTING IMPROVEMENT	21-NOV-1998 H: 388.00					
	Notes COMPLIED WITH						
SB 550-24-32 Airframe SB - Complied With #713	GCU START MODIFICATION	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-24-36 Airframe SB - Complied With #637	CIRCUIT BREAKER INSULATOR INSTALLATION	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-24-37 R1 Airframe SB - Complied With #746	ELECTRICAL POWER - MAIN POWER WIRE ANCHOR IMPROVEMENT (SUPERSEDED BY 550-24-37 R02)	21-FEB-2003 H: 2667.00					
	Notes COMPLIED WITH						
SB 550-24-37 R3 Airframe SB - Open #533	ELECTRICAL POWER - MAIN POWER WIRE ANCHOR IMPROVEMENT						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-24-38 Airframe SB - Open #550	SEALED LEAD ACID BATTERY INSTALLATION						
SB 550-24-39 Airframe SB - Complied With #692	TAILCONE WIRE BUNDLE ASSEMBLY ROUTING IMPROVEMENT Notes COMPLIED WITH	20-DEC-2002 H: 2499.00					
SB 550-24-40 R1 Airframe SB - Open #644	ELECTRICAL POWER - CIRCUIT BREAKER AMPERAGE INCREASE FOR MEGGITT SECONDARY FLIGHT DISPLAY (SUPERSEDED BY 550-24-40 R02)						
SB 550-24-40 R2 Airframe SB - Open #574	ELECTRICAL POWER - CIRCUIT BREAKER AMPERAGE INCREASE FOR MEGGITT SECONDARY FLIGHT DISPLAY						
SB 550-25-34 Airframe SB - Complied With #739	PASSENGER SEAT TRACKING CONTROL ASSEMBLY REPLACEMENT Notes COMPLIED WITH	08-JUL-1999 H: 579.00					
SB 550-25-40 Airframe SB - Open #779	PASSENGER SEAT ARMREST MODIFICATION						
SB 550-25-43 R1 Airframe SB - Open #703	EQUIPMENT/FURNISHINGS - GLARESHIELD LEATHER STRIP INSTALLATION						
SB 550-25-44 R3 Airframe SB - Open #773	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)						
SB 550-25-45 R1 Airframe SB - Open #757	EQUIPMENT/FURNISHINGS - TOILET TRAY AND PAD INSTALLATION						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-26-04 Airframe SB - Complied With #514	FIRE DETECT CLAMP REPLACEMENT	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-26-05 Airframe SB - Complied With #745	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	25-APR-2005 H: 4748.00					
	Notes COMPLIED WITH						
SB 550-27-20 R1 Airframe SB - Complied With #723	AILERON FASTENER INSPECTION/INSTALLATION	23-OCT-2000					
	Notes COMPLIED WITH						
SB 550-27-21 Airframe SB - Open #787	TRIM TAB ACTUATOR GREASE FITTING INSTALLATION						
SB 550-27-22 R2 Airframe SB - Open #695	FLIGHT CONTROLS - STEEP APPROACH CERTIFICATION						
SB 550-28-09 Airframe SB - Complied With #613	RIGHT FUEL PROBE REPLACEMENT	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-28-11 Airframe SB - Complied With #711	MOTIVE FLOW FUEL TUBE REPLACEMENT (SUPERSEDED BY 550-28-11 R01)	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-28-12 Airframe SB - Complied With #655	TANK BRACKET AND CLAMP INSTALLATION/INSPECTION	08-MAY-2001 H: 1161.00					
	Notes COMPLIED WITH						
SB 550-28-13 R2 Airframe SB - Complied With #790	FUEL - WING FUEL TANK DRAIN INSTALLATION AND FUEL PROBE BRACKET INSPECTION	21-NOV-2003					
	Notes COMPLIED WITH						
SB 550-28-15 Airframe SB - Complied With #725	FUEL - WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT (SUPERSEDED BY 550-28-15 R01)	07-MAR-2004 H: 3720.00					
	Notes COMPLIED WITH						
SB 550-28-16 Airframe SB - Complied With #689	FUEL - FUEL CHECK VALVE MODIFICATION (SUPERSEDED BY 550-28-16 R01)	17-JUN-2011 H: 7501.30 L: 5631					
	Notes COMPLIED WITH - SB550-28-16 DATED 02-17-09 FUEL CHECK VALVE MODIFICATION LEFT AND RIGHT. LEAK CHECKED VALUES AND OPERATIONAL TEST TO ENSURE "FUEL PRESS LO" DOES NOT ILLUMINATE						
SB 550-28-16 R1 Airframe SB - Open #800	FUEL - FUEL CHECK VALVE MODIFICATION						
SB 550-29-09 Airframe SB - Complied With #595	HYDRAULIC LINE CHAFING	21-NOV-1998 H: 388.00					
	Notes COMPLIED WITH						
SB 550-29-11 Airframe SB - Complied With #523	HYDRAULIC LINE IMPROVEMENT	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-29-12 Airframe SB - Complied With #481	LNDG GEAR RETURN LINE CK VALV	15-JAN-2002 H: 1636.00					
SB 550-30-04 Airframe SB - Complied With #646	WINDSHIELD ANTI-ICE BLEED AIR SWITCH INSPECTION/REPLACEMENT Notes COMPLIED WITH	15-JAN-2002 H: 1636.00					
SB 550-30-05 Airframe SB - Complied With #806	ANTI-ICE WING LEADING EDGE INSTALLATION, FASTENER CHANGE Notes COMPLIED WITH	16-AUG-2001 H: 1317.00					
SB 550-30-06 Airframe SB - Open #770	ELECTRIC HEATED LEADING EDGE RESISTOR IMPROVEMENT						
SB 550-31-06 Airframe SB - Complied With #630	INDICATING/RECORDING SYSTEMS - INADVERTENT POWER BRAKE LOW PRESSURE ANUNCIATION (SUPERSEDED BY 550-31-06 R01) Notes COMPLIED WITH	04-SEP-2002 H: 2206.00					
SB 550-32-28 Airframe SB - Complied With #513	MAIN LANDING GEAR UPLOCK HOOK REPLACEMENT Notes COMPLIED WITH	21-NOV-1998 H: 388.00					
SB 550-32-29 Airframe SB - Complied With #631	EMERGENCY GEAR RELEASE CABLE RUB BLOCK INSTALLATION Notes COMPLIED WITH	21-NOV-1998 H: 388.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-32-30 Airframe SB - Complied With #733	ANTISKID SYSTEM DIODE REMOVAL	21-NOV-1998 H: 388.00					
	Notes COMPLIED WITH						
SB 550-32-31 Airframe SB - Complied With #639	BRAKE SYSTEM BLEED FITTING INSTALLATION	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-32-33 Airframe SB - Complied With #569	BRAKE MOTOR COUPLING REPLACEMENT	25-JUL-2000 H: 917.00					
	Notes COMPLIED WITH						
SB 550-32-35 R1 Airframe SB - Complied With #520	MAIN LANDING GEAR OLEO MODIFICATION	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-32-37 Airframe SB - Complied With #716	HYDRAULIC AND PNEUMATIC BRAKE HOSE ASSEMBLY INSPECTION	22-OCT-1998 H: 356.00					
	Notes COMPLIED WITH						
SB 550-32-38 R1 Airframe SB - Complied With #753	LANDING GEAR - BRAKE LINE REPLACEMENT (SUPERSEDED BY 550-32-38 R02)	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-32-38 R2 Airframe SB - Complied With #579	LANDING GEAR - BRAKE LINE REPLACEMENT (SUPERSEDED BY 550-32-38 R03)	08-MAY-2001 H: 1161.00					
	Notes COMPLIED WITH						
SB 550-32-38 R3 Airframe SB - Complied With #788	LANDING GEAR - BRAKE LINE REPLACEMENT	04-SEP-2002 H: 2206.00					
	Notes COMPLIED WITH						
SB 550-32-39 Airframe SB - Complied With #525	MAIN LANDING GEAR SCUFF PROTECTION MODIFICATION	25-JUL-2000 H: 917.00					
	Notes COMPLIED WITH						
SB 550-32-40 R3 Airframe SB - Complied With #810	LANDING GEAR ON GROUND OPERATION AND MODIFICATION	08-MAY-2001 H: 1161.00					
	Notes COMPLIED WITH						
SB 550-32-43 Airframe SB - Complied With #700	MAIN LANDING GEAR WIRE BUNDLE ANCHOR IMPROVEMENT	08-MAY-2001 H: 1161.00					
	Notes COMPLIED WITH						
SB 550-32-44 Airframe SB - Complied With #134	EMER GEAR BLOWDOWN BTL ACT MO	15-JAN-2002 H: 1636.00					
SB 550-32-46 R1 Airframe SB - Complied With #654	BRAKE LOW PRESSURE NON-CANCELABLE MASTER CAUTION IMPROVEMENT (SUPERSEDED BY 550-32-46 R02)	19-JUL-2003 H: 3105.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-32-48 R1 Airframe SB - Complied With #652	LANDING GEAR - NLG ACTUATOR REPLACEMENT (SUPERSEDED BY 550-32-48 R02)	27-JUN-2004 H: 4011.00					
	Notes COMPLIED WITH						
SB 550-32-48 R2 Airframe SB - Complied With #674	LANDING GEAR - NLG ACTUATOR REPLACEMENT (SUPERSEDED BY 550-32-48 R03)	17-OCT-2004					
	Notes COMPLIED WITH						
SB 550-32-48 R3 Airframe SB - Complied With #708	LANDING GEAR - NLG ACTUATOR REPLACEMENT	22-MAR-2005 H: 4631.00					
	Notes COMPLIED WITH						
SB 550-32-50 R1 Airframe SB - Open #812	LANDING GEAR - PARKING BRAKE CABLE REPLACEMENT						
SB 550-32-52 Airframe SB - Complied With #781	LANDING GEAR-BRAKE HYDRAULIC PACK FILTER BOWL REPLACEMENT	21-AUG-2006 H: 5870.00					
	Notes COMPLIED WITH						
SB 550-33-22 Airframe SB - Complied With #529	MAIN LANDING GEAR TAXI LIGHT GLARESHIELD INSTALLATION	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-33-24 Airframe SB - Complied With #741	WING TIP LANDING LIGHT ASSEMBLY 250W LAMP INSTALLATION	17-FEB-2012 H: 7649.30 L: 5731					
	Notes COMPLIED WITH - COMPLIED WITH SB550-33-24, BY REMOVING THE EXISTING 150W WING TIP LANDING LAMP ASSEMBLIES AND INSTALL 250W WING TIP LANDING LAMP ASSEMBLIES PER ACCOMPLISHMENT INSTRUCTIONS.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-33-26 Airframe SB - Complied With #540	G-SWITCH MOUNTING IMPROVEMENT	25-JUL-2000 H: 917.00					
	Notes COMPLIED WITH						
SB 550-33-29 Airframe SB - Open #558	LED TAIL POSITION LITE REPLAC						
SB 550-33-31 Airframe SB - Open #554	CHART LIGHT MODIFICATION						
SB 550-34-101 Airframe SB - Open #682	NAVIGATION - UNIVERSLA AVIONICS UNS-1CSP UPGRADE TO UNS-1CSP+ WITH SOFTWARE CONTROL NUMBER (SCN) 802.2						
SB 550-34-104 Airframe SB - Complied With #599	HONEYWELL PRIMUS 1000 PHASE III SOFTWARE UPGRADE (SUPERSEDED BY 550-34-104 R01)	01-DEC-2005 H: 5242.00					
	Notes COMPLIED WITH						
SB 550-34-107 Airframe SB - Open #605	RUNWAY AWARENESS AND ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION						
SB 550-34-111 Airframe SB - N/A #752	NAVIGATION - GNS-XLS SOFTWARE MOD 8 UPGRADE (SUPERSEDED BY 550-34-111 R01)	07-NOV-2007 H: 6766.82 L: 5043					
	Notes NOT APPLICABLE - A/C NOT EQUIPED WITH XLS FMS						
SB 550-34-112 R1 Airframe SB - Open #664	NAVIGATION - MEGGITT MARK II SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT INSTALLATION (SUPERSEDED BY 550-34-112 R02)						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-34-112 R2 Airframe SB - Open #670	NAVIGATION - MEGGITT MARK I SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT REPLACEMENT OR MARK II SECONDARY FLIGHT DISPLAY INDICATOR REPLACEMENT (SUPERSEDED BY 550-34-112 R03)						
SB 550-34-112 R3 Airframe SB - Open #608	NAVIGATION - MEGGITT MARK I SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT REPLACEMENT OR MARK II SECONDARY FLIGHT DISPLAY INDICATOR REPLACEMENT						
SB 550-34-115 Airframe SB - Open #740	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 550-34-115 R01)						
SB 550-34-115 R1 Airframe SB #712	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 550-34-115 R02) Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.	24-JAN-2013 H: 7822.20 L: 5828					
SB 550-34-115 R2 Airframe SB - Open #572	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS						
SB 550-34-116 Airframe SB - Open #590	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE						
SB 550-34-116 R1 Airframe SB - Open #592	NAVIGATION - UNIVERSAL SOLID STATE TRANSFER UNIT (SSDTU) UPGRADE						
SB 550-34-117 Airframe SB - Open #767	NAVIGATION - UNIVERSAL FMS WAAS UNS-1LW UPGRADE (SUPERSEDED BY 550-34-117 R01)						
SB 550-34-117 R1 Airframe SB - Open #521	NAVIGATION - UNIVERSAL FMS WAAS UNS-1LW UPGRADE						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-34-118 Airframe SB - Open #793	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE						
SB 550-34-64 R1 Airframe SB - Complied With #614	NAVIGATION - MEGGITT SECONDARY FLIGHT DISPLAY IMPROVEMENTS Notes COMPLIED WITH	01-DEC-2000 H: 1010.00					
SB 550-34-69 Airframe SB - Complied With #541	GNS-XLS SOFTWARE MOD 3 UPGRADE Notes COMPLIED WITH	21-NOV-1998 H: 388.00					
SB 550-34-70 Airframe SB - Complied With #671	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION (SUPERSEDED BY 550-34-70 R01) Notes COMPLIED WITH	21-NOV-2003 H: 3401.00					
SB 550-34-70 R1 Airframe SB - Complied With #758	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION Notes COMPLIED WITH	07-MAR-2004 H: 3720.00					
SB 550-34-71 R1 Airframe SB - Complied With #657	HONEYWELL PRIMUS 1000 PHASE II SOFTWARE UPGRADE Notes COMPLIED WITH	23-OCT-2000 H: 1010.00					
SB 550-34-72 Airframe SB - Open #545	AVIONICS MASTER SWITCH REPLACEMENT						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-34-73 Airframe SB - Complied With #782	GNS-X/LS SOFTWARE MOD 4 UPGRADE	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-34-74 Airframe SB - Open #532	TCAS II SOFTWARE CHANGE 7 UPGRADE						
SB 550-34-75 Airframe SB - Complied With #659	ARINC COMPUTER MODIFICATION	15-JAN-2002					
	Notes COMPLIED WITH						
SB 550-34-76 R2 Airframe SB - N/A #656	NAVIGATION - UNS-1K 603.4 SOFTWARE UPGRADE	23-JUL-2003 H: 3109.00					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
SB 550-34-77 Airframe SB - N/A #601	UNS-1CSP 603.4 SOFTWARE UPGRADE	23-JUL-2003 H: 3109.00					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
SB 550-34-80 Airframe SB - Complied With #591	GNS-XLS FMS MOD 6 SOFTWARE UPGRADE (SUPERSEDED BY 550-34-80 R01)	12-MAR-2002 H: 1785.00					
	Notes COMPLIED WITH						
SB 550-34-81 Airframe SB - N/A #698	UNIVERSAL AVIONICS UNS-1K FLIGHT MANAGEMENT SYSTEM FLAT PANEL CONTROL DISPLAY UNIT UPGRADE TO MOD 8	23-JUL-2003 H: 3109.00					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-34-82 R1 Airframe SB - Complied With #736	NAVIGATION - MEGGITT AIR DATA UNIT UPGRADE	21-NOV-2003 H: 3401.00					
	Notes COMPLIED WITH						
SB 550-34-85 Airframe SB - N/A #555	NAVIGATION - TCAS RAIN COVER INSTALLATION (SUPERSEDED BY 550-34-85 R01)	02-APR-2003 H: 2808.00					
	Notes NOT APPLICABLE						
SB 550-34-88 R1 Airframe SB - Open #755	NAVIGATION - MARK VIII TERRAIN AWARENESS & WARNING SYSTEM (TAWS) INSTALLATION						
SB 550-34-89 R1 Airframe SB - Open #798	NAVIGATION - MARK VII TERRAIN AWARENESS & WARNING SYSTEM (TAWS) INSTALLATION						
SB 550-34-90 Airframe SB - Open #636	5 AMP-HOUR STANDBY GYRO BATTERY INSTALLATION						
SB 550-34-91 R1 Airframe SB - Open #738	NAVIGATION - HONEYWELL TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE						
SB 550-34-92 R3 Airframe SB - Open #542	NAVIGATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE						
SB 550-34-98 R1 Airframe SB - Open #564	NAVIGATION - HONEYWELL MARK VII EGPWS SOFTWARE UPDATE TO VERSION -219-219						
SB 550-34-99 Airframe SB - Open #803	RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) INSTALLATION						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-35-03 R4 Airframe SB - Complied With #720	OXYGEN - EROS OXYGEN MASK INSTALLATION	08-FEB-2006					
	Notes COMPLIED WITH						
SB 550-35-06 R1 Airframe SB - Open #776	EROS MLD20-506 OXYGEN MASK INSTALLATION						
SB 550-35-08 Airframe SB - Open #735	EROS MLD20-510 OXYGEN MASK INSTALLATION						
SB 550-36-05 Airframe SB - Open #629	DOOR SEAL VALVE REPLACEMENT AND WATER TRAP INSTALLATION						
SB 550-36-08 Airframe SB - Complied With #549	BLEED AIR TUBE INSPECTION/REPLACEMENT (SUPERSEDED BY 550-36-08 R01)	02-APR-2003 H: 2808.00					
	Notes COMPLIED WITH						
SB 550-36-09 R1 Airframe SB - Open #772	TAILCONE PNEUMATIC TUBE IMPROVEMENT						
SB 550-52-27 Airframe SB - Complied With #672	MAIN LANDING GEAR DOOR MODIFICATION	21-NOV-1998 H: 388.00					
	Notes COMPLIED WITH						
SB 550-52-28 Airframe SB - Complied With #807	CABIN DOOR STEP HANDLE AND DRAIN HOLE INSTALLATION	25-JUL-2000 H: 917.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-52-29 Airframe SB - Complied With #792	RATE CONTROL STEP ASSEMBLY	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-52-30 Airframe SB - Complied With #685	RTM CABIN DOOR STEP ASSEMBLY INSTALLATION	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-52-33 Airframe SB - Complied With #734	DOORS-RAIN GUTTER FASTENER INSTALLATION (SUPERSEDED BY 550-52-33 R01)	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-52-35 Airframe SB - Complied With #607	MODIFICATION OF THE COMPOSITE STEP RATE CONTROL ATTACHMENTS	15-JAN-2002 H: 1636.00					
	Notes COMPLIED WITH						
SB 550-52-36 R1 Airframe SB - Complied With #583	DOORS - ENTRY DOOR CABLE REPLACEMENT	21-NOV-2003 H: 3401.00					
	Notes COMPLIED WITH						
SB 550-52-37 Airframe SB - Complied With #777	CABIN ENTRANCE DOOR THRESHOLD STEP CLOSEOUT IMPROVEMENT	21-FEB-2003 H: 2667.00					
	Notes COMPLIED WITH						
SB 550-52-38 R1 Airframe SB - Open #679	DOORS - IMPROVEMENT FOR THE CABIN ENTRY STEPS						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-52-39 Airframe SB - Open #567	DOORS - WIDE DOOR MODIFICATION						
SB 550-53-29 Airframe SB - Complied With #668	MAIN GEAR WHEEL WELL SKIN REPAIR Notes COMPLIED WITH	25-JUL-2000 H: 917.00					
SB 550-53-31 Airframe SB - Open #642	FUSELAGE MOISTURE DRAIN INSTALLATION						
SB 550-53-32 Airframe SB - Complied With #696	FUSELAGE - NOSE WHEEL STEERING BRACKET REPLACEMENT (SUPERSEDED BY 550-53-32 R01) Notes COMPLIED WITH	23-OCT-2000 H: 1010.00					
SB 550-53-32 R2 Airframe SB - Complied With #587	FUSELAGE - NOSE WHEEL STEERING BRACKET REPLACEMENT Notes COMPLIED WITH	08-MAY-2001 H: 1161.00					
SB 550-53-33 Airframe SB - Complied With #784	ENGINE CARRY THRU BEAM BRACKET INSTALLATION Notes COMPLIED WITH	01-DEC-2000 H: 1010.00					
SB 550-53-34 Airframe SB - Open #764	FLOORBOARD IMPROVEMENT						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-53-35 Airframe SB - Complied With #524	TAILCONE RIVET INSPECTION/INSTALLATION	04-SEP-2002 H: 2206.00					
	Notes COMPLIED WITH						
SB 550-53-37 Airframe SB - Complied With #611	WHEEL WELL BOX/SKIN GAP IMPROVEMENT	21-NOV-2003 H: 3401.00					
	Notes COMPLIED WITH						
SB 550-54-07 Airframe SB - Complied With #786	NACELLES/PYLONS - NACELLE APRON MODIFICATION (SUPERSEDED BY 550-54-07 R01)	01-DEC-2000					
	Notes COMPLIED WITH						
SB 550-54-08 R1 Airframe SB - Complied With #702	NACELLE OIL DOOR HINGE IMPROVEMENT (SUPERSEDED BY 550-54-08 R02)	07-MAY-2002 H: 1952.00					
	Notes COMPLIED WITH						
SB 550-54-08 R2 Airframe SB - Complied With #742	NACELLE OIL DOOR HINGE IMPROVEMENT	02-APR-2003 H: 2808.00					
	Notes COMPLIED WITH						
SB 550-54-09 Airframe SB #573	NACELLES/PYLONS - OIL DOOR IMPROVEMENT (SUPERSEDED BY 550-54-09 R01)	24-JAN-2013 H: 7822.20 L: 5828					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-54-09 R1 Airframe SB #553	NACELLES/PYLONS - OIL DOOR IMPROVEMENT	24-JAN-2013 H: 7822.20 L: 5828					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						
SB 550-56-02 R1 Airframe SB - Complied With #582	WINDOWS - COPILOT SIDE WINDOW REPAIR (SUPERSEDED BY 550-56-02 R02)	16-AUG-2001 H: 1317.00					
	Notes COMPLIED WITH						
SB 550-56-02 R3 Airframe SB - Complied With #645	WINDOWS - COPILOT SIDE WINDOW INSPECTION AND REPAIR	21-NOV-2003					
	Notes COMPLIED WITH						
SB 550-57-09 Airframe SB - Complied With #729	WHEEL WELL STRUCTURE IMPROVEMENTS	25-JUL-2000 H: 917.00					
	Notes COMPLIED WITH						
SB 550-57-10 Airframe SB - Complied With #518	WING RIVET INSPECTION (SUPERSEDED BY 550-57-10 R01)	22-MAR-2005 H: 4631.00					
	Notes COMPLIED WITH						
SB 550-71-05 Airframe SB - Complied With #556	ENGINE DRAIN LINE MODFICATION	07-MAR-2004 H: 3720.00					
	Notes COMPLIED WITH						
SB 550-71-07 Airframe SB - Open #718	ACCOMPLISH POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION LH ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-71-07 Airframe SB - Open #666	ACCOMPLISH POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION RH ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION						
SB 550-71-07 Airframe SB - Open #643	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION						
SB 550-73-05 Airframe SB - Complied With #606	ENGINE HYDRAULIC LINE CLAMP INSTALLATION	07-MAR-2004 H: 3720.00					
	Notes COMPLIED WITH						
SB 550-74-02 Airframe SB - Complied With #594	RF FILTER REMOVAL	12-MAR-2001 H: 1049.00					
	Notes COMPLIED WITH						
SB 550-76-03 Airframe SB - Complied With #568	THROTTLE CAMP RELOCATION	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-76-05 Airframe SB - Complied With #783	THRUST REVERSER MAXIMUM THRUST SETTING (SUPERSEDED BY 550-76-05 R01)	15-JAN-2002 H: 1636.00					
	Notes COMPLIED WITH						
SB 550-77-01 Airframe SB - Complied With #563	TOTAL TEMPERATURE ZERO (TT0) PROBE INLET ENGINE COWLS OPENING	22-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 550-79-02 Airframe SB - Complied With #537	OIL IMPENDING BYPASS SWITCH CONNECTOR	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SB 550-80-05 Airframe SB - Complied With #813	STARTER GENERATOR POWER CABLE SLEEVING INSTALLATION	21-NOV-2003 H: 3401.00					
	Notes COMPLIED WITH						
SB ASL 550-29-11 Airframe SB - Complied With #561	TAILCONE HYDRAULIC TUBE INSP	04-SEP-2002 H: 2206.00					
	Notes COMPLIED WITH						
SB PW500-72-30001 Engine 1 SB - Open #59	REPLACEMENT OF FAN RETAINING NUT INTERNAL KEY WASHER						
	Notes CATEGORY 3						
SB PW500-72-30001 Engine 2 SB - Open #122	REPLACEMENT OF FAN RETAINING NUT INTERNAL KEY WASHER						
	Notes CATEGORY 3						
SB PW500-72-30002 Engine 1 SB - Open #165	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX DRIVE SHAFT (TOWERSHAFT)						
	Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30002 Engine 2 SB - Open #71	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX DRIVE SHAFT (TOWERSHAFT)						
	Notes CATEGORY 6						
SB PW500-72-30003 R1 Engine 1 SB - Open #97	REPLACEMENT OF THROTTLE/THRUST REVERSER LINKAGE BELLCRANK SHAFT ARM						
	Notes CATEGORY 7						
SB PW500-72-30003 R1 Engine 2 SB - Open #57	REPLACEMENT OF THROTTLE/THRUST REVERSER LINKAGE BELLCRANK SHAFT ARM						
	Notes CATEGORY 7						
SB PW500-72-30004 Engine 1 SB - Open #73	REPLACEMENT/MODIFICATION OF HIGH COMPRESSOR ROTOR						
	Notes CATEGORY 5						
SB PW500-72-30004 Engine 2 SB - Open #114	REPLACEMENT/MODIFICATION OF HIGH COMPRESSOR ROTOR						
	Notes CATEGORY 5						
SB PW500-72-30005 Engine 1 SB - Open #108	REPLACEMENT OF FAN RETAINING NUT						
	Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30005 Engine 2 SB - Open #158	REPLACEMENT OF FAN RETAINING NUT Notes CATEGORY 3						
SB PW500-72-30006 Engine 1 SB - Open #148	REPLACEMENT OF IGNITION EXCITER Notes CATEGORY 3						
SB PW500-72-30006 Engine 2 SB - Open #144	REPLACEMENT OF IGNITION EXCITER Notes CATEGORY 3						
SB PW500-72-30008 Engine 1 SB - Open #151	REPLACEMENT OF OIL PUMP FRONT COVER Notes CATEGORY 3						
SB PW500-72-30008 Engine 2 SB - Open #149	REPLACEMENT OF OIL PUMP FRONT COVER Notes CATEGORY 3						
SB PW500-72-30009 Engine 1 SB - Open #132	REPLACEMENT OF EXCITER TO IGNITOR IGNITION CABLE Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30009 Engine 2 SB - Open #108	REPLACEMENT OF EXCITER TO IGNITOR IGNITION CABLE Notes CATEGORY 3						
SB PW500-72-30010 R2 Engine 1 SB - Open #166	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE SERVO-VALVE Notes CATEGORY 3						
SB PW500-72-30010 R2 Engine 2 SB - Open #131	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE SERVO-VALVE Notes CATEGORY 3						
SB PW500-72-30011 R2 Engine 1 SB - Open #124	REPLACEMENT OF FUEL CONTROL UNIT (FCU) AND FLOW DIVIDER VALVE Notes CATEGORY 3						
SB PW500-72-30011 R2 Engine 2 SB - Open #56	REPLACEMENT OF FUEL CONTROL UNIT (FCU) AND FLOW DIVIDER VALVE Notes CATEGORY 3						
SB PW500-72-30012 R1 Engine 1 SB - Open #63	REPLACEMENT OF REAR BY-PASS DUCT ASSEMBLY Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30012 R1 Engine 2 SB - Open #53	REPLACEMENT OF REAR BY-PASS DUCT ASSEMBLY Notes CATEGORY 3						
SB PW500-72-30013 Engine 1 SB - Open #163	REPLACEMENT OF BOLTS CONNECTING HIGH PRESSURE TURBINE BAFFLE TO REAR DIFFUSER CASE FLANGE Notes CATEGORY 8						
SB PW500-72-30013 Engine 2 SB - Open #139	REPLACEMENT OF BOLTS CONNECTING HIGH PRESSURE TURBINE BAFFLE TO REAR DIFFUSER CASE FLANGE Notes CATEGORY 8						
SB PW500-72-30014 Engine 1 SB - Open #146	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY INTERSHAFT SEAL CARRIER ASSEMBLY AND ACCESSORY Notes CATEGORY 7						
SB PW500-72-30014 Engine 2 SB - Open #116	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY INTERSHAFT SEAL CARRIER ASSEMBLY AND ACCESSORY Notes CATEGORY 7						
SB PW500-72-30015 R1 Engine 1 SB - Open #91	MODIFICATION/REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY Notes CATEGORY 5						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30015 R1 Engine 2 SB - Open #146	MODIFICATION/REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY Notes CATEGORY 5						
SB PW500-72-30016 Engine 1 SB - Open #66	REPLACEMENT OF LOW PRESSURE COMPRESSOR INLET AND FAN EXIT VANE RING ASSEMBLIES Notes CATEGORY 7						
SB PW500-72-30016 Engine 2 SB - Open #163	REPLACEMENT OF LOW PRESSURE COMPRESSOR INLET AND FAN EXIT VANE RING ASSEMBLIES Notes CATEGORY 7						
SB PW500-72-30017 R1 Engine 1 SB - Open #167	REPLACEMENT OF FLOW DIVIDER VALVE Notes CATEGORY 3						
SB PW500-72-30017 R1 Engine 2 SB - Open #159	REPLACEMENT OF FLOW DIVIDER VALVE Notes CATEGORY 3						
SB PW500-72-30018 R1 Engine 1 SB - Open #89	REPLACEMENT OF THRUST REVERSER LINKAGE SLEEVE BUSHING Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30018 R1 Engine 2 SB - Open #111	REPLACEMENT OF THRUST REVERSER LINKAGE SLEEVE BUSHING						
	Notes CATEGORY 3						
SB PW500-72-30019 Engine 1 SB - Open #122	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY INCORPORATING OIL TANK VENT HOLE						
	Notes CATEGORY 3						
SB PW500-72-30019 Engine 2 SB - Open #164	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY INCORPORATING OIL TANK VENT HOLE						
	Notes CATEGORY 3						
SB PW500-72-30020 R1 Engine 1 SB - Open #98	MODIFICATION/REPLACEMENT OF LOW PRESSURE TURBINE ROTOR BALANCING ASSEMBLY						
	Notes CATEGORY 8						
SB PW500-72-30020 R1 Engine 2 SB - Open #65	MODIFICATION/REPLACEMENT OF LOW PRESSURE TURBINE ROTOR BALANCING ASSEMBLY						
	Notes CATEGORY 8						
SB PW500-72-30021 Engine 1 SB - Open #79	INTRODUCTION OF T1/T13 WIRING HARNESS - REROUTING OF ATTACHMENT HARDWARE FOR AIRCRAFT GROUNDING LUGS- , REPLACEMENT OF ENGINE MOUNT PAD BLANKING COVERS						
	Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30021 Engine 2 SB - Open #104	INTRODUCTION OF T1/T13 WIRING HARNESS - REROUTING OF ATTACHMENT HARDWARE FOR AIRCRAFT GROUNDING LUGS- , REPLACEMENT OF ENGINE MOUNT PAD BLANKING COVERS Notes CATEGORY 3						
SB PW500-72-30022 Engine 1 SB - Open #107	INTRODUCTION OF INCREASED TAKE-OFF AND MAXIMUM CLIMB/MAXIMUM CONTINUOUS THRUST RATING ON DATA PLATES Notes CATEGORY 3						
SB PW500-72-30022 Engine 2 SB - Open #109	INTRODUCTION OF INCREASED TAKE-OFF AND MAXIMUM CLIMB/MAXIMUM CONTINUOUS THRUST RATING ON DATA PLATES Notes CATEGORY 3						
SB PW500-72-30023 Engine 1 SB - Open #61	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR ASSEMBLY Notes CATEGORY 5						
SB PW500-72-30023 Engine 2 SB - Open #61	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR ASSEMBLY Notes CATEGORY 5						
SB PW500-72-30024 Engine 1 SB - Open #60	REPLACEMENT OF FAN RETAINING NUT INTERNAL KEY WASHER Notes CATEGORY 5						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30024 Engine 2 SB - Open #148	REPLACEMENT OF FAN RETAINING NUT INTERNAL KEY WASHER Notes CATEGORY 5						
SB PW500-72-30025 Engine 1 SB - Open #94	REPLACEMENT OF IGNITER FAIRING GASKET AND REAR FUEL DRAIN GASKET Notes CATEGORY 8						
SB PW500-72-30025 Engine 2 SB - Open #128	REPLACEMENT OF IGNITER FAIRING GASKET AND REAR FUEL DRAIN GASKET Notes CATEGORY 8						
SB PW500-72-30026 Engine 1 SB - Open #143	REPLACEMENT OF COMBUSTOR SUPPORT PIN Notes CATEGORY 5						
SB PW500-72-30026 Engine 2 SB - Open #73	REPLACEMENT OF COMBUSTOR SUPPORT PIN Notes CATEGORY 5						
SB PW500-72-30027 Engine 1 SB - Open #120	REPLACEMENT OF FUEL NOZZLE ATTACHMENT BOLTS Notes CATEGORY 5						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30027 Engine 2 SB - Open #89	REPLACEMENT OF FUEL NOZZLE ATTACHMENT BOLTS						
	Notes CATEGORY 5						
SB PW500-72-30028 Engine 1 SB - Open #138	REPLACEMENT OF LOW PRESSURE COMPRESSOR INLET VANE RING ASSEMBLY						
	Notes CATEGORY 7						
SB PW500-72-30028 Engine 2 SB - Open #143	REPLACEMENT OF LOW PRESSURE COMPRESSOR INLET VANE RING ASSEMBLY						
	Notes CATEGORY 7						
SB PW500-72-30029 Engine 1 SB - Complied With #121	REPLACEMENT OF FUEL DIFFERENTIAL PRESSURE SWITCH	14-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 8						
SB PW500-72-30029 Engine 2 SB - Complied With #67	REPLACEMENT OF FUEL DIFFERENTIAL PRESSURE SWITCH	26-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 8						
SB PW500-72-30030 Engine 1 SB - Open #78	REPLACEMENT OF PLAIN SEAL FOR OIL PUMP						
	Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30030 Engine 2 SB - Open #76	REPLACEMENT OF PLAIN SEAL FOR OIL PUMP Notes CATEGORY 6						
SB PW500-72-30031 Engine 1 SB - Open #54	REPLACEMENT OF FLOW DIVIDER VALVE Notes CATEGORY 8						
SB PW500-72-30031 Engine 2 SB - Open #82	REPLACEMENT OF FLOW DIVIDER VALVE Notes CATEGORY 8						
SB PW500-72-30033 Engine 1 SB - Open #130	REPLACEMENT OF AIR TUBE COVER ASSEMBLIES (SUPERSEDED BY PW500-72-30033 R01) Notes CATEGORY 6						
SB PW500-72-30033 Engine 2 SB - Open #96	REPLACEMENT OF AIR TUBE COVER ASSEMBLIES (SUPERSEDED BY PW500-72-30033 R01) Notes CATEGORY 6						
SB PW500-72-30033 R1 Engine 1 SB - Open #149	REPLACEMENT OF AIR TUBE COVER ASSEMBLIES TURBOFAN ENGINE Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30033 R1 Engine 2 SB - Open #63	REPLACEMENT OF AIR TUBE COVER ASSEMBLIES TURBOFAN ENGINE Notes CATEGORY 6						
SB PW500-72-30034 Engine 1 SB - Open #141	REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT (FCU) Notes CATEGORY 3						
SB PW500-72-30034 Engine 2 SB - Open #120	REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT (FCU) Notes CATEGORY 3						
SB PW500-72-30035 Engine 1 SB - Open #77	REPLACEMENT OF IGNITER FAIRING GASKET AND REAR FUEL DRAIN GASKET Notes CATEGORY 7						
SB PW500-72-30035 Engine 2 SB - Open #51	REPLACEMENT OF IGNITER FAIRING GASKET AND REAR FUEL DRAIN GASKET Notes CATEGORY 7						
SB PW500-72-30036 Engine 1 SB - Open #72	REPLACEMENT OF NO. 4 BEARING CARBON SEAL Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30036 Engine 2 SB - Open #66	REPLACEMENT OF NO. 4 BEARING CARBON SEAL Notes CATEGORY 6						
SB PW500-72-30037 Engine 1 SB - Open #113	REPLACEMENT OF COMPRESSOR RETAINING NUT Notes CATEGORY 6						
SB PW500-72-30037 Engine 2 SB - Open #55	REPLACEMENT OF COMPRESSOR RETAINING NUT Notes CATEGORY 6						
SB PW500-72-30038 Engine 1 SB - Open #161	REPLACEMENT OF FUEL NOZZLE GASKETS Notes CATEGORY 6						
SB PW500-72-30038 Engine 2 SB - Open #132	REPLACEMENT OF FUEL NOZZLE GASKETS Notes CATEGORY 6						
SB PW500-72-30040 Engine 1 SB - Open #158	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT Notes CATEGORY 7						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30040 Engine 2 SB - Open #153	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT Notes CATEGORY 7						
SB PW500-72-30042 R1 Engine 1 SB - Open #156	IDENTIFICATION OF OIL PRESSURE TUBE IN TURBINE EXHAUST CASE Notes CATEGORY 6						
SB PW500-72-30042 R1 Engine 2 SB - Open #145	IDENTIFICATION OF OIL PRESSURE TUBE IN TURBINE EXHAUST CASE Notes CATEGORY 6						
SB PW500-72-30043 Engine 1 SB - Complied With #81	INTRODUCTION OF SEALANT ADDED TO HIGH PRESSURE COMPRESSOR ROTOR ASSEMBLY Notes CATEGORY 6	14-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30043 Engine 2 SB - Complied With #102	INTRODUCTION OF SEALANT ADDED TO HIGH PRESSURE COMPRESSOR ROTOR ASSEMBLY Notes CATEGORY 6	26-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30044 R2 Engine 1 SB - Open #96	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR (2 STG.) ASSEMBLY (SUPERSEDED BY PW500-72-30044 R03) Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30044 R2 Engine 2 SB - Open #136	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR (2 STG.) ASSEMBLY (SUPERSEDED BY PW500-72-30044 R03) Notes CATEGORY 6						
SB PW500-72-30044 R3 Engine 1 SB - Open #111	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR (2 STG.) ASSEMBLY Notes CATEGORY 6						
SB PW500-72-30044 R3 Engine 2 SB - Open #86	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR (2 STG.) ASSEMBLY Notes CATEGORY 6						
SB PW500-72-30045 Engine 1 SB - Open #131	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY Notes CATEGORY 7						
SB PW500-72-30045 Engine 2 SB - Open #105	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY Notes CATEGORY 7						
SB PW500-72-30048 R1 Engine 1 SB - Open #95	REPLACEMENT OF IGNITION EXCITER TO IGNITOR CABLE Notes CATEGORY 5						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30048 R1 Engine 2 SB - Open #70	REPLACEMENT OF IGNITION EXCITER TO IGNITOR CABLE Notes CATEGORY 5						
SB PW500-72-30049 Engine 1 SB - Open #99	REPLACEMENT OF FUEL NOZZLES Notes CATEGORY 8						
SB PW500-72-30049 Engine 2 SB - Open #80	REPLACEMENT OF FUEL NOZZLES Notes CATEGORY 8						
SB PW500-72-30050 R1 Engine 1 SB - Open #112	REPLACEMENT OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH Notes CATEGORY 8						
SB PW500-72-30050 R1 Engine 2 SB - Open #119	REPLACEMENT OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH Notes CATEGORY 8						
SB PW500-72-30051 Engine 1 SB - Open #116	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY Notes CATEGORY 8						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30051 Engine 2 SB - Open #121	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY Notes CATEGORY 8						
SB PW500-72-30053 R1 Engine 1 SB - Open #126	REPLACEMENT/MODIFICATION OF HIGH COMPRESSOR ROTOR Notes CATEGORY 5						
SB PW500-72-30053 R1 Engine 2 SB - Open #110	REPLACEMENT/MODIFICATION OF HIGH COMPRESSOR ROTOR Notes CATEGORY 5						
SB PW500-72-30059 R3 Engine 1 SB - Open #103	INSPECTION OF FAN INLET CASE ABRADABLE Notes CATEGORY 3						
SB PW500-72-30059 R3 Engine 2 SB - Open #69	INSPECTION OF FAN INLET CASE ABRADABLE Notes CATEGORY 3						
SB PW500-72-30063 R2 Engine 1 SB - Open #154	BORESCOPE INSPECTION OF SECOND STAGE HP COMPRESSOR ROTOR CLEARANCE Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30063 R2 Engine 2 SB - Open #113	BORESCOPE INSPECTION OF SECOND STAGE HP COMPRESSOR ROTOR CLEARANCE						
	Notes CATEGORY 3						
SB PW500-72-30064 Engine 1 SB - Open #55	REPLACEMENT OF TURBOFAN ENGINE FUEL NOZZLES (SUPERSEDED BY PW500-72-30064 R01)						
	Notes CATEGORY 3						
SB PW500-72-30064 Engine 2 SB - Open #167	REPLACEMENT OF TURBOFAN ENGINE FUEL NOZZLES (SUPERSEDED BY PW500-72-30064 R01)						
	Notes CATEGORY 3						
SB PW500-72-30064 R1 Engine 1 SB - Complied With #69	REPLACEMENT OF FUEL NOZZLES						
	Notes CATEGORY 3						
SB PW500-72-30064 R1 Engine 2 SB - Complied With #90	REPLACEMENT OF FUEL NOZZLES						
	Notes CATEGORY 3						
SB PW500-72-30070 R3 Engine 1 SB - Open #65	REPLACEMENT OF SERVO FOR INTERCOMPRESSOR BLEED VALVE						
	Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30070 R3 Engine 2 SB - Open #83	REPLACEMENT OF SERVO FOR INTERCOMPRESSOR BLEED VALVE						
	Notes CATEGORY 3						
SB PW500-72-30072 Engine 1 SB - Open #153	INSPECTION/REPLACEMENT OF NO. 4 BEARING CARBON SEAL						
	Notes CATEGORY 6						
SB PW500-72-30072 Engine 2 SB - Open #60	INSPECTION/REPLACEMENT OF NO. 4 BEARING CARBON SEAL						
	Notes CATEGORY 6						
SB PW500-72-30113 Engine 1 SB - Complied With #67	REPLACEMENT OF FAN RETAINING KEY WASHER	14-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 5						
SB PW500-72-30113 Engine 2 SB - Complied With #165	REPLACEMENT OF FAN RETAINING KEY WASHER	26-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 5						
SB PW500-72-30156 R1 Engine 1 SB - Complied With #157	REPLACEMENT OF ANTI-ICING VALVE	14-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 7						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30156 R1 Engine 2 SB - Complied With #107	REPLACEMENT OF ANTI-ICING VALVE	26-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 7						
SB PW500-72-30178 Engine 2 SB - Complied With #84	REPLACEMENT OF ELECTRICAL WIRING HARNESS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 7						
SB PW500-72-30181 Engine 1 SB - Complied With #150	INTRODUCTION OF HIGH PRESSURE TEMPERATURE PREFORMED PACKINGS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 6						
SB PW500-72-30181 Engine 2 SB - Complied With #78	INTRODUCTION OF HIGH PRESSURE TEMPERATURE PREFORMED PACKINGS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes CATEGORY 6						
SB PW500-72-30197 R5 Engine 1 SB #93	INTRODUCTION OF NEW FUEL MANIFOLD	17-FEB-2020 H: 8759.50 C: 6379					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						
SB PW500-72-30197 R5 Engine 2 SB #166	INTRODUCTION OF NEW FUEL MANIFOLD	17-FEB-2020 H: 8759.50 C: 6379					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30202 R2 Engine 2 SB - Complied With #117	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30217 R2 Engine 1 SB - Complied With #136	INSPECTION OF FUEL TUBE (SUPERSEDED BY PW500-72-30217 R03)	28-OCT-2019 H: 8694.50 C: 6348					
	Notes COMPLIED WITH - PCW						
SB PW500-72-30217 R2 Engine 2 SB - Complied With #112	INSPECTION OF FUEL TUBE (SUPERSEDED BY PW500-72-30217 R03)	28-OCT-2019 H: 8694.50 C: 6348					
	Notes COMPLIED WITH - PCW						
SB PW500-72-30217 R3 Engine 1 SB - Complied With #129	INSPECTION OF FUEL TUBE	28-OCT-2019 H: 8694.50 C: 6348					
	Notes COMPLIED WITH - PCW						
SB PW500-72-30217 R3 Engine 2 SB - Complied With #155	INSPECTION OF FUEL TUBE	28-OCT-2019 H: 8694.50 C: 6348					
	Notes COMPLIED WITH - PCW						
SB PW500-72-30218 R1 Engine 2 SB - Complied With #134	REPLACEMENT/MODIFICATION OF FOKKER ELMO ENGINE HARNESS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30261 R3 Engine 1 SB #115	INTRODUCTION OF FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR	17-FEB-2020 H: 8759.50 C: 6379					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME						
SB PW500-72-30261 R3 Engine 2 SB #106	INTRODUCTION OF FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR	17-FEB-2020 H: 8759.50 C: 6379					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME						
SB PW500-72-30266 Engine 1 SB - Open #241	REPLACEMENT/MODIFICATION OF IGNITION EXCITER (SUPERSEDED BY PW500-72-30266 R01)						
	Notes CATEGORY 7						
SB PW500-72-30266 Engine 2 SB - Open #241	REPLACEMENT/MODIFICATION OF IGNITION EXCITER (SUPERSEDED BY PW500-72-30266 R01)						
	Notes CATEGORY 7						
SB PW500-72-30282 R1 Engine 1 SB - Complied With #58	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30282 R1 Engine 2 SB - Complied With #79	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30300 R3 Engine 1 SB - Complied With #82	REPLACEMENT OF OIL PUMP PLAIN SEAL	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30300 R3 Engine 2 SB - Complied With #129	REPLACEMENT OF OIL PUMP PLAIN SEAL	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30301 Engine 1 SB - Open #203	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30301 R01)						
	Notes CATEGORY 6						
SB PW500-72-30301 Engine 2 SB - Open #239	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30301 R01)						
	Notes CATEGORY 6						
SB PW500-72-30308 Engine 1 SB - Complied With #133	REPLACEMENT COMPRESSOR RETAINING NUT	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30308 Engine 2 SB - Complied With #154	REPLACEMENT COMPRESSOR RETAINING NUT	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30325 Engine 1 SB - Open #212	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R01)						
	Notes CATEGORY 6						
SB PW500-72-30325 Engine 2 SB - Open #244	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R01)						
	Notes CATEGORY 6						
SB PW500-72-30325 R01 Engine 1 SB - Open #220	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R02)						
	Notes CATEGORY 6						
SB PW500-72-30325 R01 Engine 2 SB - Open #212	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R02)						
	Notes CATEGORY 6						
SB PW500-72-30325 R3 Engine 1 SB - Complied With #118	REPLACEMENT OF OIL-PUMP PLAIN SEAL	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30325 R3 Engine 2 SB - Complied With #77	REPLACEMENT OF OIL-PUMP PLAIN SEAL	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30326 Engine 1 SB - Complied With #159	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30326 Engine 2 SB - Complied With #75	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30327 Engine 1 SB - Complied With #155	REPLACEMENT OF NO.4 BEARING CARBON SEAL	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30327 Engine 2 SB - Complied With #160	REPLACEMENT OF NO.4 BEARING CARBON SEAL	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30340 Engine 1 SB - Open #202	REPLACEMENT OF IGNITERS AND IGNITION CABLES (SUPERSEDED BY PW500-72-30340 R01)						
	Notes CATEGORY 7						
SB PW500-72-30340 Engine 2 SB - Open #208	REPLACEMENT OF IGNITERS AND IGNITION CABLES (SUPERSEDED BY PW500-72-30340 R01)						
	Notes CATEGORY 7						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30340 R1 Engine 1 SB - Open #200	REPLACEMENT OF IGNITERS AND IGNITION CABLES (SUPERSEDED BY PW500-72-30340 R02)						
	Notes CATEGORY 7						
SB PW500-72-30340 R1 Engine 2 SB - Open #233	REPLACEMENT OF IGNITERS AND IGNITION CABLES (SUPERSEDED BY PW500-72-30340 R02)						
	Notes CATEGORY 7						
SB PW500-72-30340 R2 Engine 1 SB - Complied With #164	REPLACEMENT OF IGNITERS AND IGNITION CABLES	11-MAY-2010 H: 7495.53 C: 5625					
	Notes COMPLIED WITH - IAW THE SB						
SB PW500-72-30340 R2 Engine 2 SB - Complied With #64	REPLACEMENT OF IGNITERS AND IGNITION CABLES	11-MAY-2010 H: 7495.53 C: 5625					
	Notes COMPLIED WITH - IAW THE SB						
SB PW500-72-30343 R04 Engine 1 SB - Open #238	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R05)						
	Notes CATEGORY 7						
SB PW500-72-30343 R04 Engine 2 SB - Open #211	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R05)						
	Notes CATEGORY 7						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30346 R1 Engine 1 SB - Complied With #90	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30346 R1 Engine 2 SB - Complied With #118	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30348 R1 Engine 1 SB - Complied With #145	MODIFICATION OF AGB DRIVE-SHAFT LOWER-BEARING TO INTERMEDIATE CASE INSTALLATION	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30348 R1 Engine 2 SB - Complied With #59	MODIFICATION OF AGB DRIVE-SHAFT LOWER-BEARING TO INTERMEDIATE CASE INSTALLATION	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30351 R1 Engine 1 SB - Open #224	INTRODUCTION OF TURBINE EXHAUST CASE REINFORCEMENT RING (SUPERSEDED BY PW500-72-30351 R02)						
	Notes CATEGORY 6						
SB PW500-72-30351 R1 Engine 2 SB - Open #201	INTRODUCTION OF TURBINE EXHAUST CASE REINFORCEMENT RING (SUPERSEDED BY PW500-72-30351 R02)						
	Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30351 R2 Engine 1 SB - Complied With #88	INTRODUCTION OF TURBINE EXHAUST CASE REINFORCEMENT RING	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30351 R2 Engine 2 SB - Complied With #141	INTRODUCTION OF TURBINE EXHAUST CASE REINFORCEMENT RING	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30353 R1 Engine 1 SB - Complied With #57	REPLACEMENT OF INTERSHAFT CARBON SEALS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30353 R1 Engine 2 SB - Complied With #100	REPLACEMENT OF INTERSHAFT CARBON SEALS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30357 Engine 1 SB - Open #221	REPLACEMENT/MODIFICATION HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS (SUPERSEDED BY PW500-72-30357 R01)						
	Notes CATEGORY 6						
SB PW500-72-30357 Engine 2 SB - Open #202	REPLACEMENT/MODIFICATION HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS (SUPERSEDED BY PW500-72-30357 R01)						
	Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30357 R02 Engine 1 SB - Open #208	REPLACEMENT/MODIFICATION HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS (SUPERSEDED BY PW500-72-30357 R03)						
	Notes CATEGORY 6						
SB PW500-72-30357 R02 Engine 2 SB - Open #199	REPLACEMENT/MODIFICATION HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS (SUPERSEDED BY PW500-72-30357 R03)						
	Notes CATEGORY 6						
SB PW500-72-30358 R01 Engine 1 SB - Open #229	P3 AIR INERTIAL SEPARATOR WITH NO SILVER PLATING						
	Notes CATEGORY 7						
SB PW500-72-30358 R01 Engine 2 SB - Open #246	P3 AIR INERTIAL SEPARATOR WITH NO SILVER PLATING						
	Notes CATEGORY 7						
SB PW500-72-30362 Engine 1 SB - Complied With #75	REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30362 Engine 2 SB - Complied With #88	REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30365 Engine 1 SB - Open #214	REPLACEMENT INLET PRESSURE OIL TUBE ASSY Notes CATEGORY 7						
SB PW500-72-30365 Engine 2 SB - Open #240	REPLACEMENT INLET PRESSURE OIL TUBE ASSY Notes CATEGORY 7						
SB PW500-72-30372 Engine 1 SB - Open #206	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION (SUPERSEDED BY PW500-72-30372 R01) Notes CATEGORY 6						
SB PW500-72-30372 Engine 2 SB - Open #245	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION (SUPERSEDED BY PW500-72-30372 R01) Notes CATEGORY 6						
SB PW500-72-30372 R02 Engine 1 SB - Open #217	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION (SUPERSEDED BY PW500-72-30372 R03) Notes CATEGORY 6						
SB PW500-72-30372 R02 Engine 2 SB - Open #243	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION (SUPERSEDED BY PW500-72-30372 R03) Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30376 Engine 1 SB - Open #199	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR (SUPERSEDED BY PW500-72-30376 R01)						
	Notes CATEGORY 7						
SB PW500-72-30376 Engine 2 SB - Open #223	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR (SUPERSEDED BY PW500-72-30376 R01)						
	Notes CATEGORY 7						
SB PW500-72-30380 Engine 1 SB - Open #218	GEARBOX-DRIVE-SHAFT-ACCESSORY, GEARBOX DRIVE GEARSHAFT-ASSEMBLY, GEARBOX DRIVE SPLINE BEVEL- GEARSHAFT/REPLACEMENT						
	Notes CATEGORY 7						
SB PW500-72-30380 Engine 2 SB - Open #206	GEARBOX-DRIVE-SHAFT-ACCESSORY, GEARBOX DRIVE GEARSHAFT-ASSEMBLY, GEARBOX DRIVE SPLINE BEVEL- GEARSHAFT/REPLACEMENT						
	Notes CATEGORY 7						
SB PW500-72-30381 Engine 1 SB - Complied With #49	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING (SUPERSEDED BY PW500-72-30381 R01)	05-NOV-2009 H: 7495.53 C: 5625					
	Notes COMPLIED WITH						
SB PW500-72-30381 R1 Engine 1 SB - Complied With #144	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING (SUPERSEDED BY PW500-72-30381 R02)	05-NOV-2009 H: 7495.53 C: 5625					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30381 R1 Engine 2 SB - Complied With #127	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING (SUPERSEDED BY PW500-72-30381 R02) Notes COMPLIED WITH	05-NOV-2009 H: 7495.53 C: 5625					
SB PW500-72-30381 R2 Engine 1 SB - Complied With #51	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING Notes COMPLIED WITH	05-NOV-2009 H: 7497.63 C: 5626					
SB PW500-72-30381 R2 Engine 2 SB - Complied With #168	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING Notes COMPLIED WITH	05-NOV-2009 H: 7497.63 C: 5626					
SB PW500-72-30387 Engine 1 SB - Open #246	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R01) Notes CATEGORY 6						
SB PW500-72-30387 Engine 2 SB - Open #222	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R01) Notes CATEGORY 6						
SB PW500-72-30387 R01 Engine 1 SB - Open #219	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY(SUPERSEDED BY PW500-72-30387 R02)						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30387 R01 Engine 2 SB - Open #236	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY(SUPERSEDED BY PW500-72-30387 R02)						
SB PW500-72-30387 R6 Engine 1 SB - Complied With #127	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30387 R6 Engine 2 SB - Complied With #130	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30389 Engine 1 SB - Complied With #117	REPLACEMENT OF CARBON SEAL, NO. 4 BEARING Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30389 Engine 2 SB - Complied With #95	REPLACEMENT OF CARBON SEAL, NO. 4 BEARING Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30390 Engine 1 SB - N/A #230	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30390 R01) Notes NOT APPLICABLE - SUPERSEDED BY SB PW500-72-30409						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30390 Engine 2 SB - N/A #205	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30390 R01) Notes NOT APPLICABLE - SUPERSEDED BY SB PW500-72-30409						
SB PW500-72-30390 R01 Engine 1 SB - Open #235	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30390 R02) Notes NOT APPLICABLE - SUPERSEDED BY SB PW500-72-30409						
SB PW500-72-30390 R01 Engine 2 SB - Open #227	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30390 R02) Notes NOT APPLICABLE - SUPERSEDED BY SB PW500-72-30409						
SB PW500-72-30390 R02 Engine 1 SB - Open #226	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30390 R03) Notes NOT APPLICABLE - SUPERSEDED BY SB PW500-72-30409						
SB PW500-72-30390 R02 Engine 2 SB - Open #232	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30390 R03) Notes NOT APPLICABLE - SUPERSEDED BY SB PW500-72-30409						
SB PW500-72-30390 R03 Engine 1 SB - Open #201	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30390 R04) Notes NOT APPLICABLE - SUPERSEDED BY SB PW500-72-30409						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30390 R03 Engine 2 SB - Open #209	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30390 R04) Notes NOT APPLICABLE - SUPERSEDED BY SB PW500-72-30409						
SB PW500-72-30391 Engine 1 SB - Open #213	REPLACEMENT INLET PRESSURE OIL TUBE ASSY Notes CATEGORY 7						
SB PW500-72-30391 Engine 2 SB - Open #200	REPLACEMENT INLET PRESSURE OIL TUBE ASSY Notes CATEGORY 7						
SB PW500-72-30400 Engine 1 SB - Superseded #215	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R01) Notes SUPERSEDED						
SB PW500-72-30400 Engine 2 SB - Superseded #230	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R01) Notes SUPERSEDED						
SB PW500-72-30400 R01 Engine 1 SB - Open #222	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R02) Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30400 R01 Engine 2 SB - Open #214	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R02) Notes CATEGORY 6						
SB PW500-72-30400 R4 Engine 1 SB - Complied With #106	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30400 R4 Engine 2 SB - Complied With #157	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30403 Engine 1 SB - Open #232	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R01) Notes CATEGORY 6						
SB PW500-72-30403 Engine 2 SB - Open #242	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R01) Notes CATEGORY 6						
SB PW500-72-30403 R01 Engine 1 SB - Open #242	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R02) Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30403 R01 Engine 2 SB - Open #228	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R02) Notes CATEGORY 6						
SB PW500-72-30403 R4 Engine 1 SB - Complied With #70	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30403 R4 Engine 2 SB - Complied With #125	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30404 R01 Engine 1 SB - Open #205	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE (SUPERSEDED BY PW500-72-30404 R02) Notes CATEGORY 7						
SB PW500-72-30404 R01 Engine 2 SB - Open #218	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE (SUPERSEDED BY PW500-72-30404 R02) Notes CATEGORY 7						
SB PW500-72-30404 R02 Engine 1 SB - Open #210	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE (SUPERSEDED BY PW500-72-30404 R03) Notes CATEGORY 7						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30404 R02 Engine 2 SB - Open #235	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE (SUPERSEDED BY PW500-72-30404 R03)						
	Notes CATEGORY 7						
SB PW500-72-30404 R3 Engine 1 SB - Open #237	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE						
	Notes CATEGORY 7						
SB PW500-72-30404 R3 Engine 2 SB - Open #225	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE						
	Notes CATEGORY 7						
SB PW500-72-30405 R4 Engine 1 SB - Complied With #50	REPLACEMENT OF FUEL NOZZLE MANIFOLD	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30405 R4 Engine 2 SB - Complied With #137	REPLACEMENT OF FUEL NOZZLE MANIFOLD	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30408 Engine 1 SB - Complied With #152	REPLACEMENT OF ENGINE GASKET	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30408 Engine 2 SB - Complied With #150	REPLACEMENT OF ENGINE GASKET	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30409 Engine 1 SB - Open #228	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R01)						
	Notes CATEGORY 3						
SB PW500-72-30409 Engine 2 SB - Open #204	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R01)						
	Notes CATEGORY 3						
SB PW500-72-30409 R01 Engine 1 SB - Open #211	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R02)						
	Notes CATEGORY 3						
SB PW500-72-30409 R01 Engine 2 SB - Open #207	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R02)						
	Notes CATEGORY 3						
SB PW500-72-30409 R04 Engine 1 SB - N/A #236	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R05)						
	Notes NOT APPLICABLE - SUPERSEDED SEE REVISION 5						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30409 R04 Engine 2 SB - N/A #238	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R05)						
	Notes NOT APPLICABLE - SUPERSEDED SEE REVISION 5						
SB PW500-72-30409 R05 Engine 1 SB - Complied With #225	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R06)						
	Notes COMPLIED WITH - PREVIOUSLY EARLIER ISSUE OF SERVICE BULLETIN HAS BEEN ADDRESSED.						
SB PW500-72-30409 R05 Engine 2 SB - Complied With #216	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R06)						
	Notes COMPLIED WITH - PREVIOUSLY EARLIER ISSUE OF SERVICE BULLETIN HAS BEEN ADDRESSED.						
SB PW500-72-30409 R06 Engine 1 SB - Open #227	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R07)						
	Notes CATEGORY 3						
SB PW500-72-30409 R06 Engine 2 SB - Open #237	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R07)						
	Notes CATEGORY 3						
SB PW500-72-30409 R07 Engine 1 SB - Open #231	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30409 R08)						
	Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30409 R07 Engine 2 SB - Open #224	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30409 R08)						
	Notes CATEGORY 3						
SB PW500-72-30409 R2 Engine 1 SB - Complied With #119	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R03)	11-MAY-2010 H: 7497.63 C: 5626					
	Notes COMPLIED WITH - IAW THE SB						
SB PW500-72-30409 R2 Engine 2 SB - Complied With #135	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R03)	11-MAY-2010 H: 7497.63 C: 5626					
	Notes COMPLIED WITH - IAW THE SB						
SB PW500-72-30415 R04 Engine 1 SB - Open #234	REPLACEMENT OF NO. 4 ROLLER BEARING						
	Notes CATEGORY 6						
SB PW500-72-30415 R04 Engine 2 SB - Open #219	REPLACEMENT OF NO. 4 ROLLER BEARING						
	Notes CATEGORY 6						
SB PW500-72-30415 R3 Engine 1 SB - Complied With #160	REPLACEMENT OF NO. 4 ROLLER BEARING	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30420 Engine 1 SB - Open #204	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R01)						
	Notes NOT APPLICABLE - SUPERSEDED BY REVISION 1						
SB PW500-72-30420 Engine 2 SB - Open #203	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R01)						
	Notes NOT APPLICABLE - SUPERSEDED BY REVISION 1						
SB PW500-72-30420 R4 Engine 1 SB - Complied With #83	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-3042 R05)	20-APR-2015 H: 8201.80 C: 6057					
	Notes COMPLIED WITH - BLV SOLENOID VALVE REPLACED WITH A NEW UNIT IAW SB PW500-72-30420 R4.						
SB PW500-72-30420 R5 Engine 2 SB - Complied With #52	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30423 R1 Engine 1 SB - Complied With #128	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30423 R1 Engine 2 SB - Complied With #99	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30428 R6 Engine 1 SB - Complied With #85	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30428 R6 Engine 2 SB - Complied With #140	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30442 R4 Engine 1 SB - Complied With #123	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30442 R4 Engine 2 SB - Complied With #123	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30447 R1 Engine 1 SB - Complied With #64	NEW COATING MODIFICATION OF GAS GENERATOR CASE	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30447 R1 Engine 2 SB - Complied With #49	NEW COATING MODIFICATION OF GAS GENERATOR CASE	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30455 R5 Engine 1 SB - Complied With #53	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30455 R5 Engine 2 SB - Complied With #94	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30465 R2 Engine 1 SB - Complied With #104	REPLACEMENT OF FUEL MANIFOLD TUBES	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30465 R2 Engine 2 SB - Complied With #103	REPLACEMENT OF FUEL MANIFOLD TUBES	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30490 Engine 1 SB - Complied With #76	INSPECTION/REPLACEMENT OF FUEL PRESSURE TUBE INSTALLATION	28-MAR-2014 H: 8081.70 C: 5970					
	Notes COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30490, NO.1 ENGINE INSPECTION / REPLACEMENT OF FUEL PRESSURE TUBE INSTALLATION. REMOVED EXISTING FUEL PRESSURE TUBE P/N 31J2350-01 AND REPLACED WITH NEW PRESSURE TUBE P/N 30J3312-01. INSTALLED NEW FLOW DIVIDER VALVE RETURN SCREEN P/N 1009050-1 AS CALLED OUT IN SERVICE BULLETIN PW500-72-30490,						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30490 Engine 2 SB - Complied With #162	INSPECTION/REPLACEMENT OF FUEL PRESSURE TUBE INSTALLATION	28-MAR-2014 H: 8081.70 C: 5970					
	Notes COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30490, NO.1 ENGINE INSPECTION / REPLACEMENT OF FUEL PRESSURE TUBE INSTALLATION. REMOVED EXISTING FUEL PRESSURE TUBE P/N 31J2350-01 AND REPLACED WITH NEW PRESSURE TUBE P/N 30J3312-01. INSTALLED NEW FLOW DIVIDER VALVE RETURN SCREEN P/N 1009050-1 AS CALLED OUT IN SERVICE BULLETIN PW500-72-30490,						
SB PW500-72-30501 Engine 1 SB - Complied With #134	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30501 Engine 2 SB - Complied With #93	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30505 R03 Engine 1 SB - Open #233	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS						
	Notes CATEGORY 3						
SB PW500-72-30505 R03 Engine 2 SB - Open #210	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS						
	Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30505 R1 Engine 1 SB - Complied With #92	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02)	20-APR-2015 H: 8203.60 C: 6058					
	Notes COMPLIED WITH - SB CARRIED OUT IAW INSTRUCTIONS FOUND IN PW500-72-30505 R1. OLD GASKETS REMOVED AND IMPROVED UNITS INSTALLED IN PLACE WITH NEW HARDWARE. SYSTEM FUNCTION TESTED AND FOUND TO BE SERVICEABLE IAW EMM 75-30-01.						
SB PW500-72-30505 R1 Engine 2 SB - Complied With #161	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02)	20-APR-2015 H: 8203.60 C: 6058					
	Notes COMPLIED WITH - SB CARRIED OUT IAW INSTRUCTIONS FOUND IN PW500-72-30505 R1. OLD GASKETS REMOVED AND IMPROVED UNITS INSTALLED IN PLACE WITH NEW HARDWARE. SYSTEM FUNCTION TESTED AND FOUND TO BE SERVICEABLE IAW EMM 75-30-01.						
SB PW500-72-30505 R2 Engine 1 SB - Complied With #125	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30505 R2 Engine 2 SB - Complied With #54	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30506 R2 Engine 1 SB - Complied With #74	REPLACEMENT OF FUEL MANIFOLD ADAPTERS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30506 R2 Engine 2 SB - Complied With #85	REPLACEMENT OF FUEL MANIFOLD ADAPTERS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30511 R02 Engine 1 SB - Open #239	RE-TORQUEING OF AGB COVER BOLTS OR NUTS						
	Notes CATEGORY 6						
SB PW500-72-30511 R02 Engine 2 SB - Open #215	RE-TORQUEING OF AGB COVER BOLTS OR NUTS						
	Notes CATEGORY 6						
SB PW500-72-30511 R1 Engine 1 SB - Complied With #80	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30511 R1 Engine 2 SB - Complied With #138	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30512 Engine 1 SB #102	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R01)	08-JUL-2016 H: 8348.70 C: 6140					
	Notes DECLINED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30512 Engine 2 SB #97	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R01)	08-JUL-2016 H: 8348.70 C: 6140					
	Notes DECLINED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						
SB PW500-72-30512 R1 Engine 1 SB #105	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R02)	08-JUL-2016 H: 8348.70 C: 6140					
	Notes DECLINED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						
SB PW500-72-30512 R1 Engine 2 SB #91	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R02)	08-JUL-2016 H: 8348.70 C: 6140					
	Notes DECLINED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						
SB PW500-72-30512 R2 Engine 1 SB #147	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)	08-JUL-2016 H: 8348.70 C: 6141					
	Notes DECLINED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						
SB PW500-72-30512 R2 Engine 2 SB - Open #81	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)						
	Notes DECLINED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.						
SB PW500-72-30516 R2 Engine 1 SB - Complied With #56	REPLACEMENT OF HP TURBINE SEAL RINGS	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30516 R2 Engine 2 SB - Complied With #50	REPLACEMENT OF HP TURBINE SEAL RINGS Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30517 R1 Engine 1 SB - Complied With #71	DELETION OF IGNITER FLANGE GASKETS Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30517 R1 Engine 2 SB - Complied With #133	DELETION OF IGNITER FLANGE GASKETS Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30533 R1 Engine 1 SB - Complied With #140	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30533 R1 Engine 2 SB - Complied With #152	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
SB PW500-72-30545 R3 Engine 1 SB - Complied With #52	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72-30545 R3 Engine 2 SB - Complied With #101	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
SB PW500-72-30545 R4 Engine 1 SB - Complied With #109	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	21-JUN-2021 H: 8836.80 C: 6432					
	Notes COMPLIED WITH - COMPLIED WITH SB PW500-72-30545 R04. REPLACEMENT OF HMFU						
SB PW500-72-30545 R4 Engine 2 SB - Complied With #156	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	21-JUN-2021 H: 8836.80 C: 6432					
	Notes COMPLIED WITH - COMPLIED WITH SB PW500-72-30545 R04. REPLACEMENT OF HMFU						
SB PW500-72- 30075 Engine 1 SB - Open #168	REPLACEMENT OF EXTERNAL MOUNTING HARDWARE (SUPERSEDED BY PW500-72-30075 R01)						
	Notes CATEGORY 8						
SB PW500-72- 30075 Engine 2 SB - Open #169	REPLACEMENT OF EXTERNAL MOUNTING HARDWARE (SUPERSEDED BY PW500-72-30075 R01)						
SB PW500-72- 30091 R2 Engine 1 SB - Open #169	REPLACEMENT OF FAN CASE ASSEMBLY						
	Notes CATEGORY 8						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30091 R2 Engine 2 SB - Open #170	REPLACEMENT OF FAN CASE ASSEMBLY						
	Notes CATEGORY 8						
SB PW500-72- 30128 Engine 1 SB - Open #170	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						
	Notes CATEGORY 5						
SB PW500-72- 30128 Engine 2 SB - Open #171	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						
	Notes CATEGORY 5						
SB PW500-72- 30130 Engine 1 SB - Open #171	REPLACEMENT OF FUEL NOZZLES						
	Notes CATEGORY 8						
SB PW500-72- 30130 Engine 2 SB - Open #172	REPLACEMENT OF FUEL NOZZLES						
	Notes CATEGORY 8						
SB PW500-72- 30146 Engine 1 SB - Open #172	REPLACEMENT OF TWO PART EPOXY TO INSPECTION LACQUER						
	Notes CATEGORY 8						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30146 Engine 2 SB - Open #173	REPLACEMENT OF TWO PART EPOXY TO INSPECTION LACQUER						
	Notes CATEGORY 8						
SB PW500-72- 30151 R1 Engine 1 SB - Open #173	REPLACMENT OF GAS GENERATOR CASE						
	Notes CATEGORY 7						
SB PW500-72- 30151 R1 Engine 2 SB - Open #174	REPLACMENT OF GAS GENERATOR CASE						
	Notes CATEGORY 7						
SB PW500-72- 30151 R2 Engine 1 SB - Open #174	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE						
	Notes CATEGORY 7						
SB PW500-72- 30151 R2 Engine 2 SB - Open #175	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE						
	Notes CATEGORY 7						
SB PW500-72- 30171 Engine 1 SB - Open #175	REPLACMENT OF DIFFUSER SET						
	Notes CATEGORY 7						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30171 Engine 2 SB - Open #176	REPLACMENT OF DIFFUSER SET						
	Notes CATEGORY 7						
SB PW500-72- 30174 R1 Engine 1 SB - Open #176	REPLACEMENT OF IGNITION EXCITER BOX						
	Notes CATEGORY 5						
SB PW500-72- 30174 R1 Engine 2 SB - Open #177	REPLACEMENT OF IGNITION EXCITER BOX						
	Notes CATEGORY 5						
SB PW500-72- 30197 R3 Engine 1 SB - Open #177	INTRODUCTION OF NEW FUEL MANIFOLD (SUPERSEDED BY PW500-72-30197 R04)						
	Notes CATEGORY 3						
SB PW500-72- 30197 R3 Engine 2 SB - Open #178	INTRODUCTION OF NEW FUEL MANIFOLD (SUPERSEDED BY PW500-72-30197 R04)						
	Notes CATEGORY 3						
SB PW500-72- 30197 R4 Engine 1 SB - Open #178	INTRODUCTION OF NEW FUEL MANIFOLD (SUPERSEDED BY PW500-72-30197 R05)						
	Notes CATEGORY 3						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30197 R4 Engine 2 SB - Open #179	INTRODUCTION OF NEW FUEL MANIFOLD (SUPERSEDED BY PW500-72-30197 R05)						
	Notes CATEGORY 3						
SB PW500-72- 30198 Engine 1 SB - Open #179	INSPECTION/REPLACEMENT OF BLEED VALVE CONTROL						
	Notes CATEGORY 8						
SB PW500-72- 30198 Engine 2 SB - Open #180	INSPECTION/REPLACMENTS OF BLEED VALVE CONTROL						
	Notes CATEGORY 8						
SB PW500-72- 30204 Engine 1 SB - Open #180	INTRODUCTION OF NEW DIFFUSER EXIT DUCT						
	Notes CATEGORY 9						
SB PW500-72- 30204 Engine 2 SB - Open #181	INTRODUCTION OF NEW DIFFUSER EXIT DUCT						
	Notes CATEGORY 9						
SB PW500-72- 30207 Engine 1 SB - Open #181	REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY PW500-72-30207 R01)						
	Notes CATEGORY 7						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30207 Engine 2 SB - Open #182	REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY PW500-72-30207 R01)						
	Notes CATEGORY 7						
SB PW500-72- 30218 R1 Engine 1 SB - Open #182	REPLACEMENT/MODIFICATION OF FOKKER ELMO ENGINE HARNESS						
	Notes CATEGORY 8						
SB PW500-72- 30222 R01 Engine 2 SB - Open #183	REPLACEMENT OF HIGH COMPRESSOR ROTOR						
	Notes REPLACMENT OF HIGH COMPRESSOR ROTOR						
SB PW500-72- 30222 R1 Engine 1 SB - Open #183	REPLACEMENT OF HIGH COMPRESSOR ROTOR						
	Notes CATEGORY 7						
SB PW500-72- 30223 Engine 2 SB - Open #184	REPLACEMENT OF THE INTERMEDIATE CASE						
	Notes CATEGORY 7						
SB PW500-72- 30223 Engine 1 SB - Open #184	SB PW500-72- 30223						
	Notes SB PW500-72- 30223						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30235 Engine 1 SB - Open #185	REPLACEMENT OF REAR BYPASS DUCT MOUNTING FLANGE FRONT AND REAR HEAT SHIELDS						
	Notes CATEGORY 7						
SB PW500-72- 30235 Engine 2 SB - Open #185	REPLACEMENT OF REAR BYPASS DUCT MOUNTING FLANGE FRONT AND REAR HEAT SHIELDS						
	Notes CATEGORY 7						
SB PW500-72- 30246 Engine 1 SB - Open #186	REPLACEMENT OF STARTER GENERATOR DRIVE GEARSHAFT						
	Notes CATEGORY 7						
SB PW500-72- 30246 Engine 2 SB - Open #186	REPLACEMENT OF STARTER GENERATOR DRIVE GEARSHAFT						
	Notes CATEGORY 7						
SB PW500-72- 30259 R1 Engine 1 SB - Open #187	REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT						
	Notes CATEGORY 8						
SB PW500-72- 30259 R1 Engine 2 SB - Open #187	REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT						
	Notes CATEGORY 8						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30263 Engine 1 SB - Open #188	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL (SUPERSEDED BY PW500-72-30263 R01)						
	Notes CATEGORY 8						
SB PW500-72- 30263 Engine 2 SB - Open #188	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL (SUPERSEDED BY PW500-72-30263 R01)						
	Notes CATEGORY 8						
SB PW500-72- 30269 Engine 1 SB - Open #189	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING (SUPERSEDED BY PW500-72-30269 R01)						
	Notes CATEGORY 7						
SB PW500-72- 30269 Engine 2 SB - Open #189	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING (SUPERSEDED BY PW500-72-30269 R01)						
	Notes CATEGORY 7						
SB PW500-72- 30277 R1 Engine 1 SB - Open #190	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL						
	Notes CATEGORY 8						
SB PW500-72- 30277 R1 Engine 2 SB - Open #190	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL						
	Notes CATEGORY 8						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30279 R1 Engine 1 SB - Open #191	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30279 R02)						
	Notes CATEGORY 8						
SB PW500-72- 30279 R1 Engine 2 SB - Open #191	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30279 R02)						
	Notes CATEGORY 8						
SB PW500-72- 30280 Engine 1 SB - Open #192	REPLACEMENT/INSPECTION OF OIL PUMP GEARSHAFT SPUR						
	Notes CATEGORY 8						
SB PW500-72- 30280 Engine 2 SB - Open #192	REPLACEMENT/INSPECTION OF OIL PUMP GEARSHAFT SPUR						
	Notes CATEGORY 8						
SB PW500-72- 30285 Engine 1 SB - Open #193	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL						
	Notes CATEGORY 6						
SB PW500-72- 30285 Engine 2 SB - Open #193	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL						
	Notes CATEGORY 6						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30291 R1 Engine 1 SB - Open #194	REPLACEMENT OF FIRST STAGE HIGH COMPRESSOR ROTOR						
	Notes CATEGORY 6						
SB PW500-72- 30291 R1 Engine 2 SB - Open #194	REPLACEMENT OF FIRST STAGE HIGH COMPRESSOR ROTOR						
	Notes CATEGORY 6						
SB PW500-72- 30293 Engine 1 SB - Open #195	MODIFICATION OF FAN ROTOR BALANCING						
	Notes CATEGORY 9						
SB PW500-72- 30293 Engine 2 SB - Open #195	MODIFICATION OF FAN ROTOR BALANCING						
	Notes CATEGORY 9						
SB PW500-72- 30300 R1 Engine 1 SB - Open #196	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30300 R02)						
	Notes CATEGORY 8						
SB PW500-72- 30300 R1 Engine 2 SB - Open #196	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30300 R02)						
	Notes CATEGORY 8						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30404 Engine 1 SB - Open #243	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE (SUPERSEDED BY PW500-72-30404 R01)						
	Notes CATEGORY 7						
SB PW500-72- 30404 Engine 2 SB - Open #213	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE (SUPERSEDED BY PW500-72-30404 R01)						
	Notes CATEGORY 7						
SB PW500-72- 30409 R3 Engine 1 SB - Complied With #198	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R04)						
	Notes COMPLIED WITH - PREVIOUSLY ADDRESSED IN AN EARLIER ISSUE.						
SB PW500-72- 30409 R3 Engine 2 SB - Complied With #198	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R04)						
	Notes COMPLIED WITH - PREVIOUSLY PER THE PREVIOUS ISSUE						
SB PW500-72- 30414 Engine 1 SB - Open #245	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE						
SB PW500-72- 30414 Engine 2 SB - Open #229	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE						
SB PW500-72- 30416 Engine 1 SB - Open #223	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30416 R01)						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30416 Engine 2 SB - Open #231	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30416 R01)						
SB PW500-72- 30420 R6 Engine 1 SB - Open #216	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE						
	Notes CATEGORY 3						
SB PW500-72- 30420 R6 Engine 2 SB - Open #220	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE						
	Notes CATEGORY 3						
SB PW500-72- 30548 R2 Engine 1 SB - Complied With #197	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH CATEGORY 7						
SB PW500-72- 30548 R2 Engine 2 SB - Complied With #197	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH CATEGORY 7						
SB PW500-72- 30554 R1 Engine 1 SB - Open #207	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE						
	Notes CATEGORY 7						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW500-72- 30554 R1 Engine 2 SB - Open #221	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE						
	Notes CATEGORY 7						
SB PW500-72-30351 R2 Airframe SB - Open #557	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)						
SB PW500-72-30372 R01 Engine 1 SB - Open #244	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION (SUPERSEDED BY PW500-72-30372 R02)						
	Notes CATEGORY 6						
SB PW500-72-30372 R01 Engine 2 SB - Open #226	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION (SUPERSEDED BY PW500-72-30372 R02)						
	Notes CATEGORY 6						
SL 550-03-02 R1 Airframe SB - Open #609	SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)						
SL 550-20-05 Airframe SB - Open #721	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL						
SL 550-21-24 Airframe SB - Complied With #511	CABIN TEMPERATURE SENSOR ORIENTATION INSPECTION	21-NOV-1998 H: 388.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-21-27 R1 Airframe SB - Open #794	RAM AIR INLET DRAIN LINE INSPECTION						
SL 550-23-28 Airframe SB - N/A #715	TRANSMITTAL OF AIRSHOW SERVICE BULLETIN 920720-1 AIRSHOW 400 DIGITAL INTERFACE UNIT	23-JUL-2003					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
SL 550-23-29 Airframe SB - Complied With #539	TRANSMITTAL OF ALLIEDSIGNAL BENDIX/KING SERVICE BULLETIN KY 196A-9 - KY 196A VHF COMM TRANSCEIVER	01-DEC-2000					
	Notes COMPLIED WITH						
SL 550-23-30 Airframe SB - N/A #610	TRANSMITTAL OF ALLIEDSIGNAL BENDIX/KING SB KY 196B-2 - KY 196B VHF COMM TRANSCEIVER	23-JUL-2003					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
SL 550-23-31 R1 Airframe SB - N/A #570	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE	23-JUL-2003 H: 3109.00					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
SL 550-24-16 Airframe SB - Complied With #663	AFT J-BOX BUS BAR AND WASHER INSPECTION (SUPERSEDED BY SL550-24-16 R01)	17-JUN-2011 H: 7501.30 L: 5631					
	Notes COMPLIED WITH - SL550-24-16 ELETRICAL POWER AFT J-BOX BUS BAR AND WASHER INSPECTION. NOTE: FOUND WASHERS FOR FL1, FL2, FL10 AND FL11 OF STEEL CONSTRUCTION. UPON REMOVAL OF FL10 FOUND WASHERS FUSED (WELDED) TOGETHER AND CORRODED. FUSE FL10 HAD EXCESSIVE HEAT DAMAGE AND FUSE HOLDER STUD/PLASTIC BURNT. NEW R/H WING DE-ICE FUSE HOLDER FL10 INSTALLED. FUSE FL10 REPLACED WITH NEW LIMITER IAW CESSNA 550B AMM 24-50-03. SYSTEM TESTED OK.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-24-16 R1 Airframe SB #694	AFT J-BOX BUS BAR AND WASHER INSPECTION (SUPERSEDED BY SL550-24-16 R02)	13-DEC-2011 H: 7605.00 L: 5710					
	Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY WITH AT THIS TIME.						
SL 550-24-16 R3 Airframe SB - Complied With #785	AFT J-BOX BUS BAR AND WASHER INSPECTION	28-MAR-2014 H: 8080.20 L: 5969					
	Notes COMPLIED WITH - COMPLIED WITH CESSNA SERVICE LETTER SL550-24-16 R3 AFT J-BOX BUS BAR AND WASHER INSPECTION. INSTALLED NEW HARDWARE IAW SL550-24-16 R3.						
SL 550-25-12 Airframe SB - Open #622	EQUIPMENT/FURNISHINGS - CABIN SYSTEMS AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) 920040 SERVICE BULLETIN 920040-44-01 SAVE MAIN CPU CMOS SETUP SETTINGS TO FLASH MEMORY						
SL 550-25-14 Airframe SB - Complied With #717	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	07-MAR-2008 H: 7010.70 L: 5238					
	Notes COMPLIED WITH						
SL 550-27-10 Airframe SB - Complied With #625	ELEVATOR ELECTRIC TRIM TAB ACTUATOR MOUNT INSPECTION	08-NOV-2002 H: 2372.00					
	Notes COMPLIED WITH						
SL 550-27-11 Airframe SB - Complied With #774	AILERON CABLE TURNBUCKLE CLEARANCE (SUPERSEDED BY SL550-27-11 R01)	04-SEP-2002 H: 2206.00					
	Notes COMPLIED WITH						
SL 550-27-12 Airframe SB - Complied With #815	ELEVATOR TORQUE TUBE INSPECTION	20-DEC-2002 H: 2499.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-27-14 Airframe SB - Complied With #804	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT INSPECTION	07-NOV-2007 H: 6766.82 L: 5043					
	Notes COMPLIED WITH						
SL 550-29-13 Airframe SB - Complied With #778	HYDRAULIC TUBE INSPECTION AND CLAMP ATTACHMENT (SUPERSEDED BY SL550-29-13 R01)	27-APR-2004 H: 3860.00					
	Notes COMPLIED WITH						
SL 550-29-15 Airframe SB - Complied With #795	HYDRAULIC POWER - HYDRAULIC FIREWALL SHUTOFF VALVE INSPECTION	07-NOV-2007 H: 6766.82 L: 5043					
	Notes COMPLIED WITH						
SL 550-30-05 Airframe SB - Complied With #621	WING ANTI-ICE TEMPERATURE CONTROLLER REPLACEMENT	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SL 550-32-30 Airframe SB - Complied With #548	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1588-32-1, INTRODUCTION OF NEW PREFORMED PACKINGS	21-NOV-2003 H: 3401.00					
	Notes COMPLIED WITH						
SL 550-32-74 Airframe SB - Complied With #522	GEAR EMERERGENCY BRACKET SPACER INSPECTION/INSTALLATION (SUPERSEDED BY SL550-32-74 R01)	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-32-77 Airframe SB - Complied With #559	NOSE LANDING GEAR ACTUATOR UNLOCK PRESS TEST (SUPERSEDED BY SL550-32-77 R01) Notes COMPLIED WITH	19-JUL-2003 H: 3105.00					
SL 550-32-79 R1 Airframe SB - Open #809	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION						
SL 550-32-83 Airframe SB - Complied With #566	HYDRAULIC LINE INSPECTION/REPLACEMENT Notes COMPLIED WITH	29-JUN-2007 H: 6480.50 L: 4791					
SL 550-32-84 Airframe SB - Complied With #648	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE LETTER 2056 Notes COMPLIED WITH - LH WHEEL S/N 0345RH WHEEL S/N 0638	26-MAY-1915 H: 6766.82 L: 5043					
SL 550-32-86 Airframe SB - Complied With #600	LANDING GEAR - LEFT TRAILING LINK FORWARD BORE CORROSION PROTECTION (SUPERSEDED BY SL550-32-86 R01) Notes COMPLIED WITH	05-NOV-2009 H: 7495.53 L: 5625					
SL 550-32-86 Airframe SB - Complied With #801	LANDING GEAR - RIGHT TRAILING LINK FORWARD BORE CORROSION PROTECTION (SUPERSEDED BY SL550-32-86 R01) Notes COMPLIED WITH	05-NOV-2009 H: 7495.53 L: 5625					
SL 550-32-86 R1 Airframe SB - Open #750	TRAILING LINK FORWARD BORE CORROSION PROTECTION						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-32-86 R1 Airframe SB - Open #528	TRAILING LINK FORWARD BORE CORROSION PROTECTION						
SL 550-32-87 Airframe SB - Complied With #765	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	22-FEB-2011 H: 7495.80 L: 5626					
	Notes COMPLIED WITH - ACCOMPLISHED EMERGENCY GEAR RELEASE INSPECTION IN ACCORDANCE WITH CESSNA SL550-32-87						
SL 550-32-88 Airframe SB - Complied With #588	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1588-32-3, REPLACEMENT OF BLEEDER SCREWS AND BLEEDER FITTINGS WITH BLEEDER PLUGS (SUPERSEDED BY SL550-32-88 R01)	20-NOV-2015 H: 8255.60 L: 6095					
	Notes COMPLIED WITH						
SL 550-32-88 R1 Airframe SB - Complied With #756	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1588-32-3, REPLACEMENT OF BLEEDER SCREWS AND BLEEDER FITTINGS WITH BLEEDER PLUGS	20-NOV-2015 H: 8255.60 L: 6095					
	Notes COMPLIED WITH - SB 2-1588-32-3 R1 COMPLIED WITH DURING BRAKE OVERHAUL BY REPLACEMENT OF BLEEDER FITTINGS WITH CAPS.						
SL 550-34-41 Airframe SB - Complied With #620	INSPECT FOR PRESENCE OF VENDOR SPECIFIC COMPONENTS AND REPLACE AS REQUIRED	07-MAR-2004					
	Notes COMPLIED WITH						
SL 550-34-45 Airframe SB - N/A #762	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014700-34-0040	21-NOV-2003					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
SL 550-34-51 Airframe SB - Open #602	TRANSMITTAL OF HONEYWELL SOFTWARE BULLETIN SWB TPU 67A-SW8						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-34-57 Airframe SB - Open #575	NAVIGATION - TRANSMITTAL OF HONEYWELL SWB MST 67A-SW5						
SL 550-35-08 Airframe SB - Open #811	OXYGEN - OXYGEN BOTTLE INSPECTION						
SL 550-35-09 R2 Airframe SB #660	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 Notes DEFERRED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME.	04-JUN-2013 H: 7899.00 L: 5865					
SL 550-36-03 Airframe SB - Complied With #278	ENG B/A CPLNG SFTY WIRE ADD	07-MAY-2002 H: 1952.00					
SL 550-53-03 Airframe SB - Complied With #805	LIGHTNING DIVERTER STRIP INSTALLATION/REPAIR PROCEDURE CHANGE (RADOME) Notes COMPLIED WITH	12-SEP-2001 H: 1345.00					
SL 550-53-06 Airframe SB - Complied With #704	DORSAL FIN VANE INSPECTION Notes COMPLIED WITH	22-MAR-2005 H: 4631.00					
SL 550-53-07 Airframe SB - Complied With #627	INTERCOSTAL DRAIN PATH INSPECTION (SUPERSEDED BY SL550-53-07 R01) Notes COMPLIED WITH	15-SEP-2005 H: 5106.00					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-71-08 Airframe SB - Superseded #665	LOWER ENGINE COWLING DRAIN HOLE INSTALLATION	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SL 550-71-10 Airframe SB - Complied With #731	ENGINE ELECTRICAL GROUND STUD INSPECTION (SUPERSEDED BY SL550-71-10 R01)	07-MAR-2004 H: 3720.00					
	Notes COMPLIED WITH						
SL 550-71-11 R1 Airframe SB - Complied With #681	POWER PLANT - ENGINE WIRE BUNDLE INSPECTION (SUPERSEDED BY SL550-71-11 R02)	07-NOV-2007 H: 6766.82 L: 5043					
	Notes COMPLIED WITH						
SL 550-71-11 R2 Airframe SB - Complied With #544	POWER PLANT - ENGINE WIRE BUNDLE INSPECTION	01-MAY-2009 H: 7442.10 L: 5585					
	Notes COMPLIED WITH						
SL 550-72-18 Airframe SB - Complied With #732	TRANSMITTAL OF P&WC SB PW500-72-30048, TURBOFAN ENGINE, IGNITION EXCITER - REPLACEMENT OF IGNITION EXCITER TO IGNITER CABLE	23-OCT-2000 H: 1010.00					
	Notes COMPLIED WITH						
SL 550-72-19 Airframe SB - Complied With #796	TRANSMITTAL OF P&WC SB PW500-72-30058R1, TURBOFAN ENGINE FAN INLET CASE ABRADABLE - INSPECTION OF	25-JUL-2000 H: 917.00					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-72-20 Airframe SB - Complied With #727	TRANSMITTAL OF P&WC SERIVCE BULLETIN PW500-72-30063, TURBOFAN ENGINE SECOND STAGE HP COMPRESSOR ROTOR CLEARANCE - BOROSCOPE (SUPERSEDED BY SL550-72-20 R01) Notes COMPLIED WITH	11-JUN-1998 H: 285.00					
SL 550-72-21 Airframe SB - Complied With #547	TRANSMIT P&WC SB PW500-72-30044, TURBOFAN ENGINE COMPRESSOR STATOR (2 STG.) ASSEMBLY - REPLACEMENT/MODIFICATION OF Notes COMPLIED WITH	01-DEC-2000 H: 1010.00					
SL 550-72-23 Airframe SB - Complied With #686	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE FUEL CONTROL UNIT Notes COMPLIED WITH	01-DEC-2000 H: 1010.00					
SL 550-72-25 Airframe SB - Complied With #536	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30217, INSPECTION OF TURBOFAN ENGINE FUEL TUBE Notes COMPLIED WITH	02-APR-2003 H: 2808.00					
SL 550-72-28 Airframe SB - Complied With #714	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT - REPLACEMENT/MODIFICATION OF Notes COMPLIED WITH - IAW THE SB	11-MAY-2010 H: 7495.53 L: 5625					
SL 550-72-28 Airframe SB - Complied With #576	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT REPLACEMENT,MODIFICATION OF Notes COMPLIED WITH - IAW THE SB	11-MAY-2010 H: 7495.53 L: 5625					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-73-02 Airframe SB - Complied With #598	TRANSMITTAL OF P&WC SB PW500-72-A30108, REV. 2, TURBOFAN ENGINE DECAL TEST Notes COMPLIED WITH	04-NOV-1999 H: 713.00					
SL 550-73-03 Airframe SB - Complied With #626	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-30122 REPLACMENT OF TURBOFAN ENGINE FUEL TUBE Notes COMPLIED WITH	25-JUL-2000					
SL 550-73-04 Airframe SB - Complied With #771	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN 30249 TURBOFAN ENGINE FUEL MANIFOLD - INSPECTION/REPLACEMENT OF AND COMMERCIAL SUPPORT PROGRAM NOTIFICATON (CSPN) A03008 Notes COMPLIED WITH	07-MAR-2004 H: 3720.00					
SL 550-73-07 Airframe SB - N/A #667	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN 30307 TURBOFAN ENGINE HFC UNIT RATIO SETSCREW ADJUSTMENT AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) 1001503 Notes NOT APPLICABLE - BY SERIAL NUMBER N/A BY COMPONENT SERIAL NUMBER	09-JAN-2007 H: 6170.00					
SL 550-73-08 Airframe SB - Complied With #653	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF Notes COMPLIED WITH - PREVIOUSLY PREVIOUSLY BY COMPLYING WITH SERVICE BULLETIN PW500-72-30381	18-FEB-2010 H: 7495.53 L: 5625					
SL 550-73-08 Airframe SB - Complied With #633	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETINPW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF Notes COMPLIED WITH - PREVIOUSLY PREVIOUSLY BY COMPLYING WITH SERVICE BULLETIN PW500-72-30381	18-FEB-2010 H: 7495.53 L: 5625					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 550-76-04 Airframe SB - Complied With #617	ENGINE THROTTLE FRICTION BLOCK INSPECTION	25-JUL-2000 H: 917.00					
	Notes COMPLIED WITH						
SL 550-78-10 Airframe SB - Complied With #586	TRANSMITTAL OF THE NORDAM GROUP SB CIT BV 78-1 EXHAUST - THRUST REVERSER - LOWER DOOR - ADDITION OF DRAIN HOLE	01-DEC-2000 H: 1010.00					
	Notes COMPLIED WITH						
SL 550-99-05 R7 Airframe SB - Open #808	CESCOM PRICING						
SL 550-99-08 Airframe SB - Open #722	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS						
SL 550-99-09 Airframe SB - Open #619	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION						
SL CIL-20-01 Airframe SB - Open #759	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)						
SL CIL-20-01 R2 Airframe SB - Open #543	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL						
SL CIL-21-01 Airframe SB - Open #768	COMPRESSOR MOTOR BRUSH LIFE LIMIT						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL CIL-21-02 R1 Airframe SB - N/A #510	AIR CONDITIONING - ENVIRONMENTAL HOUR METER INSTALLATION	H: 8201.80 L: 6057					
	Notes NOT APPLICABLE - HOUR METER PREVIOUSLY INSTALLED. SL PCW						
SL CIL-26-01 Airframe SB - Open #690	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)						
SL CIL-26-01 R1 Airframe SB - Open #651	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING						
SL CIL-30-01 R1 Airframe SB - Open #649	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES						
SL CIL-31-01 Airframe SB - Open #661	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION						
SL CIL-32-01 Airframe SB - Open #616	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL						
SL CIL-32-03 Airframe SB - Complied With #688	NLG UPLOCK ROLLER BRACKET INSPECTION	16-FEB-2018 H: 8500.00 L: 6240					
	Notes COMPLIED WITH - NLG UPLOCK BRACKET INSPECTED PER SL CIL-32-03. NO FAULTS FOUND AT THIS TIME. REF BAS 10766-4						
SL CIL-32-04 Airframe SB - Open #538	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION						
SL CIL-32-06 Airframe SB - Open #612	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL CIL-33-01 Airframe SB - Open #751	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY						
SL CIL-34-01 Airframe SB - Open #687	NAVIGATION - TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.( )-34-3508						
SL CIL-34-03 Airframe SB - Open #584	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R01)						
SL CIL-34-03 R1 Airframe SB - Open #699	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGHVOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R02)						
SL CIL-34-03 R2 Airframe SB - Open #552	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY						
SL CIL-35-05 Airframe SB - Complied With #628	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 Notes COMPLIED WITH - OXYGEN MASKS INSPECTED. FOUND PN: MC10-16-101, SNS: 118532 AND 100269. WHEN COMPARED TO APPENDIX I OF MCF-SBU-35-001 IT SHOWS THIS SERVICE BULLETIN TO BE NA. MASKS MARKED IAW PART B(1) OF MCF-SBU-35-001. NO RECURRENT INSPECTION REQUIRED AT THIS TIME.	11-MAY-2016 H: 8332.50 L: 6132					
SL CIL-99-01 Airframe SB - Open #802	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R01)						
SL CIL-99-01 R03 Airframe SB - Open #850	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS						
SL CIL-99-01 R1 Airframe SB - Open #701	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R02)						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL CIL-99-01 R2 Airframe SB - Open #531	USE OF CORROSION INHIBITING COMPOUNDS						
SL CIL-99-02 Airframe SB - Open #623	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS						
SL CIL-99-02 R01 Airframe SB - Open #841	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS						
SL CIL-99-03 Airframe SB - Open #791	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)						
SL CIL-99-03 R02 Airframe SB - Open #865	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)						
SL CIL-99-03 R1 Airframe SB - Open #766	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)						
SL CIL-99-04 Airframe SB - Open #603	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW						
SL CIL-99-04 R01 Airframe SB - Open #859	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW						
AD 1974-08-09 R2 Airframe AD - Complied With FAA #797	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3) Notes COMPLIED WITH - AIRCRAFT INSPECTED FOR APPROPRIATE MARKINGS. FOUND THEM TO STILL BE INSTALLED, CLEAR AND LEGIBLE AT THIS TIME ON BOTH FORE AND AFT WASTE BINS.	11-MAY-2016 H: 8332.50 L: 6132					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1974-08-09 R3 Airframe AD - Complied With FAA #640	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	08-JUL-2016 H: 8348.70 L: 6140	H: 1000.00			H: 9348.70	H: 408.40
	Notes COMPLIED WITH						
AD 1974-08-09- R2 Airframe AD - Complied With #414	LAV SMOKING PLACARD	20-APR-2006 H: 5553.00					
AD 1979-12-06 Airframe AD - N/A FAA #843	UPPER & LOWER SPAR CAP STEMS						
	Notes NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER						
AD 1980-09-09 Airframe AD - N/A FAA #831	DUAL FLIGHT DIRECTOR INSTALLATION						
	Notes NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER						
AD 1988-06-02 Airframe AD - N/A FAA #838	ELECTRICAL POWER						
	Notes NOT APPLICABLE - BY SERIAL NUMBER						
AD 1989-16-10 Airframe AD - N/A FAA #822	FUEL FLOW TRANSMITTER						
	Notes NOT APPLICABLE - BY SERIAL NUMBER						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1990-07-10 R1 Airframe AD - N/A FAA #615	AIR CONDITIONING SYSTEM						
	Notes NOT APPLICABLE - APPLICABILITY: MODEL 550, 551, AND S550 SERIES AIRPLANES, EQUIPPED WITH STC SA2698SW FREON AIR CONDITIONERS INSTALLED IN THE AFT SECTION OF THE BAGGAGE COMPARTMENT, CERTIFICATED IN ANY CATEGORY.						
AD 1993-05-15 Airframe AD - N/A FAA #526	THRUST REVERSER THROTTLE LOAD LIMITER						
	Notes NOT APPLICABLE - BY SERIAL NUMBER						
AD 1995-22-01 Airframe AD - N/A FAA #675	APPLIANCE AD - AEROSPACE LIGHTING POWER UNIT						
	Notes NOT APPLICABLE - PARTS NOT INSTALLED						
AD 1995-25-10 Airframe AD - N/A FAA #516	OUTFLOW/SAFETY VALVE						
	Notes NOT APPLICABLE - PARTS NOT INSTALLED						
AD 1997-05-03 R1 Airframe AD - Complied With FAA #780	APPLIANCE AD - ALLIEDSIGNAL GNS-XLS & GNS-XL	18-JUN-1997					
	Notes COMPLIED WITH						
AD 1998-04-38 Airframe AD - Complied With FAA #589	AFM-LIMITATIONS SECTION-ICING	29-JUN-1998					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1998-17-10 Engine 1 AD - Complied With FAA #142	TO PREVENT INFLIGHT ENGINE SHUTDOWN DUE TO RUBBING OF THE SECOND STAGE STATOR VANES ON THE COMPRESSOR ROTOR	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD 1998-17-10 Engine 2 AD - Complied With FAA #74	TO PREVENT INFLIGHT ENGINE SHUTDOWN DUE TO RUBBING OF THE SECOND STAGE STATOR VANES ON THE COMPRESSOR ROTOR	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD 1998-25-02 Airframe AD - N/A FAA #763	APPLIANCE AD - BFGOODRICH SKYWATCH SKY497	25-JUL-2000 H: 917.00					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
AD 1998-25-10 Airframe AD - Complied With FAA #562	APPLIANCE AD - AIRCRAFT BELTS, INC.	05-FEB-1999 H: 445.00					
	Notes COMPLIED WITH						
AD 1999-08-21 Airframe AD - Complied With FAA #814	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM C	25-JUL-2000					
	Notes COMPLIED WITH						
AD 2001-22-14 Airframe AD - N/A FAA #827	APPLIANCE AD - OVERLAND AVIATION SERVICES						
	Notes NOT APPLICABLE - BY COMPONENT PART NUMBER						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2001-23-17 Airframe AD - N/A FAA #697	APPLIANCE AD - GARMIN INTERNATIONAL GNS 430 Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	07-MAR-2002					
AD 2003-03-21 Engine 1 AD - Complied With FAA #68	ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
AD 2003-03-21 Engine 2 AD - Complied With FAA #126	ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
AD 2003-04-06 Airframe AD - N/A FAA #852	2003-04-06 APPLIANCE AD - HNYWELL PRIMUS RNZ-850/851 NM Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED						
AD 2003-13-08 Airframe AD - N/A FAA #693	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	18-JUL-2003 H: 3105.00					
AD 2003-26-14 Airframe AD - N/A FAA #728	APPLIANCE AD - KIDDE AEROSPACE HAND HELD BOTTLE Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	27-APR-2004 H: 3800.90 L: 2808					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2004-08-15 Airframe AD - N/A FAA #707	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	21-APR-2004					
AD 2004-09-05 Airframe AD - N/A FAA #847	BRAKE STATOR DISKS Notes NOT APPLICABLE - BY SERIAL NUMBER						
AD 2006-04-10 Airframe AD - Complied With FAA #749	INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS. Notes COMPLIED WITH	22-MAR-2006 H: 5469.00					
AD 2006-06-03 Airframe AD - Complied With FAA #604	WING FUEL BOOST PUMP WIRING Notes COMPLIED WITH	24-MAR-2006					
AD 2006-16-18 AMD PARA(H) Airframe AD - N/A FAA #581	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	06-OCT-2006					
AD 2006-16-18 Airframe AD - N/A FAA #744	APPLIANCE AD - SANDEL ST3400 TAWS/RMI PLACARD Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	12-FEB-2009 H: 7371.17 L: 5525					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2006-16-18 AMD PARA(F) Airframe AD - N/A FAA #678	INSTALL SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI) PLACARD Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	06-OCT-2006					
AD 2006-16-18 AMD PARA(G) Airframe AD - N/A FAA #635	REVISE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI) AIRPLANE FLIGHT MANUAL (AFM) Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	06-OCT-2006					
AD 2006-16-18 AMD PARA(H) Airframe AD - N/A FAA #705	UPDATE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI) SOFTWARE Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	06-OCT-2006					
AD 2006-19-04 Airframe AD - N/A FAA #658	APPLIANCE AD - HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED	06-OCT-2006					
AD 2006-19-04 AMD PARA(G) Airframe AD - N/A FAA #761	REPLACE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS IDENTIFICATION PLATE Notes NOT APPLICABLE	06-OCT-2006					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2006-19-04 AMD PARA(F) Airframe AD - N/A FAA #530	REVISE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS AIRPLANE FLIGHT MANUAL (AFM) Notes NOT APPLICABLE	06-OCT-2006					
AD 2007-11-17 Airframe AD - Complied With FAA #571	IDENTIFY WIRES FOR ENGINE/APU FIRE EXTINGUISHING BOTTLES Notes COMPLIED WITH - PREVIOUSLY PER AD 2006-04-10	21-JUN-2007					
AD 2009-21-10 Airframe AD - N/A FAA #585	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE Notes NOT APPLICABLE - BY PART NUMBER	11-MAR-2010 H: 7495.53 L: 5625					
AD 2009-21-10 R1 Airframe AD - N/A FAA #726	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE Notes NOT APPLICABLE - BY PART NUMBER	11-MAR-2010 H: 7495.53 L: 5625					
AD 2010-04-16 Airframe AD - N/A FAA #593	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI Notes NOT APPLICABLE - BY PART NUMBER EQUIPMENT NOT INSTALLED	23-FEB-2010 H: 7495.53 L: 5625					
AD 2010-04-16 AMD PARA (G) Airframe AD - N/A FAA #618	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT Notes NOT APPLICABLE - BY PART NUMBER EQUIPMENT NOT INSTALLED	23-FEB-2010 H: 7495.53 L: 5625					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-04-16 AMD PARA (H) Airframe AD - N/A FAA #515	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER Notes NOT APPLICABLE - BY PART NUMBER EQUIPMENT NOT INSTALLED	23-FEB-2010 H: 7495.53 L: 5625					
AD 2010-11-05 Airframe AD - Open FAA #820	APPLIANCE AD - INSPECT FOR AND REMOVE SUBSTANDARD OXYGEN CYLINDERS FROM AIRPLANE						
AD 2010-18-09 AMD PARA (E)(3) Engine 1 AD - Complied With FAA #62	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
AD 2010-18-09 AMD PARA (E)(3) Engine 2 AD - Complied With FAA #68	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					
AD 2010-18-09 AMD PARA (E)(2) Engine 1 AD - Complied With FAA #137	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
AD 2010-18-09 AMD PARA (E)(2) Engine 2 AD - Complied With FAA #62	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-18-09 Engine 1 AD - Complied With FAA #135	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD 2010-18-09 Engine 2 AD - Complied With FAA #98	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD 2012-02-08 Airframe AD - N/A FAA #754	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	20-FEB-2015 H: 8184.40 L: 6049					
	Notes NOT APPLICABLE - AD REVIEWED AND FOUND TO BE N/A AT THIS TIME DUE TO INSTALLED EQUIPMENT NOT BEING LISTED IN THE TABLE OF APPLICABILITY. INSTALLED SYSTEM IS A HONEYWELL UNIT AND CURRENTLY NOT SUBJECT TO THE CONDITIONS OF FAA AD 2012-02-08. NO FURTHER ACTIONS REQUIRED AT THIS TIME.						
AD 2013-0020 R4 AMD PARA (4) Airframe AD - N/A EASA #669	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD	30-JUL-2014 H: 8121.50 L: 6009					
	Notes NOT APPLICABLE - AD IS NA DUE TO APPLICABILITY LISTED IN THE AD DOCUMENT ITSELF. FURTHERMORE, BEING A EUROPEAN AD, IT HAS NO BEARING ON A CANADIAN OPERATED, AMERICAN BUILT AIRCRAFT IAW THE CARS AND FARS RESPECTIVELY. REMOVE FROM TRACKING.						
AD 2013-0020 R4 Airframe AD - N/A EASA #560	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT	30-JUL-2014 H: 8121.50 L: 6009					
	Notes NOT APPLICABLE - AD IS NA DUE TO APPLICABILITY LISTED IN THE AD DOCUMENT ITSELF. FURTHERMORE, BEING A EUROPEAN AD, IT HAS NO BEARING ON A CANADIAN OPERATED, AMERICAN BUILT AIRCRAFT IAW THE CARS AND FARS RESPECTIVELY. REMOVE FROM TRACKING						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2013-0020 R4 AMD PARA (1) Airframe AD - N/A EASA #632	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER	30-JUL-2014 H: 8121.50 L: 6009					
	Notes NOT APPLICABLE - AD IS NA DUE TO APPLICABILITY LISTED IN THE AD DOCUMENT ITSELF. FURTHERMORE, BEING A EUROPEAN AD, IT HAS NO BEARING ON A CANADIAN OPERATED, AMERICAN BUILT AIRCRAFT IAW THE CARS AND FARS RESPECTIVELY. REMOVE FROM TRACKING.						
AD 2013-0020 R4 AMD PARA (3) Airframe AD - N/A EASA #596	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE	30-JUL-2014 H: 8121.50 L: 6009					
	Notes NOT APPLICABLE - AD IS NA DUE TO APPLICABILITY LISTED IN THE AD DOCUMENT ITSELF. FURTHERMORE, BEING A EUROPEAN AD, IT HAS NO BEARING ON A CANADIAN OPERATED, AMERICAN BUILT AIRCRAFT IAW THE CARS AND FARS RESPECTIVELY. REMOVE FROM TRACKING.						
AD 2013-0020 R4 AMD PARA (2) Airframe AD - N/A EASA #737	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD	30-JUL-2014 H: 8121.50 L: 6009					
	Notes NOT APPLICABLE - AD IS NA DUE TO APPLICABILITY LISTED IN THE AD DOCUMENT ITSELF. FURTHERMORE, BEING A EUROPEAN AD, IT HAS NO BEARING ON A CANADIAN OPERATED, AMERICAN BUILT AIRCRAFT IAW THE CARS AND FARS RESPECTIVELY. REMOVE FROM TRACKING.						
AD 2013-09-11 Airframe AD - Complied With FAA #638	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	16-AUG-2013 H: 7979.80 L: 5914					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2013-09-11 AMD PARA (K) Air Conditioner 1 AD - Complied With FAA #8	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	16-AUG-2013 H: 7979.80 L: 5914					
	Notes COMPLIED WITH - FREON AIR CONDITIONING ASSEMBLY REMOVED AND SENT TO CANADIAN AERO ACCESSORIES FOR INSPECTION/REPAIR AND REPLACEMENT OF THE MOTOR BRUSHES. MOTOR SN: 3758 RETURNED AFTERREPAIR/BRUSH REPLACEMENT AND INSTALLED IN AIRCRAFT. SYSTEM NOT CHARGED AT THIS TIME						
AD 2013-09-11 AMD PARA (H) Airframe AD - Complied With FAA #789	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A\C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	16-AUG-2013 H: 7979.80 L: 5914					
	Notes COMPLIED WITH						
AD 2013-09-11 AMD PARA (G) Airframe AD - Complied With FAA #775	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	16-AUG-2013 H: 7979.80 L: 5914					
	Notes COMPLIED WITH - FREON AIR CONDITIONING ASSEMBLY REMOVED AND SENT TO CANADIAN AERO ACCESSORIES FOR INSPECTION/REPAIR AND REPLACEMENT OF THE MOTOR BRUSHES. MOTOR SN: 3758 RETURNED AFTER REPAIR/BRUSH REPLACEMENT AND INSTALLED IN AIRCRAFT. SYSTEM NOT CHARGED AT THIS TIME.						
AD 2013-09-11 AMD PARA (M) Airframe AD - Complied With FAA #546	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	28-AUG-2013 H: 7992.60 L: 5920					
	Notes COMPLIED WITH - PARTS RETURNED BY CANADIAN AERO ACCESSORIES AS PART OF THE BRUSH REPLACEMENT PROCEDURE.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2013-09-11 AMD PARA (L) Airframe AD - Complied With FAA #760	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM Notes COMPLIED WITH - AIR CONDITIONING SYSTEM CHARGED IN ACCORDANCE WITH AMM 12-19-02. SYSTEM FUNCTION TESTED SERVICEABLE AFTER SERVICING. NO LEAKS NOTED. PLACARDS REMOVED FROM COCKPIT AND CIRCUIT BREAKER RESET AFTER COLLAR REMOVAL.	28-AUG-2013 H: 7992.60 L: 5920					
AD 2013-09-11 AMD PARA (I) & (J) Air Conditioner 1 AD - Complied With FAA #7	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION Notes COMPLIED WITH	16-AUG-2013 H: 1362.00	H: 500.00			H: 1862.00	H: 360.00
AD 2014-0142 AMD PARA (1) Airframe AD - Open EASA #858	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445952 WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS						
AD 2014-0142 AMD PARA (2) Airframe AD - Open EASA #839	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD						
AD 2014-0142 AMD PARA (3) Airframe AD - Open EASA #824	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD.						
AD 2014-0142 Airframe AD - Open EASA #851	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-0142 R1 AMD PARA (1) Airframe AD - Complied With EASA #662	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS Notes COMPLIED WITH - MASKS INSPECTED AND FOUND TO BE N/A AT THIS TIME. DATE OF MANUFACTURE IS PRIOR TO THE AFFECTED DATE, BUT THE PNS AND SNS ARE NOT LISTED IN THE CURRENT REVISION OF THE AD. NO FURTHER ACTIONS ARE REQUIRED AT THIS TIME.	11-MAY-2016 H: 8332.50 L: 6132					
AD 2014-0142 R1 AMD PARA (2) Airframe AD - Open EASA #834	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD						
AD 2014-0142 R1 AMD PARA (3) Airframe AD - Open EASA #837	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUI						
AD 2014-0142 R1 Airframe AD - Open EASA #864	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT						
AD 2014-0187 Airframe AD - Open EASA #848	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / REPLACEMENT						
AD 2014-0187 AMD PARA (4) Airframe AD - Open EASA #819	AS AN ALTERNATIVE TO THE CORRECTIVE ACTIONS AS REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, BEFORE NEXT FLIGHT, BLOCK EACH AFFECTED SEAT FOR OCCUPANCY, PENDING ACCOMPLISHMENT OF THE APPLICABLE CORRECTIVE ACTION(S).						
AD 2014-0187 AMD PARA (3) Airframe AD - Open EASA #849	FOR SPECIFIC D1-03 SEAT ASSEMBLIES (P/N AS IDENTIFIED IN TABLE 1.1.1 OF GEVEN SB NO. D103-25-004 REVISION 2, EFF CODE FROM AAA TO AUC), WITHIN 6 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY THE SEAT BELT ATTACHMENT ASSEMBLY ON THE AISLE SIDE SPREADER OF STANDARD AND LAST ROW SEATS IN ACCORDANCE WITH THE INSTRUCTIONS OF GEVEN SB NO. D103-25-004 REVISION 2						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-0187 AMD PARA (2) Airframe AD - Open EASA #817	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DETACHED OR LOOSENED SAFETY BELT ATTACHMENT BOLTS ARE FOUND, BEFORE NEXT FLIGHT, RE-TORQUE THE AFFECTED BOLTS TO THE VALUE AS DEFINED IN, AND IN ACCORDANCE WITH THE INSTRUCTIONS OF, GEVEN SB NO. D103-25-004 REVISION 2						
AD 2014-0187 AMD PARA (1) Airframe AD - Open EASA #816	INSPECT THE SAFETY BELT ATTACHMENT BOLTS						
AD 2014-18-01 Airframe AD - Open FAA #821	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION						
AD 2015-0093 AMD PARA (1) Airframe AD - Open EASA #832	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)						
AD 2015-0093 Airframe AD - Open EASA #856	APPLIANCE AD - NAVIGATION - ATTITUDE HEADING REFERENCE SYSTEM - MODIFICATION / REPLACEMENT						
AD 2015-0093 AMD PARA (3) Airframe AD - Open EASA #846	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT						
AD 2015-0093 AMD PARA (4) Airframe AD - Open EASA #836	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRS UNIT, HAVING A P/N SPECIFIED AS ‘OLD’ IN TABLE 1 OF THIS AD						
AD 2015-0093 AMD PARA (2) Airframe AD - Open EASA #829	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS ‘OLD’ IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS ‘NEW’ IN TABLE 2 OF THIS AD						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-10-51 Airframe AD - Open FAA #855	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS						
AD 2015-10-51 AMD E Airframe AD - Open FAA #861	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.						
AD 2015-17-12 Airframe AD - N/A FAA #680	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA Notes NOT APPLICABLE - AIRCRAFT RECORDS INSPECTED AND FOUND THE REQUIREMENTS OF AD 2015-17-12 TO BE PREVIOUSLY COMPLIED WITH BY MEANS OF COMPLIANCE WITH AD 2013-09-11. UPON REVIEW OF THE WORK COMPLETED 28 AUG 2013 IT WAS FOUND THAT ALL THE REQUIREMENTS OF 2015-17-12 ALIGNED WITH THE PREVIOUS AD.	28-AUG-2015 H: 8251.30 L: 6090					
AD 2015-17-12 AMD PARA (K) Airframe AD - Open FAA #830	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)						
AD 2015-17-12 AMD PARA (H) Airframe AD - N/A FAA #527	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND) Notes NOT APPLICABLE - AIRCRAFT RECORDS INSPECTED AND FOUND THE REQUIREMENTS OF AD 2015-17-12 TO BE PREVIOUSLY COMPLIED WITH BY MEANS OF COMPLIANCE WITH AD 2013-09-11. UPON REVIEW OF THE WORK COMPLETED 28 AUG 2013 IT WAS FOUND THAT ALL THE REQUIREMENTS OF 2015-17-12 ALIGNED WITH THE PREVIOUS AD.	28-AUG-2015 H: 8251.30 L: 6090					
AD 2015-17-12 AMD PARA (L) Airframe AD - Open FAA #823	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-17-12 AMD PARA (G) Airframe AD - N/A FAA #551	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	28-AUG-2015 H: 8251.30 L: 6090					
	Notes NOT APPLICABLE - AIRCRAFT RECORDS INSPECTED AND FOUND THE REQUIREMENTS OF AD 2015-17-12 TO BE PREVIOUSLY COMPLIED WITH BY MEANS OF COMPLIANCE WITH AD 2013-09-11. UPON REVIEW OF THE WORK COMPLETED 28 AUG 2013 IT WAS FOUND THAT ALL THE REQUIREMENTS OF 2015-17-12 ALIGNED WITH THE PREVIOUS AD.						
AD 2015-17-12 AMD PARA (I) Air Conditioner 1 AD - N/A FAA #6	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	28-AUG-2015 H: 1362.00					
	Notes NOT APPLICABLE - N/A AT THIS TIME.						
AD 2015-17-12 AMD PARA (M) Airframe AD - Open FAA #835	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY						
AD 2016-0024 Airframe AD - Open EASA #825	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT						
AD 2016-0024 AMD PARA (3) Airframe AD - Open EASA #862	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'						
AD 2016-0024 AMD PARA (1) Airframe AD - Open EASA #818	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-0024 AMD PARA (2.1) Airframe AD - Open EASA #853	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2						
AD 2016-0024 AMD PARA (2.2) Airframe AD - Open EASA #845	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3						
AD 2016-0024 AMD PARA (2.3) Airframe AD - Open EASA #828	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1						
AD 2016-0044 AMD PARA (2) Airframe AD - Open EASA #857	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1). Part Number 362						
AD 2016-0044 Airframe AD - Open EASA #844	APPLIANCE AD - ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL						
AD 2016-0044 AMD PARA (3) Airframe AD - Open EASA #833	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REV Part Number 381						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-0044 AMD PARA (1) Airframe AD - Open EASA #863	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1 Part Number 291						
AD 2016-11-20 Engine 1 AD - N/A FAA #139	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12 Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED. AD IS N/A	15-SEP-2016 H: 8358.00 C: 6157					
AD 2016-11-20 AMD PARA (G) Airframe AD - N/A FAA #650	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12 Notes NOT APPLICABLE - AD IS NOT APPLICABLE TO THIS AIRCRAFT AT THIS TIME. NO SUCH EQUIPMENT INSTALLED.	15-SEP-2016 H: 8358.00 L: 6157					
AD 2016-11-20 AMD PARA (H.1) Engine 1 AD - N/A FAA #84	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12 Notes NOT APPLICABLE - AD IS NOT APPLICABLE TO THIS AIRCRAFT AT THIS TIME. NO SUCH EQUIPMENT INSTALLED.	15-SEP-2016 H: 8358.00 C: 6157					
AD 2016-11-20 AMD PARA (H.2) Engine 2 AD - N/A FAA #92	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12 Notes NOT APPLICABLE - AD IS NOT APPLICABLE TO THIS AIRCRAFT AT THIS TIME. NO SUCH EQUIPMENT INSTALLED.	15-SEP-2016 H: 8358.00 C: 6157					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-16-01 Airframe AD - N/A FAA #634	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	02-AUG-2018 H: 8577.20 L: 6283					
	Notes NOT APPLICABLE - FAA AD 2017-16-01 IS NOT APPLICABLE BY EQUIPMENT NOT INSTALLED. NO AMERIKING ELTS INSTALLED AT THIS TIME. REF BAS 10862-4						
AD 2017-16-01 AMD PARA (J) Airframe AD - N/A FAA #747	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	02-AUG-2018 H: 8577.20 L: 6283					
	Notes NOT APPLICABLE - FAA AD 2017-16-01 IS NOT APPLICABLE BY EQUIPMENT NOT INSTALLED. NO AMERIKING ELTS INSTALLED AT THIS TIME. REF BAS 10862-4						
AD 2017-16-01 AMD PARA (G) Airframe AD - N/A FAA #684	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	02-AUG-2018 H: 8577.20 L: 6283					
	Notes NOT APPLICABLE - FAA AD 2017-16-01 IS NOT APPLICABLE BY EQUIPMENT NOT INSTALLED. NO AMERIKING ELTS INSTALLED AT THIS TIME. REF BAS 10862-4						
AD 2017-18-12 Airframe AD - Open FAA #826	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003- 11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES						
AD 2017-18-12 AMD PARA (I) & (J) Engine 2 AD - N/A FAA #58	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004- 02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	09-MAR-2018 H: 8511.50 C: 6245					
	Notes NOT APPLICABLE - NO AFFECTED PBE INSTALLED IN THE AIRCRAFT AT THIS TIME. AD IS N/A BY EQUIPMENT INSTALLED. REF BAS 10798-2						
AD 2017-18-12 AMD PARA (G) Airframe AD - Open FAA #840	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-18-12 AMD PARA (H) Airframe AD - Open FAA #860	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED						
AD 2021-07-13 Airframe AD - Complied With FAA #842	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	23-JUL-2021 H: 8838.50 L: 6434					
AD 2021-07-13 AMD PARA (E)(3) Airframe AD - Complied With FAA #854	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	23-JUL-2021 H: 8838.50 L: 6434					
AD 2021-07-13 AMD PARA (E)(1) Airframe AD - Complied With FAA #519	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	23-JUL-2021 H: 8838.50 L: 6434					
AD 2021-07-13 AMD PARA (E)(2) Airframe AD - Complied With FAA #577	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	23-JUL-2021 H: 8838.50 L: 6434					
AD CF-1998-18 Engine 1 AD - Complied With None #101	PERFORM BORESCOPE INSPECTION OF GAP BETWEEN SECOND-STAGE HP COMPRESSOR ROTOR AND STATOR, MODIFY THE HP COMPRESSOR ROTOR ASSEMBLY Notes COMPLIED WITH	14-AUG-2019 H: 8669.40 C: 6334					
AD CF-1998-18 Engine 2 AD - Complied With None #115	PERFORM BORESCOPE INSPECTION OF GAP BETWEEN SECOND-STAGE HP COMPRESSOR ROTOR AND STATOR, MODIFY THE HP COMPRESSOR ROTOR ASSEMBLY Notes COMPLIED WITH	26-AUG-2019 H: 8669.40 C: 6334					

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2002-42 Engine 1 AD - Complied With None #86	PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A, AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD CF-2002-42 Engine 2 AD - Complied With None #151	PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A, AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD CF-2010-19 AMD STEP A,B,C,D,E,F,G Engine 1 AD - Complied With None #100	INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD CF-2010-19 AMD STEP A,B,C,D,E,F,G Engine 2 AD - Complied With None #124	INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD CF-2010-19 Engine 1 AD - Complied With None #110	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD CF-2010-19 Engine 2 AD - Complied With None #72	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Maintenance Items

C-GOKO

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2010-19 AMD STEP H. Engine 1 AD - Complied With None #114	TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A	14-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD CF-2010-19 AMD STEP H. Engine 2 AD - Complied With None #147	TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A	26-AUG-2019 H: 8669.40 C: 6334					
	Notes COMPLIED WITH						
AD CF-2013-25 Airframe AD - Complied With None #641	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING INSTALLATION DISCREPANCIES	20-DEC-2013 H: 8039.70 L: 5952					
	Notes COMPLIED WITH - COMMENTS: AIRCRAFT RECORDS INSPECTED TO THE DEGREE NECESSARY TO DETERMINE THAT THERE IS NO AFFECTED EQUIPMENT INSTALLED ON THE AIRCRAFT AT THIS TIME.						

Copyright © 2022 Flightdocs, Inc. All Rights Reserved