AVTRAK
Phone: +1-316-462-2432
Fax: 316-462-2442
Analyst: Mark Rieger

Maintenance Next Due Report

Report Created On: 20 Aug 2020

Sorted by: Due Date
No service information included
^ Due Flag Indicates Items Due Within Standard Projection

Textron Aviation Inc. BAE.125-800
N910CF

S/N: 258267
Regulation: PART 135
Airworthiness Date: 27 Apr 1995

Airframe & Component Times					Total Time	
Logbook	Position	Description	Serial No.	Log Date	Hours	Cycles
Airframe		TEXTRON AVIATION INC. BAE.125-800	258267	18 Aug 2020	10844:03	7176
Engine	1	HONEYWELL TFE731-5R-1H	P-91307	18 Aug 2020	12238:58	10147
Engine	2	HONEYWELL TFE731-5R-1H	P-91308	18 Aug 2020	12202:10	10109
APU		HAMILTON SUNDSTRAND CORPORATION T -62T-40C8D1	SP-E-935323	11 Aug 2020	5794:18	10460

Projected Through 18 Nov 2020	
Hours	Cycles
11044:03	7376
12438:58	10347
12402:10	10309
5994:18	10470

The Next Scheduled Hourly Item is due at 10815:59 Hrs (TOL ~(+ 71:56) Hrs Rem), Logbook: Airframe, ATA: 240001

The Next Scheduled Cycle Item is due at 7303 Cyc (127 Cyc Rem), Logbook: Airframe, ATA: 324121

The Next Scheduled Calendar Item is due at 14 Sep 2020 (25d Rem), Logbook: Airframe, ATA: 00200

ATA / Logbook	Description / Notes	Part Number / Serial Number	Source Document: Section / Revision	Source Document: Page / Date Issued	UOM	Complied With	Freq (**Initial)	Next Due (*=Adj)	Max Due	Remains (^=Due)	Projected Due Date
A031-200313	APU - Review Sb-T-62T-49-76 Rev 14		-		HRS						
					APUS						
APU			A031	A031	MOS					NEW REQMT	
	Notes:				MSC		-			NEW REQMT	
240001	Inspect/Check No. 2 Engine Starter/Generator	23080-064	AFMS-800		HRS	10614:17	300	10815:59	10915:59	TOL (+71:56) ^	17 Jul 2020
(240001.2)		P1328	OUT OF PHASE	3	AFL	7015					
Airframe	Notes: PN: 23080-005 SN: 515.		19	01-Mar-16	MOS	13 Apr 2019					
00200U	Reduced Vertical Separation Minimum (RVSM) Monitoring Requirements				HRS	10342:21					14 Sep 2020
(00200)					AFL	6866					
Airframe	Notes: PN: SCHEDULING REQUIRED SN: <NONE>. MFG REF NUMBER: N/A, DOC: , REV: , ISSUED: 09 MAR 2011, SECTION: NOTAM				MOS	14 Sep 2018	24	14 Sep 2020		25d^	

ATA / Logbook	Description / Notes	Part Number / Serial Number	Source Document: Section / Revision	Source Document: Page / Date Issued	UOM	Complied With	Freq (**Initial)	Next Due (*=Adj)	Max Due	Remains (^=Due)	Projected Due Date
262109 (262059) Airframe	Cockpit Portable FIRE Extinguisher (Life Limit) Notes:	C352TS Y-691656	CJE-HPA-C-GEN-AW1667 CHAPTER 26 10	3 01-Mar-12	HRS AFL MOS	7322 5181 16 Sep 2010	120	16 Sep 2020		27d^	16 Sep 2020
050001U Airframe	Monthly Check Notes:				HRS AFL MOS	10829:23 7164 11 Aug 2020	1	30 Sep 2020		41d	30 Sep 2020
262123U Airframe	Portable H2O FIRE Extinguisher - Inspection Notes:				HRS AFL MOS	10829:23 7164 11 Aug 2020	1	30 Sep 2020		41d	30 Sep 2020
262145-U1U (262145) Airframe	Periodic Inspection-Cockpit FIRE Extinguisher. Notes: PN: C352TS SN: Y-691656.				HRS AFL MOS	10829:23 7164 11 Aug 2020	1	30 Sep 2020		41d	30 Sep 2020
262150U (262150) Airframe	Periodic Inspection-Cabin FIRE Extinguisher Notes: PN: C352TS SN: Y-691655.				HRS AFL MOS	10829:23 7164 11 Aug 2020	1	30 Sep 2020		41d	30 Sep 2020
300007 (300007) Airframe	Purge Ice Protection System Notes:		AFMS-800 OUT OF PHASE 19	5 01-Mar-16	HRS AFL MOS	10829:23 7164 11 Aug 2020	1	30 Sep 2020		41d	30 Sep 2020
760130 Engine	No. 1 Engine - Download Ectm Notes: Engine changed on April 13, 2019 ACTT 10614:17 Landings 7015 by Standard Aero - Augusta CZI & MPI C/W on April 11, 2019. At install TSN 12009:12.		72-02-75 72-00-00 08	5 OF 13 25-Apr-07	HRS ENC MOS	12190:12 10112 10 Jul 2020	50	10162		15	04 Oct 2020

ATA / Logbook	Description / Notes	Part Number / Serial Number	Source Document: Section / Revision	Source Document: Page / Date Issued	UOM	Complied With	Freq (**Initial)	Next Due (*=Adj)	Max Due	Remains (^=Due)	Projected Due Date
760130 Engine	No. 2 Engine - Download Ectm Notes: Engine changed on April 13, 2019 ACTT 10614:17 Landings 7015 by Standard Aero - Augusta CZI & MPI C/W on April 11, 2019. At install TSN 11972:24.		72-02-75 72-00-00 08	5 OF 13 25-Apr-07	HRS ENC MOS	12153:24 10074 10 Jul 2020	50	10124		15	04 Oct 2020
210001 (210001) Airframe	Change Cooling Turbine Oil Notes: PN: 203880-3-1 SN: 58-880.		AFMS-800 OUT OF PHASE 19	2 01-Mar-16	HRS AFL MOS	10486:50 6948 28 Nov 2018	400	10886:50	10926:50	42:47 (+40)	10 Oct 2020
210022 (210022) Airframe	Inspect Cooling Turbine Notes:		AFMS-800 OUT OF PHASE 19	2 01-Mar-16	HRS AFL MOS	10486:50 6948 28 Nov 2018	400	10886:50	10926:50	42:47 (+40)	10 Oct 2020
057120 Engine	No. 1 Engine - 300 to 400 Hour Inspection Notes:		72-02-75 72-00-00 08	3 OF 3 25-Apr-07	HRS ENC MOS	12007:12 9985 11 Apr 2019	300	12307:12	12407:12	68:14 (+100)	10 Nov 2020
057120 Engine	No. 2 Engine - 300 to 400 Hour Inspection Notes:		72-02-75 72-00-00 08	3 OF 3 25-Apr-07	HRS ENC MOS	11970:24 9947 11 Apr 2019	300	12270:24	12370:24	68:14 (+100)	10 Nov 2020
057110 Engine	No. 1 Engine - 150 to 250 Hour Inspection Notes:		72-02-75 72-00-00 08	2 OF 3 25-Apr-07	HRS ENC MOS	12190:12 10112 10 Jul 2020	150	12340:12	12440:12	101:14 (+ 100)	19 Dec 2020
057110 Engine	No. 2 Engine - 150 to 250 Hour Inspection Notes:		72-02-75 72-00-00 08	2 OF 3 25-Apr-07	HRS ENC MOS	12153:24 10074 10 Jul 2020	150	12303:24	12403:24	101:14 (+ 100)	19 Dec 2020

ATA / Logbook	Description / Notes	Part Number / Serial Number	Source Document: Section / Revision	Source Document: Page / Date Issued	UOM	Complied With	Freq (**Initial)	Next Due (*=Adj)	Max Due	Remains (^=Due)	Projected Due Date
334016 (334005.1) Airframe	Test Left Wing Strobe Light Intensity Notes: PN: 31-2059-11 SN: 0613771096.	30-0538-7, -8 SN-UNKNOWN	AFMS-800 COMPONENT REQ. 19	7 01-Mar-16	HRS AFL MOS	10550:19 6981 16 Jan 2019	400	10950:19	11000:19	106:16 (+50)	26 Dec 2020
334017 (334005.2) Airframe	Test Right Wing Strobe Light Intensity Notes: PN: 31-2059-11 SN: <NONE>.	30-0538-7, -8 SN-UNKNOWN	AFMS-800 COMPONENT REQ. 19	7 01-Mar-16	HRS AFL MOS	10550:19 6981 16 Jan 2019	400	10950:19	11000:19	106:16 (+50)	26 Dec 2020
334047 (334005.3) Airframe	Test Tail Strobe Light Intensity Notes: PN: 30-0531-1, 30-516-1 SN: <NONE>.	30-0531-1, 30-516-1 SN-UNKNOWN	AFMS-800 COMPONENT REQ. 19	7 01-Mar-16	HRS AFL MOS	10550:19 6981 16 Jan 2019	400	10950:19	11000:19	106:16 (+50)	26 Dec 2020
490010 (492001) APU	APU - Accomplish 6 Month/125 Hour/250 Cycle Inspection Notes:		4511534 49-20-00 4	 15-Mar-06	HRS APUS MOS	5774:6 10421 10 Jul 2020	125 250 6	5899:06 10671 10 Jan 2021		104:48 211 4m 21d	10 Jan 2021
324121 (324105) Airframe	Brake Control Valve Left Outer Knife Edge (Life Limit) Notes:	ACO34630 SN-UNKNOWN	CJE-HPA-C-GEN-AW1667 CHAPTER 32 10	 10 01-Mar-12	HRS AFL MOS	3430 2803 09 Oct 2001	4500	7303		127	20 Jan 2021
324122 (324106) Airframe	Brake Control Valve Right Outer Knife Edge (Life Limit) Notes:	ACO34629 SN-UNKNOWN	CJE-HPA-C-GEN-AW1667 CHAPTER 32 10	 10 01-Mar-12	HRS AFL MOS	3430 2803 09 Oct 2001	4500	7303		127	20 Jan 2021
324123 (324107) Airframe	Brake Control Valve Inner Knife Edge (Life Limit) Notes:	ACO36133 SN-UNKNOWN	CJE-HPA-C-GEN-AW1667 CHAPTER 32 10	 10 01-Mar-12	HRS AFL MOS	3430 2803 09 Oct 2001	4500	7303		127	20 Jan 2021

ATA / Logbook	Description / Notes	Part Number / Serial Number	Source Document: Section / Revision	Source Document: Page / Date Issued	UOM	Complied With	Freq (**Initial)	Next Due (*=Adj)	Max Due	Remains (^=Due)	Projected Due Date
120001 (050050) Airframe	Lubricate AREA G-200 Hour Notes:		AFMS-800 200 HR 19	2 01-Mar-16	HRS AFL MOS	10795:17 7141 10 Jul 2020	200	10995:17	11035:17	151:14 (+40)	17 Feb 2021
781021 (783003) Airframe	Inspect No. 1 Engine Thrust Reverser (191-240) Notes:		TR5000 78-30-00 07	602 22-Oct-15	HRS AFL MOS	10795:17 7141 10 Jul 2020	200	10995:17	11035:17	151:14 (+40)	17 Feb 2021
781022 (783004) Airframe	Inspect No. 2 Engine Thrust Reverser (191-240) Notes:		TR5000 78-30-00 07	602 22-Oct-15	HRS AFL MOS	10795:17 7141 10 Jul 2020	200	10995:17	11035:17	151:14 (+40)	17 Feb 2021
050800 (050800) Airframe	Inspection 400 Hour Detailed Walk-Around Notes:		AFMS-800 400 HR 19	1-15 01-Mar-16	HRS AFL MOS	10614:17 7015 03 Jul 2019	400	11014:17	11054:17	170:14 (+40)	12 Mar 2021
120003 (050790) Airframe	Lubricate AREA F1-400 Hour Notes:		AFMS-800 400 HR 19	2 01-Mar-16	HRS AFL MOS	10614:17 7015 03 Jul 2019	400	11014:17	11054:17	170:14 (+40)	12 Mar 2021
120004 (050790) Airframe	Lubricate AREA T1-400 Hour Notes:		AFMS-800 LUBRICATION 19	2 01-Mar-16	HRS AFL MOS	10614:17 7015 03 Jul 2019	400	11014:17	11054:17	170:14 (+40)	12 Mar 2021
120007 (050790) Airframe	Lubricate AREA W1/W2-400 Hour Notes:		AFMS-800 400 HR 19	2 01-Mar-16	HRS AFL MOS	10614:17 7015 03 Jul 2019	400	11014:17	11054:17	170:14 (+40)	12 Mar 2021
240029 Airframe	Visual Inspection Panel Gg and Terminal Block M Notes:		AFMS-800 OUT OF PHASE 19	3 01-Mar-16	HRS AFL MOS	10614:17 7015 03 Jul 2019	400	11014:17	11054:17	170:14 (+40)	12 Mar 2021

ATA / Logbook	Description / Notes	Part Number / Serial Number	Source Document: Section / Revision	Source Document: Page / Date Issued	UOM	Complied With	Freq (**Initial)	Next Due (*=Adj)	Max Due	Remains (^=Due)	Projected Due Date
781070 (783007) Airframe	Inspect No. 1 Engine Thrust Reverser (391-440) Notes:		TR5000 78-30-00 07	602 22-Oct-15	HRS AFL MOS	10614:17 7015 03 Jul 2019	400	11014:17	11054:17	170:14 (+40)	12 Mar 2021
781071 (783008) Airframe	Inspect No. 2 Engine Thrust Reverser (391-440) Notes:		TR5000 78-30-00 07	602 22-Oct-15	HRS AFL MOS	10614:17 7015 03 Jul 2019	400	11014:17	11054:17	170:14 (+40)	12 Mar 2021
324223 (323020) Airframe	Left Outboard Maxaret (Overhaul) Notes:	AC65218 YP032	AFMS-800 COMPONENT REQ. 19	7 01-Mar-16	HRS AFL MOS	5664:30 4352 05 Apr 2007	3000	7352		176	20 Mar 2021
324224 (323023) Airframe	Right Outboard Maxaret (Overhaul) Notes:	AC65216 029BQ	AFMS-800 COMPONENT REQ. 19	7 01-Mar-16	HRS AFL MOS	5664:30 4352 05 Apr 2007	3000	7352		176	20 Mar 2021
324225 (323021) Airframe	Left Inboard Maxaret (Overhaul) Notes:	AC65216 YY067	AFMS-800 COMPONENT REQ. 19	7 01-Mar-16	HRS AFL MOS	5664:30 4352 05 Apr 2007	3000	7352		176	20 Mar 2021
324226 (323022) Airframe	Right Inboard Maxaret (Overhaul) Notes:	AC65218 NP318	AFMS-800 COMPONENT REQ. 19	7 01-Mar-16	HRS AFL MOS	5664:30 4352 05 Apr 2007	3000	7352		176	20 Mar 2021
FAA 1989-22-16 (89-22-16) Engine	No. 1 Engine - Deec Serial Number Check (Mandatory) Notes:				HRS ENC MOS MSC	 18 Apr 1990	 A/R				
FAA 1989-22-16 (89-22-16) Engine	No. 2 Engine - Deec Serial Number Check (Mandatory) Notes:				HRS ENC MOS MSC	 16 Aug 2000	 A/R				

ATA / Logbook	Description / Notes	Part Number / Serial Number	Source Document: Section / Revision	Source Document: Page / Date Issued	UOM	Complied With	Freq (**Initial)	Next Due (*=Adj)	Max Due	Remains (^=Due)	Projected Due Date
FAA 1990-24-06 (90-24-06) Engine	No. 1 Engine - Thermocouple Lead Assemblies (Mandatory) Notes:		1990-24-06 1990-24-06		HRS ENC MOS MSC	18 Apr 1990	A/R				
FAA 1990-24-06 (90-24-06) Engine	No. 2 Engine - Thermocouple Lead Assemblies (Mandatory) Notes:		1990-24-06 1990-24-06		HRS ENC MOS MSC	16 Aug 2000	A/R				
FAA 2010-06-11 (2010-06-11) Engine	No. 1 Engine - Removal of Second Stage Low-Pressure Compressor Rotor (Lpcr) Discs and/or Third Stage Lpcr Discs (Mandatory) Notes:		2010-06-11 2010-06-11		HRS ENC MOS MSC	10 Mar 2016	-				
FAA 2010-06-11 (2010-06-11) Engine	No. 2 Engine - Removal of Second Stage Low-Pressure Compressor Rotor (Lpcr) Discs and/or Third Stage Lpcr Discs (Mandatory) Notes:		2010-06-11 2010-06-11		HRS ENC MOS MSC	10 Mar 2016	-				
FAA 2016-07-02 (2016-07-02) Engine	No. 1 Engine - Removed and Replace the Affected Itt Duct With A Part Eligible for Installation (Mandatory) Notes:		2016-07-02		HRS ENC MOS MSC	25 Jun 2018	-				
FAA 2016-07-02 (2016-07-02) Engine	No. 2 Engine - Removed and Replace the Affected Itt Duct With A Part Eligible for Installation (Mandatory) Notes:		2016-07-02		HRS ENC MOS MSC	30 May 2018	-				