Due List

PHENOM 100 S/N 50000171 C-GSBJ

OWNER:	SIERRA BRAVO JULIETTE HOLDINGS LTD.	**OPERATOR:**	SIERRA BRAVO JULIETTE HOLDINGS LTD.	**OPERATOR:**	FLIGHTPATH CHARTER AIRWAYS
ADDRESS:	BOX 2369 PRINCE GEORGE BC V2N 2S6	**ADDRESS:**	2053 PRINCE GEORGE PULPMILL RD PRINCE GEORGE BC V2K 5P5	**ADDRESS:**	P. O. BOX 321 BRESLAU ONTARIO N0B 1M0
PHONE:		**PHONE:**		**PHONE:**	1-800-753-1051 EXT 164
FAX:		**FAX:**		**FAX:**	

ANALYST: ADRIAN SABOU +1-514-448-1151 (OFFICE) 800-787-9749 (EFAX-CARDS)

EMAIL: ASABOU@CAMPSYSTEMS.COM 514-636-2020 (OFFICE) 631-980-4222 (EFAX-CARDS)

WWW.CAMPSYSTEMS.COM

PROJECTED : 48 MOS. to 02-JUN-2025

AIRCRAFT **SERIAL/REGNO:** 50000171/C-GSBJ **MODEL:** PHENOM 100 **MANUFACTURER:** EMBRAER

DATES	LAST ACTUALS			PROJECTED
CERTIFICATION DATE: 18-JUN-2010 MANUFACTURER DATE: 18-JUN-2010	3731.5 A/C HRS	as of	16-APR-2021	4932.32
	3252 AFL	as of	16-APR-2021	4452

ENGINE NO. 1 **SERIAL/PART:** PCE-LC0340/35C3100-01 **MODEL:** PW617F-E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 15-DEC-2017		LAST ACTUALS			PROJECTED
3542.8 ENG. HRS	3555.9 A/C HRS	3718.4 ENG. HRS	as of	16-APR-2021	4919.22
3096 ENC		3241 ENC	as of	16-APR-2021	4441

ENGINE NO. 2 **SERIAL/PART:** PCE-LC0315/35C3100-01 **MODEL:** PW617F-E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 21-SEP-2017		LAST ACTUALS			PROJECTED
3670.8 ENG. HRS	3542.8 A/C HRS	3696.8 ENG. HRS	as of	16-APR-2021	4897.62
3198 ENC		3222 ENC	as of	16-APR-2021	4422

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
794000	**NO. 2 ENGINE - SAMPLE ENGINE IAW PWCOAT OIL SAMPLING PROCEDURE FOR PW617F**								
	REF:	MOS HRS/MSC ENC	200 +10		06-JUN-2018 3565.50 3119	**(3765.50) 3800.20**	3775.5	68.7 (+10)	24-AUG-2021
794000	**NO. 1 ENGINE - SAMPLE ENGINE IAW PWCOAT OIL SAMPLING PROCEDURE FOR PW617F**								
	REF:	MOS HRS/MSC ENC	200 +10		06-JUN-2018 3587.10 3138	**(3787.10) 3800.20**	3797.1	68.7 (+10)	24-AUG-2021
31-31-00-011	**PERFORM THE COCKPIT VOICE DATA RECORDER INTELLIGIBILITY TEST IAW AURORA JET PARTNERS PHENOM 100 CVDR INTELLIGIBILITY TEST PROCEDURE.**							MANDATORY	
	P/N: 2100-3083-50 S/N: 000608845 REF:	MOS HRS/MSC AFL	12 3000		28-SEP-2020 3707.40 3230	**28-SEP-2021** **6707.40**		118d 2975.9	28-SEP-2021
31-31-00-012	**DOWNLOAD CVR DATA FROM CVDR USING PORTABLE INTERFACE AND ROUTE THE DATA TO VENDOR FOR CVR INTELLIGIBILITY CHECK IAW CARS 625 APPENDIX C.**							MANDATORY	
	P/N: 2100-3083-50 S/N: 000608845 REF:	MOS HRS/MSC AFL	12 3000		28-SEP-2020 3707.40 3230	**28-SEP-2021** **6707.40**		118d 2975.9	28-SEP-2021
31-31-00-014	**DOWNLOAD FDR DATA FROM CVDR USING PORTABLE INTERFACE AND ROUTE DATA TO VENDOR FOR FDR CORRELATION CHECK IAW CARS 625 APPENDIX C.**							MANDATORY	
	P/N: 2100-3083-50 S/N: 000608845 REF:	MOS HRS/MSC AFL	12 3000		28-SEP-2020 3707.40 3230	**28-SEP-2021** **6707.40**		118d 2975.9	28-SEP-2021
31-31-00-013	**REVIEW CVDR COCKPIT VOICE DATA RECORDER INTELLIGIBILITY TEST REPORT**							MANDATORY	
	P/N: 2100-3083-50 S/N: 000608845 REF:	MOS HRS/MSC AFL	12 3000		13-OCT-2020 3708.70 3231	**13-OCT-2021** **6708.70**		133d 2977.2	13-OCT-2021
	WO: C-GSBJ-6522								

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
741006	**NO. 1 ENGINE - DISCARD SPARK IGNITER**									
		MOS			26-FEB-2016					27-JAN-2022
		HRS/MSC	600	+10%	3315.70	**(3915.70) 3928.80**	3975.7	197.3	(+60)	
	REF:	ENC			2898					
26-24-01-001	**WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER**									
	P/N: RT-A1200	MOS	12		08-FEB-2021	**08-FEB-2022**		251d		08-FEB-2022
	S/N: W-760259	HRS/MSC								
	REF: AMM 26-24-01	AFL								
05-30-04	**NO. 2 ENGINE - 600 FH / 12 MO ENGINE MAINTENANCE PACKAGE**									
		MOS	12	+30d	20-FEB-2021	**20-FEB-2022**	22-MAR-2022	263d	(+30)	20-FEB-2022
		HRS/MSC	600	+10%	3682.10	**(4282.10) 4316.80**	4342.1	585.3	(+60)	
	REF:	ENC			3208					
05-30-04	**NO. 1 ENGINE - 600 FH / 12 MO ENGINE MAINTENANCE PACKAGE**									
		MOS	12	+30d	20-FEB-2021	**20-FEB-2022**	22-MAR-2022	263d	(+30)	20-FEB-2022
		HRS/MSC	600	+10%	3703.70	**(4303.70) 4316.80**	4363.7	585.3	(+60)	
	REF:	ENC			3227					
05-30-89	**RVSM PACKAGE**							MANDATORY		
		MOS	24		20-FEB-2020	**20-FEB-2022**		263d		20-FEB-2022
		HRS/MSC			3705.50					
	REF:	AFL			3228					
24-36-01-005	**FUNCTIONAL CHECK OF NO.2 MAIN BATTERY - (POST-MOD SB 500-24-0014)**									
	P/N: 7639-30LT	MOS	12	+1m/-1m	20-FEB-2021	**20-FEB-2022**	20-MAR-2022	263d	(+28)	20-FEB-2022
	S/N: G03088657	HRS/MSC			3716.80					
	REF: AMM 24-36-01	AFL			3238					
24-36-01-005	**FUNCTIONAL CHECK OF NO.1 MAIN BATTERY - (POST-MOD SB 500-24-0014)**									
	P/N: 7639-30LT	MOS	12	+1m/-1m	20-FEB-2021	**20-FEB-2022**	20-MAR-2022	263d	(+28)	20-FEB-2022
	S/N: G03108589	HRS/MSC			3716.80					
	REF: AMM 24-36-01	AFL			3238					

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
25-61-00-001	**OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER SYSTEM**								
	P/N: S1821502-02 S/N: 2622117-0040 REF: AMM 25-61-00	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d	20-FEB-2022
25-61-00-002	**GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER**								
	P/N: S1821502-02 S/N: 2622117-0040 REF: AMM 25-61-00	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d	20-FEB-2022
25-61-00-003	**REMOVE EMERGENCY LOCATOR TRANSMITTER AND ROUTE THE ELT FOR ANNUAL PERFORMANCE TESTING I.A.W. STANDARD 571 APPENDIX G - MAINTENANCE OF EMERGENCY LOCATOR TRANSMITTERS (ELTS)**							MANDATORY	
	P/N: S1821502-02 S/N: 2622117-0040 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d	20-FEB-2022
25-61-00-004	**INSTALL EMERGENCY LOCATOR TRANSMITTER INTO THE AIRCRAFT AFTER COMPLETION OF THE ANNUAL PERFORMANCE TESTING.**							MANDATORY	
	P/N: S1821502-02 S/N: 2622117-0040 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d	20-FEB-2022
25-61-00-005	**INSPECT EXTERIOR ELT POSITION STICKER FOR CONDITION AND SECURITY**								
	P/N: S1821502-02 S/N: 2622117-0040 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d	20-FEB-2022
25-62-01-001	**CHECK FIRST AID KIT IAW AURORA JET PARTNERS "AIRCRAFT FIRST AID KIT INVENTORY CHECKLIST" FORM # MPL-MF-P117 IAW CAR 625 APPENDIX C**								
	P/N: PN S/N: SN-UNKNOWN REF: AMM 25-62-01	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d	20-FEB-2022
25-62-02-002C	**VISUAL INSPECT COPILOT CREW LIFE VEST**								
	P/N: 66601-505 S/N: L4899701 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d	20-FEB-2022

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
25-62-02-002C	**VISUAL INSPECT PILOT CREW LIFE VEST**									
	P/N: 66601-505 S/N: L4899700 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d		20-FEB-2022
25-62-02-002C	**VISUAL INSPECT NO.4 PAX LIFE VEST**									
	P/N: 66601-105 S/N: L4795582 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d		20-FEB-2022
25-62-02-002C	**VISUAL INSPECT NO.3 PAX LIFE VEST**									
	P/N: 66601-105 S/N: L4795581 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d		20-FEB-2022
25-62-02-002C	**VISUAL INSPECT NO.2 PAX LIFE VEST**									
	P/N: 66601-105 S/N: L4795614 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d		20-FEB-2022
25-62-02-002C	**VISUAL INSPECT NO.1 PAX LIFE VEST**									
	P/N: 66601-105 S/N: L4795613 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d		20-FEB-2022
34-23-00-001	**FUNCTIONAL CHECK MAGNETIC COMPASS IAW CARS 625 APPENDIX C (10)**							MANDATORY		
	P/N: KCA0120W S/N: BD1310409 REF:	MOS HRS/MSC AFL	12		20-FEB-2021 3716.80 3238	**20-FEB-2022**		263d		20-FEB-2022
73-10-05-220-801	**NO. 2 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER ELEMENT**									
	REF: LMM 73-10-05	MOS HRS/MSC ENC	12	+1m	20-FEB-2021 3682.10 3208	**20-FEB-2022**	20-MAR-2022	263d	(+28)	20-FEB-2022

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
73-10-05-220-801	**NO. 1 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER ELEMENT**									
		MOS	12	+1m	20-FEB-2021	**20-FEB-2022**	20-MAR-2022	263d	(+28)	20-FEB-2022
		HRS/MSC			3703.70					
	REF: LMM 73-10-05	ENC			3227					
741006	**NO. 2 ENGINE - DISCARD SPARK IGNITER**									
		MOS			26-FEB-2016					23-FEB-2022
		HRS/MSC	600	+10%	3315.70	**(3915.70) 3950.40**	3975.7	218.9	(+60)	
	REF:	ENC			2898					
31-31-03-001	**DISCARD CVDR/UNDERWATER LOCATOR BATTERY**							DISCARD		
	P/N: PN	MOS	72		29-APR-2016	**28-FEB-2022 M**		271d		28-FEB-2022
	S/N: SN-UNKNOWN	HRS/MSC			3391.50					
	REF:	AFL			2960					
720003	**NO. 2 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)**									
		MOS	144	+1m	01-MAR-2010	**01-MAR-2022**	01-APR-2022	272d	(+31)	01-MAR-2022
		HRS/MSC			0					
	REF: GENERIC NO REF	ENC			0					
32-43-11-001	**OPERATIONAL CHECK EMERGENCY/PARKING BRAKE SHUT OFF VALVE**							AIRWORTHINESS		
	P/N: 2216-0001-401	MOS	12	+30d/-30d	08-MAR-2021	**08-MAR-2022**	07-APR-2022	279d	(+30)	08-MAR-2022
	S/N: 00195	HRS/MSC	600	+30/-30	3716.80	**4316.80**	4346.8	585.3	(+30)	
	REF: AMM 32-43-11	AFL			3238					
720003	**NO. 1 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)**									
		MOS	144	+1m	11-MAR-2010	**11-MAR-2022**	11-APR-2022	282d	(+31)	11-MAR-2022
		HRS/MSC			0					
	REF: GENERIC NO REF	ENC			0					
35-11-00-001	**OPERATIONAL CHECK OF LH CREW OXYGEN MASK AND STOWAGE BOX**									
		MOS	24	+1m/-1m	03-APR-2019	**18-MAR-2022 M**	18-APR-2022	289d	(+31)	18-MAR-2022
		HRS/MSC			3681.80					
	REF: AMM 35-11-02	AFL			3209					

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
30-41-01-003	**FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE**									
		MOS	12	+1m/-1m	09-APR-2021	**30-MAR-2022**	30-APR-2022	301d	(+31)	30-MAR-2022
		HRS/MSC			3723.90					
	REF: AMM 30-41-01	AFL			3244					
35-00-00-001	**FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE**							AIRWORTHINESS		
		MOS	36	+30d/-30d	03-APR-2019	**03-APR-2022**	03-MAY-2022	305d	(+30)	03-APR-2022
		HRS/MSC	1800	+30/-30	3681.80	**5481.80**	5511.8	1750.3	(+30)	
	REF: AMM 35-00-00	AFL			3209					
35-21-00-001	**FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE**							AIRWORTHINESS		
		MOS	36	+30d/-30d	03-APR-2019	**03-APR-2022**	03-MAY-2022	305d	(+30)	03-APR-2022
		HRS/MSC	1800	+30/-30	3681.80	**5481.80**	5511.8	1750.3	(+30)	
	REF: AMM 35-21-00	AFL			3209					
35-21-00-002	**OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE**							AIRWORTHINESS		
		MOS	36	+30d/-30d	03-APR-2019	**03-APR-2022**	03-MAY-2022	305d	(+30)	03-APR-2022
		HRS/MSC	1800	+30/-30	3681.80	**5481.80**	5511.8	1750.3	(+30)	
	REF: AMM 35-21-00	AFL			3209					
77-20-02-710-801	**NO. 2 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM**									
		MOS	36	+30d	03-APR-2019	**03-APR-2022**	03-MAY-2022	305d	(+30)	03-APR-2022
		HRS/MSC	1750	+50	3668.70	**(5418.70) 5453.40**	5468.7	1721.9	(+50)	
	REF: LMM 77-20-02	ENC			3198					
77-20-02-710-801	**NO. 1 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM**									
		MOS	36	+30d	03-APR-2019	**03-APR-2022**	03-MAY-2022	305d	(+30)	03-APR-2022
		HRS/MSC	1750	+50	3668.70	**(5418.70) 5431.80**	5468.7	1700.3	(+50)	
	REF: LMM 77-20-02	ENC			3198					
05-30-82	**36 MO MAINTENANCE PACKAGE**									
		MOS	36	+1m/-1m	03-APR-2019	**04-APR-2022**	04-MAY-2022	306d	(+30)	04-APR-2022
		HRS/MSC			3681.80					
	REF: SMR 05-30-82	AFL			3209					

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL		TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
31-31-00-015	**REVIEW FDR FLIGHT DATA RECORDER CORRELATION GROUND AND FLIGHT FUNCTION TEST REPORT**								MANDATORY		
	P/N: 2100-3083-50 S/N: 000608845 REF:	MOS HRS/MSC AFL	12 3000			09-APR-2021 3723.90 3244	**09-APR-2022** **6723.90**		311d 2992.4		09-APR-2022
WO: C-GSBJ-6522											
31-31-03-002	**OPERATIONAL TEST CVDR ULB (ULD) UNDERWATER LOCATOR BEACON & CLEAN CVDR ULB (ULD) UNDERWATER LOCATOR BEACON WATER SWITCH**										
	P/N: 266-E0305-00 S/N: SD61158 REF:	MOS HRS/MSC AFL	12			09-APR-2021 3723.90 3244	**09-APR-2022**		311d		09-APR-2022
32-11-03-004	**SERVICING LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY**										
	P/N: 2310-4000-407 S/N: 00503 REF: AMM 12-14-02	MOS HRS/MSC AFL	12 650	+1m/-1m +30/-30		09-APR-2021 3723.90 3244	**09-APR-2022** **3894**	09-MAY-2022 3924	311d 642	(+30) (+30)	09-APR-2022
WO: 01											
32-11-03-004	**SERVICING RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY**										
	P/N: 2310-4000-407 S/N: 00512 REF: AMM 12-14-02	MOS HRS/MSC AFL	12 650	+1m/-1m +30/-30		09-APR-2021 3723.90 3244	**09-APR-2022** **3894**	09-MAY-2022 3924	311d 642	(+30) (+30)	09-APR-2022
WO: 01											
35-11-02-002	**RESTORATION (OVERHAUL) OF RH CREW OXYGEN MASK**										
	P/N: 174232-93 S/N: 27837 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+1m/-1m +30/-30		27-APR-2016 3416.40	**27-APR-2022** **7016.40**	27-MAY-2022 7046.4	329d 3284.9	(+30) (+30)	27-APR-2022
05-30-80	**12 MO MAINTENANCE PACKAGE**										
	REF: SMR 05-30-80	MOS HRS/MSC AFL	12	+1m/-1m		22-APR-2021 3731.50 3252	**28-APR-2022**	28-MAY-2022	330d	(+30)	28-APR-2022

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
05-30-81	**24 MO MAINTENANCE PACKAGE**									
	REF: SMR 05-30-81	MOS HRS/MSC AFL	24	+1m/-1m	28-APR-2020 3705.50 3228	**28-APR-2022**	28-MAY-2022	330d	(+30)	28-APR-2022
22-11-00-001	**FUNCTIONAL CHECK OF AILERON SERVO**							AIRWORTHINESS		
	P/N: 011-00878-10 S/N: 71307556 REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d	09-APR-2021 3723.90 3244	**28-APR-2022**	28-MAY-2022	330d	(+30)	28-APR-2022
22-11-00-001	**FUNCTIONAL CHECK OF RUDDER SERVO**							AIRWORTHINESS		
	P/N: 011-00878-10 S/N: 71307608 REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d	09-APR-2021 3723.90 3244	**28-APR-2022**	28-MAY-2022	330d	(+30)	28-APR-2022
22-11-00-001	**FUNCTIONAL CHECK OF ELEVATOR SERVO**							AIRWORTHINESS		
	P/N: 011-00878-10 S/N: 71307604 REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d	09-APR-2021 3723.90 3244	**28-APR-2022**	28-MAY-2022	330d	(+30)	28-APR-2022
32-11-00-003	**LUBRICATION OF LEFT MAIN GEAR ASSEMBLY**									
	P/N: PN S/N: SN-UNKNOWN REF: AMM 12-21-00	MOS HRS/MSC AFL	12 650	+1m/-1m +30/-30	09-APR-2021 3723.90 3244	**28-APR-2022** **3894**	28-MAY-2022 3924	330d 642	(+30) (+30)	28-APR-2022
WO: 01										
32-11-00-003	**LUBRICATION OF RIGHT MAIN GEAR ASSEMBLY**									
	P/N: PN S/N: SN-UNKNOWN REF: AMM 12-21-00	MOS HRS/MSC AFL	12 650	+1m/-1m +30/-30	09-APR-2021 3723.90 3244	**28-APR-2022** **3894**	28-MAY-2022 3924	330d 642	(+30) (+30)	28-APR-2022
WO: 01										
32-21-00-003	**LUBRICATION OF NOSE LANDING GEAR ASSEMBLY**									
	P/N: PN S/N: SN-UNKNOWN REF: AMM 12-21-00	MOS HRS/MSC AFL	12 650	+1m/-1m +30/-30	09-APR-2021 3723.90 3244	**28-APR-2022** **3894**	28-MAY-2022 3924	330d 642	(+30) (+30)	28-APR-2022
WO: 01										

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
32-21-05-004	**SERVICING NOSE LANDING GEAR (ALUM STRUT) SHOCK ABSORBER**									
	P/N: 2310-1100-403	MOS	12	+1m/-1m	09-APR-2021	**28-APR-2022**	28-MAY-2022	330d	(+30)	28-APR-2022
	S/N: 00194	HRS/MSC			3723.90					
	REF: AMM 12-14-03	AFL	650	+30/-30	3244	**3894**	3924	642	(+30)	
WO: 01										
34-15-00-003	**SPECIAL DETAILED INSPECTION OF STATIC PORT SURROUNDING PLATE FOR FLUSHNESS**									
		MOS	24	+1m/-1m	28-APR-2020	**28-APR-2022**	28-MAY-2022	330d	(+30)	28-APR-2022
		HRS/MSC			3705.50					
	REF: AMM 34-15-00	AFL			3228					
35-11-02-002	**RESTORATION (OVERHAUL) OF LH CREW OXYGEN MASK**									
	P/N: 174232-93	MOS	72	+1m/-1m	19-JUL-2016	**31-MAY-2022 M**	30-JUN-2022	363d	(+30)	31-MAY-2022
	S/N: 27023	HRS/MSC	3600	+30/-30	3416.40	**7016.40**	7046.4	3284.9	(+30)	
	REF: AMM 35-11-02	AFL								
05-30-83	**48 MO MAINTENANCE PACKAGE**									
		MOS	48	+1m/-1m	20-JUN-2018	**20-JUN-2022**	20-JUL-2022	383d	(+30)	20-JUN-2022
		HRS/MSC			3603.60					
	REF: SMR 05-30-83	AFL			3152					
+ **25-61-04-001**	**DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY**									
	P/N: PN	MOS			19-JUL-2016	**30-JUN-2022 M**		393d		30-JUN-2022
	S/N: SN-UNKNOWN	HRS/MSC	DUE		3416.40					
	REF: AMM 25-61-04	AFL			2979					
35-11-02-001	**DETAILED VISUAL INSPECTION OF LH CREW OXYGEN MASK**									
	P/N: 174232-93	MOS	24	+1m/-1m	12-JUL-2019	**18-JUL-2022 M**	18-AUG-2022	411d	(+31)	18-JUL-2022
	S/N: 27023	HRS/MSC			3700.30					
	REF: AMM 35-11-02	AFL			3225					
35-11-02-001	**DETAILED VISUAL INSPECTION OF RH CREW OXYGEN MASK**									
	P/N: 174232-93	MOS	24	+1m/-1m	12-JUL-2019	**19-JUL-2022 M**	19-AUG-2022	412d	(+31)	19-JUL-2022
	S/N: 27837	HRS/MSC			3700.30					
	REF: AMM 35-11-02	AFL			3225					

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
05-30-01	**800 FH MAINTENANCE PACKAGE**									
		MOS			27-FEB-2016					12-SEP-2022
		HRS/MSC	800	+30/-30	3315.70	**4115.70**	4145.7	384.2	(+30)	
	REF: SMR 05-30-01	AFL			2898					
050600	**NO. 1 ENGINE - 800 HOURS**									
		MOS			26-FEB-2016					28-SEP-2022
		HRS/MSC	800	+10%	3315.70	**(4115.70) 4128.80**	4195.7	397.3	(+80)	
	REF: LMM 05-20-00	ENC			2898					
050600	**NO. 2 ENGINE - 800 HOURS**									
		MOS			26-FEB-2016					24-OCT-2022
		HRS/MSC	800	+10%	3315.70	**(4115.70) 4150.40**	4195.7	418.9	(+80)	
	REF: LMM 05-20-00	ENC			2898					
24-36-01-003	**DISCARD NO.1 MAIN BATTERY**									
	P/N: 7639-30LT	MOS	24	+1m/-1m	20-FEB-2021	**20-FEB-2023**	20-MAR-2023	628d	(+28)	20-FEB-2023
	S/N: G03108589	HRS/MSC			3716.80					
	REF: AMM 24-36-01	AFL	600	+30/-30	3238	**3838**	3868	586	(+30)	
24-36-01-003	**DISCARD NO.2 MAIN BATTERY**									
	P/N: 7639-30LT	MOS	24	+1m/-1m	20-FEB-2021	**20-FEB-2023**	20-MAR-2023	628d	(+28)	20-FEB-2023
	S/N: G03088657	HRS/MSC			3716.80					
	REF: AMM 24-36-01	AFL	600	+30/-30	3238	**3838**	3868	586	(+30)	
35-02-01-003	**DISCARD 50 CU.FT OXYGEN CYLINDER**									
	P/N: 4441122-050	MOS	180		15-OCT-2008	**15-OCT-2023**		865d		15-OCT-2023
	S/N: 0172-999	HRS/MSC								
	REF: AMM 35-02-01	AFL								
28-12-01-001	**SPECIAL DETAILED INSPECTION OF FUEL VENT NACA**									
		MOS			28-APR-2020					30-DEC-2023
		HRS/MSC	800	+30/-30	3705.50	**4505.50**	4535.5	774	(+30)	
	REF: AMM 28-12-01	AFL			3228					
	WO: 01									

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
32-43-00-001	**FUNCTIONAL CHECK OF EMERGENCY/PARKING BRAKE SYSTEM**									
	REF: AMM 32-43-00	MOS HRS/MSC 800 AFL	+30/-30		20-FEB-2020 3705.50 3228	**4505.50**	4535.5	774	(+30)	30-DEC-2023
32-43-01-001	**GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM**									
	REF: AMM 32-43-00	MOS HRS/MSC 800 AFL	+30/-30		20-FEB-2020 3705.50 3228	**4505.50**	4535.5	774	(+30)	30-DEC-2023
35-02-01-001	**FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR**									
	P/N: 4441122-050 S/N: 0172-999 REF: AMM 35-02-01	MOS 60 HRS/MSC AFL			09-JUL-2019	**09-JUL-2024**		1133d		09-JUL-2024
32-45-11-001	**RESTORATION (OVERHAUL) OF NLG WHEEL ASSEMBLY**									
	P/N: 500-19001-601 S/N: JUN09-250 REF: See Workcard	MOS HRS/MSC T/C AFL 1500	+30/-30		24-OCT-2015 3190.40 2798	**4298**	4328	1046	(+30)	28-NOV-2024
72-00-00-290-815	**NO. 1 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY**									
	REF: LMM 72-00-00	MOS HRS/MSC 1750 ENC	+50		04-AUG-2015 3019.40 2663	**(4769.40) 4782.50**	4819.4	1051	(+50)	30-NOV-2024
26-11-01-002	**OPERATIONAL CHECK LH ENGINE FIRE DETECTOR**							AIRWORTHINESS		
	P/N: 3951-49-565/211C-3.7M S/N: 42721 REF: AMM 26-11-01	MOS HRS/MSC 1200 AFL	+30/-30		10-APR-2018 3574.90 3127	**4795.60**	4825.6	1064.1	(+30)	16-DEC-2024
26-11-01-002	**OPERATIONAL CHECK RH ENGINE FIRE DETECTOR**							AIRWORTHINESS		
	P/N: 3951-49-565/211C-3.7M S/N: 42734 REF: AMM 26-11-01	MOS HRS/MSC 1200 AFL	+30/-30		10-APR-2018 3574.90 3127	**4795.60**	4825.6	1064.1	(+30)	16-DEC-2024

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
28-21-07-001	**OPERATIONAL CHECK RIGHT WING 0.75 IN SHUTOFF VALVE**							AIRWORTHINESS	
	P/N: B97-15-601 S/N: E23678 REF: AMM 28-21-07	MOS HRS/MSC AFL	1200 +30/-30		10-APR-2018 3574.90 3127	**4795.60**	4825.6	1064.1 (+30)	16-DEC-2024
28-21-07-001	**OPERATIONAL CHECK LEFT WING 0.75 IN SHUTOFF VALVE**							AIRWORTHINESS	
	P/N: B97-15-601 S/N: E23677 REF: AMM 28-21-07	MOS HRS/MSC AFL	1200 +30/-30		10-APR-2018 3574.90 3127	**4795.60**	4825.6	1064.1 (+30)	16-DEC-2024
71-20-00-001	**DISCARD LEFT ENGINE UPPER FORWARD MOUNT ISOLATOR**								
	P/N: LM-474-SA11 S/N: LK0717 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 +1m/-1m 4800 +30/-30		18-JUN-2010 0 0	**18-JUN-2030** **4800**	18-JUL-2030 4830	3303d (+30) 1068.5 (+30)	22-DEC-2024
71-20-00-001	**DISCARD RIGHT ENGINE UPPER FORWARD MOUNT ISOLATOR**								
	P/N: LM-474-SA11 S/N: LK0721 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 +1m/-1m 4800 +30/-30		18-JUN-2010 0 0	**18-JUN-2030** **4800**	18-JUL-2030 4830	3303d (+30) 1068.5 (+30)	22-DEC-2024
71-20-00-001	**DISCARD LEFT ENGINE LOWER FORWARD MOUNT ISOLATOR**								
	P/N: LM-474-SA11 S/N: LK0728 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 +1m/-1m 4800 +30/-30		18-JUN-2010 0 0	**18-JUN-2030** **4800**	18-JUL-2030 4830	3303d (+30) 1068.5 (+30)	22-DEC-2024
71-20-00-001	**DISCARD RIGHT ENGINE LOWER FORWARD MOUNT ISOLATOR**								
	P/N: LM-474-SA11 S/N: LK0716 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 +1m/-1m 4800 +30/-30		18-JUN-2010 0 0	**18-JUN-2030** **4800**	18-JUL-2030 4830	3303d (+30) 1068.5 (+30)	22-DEC-2024
71-20-00-001	**DISCARD LEFT ENGINE AFT MOUNT ISOLATOR**								
	P/N: LM-474-SA2 S/N: LK0529 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 +1m/-1m 4800 +30/-30		18-JUN-2010 0 0	**18-JUN-2030** **4800**	18-JUL-2030 4830	3303d (+30) 1068.5 (+30)	22-DEC-2024

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING		EST. DUE
71-20-00-001	**DISCARD RIGHT ENGINE AFT MOUNT ISOLATOR**									
	P/N: LM-474-SA2	MOS	240	+1m/-1m	18-JUN-2010	**18-JUN-2030**	18-JUL-2030	3303d	(+30)	22-DEC-2024
	S/N: LK0548	HRS/MSC	4800	+30/-30	0	**4800**	4830	1068.5	(+30)	
	REF: AMM 71-20-00	AFL			0					
26-21-05-001	**OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)**							AIRWORTHINESS		
		MOS			21-MAR-2014					24-DEC-2024
		HRS/MSC	2400	+30/-30	2402	**4802**	4832	1070.5	(+30)	
	REF: AMM 26-21-05	AFL			2151					
72-00-00-290-815	**NO. 2 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY**									
		MOS			04-AUG-2015					27-DEC-2024
		HRS/MSC	1750	+50	3019.40	**(4769.40) 4804.10**	4819.4	1072.6	(+50)	
	REF: LMM 72-00-00	ENC			2663					
24-31-01-001	**RESTORATION (OVERHAUL) OF NO.1 ENGINE STARTER-GENERATOR (P/N MG94F-2 AND 400SG180Q)**									
	P/N: MG94F-2	MOS			27-JUL-2018					06-JAN-2025
	S/N: 0249	HRS/MSC	800	+30/-30	3612.30	**4812.30 M**	4842.3	1080.8	(+30)	
	REF: AMM 24-31-01	AFL			3160					
24-31-01-001	**RESTORATION (OVERHAUL) OF NO.2 ENGINE STARTER-GENERATOR (P/N MG94F-2 AND 400SG180Q)**									
	P/N: MG94F-2	MOS			27-JUL-2018					06-JAN-2025
	S/N: 0840	HRS/MSC	800	+30/-30	3612.30	**4812.30 M**	4842.3	1080.8	(+30)	
	REF: AMM 24-31-01	AFL			3160					
34-15-00-002	**SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS**									
		MOS	60	+1m/-1m	20-FEB-2020	**20-FEB-2025**	20-MAR-2025	1359d	(+28)	20-FEB-2025
		HRS/MSC			3705.50					
	REF: AMM 34-15-00	AFL			3228					
080001	**REWEIGH AIRCRAFT, AMMEND WEIGHT AND BALANCE, IAW CARS 625 APPENDIX C.**							MANDATORY		
		MOS	60		05-MAY-2020	**05-MAY-2025**		1433d		05-MAY-2025
		HRS/MSC			3705.50					
	REF:	AFL			3228					

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
*** - Estimated Due (applies to New Requirement)**

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
05-30-10	**1600 FH MAINTENANCE PACKAGE**								
		MOS			27-FEB-2016				11-MAY-2025
		HRS/MSC	1600 +30/-30		3315.70	**4915.70**	4945.7	1184.2 (+30)	
		AFL			2898				
	REF: SMR 05-30-10								

© CAMP SYSTEMS

Discrepancy Due List Report

MODEL: PHENOM 100 SERIAL: 50000171 RegNo: C-GSBJ

Report Date: 02-JUN-2021

DISCR # DATE LOGGED PART/SERIAL	CATEGORY	ATA	DESCRIPTION	UNIT	INTERVAL	LOGBOOK TIMES	LOGBOOK Ref.	NEXT DUE (x Ext)	TIME REMAINING	EST. DATE

NO DATA FOUND

Discrepancy Type:

(#) - RTS-UPDATE PENDING **(!) - RTS-UPDATE OVERDUE**

© CAMP SYSTEMS