



Master AD/SI Report

CITATION M2 S/N 525-1081 N916JL

OWNER: CHARLIE ROMEO LLC
ADDRESS: 1 CHENAL VILLAGE CIRCLE
LITTLE ROCK AR 72223
PHONE:
FAX:

OPERATOR: CHARLIE ROMEO LLC
ADDRESS: 1 CHENAL VILLAGE CIRCLE
LITTLE ROCK AR 72223
PHONE:
FAX:

OPERATOR: CENTRAL FLYING SERVICE, LLC
ADDRESS: 2301 CRISP DR.
LITTLE ROCK AR 72202
PHONE: 501-975-9585 TIM SNIPEs
FAX: 501-374-2150

ANALYST: KIM DUMCUM
EMAIL: KDUMCUM@CAMPSYSTEMS.COM

+1-316-462-2464 (DIRECT)
1-866-581-2267 (OFFICE)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

AIRCRAFT SERIAL/REGNO: 525-1081/N916JL **MODEL:** CITATION M2 **MANUFACTURER:** TEXTRON AVIATION INC.

| DATES | LAST ACTUALS | | CURRENT ACTUAL | |
|---------------------------------|---------------|-------------------|----------------|----------------------|
| CERTIFICATION DATE: 17-MAY-2021 | 444.8 A/C HRS | as of 31-AUG-2023 | _____ A/C HRS | as of ____/____/____ |
| | 369 AFL | as of 31-AUG-2023 | _____ AFL | as of ____/____/____ |
| | 294.4 ACH | as of 31-AUG-2023 | _____ ACH | as of ____/____/____ |

ENGINE NO. 1 SERIAL/PART: 290565/72100-201 **MODEL:** FJ44-1AP **MANUFACTURER:** WILLIAMS INTERNATIONAL

| INSTALLED ON 12-MAY-2021 | LAST ACTUALS | | CURRENT ACTUAL | |
|---------------------------|----------------|-------------------|----------------|----------------------|
| 0 ENG. HRS 0 A/C HRS | 444.8 ENG. HRS | as of 31-AUG-2023 | _____ ENG. HRS | as of ____/____/____ |
| 0 ENC | 369 ENC | as of 31-AUG-2023 | _____ ENC | as of ____/____/____ |

ENGINE NO. 2 SERIAL/PART: 290566/72100-201 **MODEL:** FJ44-1AP **MANUFACTURER:** WILLIAMS INTERNATIONAL

| INSTALLED ON 17-MAY-2021 | LAST ACTUALS | | CURRENT ACTUAL | |
|---------------------------|----------------|-------------------|----------------|----------------------|
| 0 ENG. HRS 0 A/C HRS | 444.8 ENG. HRS | as of 31-AUG-2023 | _____ ENG. HRS | as of ____/____/____ |
| 0 ENC | 369 ENC | as of 31-AUG-2023 | _____ ENC | as of ____/____/____ |

CESSNA AND CITATION ARE TRADEMARKS OF CESSNA AIRCRAFT CO. THE GOODS AND SERVICES OF CAMP SYSTEMS INTERNATIONAL, INC. ARE NOT SPONSORED, ENDORSED, SOLD OR PROMOTED BY CESSNA AIRCRAFT CO., AND CESSNA AIRCRAFT CO. MAKES NO REPRESENTATION REGARDING THE QUALITY OF THE GOODS OR SERVICES PROVIDED BY CAMP SYSTEMS INTERNATIONAL, INC.



Master AD/SI Report

CITATION M2 S/N 525-1081 (N916JL): 444.8HRS, 369 AFL as of 31-Aug-2023

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 03-Sep-2023

| Task No. | Description | Unit | Interval | Compliance | Next Due | Disposition | MOC |
|------------------------------------|--|-----------|----------|------------|-------------|-------------|---|
| APPLIANCE - 525-1081/N916JL | | | | | | | |
| FAA 2021-23-12 | APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS | | | | | MANDATORY | COMPLIED WITH - COMPLIED WITH AD 2021-23-12 AND DOCUMENTATION ADDED TO POH. |
| 09-DEC-2021 | | MOS | | | 13-MAY-2022 | | |
| | | HRS/MSC - | | | 242.5 | | |
| | | AFL | | | 213 | | |



Master AD/SI Report

CITATION M2 S/N 525-1081 (N916JL): 444.8HRS, 369 AFL as of 31-Aug-2023

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 03-Sep-2023

| Task No. | Description | Unit | Interval | Compliance | Next Due | Disposition | MOC |
|--|---|---------|----------|-------------|--------------------|-------------|--|
| AIRFRAME - SB - 525-1081/N916JL | | | | | | | |
| SB 525-26-04 | FIRE PROTECTION - FIRE LOOP WIRING IMPROVEMENT, SERVICE BULLETIN | | | | | MANDATORY | |
| | | MOS | 12 | (EFF) | 13-JUN-2024 | | |
| 20-JUL-2022 | | HRS/MSC | 300 | | 713.53 | | |
| | | AFL | | | | | |
| SL SL525-27-12 R01 | FLIGHT CONTROLS - TRIM ACTUATOR GREASE INSTALLATION, SERVICE LETTER | | | | | RECOMMENDED | NOT APPLICABLE - SL525-27-12 CW, N/A DUE TO DOCUMENT 8 INSPECTION BEING CW ON 10/21/2022, I/A/W CITATION SL525-27-12 REV 12, DATED 2/14/2023. |
| | | MOS | | 12-MAY-2023 | | | |
| 14-FEB-2023 | | HRS/MSC | - | 392.5 | | | |
| | | AFL | | 325 | | | |
| SL SL525-52-04 | DOORS - MAIN CABIN DOOR GROMMET INSTALLATION, SERVICE LETTER | | | | | RECOMMENDED | COMPLIED WITH - [5002] - C/W CESSNA 525 SL 525-52-04,DOORS - MAIN CABIN DOOR GROMMET INSTALLATION, INSTALLED NEW GROMMET P/N MS35489-41, I/A/W CESSNA 525 SL 525-52-04 |
| | | MOS | | 27-JUN-2023 | | | |
| 05-JUL-2022 | | HRS/MSC | - | 413.2 | | | |
| | | AFL | | 344 | | | |



Master AD/SI Report

CITATION M2 S/N 525-1081 (N916JL): 444.8HRS, 369 AFL as of 31-Aug-2023

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 03-Sep-2023

| Task No. | Description | Unit | Interval | Compliance | Next Due | Disposition | MOC |
|---|------------------|--|----------|-------------|----------|-------------|--|
| ENGINE NO. 1 - SB - 290565/72100-201 | | | | | | | |
| SB | WISB-73-1027 | NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE, SERVICE BULLETIN | | | | | COMPLIED WITH - COMPLIED WITH WILLIAMS SERVICE BULLETIN 73-1027 BY THE INSTALLATION OF P/N 231111 S/N 70006220502. |
| | 22-NOV-2021 | MOS | | 09-JUN-2022 | | | |
| | | HRS/MSC - | | 259.6 | | | |
| | | AFL | | | | | |
| | | ENC | | 223 | | | |
| SB | WISB-73-1027 R01 | NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE, SERVICE BULLETIN | | | | MANDATORY | COMPLIED WITH |
| | 03-AUG-2022 | MOS | | 08-JUN-2022 | | | |
| | | HRS/MSC - | | 259.6 | | | |
| | | ENC | | 223 | | | |



Master AD/SI Report

CITATION M2 S/N 525-1081 (N916JL): 444.8HRS, 369 AFL as of 31-Aug-2023

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 03-Sep-2023

| Task No. | Description | Unit | Interval | Compliance | Next Due | Disposition | MOC | |
|---|--------------|--|----------|------------|-------------|-------------|---|--|
| ENGINE NO. 2 - SB - 290566/72100-201 | | | | | | | | |
| SB | WISB-73-1027 | NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE, SERVICE BULLETIN | | | | | COMPLIED WITH - COMPLIED WITH WILLIAMS WISB-73-1027 FCU REPLACEMENT ON RIGHT ENGINE, S/N 290566. REMOVED FCU P/N 225646-B S/N 70004 AND REPLACED WITH NEW S/N 231111 S/N 70189 REPLACING CONSUMABLES AS REQUIRED IAW FJ44-1AP MM73-19-02.TC186 CAL DUE: 3/30/2023PERFORMED ENGINE IDLE SPEED AND LEAK CHECK RUNS IAW FJ44-1AP MM 71-00-00-760-832 AND STABILITY/ACCELERATION CHECKS IAW FJ44-1AP MM71-00-00-760-834 WITH SATISFACTORY RESULTS | |
| | 22-NOV-2021 | MOS | | | 10-AUG-2022 | | | |
| | | HRS/MSC | - | | 287.3 | | | |
| | | ENC | | | 244 | | | |