



Status Report

LEARJET 60

S/N 60 210 C-FONG

**OWNER: FLIGHTPATH CHARTER
AIRWAYS**

**OPERATOR: FLIGHTPATH CHARTER
AIRWAYS**

ADDRESS: 4A-4881 FOUNTAIN ST. N., HANGAR
33,
BRESLAU ON N0B1M0

ADDRESS: HANGAR 17
BRESLAU ONTARIO N0B 1M0

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: BOUN EM
EMAIL: BEM@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
316-462-2442 (FAX)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;PN/SN-UNKNOWN Components:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE

AIRCRAFT	SERIAL/REGNO: 60 210/C-FONG	MODEL: LEARJET 60	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 29-DEC-2000		LAST ACTUALS: 5584.2 A/C HRS as of 14-DEC-2022 3705 AFL as of 14-DEC-2022 2079 APH as of 14-DEC-2022 1558.8 ACH as of 11-NOV-2021	
APU	SERIAL/PART: SP-E060449/4503135	MODEL: T-20G-10C3A (CIMMS)	MANUFACTURER: HAMILTON SUNDSTRAND CORPORATION
INSTALLED ON: 16-DEC-2021 2623 APU HRS 5539.1 A/C HRS 5076 APUS		LAST ACTUALS: 2642 APU HRS as of 14-DEC-2022 5097 APUS as of 14-DEC-2022	
ENGINE NO. 1	SERIAL/PART: PCE-CA0260/31B4067-04	MODEL: PW305A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 22-APR-2015 3616.4 ENG. HRS 3616.4 A/C HRS 2379 ENC		LAST ACTUALS: 5584.2 ENG. HRS as of 14-DEC-2022 3705 ENC as of 14-DEC-2022	
ENGINE NO. 2	SERIAL/PART: PCE-CA0259/31B4067-04	MODEL: PW305A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 14-NOV-2013 3379.4 ENG. HRS 3379.4 A/C HRS 2209 ENC		LAST ACTUALS: 5586.7 ENG. HRS as of 14-DEC-2022 3708 ENC as of 14-DEC-2022	



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
CI60-161006	REVIEW LEARJET 60 AMM REVISION A15							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF CI60							
CI60-161011	REVIEW LEARJET 60 EINSPECTOR REVISION 2016.10.11							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF CI60							
EC24-160516	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF EC24							
EC24-160516	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF EC24							
EC24-170116	NO. 1 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2							Service ATA:00
	MOS/MSC	02-Mar-17	-					REQUIREMENT CHANGE FORMS
	HRS	4007						
	ENC	2645						
EC24-170116	NO. 2 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2							Service ATA:00
	MOS/MSC	02-Mar-17	-					REQUIREMENT CHANGE FORMS
	HRS	3985.4						
	ENC	2629						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EC24-180214	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF EC24							
EC24-180214	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF EC24							
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-A1	PHASE A1-300 HOUR							Package ATA:05
	MOS	19-Oct-22	12 (+14d/-14d)		19-Oct-23	02-Nov-23	281 d (+14)	
	HRS	5563.7	300 (+25/-25)		5863.7	5888.7	279.5 (+25)	
	AFL	3693						
	PROC. REF: AMM 5-10-01							
	PKG:1							
05-10-02-A2	PHASE A2-300 HOUR							Package ATA:05
	MOS	19-Oct-22	12 (+14d/-14d)		19-Oct-23	02-Nov-23	281 d (+14)	
	HRS	5563.7	300 (+25/-25)		5863.7	5888.7	279.5 (+25)	
	AFL	3693						
	PROC. REF: AMM 5-10-02							
	PKG:2							
05-10-03-A3	PHASE A3-300 HOUR							Package ATA:05
	MOS	19-Oct-22	12 (+14d/-14d)		19-Oct-23	02-Nov-23	281 d (+14)	
	HRS	5563.7	300 (+25/-25)		5863.7	5888.7	279.5 (+25)	
	AFL	3693						
	PROC. REF: AMM 5-10-03							
	PKG:3							
05-10-04-A4	PHASE A4-300 HOUR							Package ATA:05
	MOS	19-Oct-22	12 (+14d/-14d)		19-Oct-23	02-Nov-23	281 d (+14)	
	HRS	5563.7	300 (+25/-25)		5863.7	5888.7	279.5 (+25)	
	AFL	3693						
	PROC. REF: AMM 5-10-04							
	PKG:4							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-05-A5	PHASE A5-300 HOUR							Package ATA:05
	MOS	19-Oct-22	12 (+14d/-14d)		19-Oct-23	02-Nov-23	281 d (+14)	
	HRS	5563.7	300 (+25/-25)		5863.7	5888.7	279.5 (+25)	
	AFL	3693						
PROC. REF: AMM 5-10-05								PKG:5
05-10-06-A6	PHASE A6-300 HOUR							Package ATA:05
	MOS	19-Oct-22	12 (+14d/-14d)		19-Oct-23	02-Nov-23	281 d (+14)	
	HRS	5563.7	300 (+25/-25)		5863.7	5888.7	279.5 (+25)	
	AFL	3693						
PROC. REF: AMM 5-10-06								PKG:6
05-10-07-B1	PHASE B1-600 HOUR							Package ATA:05
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4	600 (+25/-25)		5814.4	5839.4	230.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-07								PKG:7
05-10-08-B2	PHASE B2-600 HOUR							Package ATA:05
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4	600 (+25/-25)		5814.4	5839.4	230.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-08								PKG:8
05-10-09-B3	PHASE B3-600 HOUR							Package ATA:05
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4	600 (+25/-25)		5814.4	5839.4	230.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-09								PKG:9
05-10-10-B4	PHASE B4-600 HOUR							Package ATA:05
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4	600 (+25/-25)		5814.4	5839.4	230.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-10								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-11-B5	PHASE B5-600 HOUR							Package ATA:05
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4	600 (+25/-25)		5814.4	5839.4	230.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-11								PKG:11
05-10-12-B6	PHASE B6-600 HOUR							Package ATA:05
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4	600 (+25/-25)		5814.4	5839.4	230.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-12								PKG:12
05-10-13-C1	PHASE C1-1200 HOUR							Package ATA:05
	MOS	23-Mar-21	48 (+14d/-14d)		23-Mar-25	06-Apr-25	802 d (+14)	
	HRS	5214.4	1200 (+25/-25)		6414.4	6439.4	830.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-13								PKG:13
05-10-14-C2	PHASE C2-1200 HOUR							Package ATA:05
	MOS	23-Mar-21	48 (+14d/-14d)		23-Mar-25	06-Apr-25	802 d (+14)	
	HRS	5214.4	1200 (+25/-25)		6414.4	6439.4	830.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-14								PKG:14
05-10-15-C3	PHASE C3-1200 HOUR							Package ATA:05
	MOS	23-Mar-21	48 (+14d/-14d)		23-Mar-25	06-Apr-25	802 d (+14)	
	HRS	5214.4	1200 (+25/-25)		6414.4	6439.4	830.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-15								PKG:15
05-10-16-C4	PHASE C4-1200 HOUR							Package ATA:05
	MOS	23-Mar-21	48 (+14d/-14d)		23-Mar-25	06-Apr-25	802 d (+14)	
	HRS	5214.4	1200 (+25/-25)		6414.4	6439.4	830.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-16								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-17-C5	PHASE C5-1200 HOUR							Package ATA:05
	MOS	23-Mar-21	48 (+14d/-14d)		23-Mar-25	06-Apr-25	802 d (+14)	
	HRS	5214.4	1200 (+25/-25)		6414.4	6439.4	830.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-17								PKG:17
05-10-18-C6	PHASE C6-1200 HOUR							Package ATA:05
	MOS	23-Mar-21	48 (+14d/-14d)		23-Mar-25	06-Apr-25	802 d (+14)	
	HRS	5214.4	1200 (+25/-25)		6414.4	6439.4	830.2 (+25)	
	AFL	3422						
PROC. REF: AMM 5-10-18								PKG:18
05-10-19-D1	PHASE D1-2400 HOUR							Package ATA:05
	MOS	18-Apr-19	96 (+14d/-14d)		18-Apr-27	02-May-27	1558 d (+14)	
	HRS	4647.4	2400 (+25/-25)		7047.4	7072.4	1463.2 (+25)	
	AFL	2994						
PROC. REF: AMM 5-10-19								PKG:19
05-10-20-D2	PHASE D2-2400 HOUR							Package ATA:05
	MOS	21-Mar-19	96 (+14d/-14d)		21-Mar-27	04-Apr-27	1530 d (+14)	
	HRS	4647.4	2400 (+25/-25)		7047.4	7072.4	1463.2 (+25)	
	AFL	2994						
PROC. REF: AMM 5-10-20								PKG:20
05-10-21-D3	PHASE D3-2400 HOUR							Package ATA:05
	MOS	27-Apr-19	96 (+14d/-14d)		27-Apr-27	11-May-27	1567 d (+14)	
	HRS	4647.4	2400 (+25/-25)		7047.4	7072.4	1463.2 (+25)	
	AFL	2994						
PROC. REF: AMM 5-10-21								PKG:21
05-10-22-D4	PHASE D4-2400 HOUR							Package ATA:05
	MOS	25-Apr-19	96 (+14d/-14d)		25-Apr-27	09-May-27	1565 d (+14)	
	HRS	4647.4	2400 (+25/-25)		7047.4	7072.4	1463.2 (+25)	
	AFL	2994						
PROC. REF: AMM 5-10-22								PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-23-D5	PHASE D5-2400 HOUR							Package ATA:05
	MOS	24-Apr-19	96 (+14d/-14d)		24-Apr-27	08-May-27	1564 d (+14)	
	HRS	4647.4	2400 (+25/-25)		7047.4	7072.4	1463.2 (+25)	
	AFL	2994						
PROC. REF: AMM 5-10-23								PKG:23
05-10-24-D6	PHASE D6 2400 HOUR							Package ATA:05
	MOS	22-Mar-19	96 (+14d/-14d)		22-Mar-27	05-Apr-27	1531 d (+14)	
	HRS	4647.4	2400 (+25/-25)		7047.4	7072.4	1463.2 (+25)	
	AFL	2994						
PROC. REF: AMM 5-10-24								PKG:24
05-10-25-3000 LDG	3000 LANDING							Package ATA:05
	MOS	22-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)		5994	6019	2289 (+25)	
PROC. REF: AMM 5-10-25								PKG:25
05-10-26-6000 LDG	MAJOR LANDING GEAR							Package ATA:05
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)		6000	6025	2295 (+25)	
PROC. REF: AMM 5-10-26								PKG:26
05-10-27-12 YR	12 YEAR AIRFRAME							Package ATA:05
	MOS	03-Aug-12	144 (+14d/-14d)		03-Aug-24	17-Aug-24	570 d (+14)	
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)		8065	8090	4360 (+25)	
PROC. REF: AMM 05-10-27								PKG:27
05-10-28-12000 HR	12000 HOUR AIRFRAME							Package ATA:05
	MOS	29-Dec-00		TAC 0				
	HRS	0	T:12000 (+25/-25)		12000	12025	6415.8 (+25)	
	AFL	0						
PROC. REF: AMM 5-10-28								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-02	PERFORM HARD LANDING OR DEPARTURE FROM RUNWAY MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								
05-50-03	PERFORM OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT) MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								
05-50-04	PERFORM SEVERE TURBULENCE AND/OR MANEUVERS MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								
05-50-05 ^S	PERFORM NO. 1 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								PKG:29
05-50-05 ^S	PERFORM NO. 2 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								PKG:30
05-50-06	PERFORM HIGH ENERGY STOP (LANDING AND REJECTED TAKEOFF) MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-07	PERFORM PERFORM THRUST REVERSER INSPECTION FOR SLAM-STOW OR HIGH THRUST EMERGENCY STOW OPERATION (REFER TO 78-40-00)							Service ATA:05
	MOS/MSC	21-Jul-21	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	5379						
	AFL	3543						
PROC. REF: AMM 5-50-00								
05-50-08	PERFORM OVERSPEED RECOVERY LANDING GEAR INSPECTION (LANDING GEAR EXTENSION AND RETRACTION AT HIGH SPEED) (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								
05-50-09	PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								
05-50-10	PERFORM HIGH GROUND WIND GUST INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								
05-50-11	PERFORM HEAT DAMAGE INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-12	PERFORM PRESSURE CABIN SKIN THICKNESS MEASUREMENTS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	04-Dec-13	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	3381						
	AFL	2211						
	PROC. REF: AMM 5-50-00							
05-50-13	PERFORM FLAP INSPECTION AFTER CONTAMINATED RUNWAY TAKEOFF OR LANDING (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
	PROC. REF: AMM 5-50-00							
05-50-14	PERFORM VOLCANIC ASH INSPECTION AND MAINTENANCE PROCEDURES (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
	PROC. REF: AMM 5-50-00							
05-50-15	MAINTENANCE PROCEDURES ON AIRCRAFT EXTERIOR SURFACE WITHIN SALT INFLUENCED ENVIRONMENTS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
	PROC. REF: AMM 5-50-00							
05-50-16	PERFORM FLAP OVERSPEED INSPECTION AND REPAIR (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	29-Dec-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
	PROC. REF: AMM 5-50-00							
05-50-17	PERFORM FOREIGN OBJECT DAMAGE INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
	AFL							
	PROC. REF: AMM 5-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-PATS-490001	APU - INSPECT APU PER MANUFACTURERS INSTRUCTIONS							Service ATA:05
	MOS	11-Mar-22						
	HRS	2623	200		2823		181	
	APUS	5076						
PROC. REF: SMM 49-11-03								
05-PATS-490002	APU - ANNUAL INSPECTION OF APU MOUNTS FOR LOOSENESS & DAMAGE							Service ATA:05
	MOS	11-Mar-22	12		11-Mar-23		59 d	
	HRS	2623						
	APUS	5076						
PROC. REF: SMM 49-11-03								
05-PATS-490004	APU - VISUALLY INSPECT ALL APU MOUNT PARTS & FUSELAGE ATTACHMENT POINTS FOR CRACKS OR DAMAGE							Service ATA:05
	MOS	28-Mar-16						
	HRS	1561	3000		4561		1919	
	APUS							
PROC. REF: SMM 49-11-03								
05-PATS-490005	VISUALLY INSPECT ALL MOUNT PARTS AND FUSELAGE ATTACHMENT POINTS FOR CRACKS OR DAMAGE							Service ATA:05
	MOS	13-Oct-11						
	HRS	2982.2	3000		5982.2		398	
	AFL	1926						
PROC. REF: GENERIC NO REF, SMM 49-11-03								
05-PATS-490006	PERFORM EXHAUST & INLET DOUBLER FRAMES & STRINGERS							Service ATA:05
	MOS	29-Dec-00						
	HRS	0	10000		10000		4415.8	
	AFL	0						
PROC. REF: GENERIC NO REF, SMM 49-11-03								
05-PATS-490007	APU - DRAIN EPA SUMP							Service ATA:05
	MOS/MSC	29-Sep-06	O/C					
	HRS	0						
	APUS	0						
05-T20G-490001	APU - PERFORM OIL LEVEL CHECK							Service ATA:05
	MOS	04-Dec-22	1		04-Jan-23		OVD	
	HRS							
	APUS							
Special Properties: TRACKED ITEM PROC. REF: MM 49-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-T20G-490002	APU - CHECK EXTERNAL FUEL AND OIL LEAKAGE, AIR INLET AND EXHAUST DUCTS FOR OBSTRUCTION AND ATTACHING BOLTS AND SCREWS FOR ATTACHMENT AND SECURITY							Service ATA:05
	MOS	23-Sep-21						
	HRS	2567	500		3067		425	
	APUS	4970						
PROC. REF: MM 49-20-00								
05-T20G-HS-490003	APU - PERFORM APU OIL & FILTER CHANGE							Service ATA:05
	MOS	23-Mar-21	24		23-Mar-23		71 d	
	HRS	2606	500		3106		464	
	APUS	4695						
PROC. REF: MM 49-20-00, MM 49-20-00								
05-T20G-HS-490004	APU - VISUAL INSPECTION ENGINE HARNESS							Service ATA:05
	MOS	23-Sep-21						
	HRS	2567	500		3067		425	
	APUS	4970						
PROC. REF: MM 49-20-00								
05-T20G-HS-490005	APU - INSPECT IGNITER PLUG							Service ATA:05
PN:160544-1	MOS	18-Dec-20						
SN:NSN	HRS	2324	500		2824		182	
	APUS	4592						
PROC. REF: MM 49-20-00								
05-T20G-HS-490006	APU - INSPECT COMBUSTOR FUEL DRAIN LINE							Service ATA:05
	MOS	23-Sep-21						
	HRS	2567	500		3067		425	
	APUS	4970						
PROC. REF: MM 49-20-00								
05-T20G-HS-490007	APU - INSPECT OIL OVERFILL TUBE ASSEMBLY FOR CLEANLINESS AND OBSTRUCTIONS							Service ATA:05
	MOS	23-Sep-21						
	HRS	2567	500		3067		425	
	APUS	4970						
PROC. REF: MM 49-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-T20G-HS-490010	APU - INSPECT APU HOUSING, COVERS AND BRACKETS							Service ATA:05
	MOS	23-Sep-21						
	HRS	2567	500		3067		425	
	APUS	4970						
PROC. REF: MM 49-20-00								
05-T20G-HS-490011	APU - REPLACE FUEL INLET FILTER							Service ATA:05
	MOS	23-Mar-21	24		23-Mar-23		71 d	
	HRS	2387	500		2887		245	
	APUS	4695						
PROC. REF: MM 49-20-00								
052000	NO. 1 ENGINE - MINOR INSPECTION ITEMS							Package ATA:05
	MOS	23-Mar-21	36		23-Mar-24		437 d	
	HRS	5214.4	600 (-50)		(5814.4) 5814.4		230.2	
	ENC	3423						
PROC. REF: GENERIC NO REF								PKG:1
052000	NO. 2 ENGINE - MINOR INSPECTION ITEMS							Package ATA:05
	MOS	23-Mar-21	36		23-Mar-24		437 d	
	HRS	5165.7	600 (-50)		(5765.7) 5763.2		179	
	ENC	3406						
PROC. REF: GENERIC NO REF								PKG:1
055002	NO. 1 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00								
055002	NO. 2 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055003	NO. 1 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00								
055003	NO. 2 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00								
055004	NO. 1 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00								
055004	NO. 2 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00								
055005	NO. 1 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00								
055005	NO. 2 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055006	NO. 1 ENGINE - ENGINE IMMERSION IN WATER							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
				PROC. REF: RCF E029, RCF E015, RCF C172, RCF A189, RCF GMSG, RCF C2ST, RCF 00, RCF 00, RCF E024, RCF E056, RCF EH75, RCF P009, RCF A189, RCF P019, RCF P006, RCF E206, RCF EC07, RCF B429, RCF P035, RCF CA70, RCF CA75, RCF P030, RCF P034, RCF P004, RCF EC07, RCF P900, RCF P027, RCF 00, RCF EH43, RCF E21A, RCF C206, RCF 00, RCF FA7X, RCF FA7X, RCF E205, RCF B429, RCF C2ST, RCF E07X, RCF EC07, RCF B429, RCF EH45, EMM 05-50-00				
055006	NO. 2 ENGINE - ENGINE IMMERSION IN WATER							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
				PROC. REF: RCF E029, RCF E015, RCF C172, RCF A189, RCF GMSG, RCF C2ST, RCF 00, RCF 00, RCF E024, RCF E056, RCF EH75, RCF P009, RCF A189, RCF P019, RCF P006, RCF E206, RCF EC07, RCF B429, RCF P035, RCF CA70, RCF CA75, RCF P030, RCF P034, RCF P004, RCF EC07, RCF P900, RCF P027, RCF 00, RCF EH43, RCF E21A, RCF C206, RCF 00, RCF FA7X, RCF FA7X, RCF E205, RCF B429, RCF C2ST, RCF E07X, RCF EC07, RCF B429, RCF EH45, EMM 05-50-00				
055007	NO. 1 ENGINE - DROPPED ENGINE							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
				PROC. REF: EMM 05-50-00				
055007	NO. 2 ENGINE - DROPPED ENGINE							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
				PROC. REF: EMM 05-50-00				
055008	NO. 1 ENGINE - PERFORM ENGINE OPERATION IN VISIBLE VOLCANIC ASH INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
				PROC. REF: GENERIC NO REF, EMM 05-50-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055008	NO. 2 ENGINE - PERFORM ENGINE OPERATION IN VISIBLE VOLCANIC ASH INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00								
055009	NO. 1 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00								
055009	NO. 2 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00								
055010	NO. 1 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00								
055010	NO. 2 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00								
055011	NO. 1 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055011	NO. 2 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: EMM 05-50-00							
055012	NO. 1 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: GENERIC NO REF, EMM 05-50-00							
055012	NO. 2 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-00	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: GENERIC NO REF, EMM 05-50-00							
05C001 ^U	INSPECT INSPECT DOCUMENTATION AND SAFETY EQUIPMENT							Service ATA:05
	MOS	13-Oct-22	6		13-Apr-23		92 d	
	HRS							
	AFL							
ATA 08 - LEVELING AND WEIGHING								
082000	WEIGHT AND BALANCE							Service ATA:08
	MOS	19-Mar-21	36		19-Mar-24		433 d	
	HRS	5214.4						
	AFL	3422						
	PROC. REF: AMM 08-20-00							
ATA 11 - PLACARDS AND MARKINGS								
T1130001 ^S	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS. (REFER TO 11-30-00.)							Service ATA:11
	MOS	26-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 11-30-00							
					PKG:20			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
121005	PERFORM NOSE AND MAIN TIRE PRESSURE CHECKS							Service ATA:12
	DAYS/MSC	22-Apr-15	A/R					
	HRS	3616.4						
	AFL	2379						
	PROC. REF: AMM 12-10-05							
1210063 EMP ^S	NOSE GEAR SHOCK STRUT - SERVICE							Service ATA:12
	MOS	29-Dec-00	36 (+14m/-14m)					
	HRS	0	600 (+25/-25)					
	AFL	0						
	PROC. REF: AMM 12-10-03							PKG:41
1210064 EMP ^S	LEFT MAIN GEAR SHOCK STRUT - SERVICE							Service ATA:12
	MOS	29-Dec-00	36 (+14m/-14m)					
	HRS	0	600 (+25/-25)					
	AFL	0						
	PROC. REF: AMM 12-10-04							PKG:41
1210064 EMP ^S	RIGHT MAIN GEAR SHOCK STRUT - SERVICE							Service ATA:12
	MOS	29-Dec-00	36 (+14m/-14m)					
	HRS	0	600 (+25/-25)					
	AFL	0						
	PROC. REF: AMM 12-10-04							PKG:41
12CUS1 ^U	PERFORM PREVENTIVE DOSE OF BIOBOR ADDITIVE INTO FUEL TANKS							Service ATA:12
	DAYS/MSC	03-Jul-19	A/R					
	HRS	4692						
	AFL	3032						
D1221001 ^S	LUBRICATE NOSE LANDING GEAR ACTUATOR - LUBRICATE ATTACH FITTING. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-01							PKG:5
D1221002 ^S	LUBRICATE NOSE LANDING GEAR ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-01)							Service ATA:12
	MOS	28-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 12-21-01							PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
D1221006 ^S	INSPECT THRUST REVERSERS - LUBRICATE IDLER LINKS AND DRIVE LINKS. (REFER TO 12-21-04)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-04							PKG:3
D1221010 ^S	LUBRICATE MAIN LANDING GEAR AFT TRUNNION PIN. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-01							PKG:5
D1221011 ^S	LUBRICATE MAIN LANDING GEAR FORWARD TRUNNION PIN. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-01							PKG:5
D1221012 ^S	LUBRICATE MAIN LANDING GEAR TORQUE LINK BUSHINGS. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-01							PKG:5
D1221013 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR STRUT ATTACH POINT. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-01							PKG:5
F1221008 ^S	LUBRICATE MAIN LANDING GEAR DOOR ACTUATOR (48C48608) PISTON ROD FELT WIPER. (REFER TO 12-21-01).							Service ATA:12
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 12-21-01							PKG:11
G1221004 ^S	LUBRICATE NOSE LANDING GEAR DOORS HINGES. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-01							PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
G1221005 ^S	LUBRICATE MAIN LANDING GEAR DOORS HINGES. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-01							PKG:5
G1221007 ^S	LUBRICATE NOSE LANDING GEAR UPLATCH ACTUATOR PISTON ROD FELT WIPERS. (REFER TO 12-21-01).							Service ATA:12
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 12-21-01							PKG:11
G1221019 ^S	LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE. (REFER TO 12-21-03)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-03							PKG:6
G1221020 ^S	LUBRICATE SINGLE POINT REFUELING ACCESS DOOR HINGES. (REFER TO 12-21-03)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-03							PKG:6
G1221021 ^S	LUBRICATE EMERGENCY EXIT/BAGGAGE DOOR HINGES AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-03							PKG:6
G1221023 ^S	LUBRICATE TOILET SERVICING DOOR HINGE. (REFER TO 12-21-03)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-03							PKG:6
G1221024 ^S	LUBRICATE TAILCONE EQUIPMENT DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-03							PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
G1221025 ^S	LUBRICATE TAILCONE BAGGAGE DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-03							PKG:6
G1221029 ^S	INSPECT LOWER NACELLE - LUBRICATE HINGES. (REFER TO 12-21-03)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-03							PKG:3
G1221030 ^S	LUBRICATE OXYGEN SERVICING ACCESS DOOR HINGE. (REFER TO 12-21-03)							Service ATA:12
	MOS/MSC	19-Oct-22	N/A					
	HRS	5563.7						
	AFL	3693						
	PROC. REF: AMM 12-21-03							PKG:2
G1230000 ^S	INSPECT ALCOHOL ANTI-ICE TANK - CHECK FOR QUANTITY OF FLUID. (REFER TO 12-10-08)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-10-08							PKG:2
H1221003 ^S	LUBRICATE NOSE LANDING GEAR ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.)							Service ATA:12
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: AMM 12-21-01							PKG:17
H1221028 ^S	LUBRICATE UPPER AND LOWER ENTRY DOORS HINGES AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	15-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 12-21-03							PKG:12
L1221017 ^S	LUBRICATE FLAP CAM FOLLOWERS. (REFER TO 12-21-02)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-02							PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
L1221036 ^S	LUBRICATE SPOILER ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-02).							Service ATA:12
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 12-21-02							PKG:10
M1221038 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) WING ATTACH POINTS. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-01							PKG:5
M1221040 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.)							Service ATA:12
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: AMM 12-21-01							PKG:17
M1221041 ^S	INSPECT THRUST REVERSERS - LUBRICATE GUIDE RODS. (REFER TO 12-21-04)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-21-04							PKG:3
P1210051 ^S	CHECK NOSE GEAR SHOCK STRUT FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-03)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-10-03							PKG:5
P1210052 ^S	CHECK MAIN GEAR SHOCK STRUTS FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-04)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-10-04							PKG:5
P1210053 ^S	INSPECT EMERGENCY AIR PRESSURE GAUGE - CHECK FOR PROPER AIR PRESSURE (1800 TO 3000 PSI). (REFER TO 12-10-07)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 12-10-07							PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
P1210054 ^S	INSPECT OXYGEN PRESSURE GAUGE - CHECK FOR PROPER INFLATION (1500 TO 1850 PSI). (REFER TO 12-10-09)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: AMM 12-10-09							PKG:1	
P1210055 ^S	CHECK NOSE AND MAIN TIRES FOR PROPER INFLATION. (REFER TO 12-10-05)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: AMM 12-10-05							PKG:5	
P1210056 ^S	INSPECT HYDRAULIC AND THRUST REVERSER ACCUMULATORS - CHECK ACCUMULATOR PRECHARGE (850 PSI). (REFER TO 12-21-04)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: AMM 12-10-01							PKG:3	
P1221043 ^S	LUBRICATE NOSE LANDING GEAR TRUNNION PINS. (REFER TO 12-21-01)							Service ATA:12
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: AMM 12-21-01							PKG:5	
R1221039 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 2327100) PISTON ROD FELT WIPER. (REFER TO 12-21-01).							Service ATA:12
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 12-21-01							PKG:11	
X1221045 ^S	LUBRICATE R/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184)							Service ATA:12
	MOS/MSC	19-Oct-22	N/A					
	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 12-21-03							PKG:2	
X1221046 ^S	LUBRICATE L/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184)							Service ATA:12
	MOS/MSC	19-Oct-22	N/A					
	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 12-21-03							PKG:2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 20 - STANDARD PRACTICES - AIRFRAME								
206100 ^U	PERFORM PRECIPITATION STATIC (P-STATIC) TEST							Service ATA:20
	MOS/MSC	04-Dec-13	O/C					
	HRS	3381						
	AFL	2211						
ATA 21 - AIR CONDITIONING								
05-10-29-L2150053	FUNCTION TEST REFRIGERATION SYSTEM PRESSURE SWITCH							Service ATA:21
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 21-50-05								
05-10-29-N2150019	PENETRANT INSPECT AC COMPRESSOR FAN BLADES							Service ATA:21
	MOS/MSC	29-Dec-00	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT 21-50-01								
05-10-29-U2130007	PERFORM CABIN LEAK RATE CHECK							Service ATA:21
	MOS	30-Apr-19						
	HRS	4648.1	1200 (+25/-25)		5848.1	5873.1	263.9 (+25)	
	AFL	2996						
PROC. REF: AMM 21-30-00								
212001	COCKPIT AIR CHECK VALVE							Component ATA:21
PN:6600423-7	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:693	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-01								
212003	LEFT CABIN AIR CHECK VALVE							Component ATA:21
PN:6600423-10	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:509	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02								
212004	RIGHT CABIN AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212005	LEFT CABIN OVERHEAD DIFFUSER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-03								
212006	RIGHT CABIN OVERHEAD DIFFUSER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-03								
212007	AFT EVAPORATOR BLOWER ASSEMBLY							Component ATA:21
PN:66-0261-2	MOS/MSC	02-Sep-16	O/C	TSO 0				
SN:K40809	HRS	3960.5		TSO 0				
	AFL	2615		TSO 0				
PROC. REF: AMM 21-51-10								
212007A	INSPECT AFT EVAPORATOR BLOWER ASSEMBLY BRUSHES							Service ATA:21
PN:66-0261-2	MOS/MSC	02-Sep-16	O/C					
SN:K40809	HRS	3960.5						
	AFL	2615						
PROC. REF: GENERIC NO REF								
212008	FWD EVAPORATOR BLOWER ASSEMBLY							Component ATA:21
PN:66-0251-4SB	MOS/MSC	04-Mar-03	O/C	TSN 0				
SN:6602511-169	HRS	156		TSN 156				
	AFL	117						
PROC. REF: AMM 21-51-08								
212101	CABIN EVAPORATOR BLOWER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-01								
212104	COCKPIT EVAPORATOR BLOWER							Component ATA:21
PN:ES73175-4	MOS/MSC	22-Jun-18	O/C	TSO 0				
SN:19184B	HRS	4406.3		TSO 0				
	AFL	2842		TSO 0				
PROC. REF: AMM 21-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212105	COCKPIT BLOWER CONTROL BOX ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-05								
212155	LEFT BLEED AIR MUFFLER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
212156	RIGHT BLEED AIR MUFFLER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
212201	LEFT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-22-01								
212202	RIGHT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-22-01								
212205	AVIONICS COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-22-02								
213001	PRIMARY OUTFLOW VALVE							Component ATA:21
PN:6600812-10	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:50-C0042	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213002	SECONDARY OUTFLOW VALVE							Component ATA:21
PN:6600812-11	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:20-B0237	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-02								
213003	CABIN AIR PRESSURE SELECTOR							Component ATA:21
PN:6600812-13	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:30-B0215	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-03								
213004	CABIN PRESSURE CONTROLLER							Component ATA:21
PN:6600812-014	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:30-F0207	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-04								
213005	MANUAL PRESSURE CONTROLLER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-05								
213006	AIR FILTER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-06								
213008	PRESSURIZATION MODE SWITCH							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-08								
213009	EMERGENCY DEPRESSURIZATION SWITCH							Component ATA:21
PN:95-6A-14-H6-58284	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:4360	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 21-30-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213010	CABIN PRESSURE INDICATOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-10								
213011	VACUUM REGULATOR							Component ATA:21
PN:6600812-6	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:409D	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-11								
213012	VACUUM PUMP							Component ATA:21
PN:6600812-015	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:30-1462	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-12								
213013	VACUUM CHECK VALVE							Component ATA:21
PN:6600812-016	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:40-3212	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-13								
213078-701 ^U	INTEGRATED CABIN PRESSURE INDICATOR							Component ATA:21
PN:6608506-004	MOS/MSC	18-Aug-03	O/C	TSN 0				
SN:B551	HRS	355		TSN 0				
	AFL	236		TSN 0				
213101	LEFT EMERGENCY PRESSURIZATION VALVE							Component ATA:21
PN:6600252-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:793	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-01								
213102	RIGHT EMERGENCY PRESSURIZATION VALVE							Component ATA:21
PN:6600252-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:798	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213103	LEFT EMERGENCY PRESSURIZATION ANEROID SWITCH							Component ATA:21
PN:2E37C-30	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:593	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02								
213104	RIGHT EMERGENCY PRESSURIZATION ANEROID SWITCH							Component ATA:21
PN:2E37C-30	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:597	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02								
213105	LEFT CONDITIONED AIR CHECK VALVE							Component ATA:21
PN:6600210-5	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6974AC	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03								
213106	RIGHT CONDITIONED AIR CHECK VALVE							Component ATA:21
PN:6600210-5	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6988AC	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03								
213107	POSITIVE VENTILATION CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-04								
214001	FLOW CONTROL VALVE							Component ATA:21
PN:320335-3	MOS/MSC	23-Jan-13	O/C	TSN 0				
SN:099	HRS	3250.1		TSN 0				
	AFL	2119		TSN 0				
PROC. REF: AMM 21-40-01								
214002	HEAT EXCHANGER							Component ATA:21
PN:6608060-009	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:A084	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
214101	COCKPIT HEATER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-01								
214102	COCKPIT DIVERTER DOOR SOLENOID							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-02								
214103	COCKPIT DIVERTER DOOR RESISTOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-03								
214104	COCKPIT DIVERTER DOOR THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-04								
214201	LEFT AUXILIARY CABIN HEATER							Component ATA:21
PN:7026-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:155	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-42-01								
214202	RIGHT AUXILIARY CABIN HEATER							Component ATA:21
PN:7026-4	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:157	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-42-01								
214203	AUXILIARY HEAT OVERTEMPERATURE MONITOR BOX							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-42-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
214301	LEFT OUTBOARD ELECTRIC FOOT WARMER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-43-00								
214302	LEFT INBOARD ELECTRIC FOOT WARMER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-43-00								
214303	RIGHT INBOARD ELECTRIC FOOT WARMER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-43-00								
214304	RIGHT OUTBOARD ELECTRIC FOOT WARMER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-43-00								
215001	AIR CONDITIONING COMPRESSOR							Component ATA:21
PN:JBS222-1	MOS/MSC	18-May-18	O/C	TSN 0				
SN:T-C45031-02	HRS	4351.9		TSN 0				
	AFL	2820		TSN 0				
PROC. REF: AMM 21-50-01, AMM 21-51-01								
215003	CONDENSER							Component ATA:21
PN:7608061-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:796	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-03, AMM 21-51-04								
215004	RECEIVER/DRYER							Component ATA:21
PN:ES43030-3	MOS/MSC	18-May-18	O/C	TSN 0				
SN:N/A	HRS	4351.9		TSN 0				
	AFL	2820		TSN 0				
PROC. REF: AMM 21-50-04, AMM 21-51-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215005	FREON PRESSURE SWITCH							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-05, AMM 21-51-06								
215006	COCKPIT EVAPORATOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-06, AMM 21-51-07								
215007	FREON COMPRESSOR DRIVE (R134) MOTOR							Component ATA:21
PN:ES61134-3	MOS	03-Sep-20		TSO 0				OVERHAUL
SN:615	HRS	4976.3		TSO 0				
	AFL	3237		TSO 0				
	ACH	1558.8	2000 (+25/-25)	TSO 0	3558.8	3583.8	2000 (+25)	
PROC. REF: AMM 21-51-02								
215007A	INSPECT/REPLACE FREON COMPRESSOR DRIVE (R134) MOTOR BRUSHES - 05-10-29-K2150036							Service ATA:21
PN:ES61134-3	MOS	03-Sep-20						
SN:615	HRS	4976.3						
	AFL	3237						
	ACH	1558.8	1200 (+25/-25)		2758.8	2783.8	1200 (+25)	
PROC. REF: AMM 21-51-02								
215008	COCKPIT EVAPORATOR PRESSURE REGULATOR VALVE							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-08								
215009	CABIN EVAPORATOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10, AMM 21-50-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215010	CABIN EXPANSION VALVE							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-10, AMM 21-51-11								
215012	FREON MOTOR CONTROL BOX							Component ATA:21
PN:5418598-021	MOS/MSC	03-Sep-20	O/C					
SN:MRP531414-01	HRS	4976.3						
	AFL	3237						
PROC. REF: AMM 21-50-12, AMM 21-51-13								
215013	K61 FREON MOTOR CONTACTOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-13, AMM 21-51-14								
215014	K62 FREON MOTOR CONTACTOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-13, AMM 21-51-14								
215015	K63 FREON MOTOR CONTACTOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-13, AMM 21-51-14								
215016	FREON MOTOR DIFFERENTIAL CURRENT SENSOR							Component ATA:21
PN:268-1-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0005061	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-14, AMM 21-51-15								
215017	COMPRESSOR MOTOR HOURMETER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-16, AMM 21-51-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215017A	CHECK AND RECORD COMPRESSOR MOTOR HOURMETER TIME							Service ATA:21
PN:PN	MOS/MSC	29-Dec-00	A/R					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
215031	ABSOLUTE PRESSURE SWITCH							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215049	COCKPIT EXPANSION VALVE							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-07, AMM 21-51-09								
215101	FREON COMPRESSOR DRIVE (R-12) MOTOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-02								
215101A	PERFORM FREON COMPRESSOR DRIVE (R-12) MOTOR BRUSH WEAR INSPECTION - 05-10-29-K2150012							Service ATA:21
PN:PN	MOS/MSC		N/A					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 21-50-02								
215120	CONDENSER FAN							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-02								
216001	REMOTE CABIN TEMPERATURE SETTING BOX							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216002	CREW TEMPERATURE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-02								
216003	CABIN TEMPERATURE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-02								
216004	TEMPERATURE CONTROL INDICATOR							Component ATA:21
PN:6608472-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:247	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-03								
216005	COCKPIT TEMPERATURE CONTROLLER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-04								
216006	CABIN TEMPERATURE CONTROLLER							Component ATA:21
PN:6600423-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:090C-0909	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-04								
216007	COCKPIT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-05								
216008	CABIN TEMPERATURE SENSOR							Component ATA:21
PN:627962-1	MOS/MSC	27-Apr-20	O/C	TSN 19				
SN:627962-52163	HRS	4827.6		TSN 0				
	AFL	3129		TSN 0				
PROC. REF: AMM 21-60-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216009	COCKPIT TEMPERATURE SENSOR BLOWER							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-05								
216010	CABIN TEMPERATURE SENSOR BLOWER							Component ATA:21
PN:6600231-1	MOS/MSC	25-Jun-14	O/C	TSN 0				
SN:7102	HRS	3522.3		TSN 0				
	AFL	2300		TSN 0				
PROC. REF: AMM 21-60-05								
216011	COCKPIT SKIN TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-06								
216012	CABIN SKIN TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-06								
216013	COCKPIT TEMPERATURE CONTROL VALVE							Component ATA:21
PN:6600423-017	MOS/MSC	28-Apr-19	O/C					
SN:542	HRS	4647.4						
	AFL	2994						
PROC. REF: AMM 21-60-07								
216014	CABIN TEMPERATURE CONTROL VALVE							Component ATA:21
PN:6600423-017	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:426	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-07								
216015	COCKPIT TEMPERATURE CONTROL VALVE TORQUE MOTOR							Component ATA:21
PN:6600423-8	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4875	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216016	CABIN TEMPERATURE CONTROL VALVE TORQUE MOTOR							Component ATA:21
PN:6600423-8	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4871	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-08								
216017	SERVO AIR PRESSURE REGULATOR							Component ATA:21
PN:6600245-004	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:762	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-09								
216018	COCKPIT AIR DISTRIBUTION CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-10								
216019	CABIN AIR DISTRIBUTION CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-10								
216020	COCKPIT DUCT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-11								
216021	CABIN DUCT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-11								
216022	COCKPIT DUCT OVERHEAT THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216023	CABIN DUCT OVERHEAT THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-12								
216024	CLIMATE CONTROL BOX							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-13								
216025	PILOT ELECTRICAL EQUIPMENT BOX							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-14								
216050	MEMBRANE, CABIN TEMPERATURE SWITCH							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
216101	CABIN TEMPERATURE INDICATOR							Component ATA:21
PN:6608486-1	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:279	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 21-61-01								
216102	CABIN TEMPERATURE INDICATOR SENSOR							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-02								
218105	LEFT TRANSITION DUCT ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
218106	RIGHT TRANSITION DUCT ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10								
21CUS1 ^U	FREON AC COMPRESSOR DRIVE BELT							Component ATA:21
PN:ES20040-6	MOS/MSC	02-Jul-21	O/C	TSN 0				
SN:NSN	HRS	5370.9		TSN 0				
	AFL	3538		TSN 0				
B2121004 ^S	INSPECT POSITIVE VENTILATION CHECK VALVE. (REFER TO 21-31-04.)							Service ATA:21
	MOS	21-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
PROC. REF: AMM 21-31-04								
C2132030 ^S	INSPECT CABIN (PRESSURE) CONDITIONED AIR CHECK VALVES. (REFER TO 21-31-03.)							Service ATA:21
	MOS	12-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
PROC. REF: AMM 21-31-03								
C2132031 ^S	INSPECT CABIN AIR AND COCKPIT AIR CHECK VALVES. (REFER TO 21-20-01 AND 21-20-02.)							Service ATA:21
	MOS	12-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
PROC. REF: AMM 21-20-01								
E2130005 ^S	BOREScope INSPECTION PRIMARY AND SECONDARY OUTFLOW VALVE POPPETS AND SEATS FOR CONTAMINATION. (REFER TO 21-30-00).							Service ATA:21
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 21-30-00								
E2130064 ^S	REMOVE AND REPLACE CABIN AIR FILTER. (REFER TO 21-30-06).							Service ATA:21
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 21-30-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
H2132004 ^S	PERFORM FUNCTIONAL TEST OF EMERGENCY PRESSURIZATION SYSTEM. (REFER TO 21-31-00)							Service ATA:21
	MOS	18-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 21-31-00							PKG:7
H2150000 ^S	INSPECT REFRIGERATION (AIR CONDITIONING) SYSTEM COMPONENTS INSTALLATION FOR PROPER V-BELT TENSION, SECURITY OF MOUNTING, AND GENERAL CONDITION. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND SHAFT)							Service ATA:21
	MOS	03-Sep-20	24 (+14d/-14d)					
	HRS	4976.3	600 (+25/-25)					
	AFL	3237						
	PROC. REF: AMM 12-10-06, AMM 21-50-01, AMM 21-51-01							PKG:9
K2150006 ^S	PERFORM REFRIGERATION COMPRESSOR MOTOR BRUSH WEAR INSPECTION. (REFER TO 21-50-02)							Service ATA:21
	MOS/MSC	03-Sep-20	N/A					
	HRS	4976.3						
	AFL	3237						
	PROC. REF: AMM 21-50-02							PKG:9
L2150048 ^S	FUNCTIONAL TEST OF REFRIGERATION SYSTEM PRESSURE SWITCH. (REFER TO 21-50-05.)							Service ATA:21
	MOS	03-Sep-20	96 (+14d/-14d)					
	HRS	4976.3	2400 (+25/-25)					
	AFL	3237						
	PROC. REF: AMM 21-50-05							PKG:21
N2131010 ^S	FUNCTIONAL TEST OF CABIN PRESSURE WARNING SYSTEM. (REFER TO 21-30-00.)							Service ATA:21
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: AMM 21-30-00							PKG:13
N2144000 ^S	FUNCTIONAL TEST OF TAILCONE BAGGAGE COMPARTMENT HEATING SYSTEM. (REFER TO 21-44-00.)							Service ATA:21
	MOS	27-Apr-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 21-44-00							PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
N2150017 ^S	PERFORM A FLUORESCENT PENETRANT INSPECTION OF THE AIR CONDITIONER COMPRESSOR MOTOR FAN BLADES. PARTICULAR ATTENTION SHOULD BE GIVEN TO THE FAN BLADES IN THE AREA OF THE HUB. (REFER TO NDI MANUAL [NDI-2], PART 5, 21-50-01.)							Service ATA:21
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: NDT 21-50-01								PKG:15
P2130070 ^S	FUNCTIONAL TEST OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00)							Service ATA:21
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 21-30-00								PKG:13
SI-KP-210004 ^U	INSPECT R134 FORWARD AND AFT EVAPORATOR/CONDENSOR COILS.							Service ATA:21
	MOS/MSC	22-Oct-05	N/A					
	HRS	1157.4						
	AFL	774						
SI-KP-210006 ^U	INSPECT R134 REFRIGERANT HOSE(S).							Service ATA:21
	MOS/MSC	22-Oct-05	N/A					
	HRS	1157.4						
	AFL	774						
T2120001 ^S	INSPECT RAM AIR DUCTING AND HEAT EXCHANGER FRO SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:21
	MOS	21-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:21
T2130012 ^S	PERFORM FUNCTIONAL TEST OF PRESSURIZATION SYSTEM VACUUM PUMP HEATING ELEMENT. (REFER TO 21-30-12)							Service ATA:21
	MOS/MSC	18-Apr-17	N/A					
	HRS	4053.4						
	AFL	2668						
	APH	1090						
	ACH	1195.9						
PROC. REF: AMM 21-30-12								PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
T2130069 ^S	PERFORM OPERATIONAL CHECK OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00)							Service ATA:21
	MOS	25-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: AMM 21-30-00				PKG:7
T2142002 ^S	FUNCTIONAL TEST OF AUXILIARY CABIN HEAT SYSTEM. (REFER TO 21-42-00.)							Service ATA:21
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: AMM 21-42-00				PKG:13
T2144010 ^S	VISUALLY INSPECT TAILCONE BAGGAGE COMPARTMENT HEATER BLANKETS. (REFER TO 5-10-00.)							Service ATA:21
	MOS	23-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
				PROC. REF: GENERIC NO REF				PKG:21
ATA 22 - AUTO FLIGHT								
221001	AUTOPILOT CONTROLLER							Component ATA:22
PN:501-1679-02	MOS/MSC	21-Dec-20	O/C	TSR 1				
SN:1039	HRS	5128.4		TSR 0				
	AFL	3357		TSR 0				
				PROC. REF: AMM 22-10-01				
221002	AUTOPILOT ELECTRICAL BOX							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 22-10-02				
221003	PITCH SERVO ACTUATOR							Component ATA:22
PN:622-5027-102	MOS/MSC	13-May-19	O/C	TSO 0				
SN:1CVMN	HRS	4650		TSO 0				
	AFL	2999		TSO 0				
				PROC. REF: AMM 22-10-03				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221004	PITCH SERVO MOUNT							Component ATA:22
PN:622-5029-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5N9V	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-04								
221005	AUTOPITCH TRIM AMPLIFIER BOX ASSEMBLY							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-05								
221006	ROLL SERVO ACTUATOR							Component ATA:22
PN:622-5027-102	MOS/MSC	09-May-19	O/C					
SN:4NKD	HRS	4649.8						
	AFL	2998						
PROC. REF: AMM 22-10-06								
221007	ROLL DISCONNECT RELAY BOX							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-07								
221008	YAW DISCONNECT RELAY BOX							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-08								
221009	YAW SERVO ACTUATOR							Component ATA:22
PN:622-5027-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4NKB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-09								
221010	YAW SERVO MOUNT							Component ATA:22
PN:622-5029-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5ABM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221011	ROLL SERVO MOUNT							Component ATA:22
PN:6080014-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:52RJ	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-11								
221012	REMOTE TUNING RELAY BOX							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-12								
221013	NO. 1 FLIGHT GUIDANCE COMPUTER							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-14								
221014	NO. 2 FLIGHT GUIDANCE COMPUTER							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-14								
222001	MACH TRIM COMPUTER							Component ATA:22
PN:501-1132-04	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2314	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-01								
222002	MACH TRIM ADAPTER							Component ATA:22
PN:902-1-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:44006	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-02								
222003	MACH TRIM POSITION (FOLLOW UP) SENSOR							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
225001	YAW FORCE INTERFACE BOX							Component ATA:22
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-01								
225002	PILOT FORCE SENSOR							Component ATA:22
PN:6608498-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1606	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-02								
225003	COPILOT FORCE SENSOR							Component ATA:22
PN:6608498-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1441	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-02								
B2211016 ^S	CHECK PRIMARY YAW DAMPER SERVO ACTUATOR AND SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-09.)							Service ATA:22
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: AMM 22-10-10								PKG:28
B2212013 ^S	CHECK PITCH SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-06.)							Service ATA:22
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: AMM 22-10-04								PKG:28
B2213006 ^S	CHECK AUTOPILOT ROLL SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-06.)							Service ATA:22
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: AMM 22-10-11								PKG:28
H2211034 ^S	CHECK ROLL SERVO CABLE TENSION. (REFER TO 22-10-11.)							Service ATA:22
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 22-10-11								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
H2211039 ^S		CHECK PITCH SERVO AND YAW SERVO CABLE TENSION. (REFER TO 22-10-04 AND 22-10-10.)						Service ATA:22
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 22-10-04, AMM 22-10-10								PKG:15
T2211022 ^S		CHECK YAW SERVO CABLE FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR CONDITION AND SECURITY.						Service ATA:22
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:15
T2212022 ^S		INSPECT ELEVATOR SERVO CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR GENERAL CONDITION AND SECURITY.						Service ATA:22
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:15
ATA 23 - COMMUNICATIONS								
231101		NO. 1 VHF TRANSCEIVER						Component ATA:23
PN:822-1115-001	MOS/MSC	25-Aug-15	O/C	TSN 170				
SN:DVJP	HRS	3702.6		TSN 3681.6				
	AFL	2436		TSN 2416				
PROC. REF: AMM 23-11-01								
231102		NO. 2 VHF TRANSCEIVER						Component ATA:23
PN:822-1115-001	MOS/MSC	21-Dec-18	O/C	TSO 0				
SN:3802	HRS	4578.3		TSO 0				
	AFL	2948		TSO 0				
PROC. REF: AMM 23-11-01								
231103		NO. 1 VHF ANTENNA						Component ATA:23
PN:VF10-347	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4437	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231104	NO. 2 VHF ANTENNA							Component ATA:23
PN:VF10-347	MOS/MSC	26-Apr-19	O/C	TSN 0				
SN:6603	HRS	4647.4		TSN 0				
	AFL	2994		TSN 0				
PROC. REF: AMM 23-11-02								
231121	AERO M SATCOM ANTENNA							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231123	SATCOM PHONE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231180	NO. 1 HF AUDIO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231181	NO. 2 HF AUDIO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231192	HF ANTENNA LEADTHRU INSULATOR							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-03								
231201	NO. 1 HF RECEIVER/EXCITER							Component ATA:23
PN:064-1015-01	MOS/MSC	21-Dec-20	O/C	TSR 0				
SN:29847	HRS	5128.4		TSR 0				
	AFL	3357		TSR 0				
PROC. REF: AMM 23-12-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231202	NO. 2 HF RECEIVER/EXCITER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-01								
231203	PRIMARY POWER AMPLIFIER/ANTENNA COUPLER							Component ATA:23
PN:064-1017-01	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:16754	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02								
231203A	PERFORM PRIMARY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHF 1050 SYSTEM							Service ATA:23
PN:064-1017-01	MOS/MSC	29-Dec-00	N/A					NOT APPLICABLE
SN:16754	HRS	0						
	AFL	0						
PROC. REF: AMM 23-12-08								
231204	STANDBY POWER AMPLIFIER/ANTENNA COUPLER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02								
231205	HF ANTENNA							Component ATA:23
PN:5489123-2	MOS/MSC	19-Dec-17	O/C	TSN 0				
SN:UNKNOWN	HRS	4237.9		TSN 0				
	AFL	2753		TSN 0				
PROC. REF: AMM 23-12-03								
231207	NO. 1 HF CONTROL UNIT							Component ATA:23
PN:064-1016-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:11183	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231208	NO. 2 HF CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-04								
231209	HF AUDIO ADAPTER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-05								
231210	HF COMMUNICATION FUSE BOX ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-06								
231211	(CBR8) HF REMOTE CIRCUIT BREAKER							Component ATA:23
PN:10RC1C-25	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:7369	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-07								
231212	UPPER HF POWER AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02								
231213	LOWER HF POWER AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02								
231271	HF GROUND ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231301	FLITEPHONE TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-13-01								
231302	FLITEPHONE ANTENNA							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-13-02								
231303	COCKPIT FLITEPHONE BASE - CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-13-03								
231304	CABIN FLITEPHONE BASE - CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-13-03								
231305	COCKPIT ASSEMBLY PHONE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231306	CABIN ASSEMBLY PHONE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231307	COCKPIT FLIGHT PHONE (TT-3000) HANDSET							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231308	CABIN FLIGHT PHONE (TT-3000) HANDSET							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231310	AIRBORNE RADIO TELECOMMUNICATIONS TRAY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231312	CABIN DISTRIBUTION BUS REPEATER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231313	LEFT CABIN DISTRIBUTION, FLITEFONE REPEATER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231314	RIGHT CABIN DISTRIBUTION, FLITEFONE REPEATER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231315	CALL ALERTER, FLITEFONE SWITCH							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231316	ASSEMBLY, ARTU TRAY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231317	MAGNASTAR (C-2000/C-750 TMU) ARTU							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231319	MAGNASTAR ANALOG INTERFACE UNIT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231320	AIRSAT 1 TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231321	AIRSAT 1 HANDSET							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231335	CELLULAR PHONE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231340	CELL PHONE ANTENNA							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231351	SATELLITE DATA (SDU) UNIT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231401	SELCAL CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-14-01								
231402	SELCAL DECODER							Component ATA:23
PN:2800-0012-105	MOS/MSC	23-Oct-02	O/C	TSN 0				
SN:1052298	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 23-14-02								
231403	SELCAL SONALERT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-14-03								
231501	PASSENGER BRIEFER CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-01								
231502	PASSENGER BRIEFER COMPUTER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-02								
232001	IRIDIUM SATCOM TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232005	IRIDIUM SATCOM ANTENNA							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232010	COCKPIT IRIDIUM SATCOM PHONE ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232015	CABIN IRIDIUM SATCOM PHONE ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232020	AIRCELL IRIDIUM SATPHONE (CORDLESS HANDSET)							Component ATA:23
PN:310-10590-002	MOS/MSC	04-Nov-13	O/C					
SN:UNKNOWN	HRS	3381.6						
	AFL	2211						
PROC. REF: GENERIC NO REF								
232025	CABIN IRIDIUM SATCOM HANDSET							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232030	IRIDIUM SATCOM PHONE CRADLE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232035	IRIDIUM SATCOM PHONE CRADLE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232040	IRIDIUM SATCOM CORDLESS BASE UNIT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232045	IRIDIUM SATCOM CORDLESS BASE UNIT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232055	UNILINK (UL-601) PROCESSOR							Component ATA:23
PN:1066-10-000	MOS/MSC	28-Oct-02	O/C	TSN 0				
SN:235	HRS	26		TSN 0				
	AFL	24		TSN 0				
PROC. REF: GENERIC NO REF								
232105	VHF DATA LINK TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01								
232110	COMMUNICATION MANAGEMENT (CMU) UNIT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232111	CMU EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
232120	AIRCELL ANTENNA							Component ATA:23
PN:015-10306-001	MOS/MSC	04-Nov-13	O/C					
SN:UNKNOWN	HRS	3381						
	AFL	2211						
PROC. REF: GENERIC NO REF								
232501 ^U	AIRCELL IRIDIUM SATPHONE TRANSCEIVER							Component ATA:23
PN:400-1 0680-002	MOS/MSC	04-Nov-13	O/C					
SN:UNKNOWN	HRS	3381						
	AFL	2211						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232510 ^U	INSPECT AND FUNCTIONAL CHECK OF THE ATG 5000 SYSTEM AND COMPONENTS							Service ATA:23
	MOS	11-Mar-22	12		11-Mar-23		59 d	ICA
	HRS	5539.1						
	AFL	3670						
232515 ^U	EDDY CURRENT INSPECT FUSELAGE SKIN IN THE VICINITY OF THE TWO AIRCELL ATG-5000 ANTENNA							Service ATA:23
	MOS	12-Dec-16						ICA
	HRS	3980.4						
	AFL	2628	T:12000		14628		10923	
232524 ^U	INSPECT TRANSCEIVER, ROUTER AND CONFIGURATION MODULE WIRE HARNESS FOR ATG 5000 AND AXCESS SYSTEM							Service ATA:23
	MOS	23-Mar-21	48		23-Mar-25		802 d	ICA
	HRS							
	AFL							
233001	LEFT FORWARD CABIN STEREO SPEAKER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01								
233002	RIGHT FORWARD CABIN STEREO SPEAKER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01								
233003	LEFT AFT CABIN STEREO SPEAKER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01								
233004	RIGHT AFT CABIN STEREO SPEAKER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233005	PASSENGER SPEAKER AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-02								
233007	DVD PLAYER							Component ATA:23
PN:FD932DVD-LP	MOS/MSC	15-Nov-16	O/C					
SN:1544819023-RS	HRS	3980.4						
	AFL	2628						
PROC. REF: GENERIC NO REF								
233023	FORWARD WOOFER, CABIN SPEAKER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01								
233024	AFT WOOFER, CABIN SPEAKER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01								
233026	VIDEO CASSETTE PLAYER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233030	CONFIGURATION MODULE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233040	INFRARED REMOTE CONTROL							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233051	CD CHANGER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233052	CONTROL HEAD CD CHANGER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233075	CABIN DISPLAY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233084	FORWARD 15.1 LCD COLOR DISPLAY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233085	FORWARD VIDEO MONITOR-							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233086	AFT VIDEO MONITOR-							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233087	FORWARD 10.4 LCD COLOR DISPLAY							Component ATA:23
PN:AI-LCD104-01-1	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:120001494	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233088	AFT 15.1 LCD COLOR DISPLAY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233101	STEREO ANTENNA							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-01								
233102	STEREO							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-02								
233103	STEREO BATTERY							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-03								
233104	STEREO VOLTAGE REGULATOR							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-04								
233105	AUDIO DISTRIBUTION MODULE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-05								
233106	LEFT DIGITAL SELECTOR MODULE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233107	RIGHT DIGITAL SELECTOR MODULE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-06								
234101	INTERPHONE AUDIO AMPLIFIER							Component ATA:23
PN:MODEL 204	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1758	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-41-01								
235001	PILOT AUDIO CONTROL PANEL							Component ATA:23
PN:802-002	MOS/MSC	28-Oct-02	O/C	TSN 0				
SN:789	HRS	26		TSN 0				
	AFL	24		TSN 0				
PROC. REF: AMM 23-50-01								
235002	COPILOT AUDIO CONTROL PANEL							Component ATA:23
PN:802-002	MOS/MSC	20-Jan-03	O/C	TSN 0				
SN:580	HRS	110		TSN 0				
	AFL	86		TSN 0				
PROC. REF: AMM 23-50-01								
235003	LEFT AUDIO AMPLIFIER							Component ATA:23
PN:700-002	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:603	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-02								
235004	RIGHT AUDIO AMPLIFIER							Component ATA:23
PN:700-002	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:590	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-02								
236005	WEATHER WORX XM RADIO CONTROLLER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
236010	WEATHER WORX XM DATA PORT							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
237001	COCKPIT VOICE (CVR) RECORDER							Component ATA:23
PN:1602-01-3	MOS/MSC	23-Oct-02	O/C	TSN 0				
SN:801	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 23-70-01								
237002	CVR REMOTE MICROPHONE AMPLIFIER							Component ATA:23
PN:1635-02	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:231	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-03								
237003	CVR REMOTE AREA MICROPHONE							Component ATA:23
PN:16301-01	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:723	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-04								
237004	CVR INERTIA SWITCH							Component ATA:23
PN:3L0-453/8	MOS/MSC	23-Oct-02	O/C	TSN 0				
SN:L09719	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 23-70-05								
237021	CVR UNDERWATER LOCATOR (ULB) BEACON							Component ATA:23
PN:DK120	MOS/MSC	17-Jul-17	O/C	TSN 0				
SN:SD02413	HRS	4120.6		TSN 0				
	AFL	2700		TSN 0				
	APH	1129						
	ACH	1275.9						
PROC. REF: AMM 25-63-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
237021A	CLEAN/FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY							Service ATA:23
	MOS	08-Jul-21	24 (+14d/-14d)		08-Jul-23	22-Jul-23	178 d (+14)	
	HRS							
	AFL							
	PROC. REF: AMM 25-63-00							
237021B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000							Service ATA:23
	MOS/MSC	17-Jul-17	DUE		31-Jul-23 (M)		201 d	
	HRS	4120.6						
	AFL	2700						
	APH	1129						
	ACH	1275.9						
	PROC. REF: AMM 25-63-00							
237021C ^U	CVR INTELLIGIBILITY TEST IAW CAR 625							Service ATA:23
	MOS/MSC	02-May-22	A/R					
	HRS	5542.1						
	AFL	3671						
237032	AUDIO/VIDEO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 23-41-01							
238001	NO. 1 RADIO TUNING (RTU) UNIT							Component ATA:23
PN:822-1123-102	MOS/MSC	14-Dec-22	O/C					
SN:CY2J	HRS	5584.2						
	AFL	3705						
	PROC. REF: AMM 23-80-01							
238002	NO. 2 RADIO TUNING (RTU) UNIT							Component ATA:23
PN:822-1123-102	MOS/MSC	14-Dec-22	O/C					
SN:1910	HRS	5584.2						
	AFL	3705						
	PROC. REF: AMM 23-80-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
239007	NO. 1 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
239008	NO. 2 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
239009	NO. 3 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
239015	ORDINANCE SIGN SWITCH							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
239016	AUDIO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-41-01								
239501 ^U	ATG 5000 UNIT							Component ATA:23
PN:P15864-001	MOS/MSC	09-May-18	O/C					
SN:1586418363	HRS	4350.8						
	AFL	2818						
239502 ^U	GOGO BIZ UCS-500 WIFI CABIN ROUTER							Component ATA:23
PN:PN	MOS/MSC	20-Dec-16	O/C					
SN:UNKNOWN	HRS	3980.4						
	AFL	2628						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
239502A ^U	INSPECT GOGO BIZ UCS-500 WIFI CABIN ROUTER							Service ATA:23
PN:PN	MOS	23-Mar-21	24		23-Mar-23		71 d	
SN:UNKNOWN	HRS	5214.4						
	AFL	3422						
239503 ^U	FWD GOGO BIZ WIFI SYSTEM ANTENNA							Component ATA:23
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
239504 ^U	AFT GOGO BIZ WIFI SYSTEM ANTENNA							Component ATA:23
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
239505 ^U	CONFIGURATION MODULE							Component ATA:23
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
23CUS1 ^U	GENERAL VISUAL INSPECTION COLLINS VHF-422C/D COMMUNICATION SYSTEM PER STC							Service ATA:23
	MOS	11-Mar-22	12		11-Mar-23		59 d	ICA
	HRS	5539.1						
	AFL	3670						
23CUS2 ^U	GENERAL VISUAL INSPECTION OF AIRSHOW 400 CABIN VIDEO SYSTEM PER STC							Service ATA:23
	MOS/MSC	11-Jan-19	A/R					ICA
	HRS	4603.9						
	AFL	2964						
23CUS3 ^U	GENERAL VISUAL INSPECTION OF AVIONICS INSTRUMENT 1200 VA 115VAC/60HZ INVERTER PER STC							Service ATA:23
	MOS	11-Mar-22	12		11-Mar-23		59 d	ICA
	HRS	5539.1						
	AFL	3670						
23CUS4 ^U	GENERAL VISUAL INSPECTION OF COLLINS TCAS 4000 SYSTEM PER STC							Service ATA:23
	MOS	11-Mar-22	12		11-Mar-23		59 d	ICA
	HRS	5539.1						
	AFL	3670						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
E2360010 ^S	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00)							Service ATA:23
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 23-60-00							PKG:6
E2360011 ^S	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00)							Service ATA:23
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 23-60-00							PKG:6
H2360021 ^S	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.)							Service ATA:23
	MOS	26-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 23-60-00							PKG:22
P2360022 ^S	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.)							Service ATA:23
	MOS	26-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 23-60-00							PKG:24
ATA 24 - ELECTRICAL POWER								
05-10-29-B2432010	INSPECT MAIN AIRCRAFT BATTERY INSTALLATION							Service ATA:24
	MOS	07-Oct-22	6 (+14d/-14d)		07-Apr-23	21-Apr-23	86 d (+14)	
	HRS							
	AFL							
	PROC. REF: AMM 24-31-01							
05-10-29-H2431017	PERFORM BATTERY CABLES & RECEPTACLES - BATTERY CONNECTOR INSPECTION							Service ATA:24
	MOS	01-Nov-21						
	HRS	5529	300 (+25/-25)		5829	5854	244.8 (+25)	
	AFL	3656						
	PROC. REF: AMM 24-31-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242001	LEFT PRIMARY AC POWER INVERTER							Component ATA:24
PN:6608483-1	MOS/MSC	26-Oct-18	O/C					
SN:1860	HRS	4496.5						
	AFL	2901						
PROC. REF: AMM 24-20-01								
242002	RIGHT SECONDARY AC POWER INVERTER							Component ATA:24
PN:6608483-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1795	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-20-01								
242003	POWER MONITOR INDICATOR							Component ATA:24
PN:11003-003	MOS/MSC	28-Oct-18	O/C					
SN:94451	HRS	4502.1						
	AFL	2903						
PROC. REF: AMM 24-20-03								
242005	ISOLATION PARALLELING BOX							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
242009	NO. 1 GROUND FAULT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
242010	NO. 2 GROUND FAULT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
242016	GENERATOR CONTROL PANEL							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242031	DC AMMETER SENSOR							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05								
242032	NO. 1 DC CURRENT SENSOR							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05								
242033	NO. 2 DC CURRENT SENSOR							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05								
242081	1200 VA, 115 VAC, 60 HZ INVERTER							Component ATA:24
PN:2D1200-1A-1011	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:GB000660	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 24-20-01								
242505	GROUND FAULT INTERRUPTER							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
242507	60HZ POWER SYSTEM ANEROID SWITCH							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243001	NO. 1 STARTER/GENERATOR							Component ATA:24
PN:400SG138Q	MOS/MSC	04-Aug-20	O/C	TSO 0				
SN:2394	HRS	4944		TSO 0				
	AFL	3213		TSO 0				
PROC. REF: AMM 24-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243001A	OVERHAUL NO. 1 STARTER/GENERATOR - (Y2431025)							Service ATA:24
PN:400SG138Q	MOS	04-Aug-20						OVERHAUL
SN:2394	HRS	4944	1000 (+25/-25)		5944	5969	359.8 (+25)	
	AFL	3213						
PROC. REF: GENERIC NO REF								
243002	NO. 2 STARTER/GENERATOR							Component ATA:24
PN:400SG138Q	MOS/MSC	20-Jan-21	O/C	TSO 0				
SN:1365	HRS	5171.2		TSO 0				
	AFL	3384		TSO 0				
PROC. REF: AMM 24-30-01								
243002A	OVERHAUL NO. 2 STARTER/GENERATOR - (Y2431025)							Service ATA:24
PN:400SG138Q	MOS	20-Jan-21						OVERHAUL
SN:1365	HRS	5171.2	1000 (+25/-25)		6171.2	6196.2	587 (+25)	
	AFL	3384						
PROC. REF: GENERIC NO REF								
243003	APU STARTER/GENERATOR							Component ATA:24
PN:400SG159Q	MOS/MSC	22-Oct-21	O/C	TSO 0				
SN:2752	HRS	5512.1		TSO 0				
	AFL	3646		TSO 0				
PROC. REF: GENERIC NO REF, SMM 49-11-02								
243003A	OVERHAUL/REPLACE APU STARTER/GENERATOR BRUSHES							Service ATA:24
PN:400SG159Q	MOS	22-Oct-21						
SN:2752	HRS	5512.1						
	AFL	3646						
	APH	2060	1000		3060		981	
PROC. REF: GENERIC NO REF								
243005	LEFT (GCU) GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG505-16B	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1407B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243006	RIGHT (GCU) GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG505-16B	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1413B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-03								
243007	A11 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:GTSG-700	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2765	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04								
243008	2A11 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:GTSG-700	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2764	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04								
243009	A12 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:GTSG-700	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2679	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04								
243010	2A12 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:GTSG-700	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2662	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04								
243011	LEFT DC AMMETER CURRENT SENSOR							Component ATA:24
PN:256-1	MOS/MSC	24-May-18	O/C	TSN 0				
SN:00091	HRS	4364.6		TSN 0				
	AFL	2827		TSN 0				
PROC. REF: AMM 24-30-05								
243012	RIGHT DC AMMETER CURRENT SENSOR							Component ATA:24
PN:256-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:38119	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243019	UPPER MAIN AIRCRAFT - NICAD BATTERY							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-01								
243019A	SERVICE UPPER MAIN AIRCRAFT - NICAD BATTERY							Service ATA:24
PN:PN	MOS/MSC	29-Dec-00	N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 12-22-00								
243020	LOWER MAIN AIRCRAFT - NICAD BATTERY							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-01								
243020A	SERVICE LOWER MAIN AIRCRAFT - NICAD BATTERY							Service ATA:24
PN:PN	MOS/MSC	29-Dec-00	N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 12-22-00								
243049	UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY							Component ATA:24
PN:RG-380E/60L	MOS/MSC	07-Oct-22	O/C					VENDOR RECOMMENDED
SN:41041271	HRS	5563.7						
	AFL							
PROC. REF: AMM 24-31-01								
243049A	SERVICE UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY SUMP JAR - 05-10-29-G1222002							Service ATA:24
PN:RG-380E/60L	MOS/MSC		N/A					N/A EQUIPMENT NOT INSTALLED
SN:41041271	HRS							
	AFL							
PROC. REF: AMM 12-22-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243049B	CAPACITY CHECK UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002							Service ATA:24
PN:RG-380E/60L	MOS	07-Oct-22	6		07-Apr-23		86 d	
SN:41041271	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 12-22-00								
243050	LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY							Component ATA:24
PN:RG-380E/60L	MOS/MSC	07-Oct-22	O/C					VENDOR RECOMMENDED
SN:41173006	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 24-31-01								
243050A	SERVICE LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY SUMP JAR - 05-10-29-G1222002							Service ATA:24
PN:RG-380E/60L	MOS/MSC		N/A					N/A EQUIPMENT NOT INSTALLED
SN:41173006	HRS							
	AFL							
PROC. REF: AMM 12-22-00								
243050B	CAPACITY CHECK LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002							Service ATA:24
PN:RG-380E/60L	MOS	07-Oct-22	6		07-Apr-23		86 d	
SN:41173006	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 12-22-00								
243051	NO. 1 MAIN - SEALED RECUMBANT BATTERY							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-01								
243051A	SERVICE NO. 1 MAIN - SEALED RECUMBANT BATTERY - 05-10-29-G1222001							Service ATA:24
PN:PN	MOS/MSC	29-Dec-00	N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 12-22-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243052	NO. 2 MAIN - SEALED RECUMBANT BATTERY							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-01								
243052A	SERVICE NO. 2 MAIN - SEALED RECUMBANT BATTERY 05-10-29-G1222001							Service ATA:24
PN:PN	MOS/MSC	29-Dec-00	N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 12-22-00								
243055	EMERGENCY POWER (24VDC TO 5VDC) CONVERTER							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243062	NO. 1 EMERGENCY POWER BATTERY							Component ATA:24
PN:501-1712-02	MOS/MSC	11-Mar-22	O/C					
SN:1462	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 24-32-01								
243062A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 1 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010							Service ATA:24
PN:501-1712-02	MOS	04-Oct-22	6 (+14d/-14d)		04-Apr-23	18-Apr-23	83 d (+14)	
SN:1462	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 24-32-01								
243062B	PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 1 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015							Service ATA:24
PN:501-1712-02	MOS	11-Mar-22	12 (+14d/-14d)		11-Mar-23	25-Mar-23	59 d (+14)	
SN:1462	HRS	5539.1						
	AFL	3670						
PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243063	NO. 2 EMERGENCY POWER BATTERY							Component ATA:24
PN:501-1712-02	MOS/MSC	11-Mar-22	O/C					
SN:1840	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 24-32-01								
243063A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010							Service ATA:24
PN:501-1712-02	MOS	04-Oct-22	6 (+14d/-14d)		04-Apr-23	18-Apr-23	83 d (+14)	
SN:1840	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 24-32-01								
243063B	PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015							Service ATA:24
PN:501-1712-02	MOS	11-Mar-22	12 (+14d/-14d)		11-Mar-23	25-Mar-23	59 d (+14)	
SN:1840	HRS	5539.1						
	AFL	3670						
PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170								
243064	NO. 3 EMERGENCY POWER BATTERY							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-32-01								
243064A ^S	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 3 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010							Service ATA:24
PN:PN	MOS/MSC		N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 24-32-01								
243064B ^S	PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 3 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015							Service ATA:24
PN:PN	MOS/MSC		N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243103	BATTERY TEMPERATURE INDICATOR							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-03								
243301	NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK							Component ATA:24
PN:M6088352-025	MOS/MSC	01-Aug-18	O/C					
SN:N/A	HRS	4427.8						
	AFL	2859						
PROC. REF: GENERIC NO REF								
243301A	CHARGE NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030							Service ATA:24
PN:M6088352-025	MOS	11-Mar-22	12 (+14d/-14d)	11-Mar-23	25-Mar-23	59 d (+14)		
SN:N/A	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 12-23-02								
243302	NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK							Component ATA:24
PN:M6088352-025	MOS/MSC	01-Aug-18	O/C					
SN:N/A	HRS	4427.8						
	AFL	2859						
PROC. REF: GENERIC NO REF								
243302A	CHARGE NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030							Service ATA:24
PN:M6088352-025	MOS	11-Mar-22	12 (+14d/-14d)	11-Mar-23	25-Mar-23	59 d (+14)		
SN:N/A	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 12-23-02								
244002	GROUND POWER MONITOR-							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-40-02								
245001	PILOT CIRCUIT BREAKER PANEL							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
245002	COPILOT CIRCUIT BREAKER PANEL							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-01								
245003	LEFT OVERLOAD (CBR2) SENSOR							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-03								
245004	RIGHT OVERLOAD (CBR2) SENSOR							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-03								
245055	DUAL BOOST CONVERTER							Component ATA:24
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
24CUS1A ^U	INSPECT FLIGHT DISPLAY USB CHARGERS							Service ATA:24
PN:UNKNOWN	MOS	11-Mar-22	12		11-Mar-23		59 d	ICA
SN:UNKNOWN	HRS	5539.1						
	AFL	3670						
AA2432003 ^S	PERFORM OPERATIONAL CHECK OF AC POWER SYSTEM							Service ATA:24
	MOS	11-Apr-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 24-20-00								
PKG:19								
H2400004 ^S	INSPECT PEDESTAL INTERIOR WIRING FOR WIRE ROUTING, CLEARANCES, DETERIORATION, AND GENERAL CONDITION.							Service ATA:24
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								
PKG:14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
H2432001 ^S	OPERATIONAL CHECK EMERGENCY DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-51-00.)							Service ATA:24
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 24-51-00							PKG:13	
H2450021 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.							Service ATA:24
	MOS	23-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:19	
P2400008 ^S	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCE, AND GENERAL CONDITION (THAT PORTION VISIBLE THROUGH WHEEL WELLS).							Service ATA:24
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:11	
Q2400006 ^S	PERFORM INSPECTION OF ALL 4 AWG OR GREATER ELECTRICAL CABLES. VERIFY THERE IS NO HEAT DAMAGE TO THE LARGE GAUGE WIRE TERMINAL CONNECTIONS TO THE POWER DISTRIBUTION ASSEMBLY. INSPECT CONNECTORS AND TERMINAL LUGS FOR CONDITION AND SECURITY. INSPECT CABLE ROUTING TO							Service ATA:24
	MOS	28-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:9	
T2400003 ^S	INSPECT ELECTRICAL WIRING, HYDRAULIC, AND PNEUMATIC LINES UNDER FLOORBOARDS FOR EVIDENCE OF LEAKAGE, SECURITY OF CLAMPS, AND CONDITION. (REFER TO 5-10-00.)							Service ATA:24
	MOS	19-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:20	
T2400009 ^S	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCES SECURITY, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:24
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:15	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 24 - ELECTRICAL POWER									
T2432000 ^S	OPERATIONAL CHECK OF DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-50-00.)							Service	ATA:24
	MOS	15-Apr-19	96 (+14d/-14d)						
	HRS	4647.4	2400 (+25/-25)						
	AFL	2994							
	PROC. REF: AMM 24-50-00								PKG:19
T2450020 ^S	CHECK SWITCH AND CIRCUIT BREAKER PANELS FOR GENERAL CONDITION. ENSURE MARKINGS ARE CLEAR AND READABLE.							Service	ATA:24
	MOS	05-Sep-17	48 (+14d/-14d)						
	HRS	4170.4	1200 (+25/-25)						
	AFL	2721							
	PROC. REF: GENERIC NO REF								PKG:13
ATA 25 - EQUIPMENT/FURNISHINGS									
250000	STEREO/PAGE AMPLIFIER							Component	ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
	PROC. REF: GENERIC NO REF								
251001	PILOT CREW SEAT							Component	ATA:25
PN:3A213-0007-01-2	MOS/MSC	29-Dec-00	O/C	TSN 0					
SN:278910	HRS	0		TSN 0					
	AFL	0		TSN 0					
	PROC. REF: AMM 25-10-01								
251002	COPILOT CREW SEAT							Component	ATA:25
PN:3A213-0008-01-2	MOS/MSC	29-Dec-00	O/C	TSN 0					
SN:266251	HRS	0		TSN 0					
	AFL	0		TSN 0					
	PROC. REF: AMM 25-10-01								
251005	PILOT LIGHTED CHART HOLDER							Component	ATA:25
PN:10-62-01	MOS/MSC	04-Jun-01	O/C	TSN 0					
SN:3373	HRS	21		TSN 0					
	AFL	20		TSN 0					
	PROC. REF: AMM 25-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
251006	COPILOT LIGHTED CHART HOLDER							Component ATA:25
PN:10-62-01	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:3375	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 25-10-05								
252001	LEFT FORWARD PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05								
252002	RIGHT FORWARD PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05								
252003	LEFT MID PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05								
252004	RIGHT MID PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05								
252005	LEFT AFT PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05								
252006	RIGHT AFT PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252007	RIGHT PASSENGER DIVAN							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05								
252025	RIGHT LOWER DIFFUSER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-03								
252027	LEFT LOWER DIFFUSER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-03								
253007	LEFT FORWARD COLD CATHODE LAMP INVERTER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
253009	LEFT FORWARD COLD CATHODE LAMP INVERTER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
253010	RIGHT FORWARD COLD CATHODE LAMP INVERTER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
253012	RIGHT FORWARD COLD CATHODE LAMP INVERTER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
253052	VOLTAGE REGULATOR							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
253068	WARMER-LIQUID							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
253069	WARMER-LIQUID							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
253090	AM/FM/CASSETTE STEREO							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
256001	(ELT) EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:453-5000-(366)	MOS/MSC	11-Mar-22	O/C					
SN:210-05262	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-62-01								
256001A	INSPECT/FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:453-5000-(366)	MOS	11-Mar-22	12 (+14d/-14d)		11-Mar-23	25-Mar-23	59 d (+14)	
SN:210-05262	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-62-00								
256001C	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY (IF INSTALLED)							Service ATA:25
PN:453-5000-(366)	MOS/MSC		N/A					NOT INSTALLED
SN:210-05262	HRS							
	AFL							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256002 ^U	ELT BATTERY							Component ATA:25
PN:452-0133	MOS/MSC	27-Oct-21	DUE	TSN 0	01-Dec-26 (M)		1420 d	
SN:392611-006	HRS	5523.1		TSN 0				
	AFL	3652		TSN 0				
	Expiry Date: : 01-Dec-26							
256003	ELT CONTROLLER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: GENERIC NO REF							
256010	ELT/NAV INTERFACE							Component ATA:25
PN:453-6500	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:00689	HRS	21		TSN 0				
	AFL	20		TSN 0				
	PROC. REF: GENERIC NO REF							
256060 ^U	PERFORM ANNUAL INSPECTION OF ALL LIFE VESTS							Service ATA:25
	MOS	11-Mar-22	12		11-Mar-23		59 d	CUSTOMER CODE
	HRS	5539.1						
	AFL	3670						
	PROC. REF: OMM 6.3							
256061	NO. 1 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040088	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
	PROC. REF: GENERIC NO REF							
256061A	INSPECT NO. 1 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:16092040088	HRS	5539.1						
	AFL	3670						
	PROC. REF: AMM 25-61-00, CMM 25-60-05							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256062	NO. 2 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040042	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
256062A	INSPECT NO. 2 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:16092040042	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256063	NO. 3 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040066	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
256063A	INSPECT NO. 3 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:16092040066	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256064	NO. 4 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040062	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256064A	INSPECT NO. 4 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:16092040062	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256065	NO. 5 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040072	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
256065A	INSPECT NO. 5 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:16092040072	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256066	NO. 6 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040093	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
256066A	INSPECT NO. 6 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:16092040093	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-61-00, CMM 25-60-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256067	NO. 7 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040097	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
256067A	INSPECT NO. 7 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:16092040097	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256068	NO. 8 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040154	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
256068A	INSPECT NO. 8 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:16092040154	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256069A	INSPECT NO. 9 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS/MSC		N/A					
SN:L821367	HRS							
	AFL							
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256070	NO. 10 LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:L821362	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256070A	INSPECT NO. 10 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Mar-22	60		29-Sep-26 (M)		1357 d	
SN:L821362	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256071	PILOT LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040007	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
256071A	INSPECT PILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	29-Sep-21	60		29-Sep-26 (M)		1357 d	
SN:16092040007	HRS							
	AFL							
PROC. REF: AMM 25-61-00, CMM 25-60-05								
256072	COPILOT LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	30-Jan-17	O/C	TSN 0				
SN:16092040098	HRS	3983.4		TSN 0				
	AFL	2631		TSN 0				
	APH	1034						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
256072A	INSPECT COPILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS	29-Sep-21	60		29-Sep-26 (M)		1357 d	
SN:16092040098	HRS							
	AFL							
PROC. REF: AMM 25-61-00								
256075 ^U	LIFE RAFT							Component ATA:25
PN:PN	MOS/MSC	06-Nov-19	O/C					
SN:NOT INSTALLED	HRS	4714.7						
	AFL	3050						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256075A ^{U S}	INSPECT LIFE RAFT IAW MANUFACTURERS INSTRUCTIONS							Service ATA:25
PN:PN	MOS		12 (+14d/-14d)					
SN:NOT INSTALLED	HRS							
	AFL							
	APH							
	ACH							
256076	FIRST AID KIT							Component ATA:25
PN:70001-00	MOS/MSC	11-Mar-22	O/C	TSN 0				
SN:UNKNOWN	HRS	5539.1		TSN 0				
	AFL	3670		TSN 0				
PROC. REF: GENERIC NO REF								
256076A	CONDITION CHECK FIRST AID KIT INVENTORY & EXPIRATION DATES							Service ATA:25
PN:70001-00	MOS	11-Mar-22	12 (+10d/-10d)		11-Mar-23	21-Mar-23	59 d (+10)	
SN:UNKNOWN	HRS	5539.1						
	AFL	3670						
PROC. REF: GENERIC NO REF								
256076B	INSPECT FIRST AID KIT CONTENTS							Service ATA:25
PN:70001-00	MOS	11-Mar-22	12 (+10d/-10d)		11-Mar-23	21-Mar-23	59 d (+10)	
SN:UNKNOWN	HRS	5539.1						
	AFL	3670						
PROC. REF: GENERIC NO REF								
256078	EMERGENCY MEDICAL KIT							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
256116	ELT REMOTE SWITCH PANEL							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256202	ELT ANTENNA							Component ATA:25
PN:110-337	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:1023988	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 25-62-02								
256410	(ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
257101	NOSE AVIONICS EXHAUST BLOWER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-71-01								
258002-701 ^U	COCKPIT CONTROL - AIRSHOWW 400 UNIT							Component ATA:25
PN:911010-2	MOS/MSC	20-Jun-03	O/C	TSN 0				
SN:152	HRS	273						
	AFL	190						
258010	AIRSHOW DIGITAL INTERFACE UNIT							Component ATA:25
PN:920040	MOS/MSC	13-Sep-13	O/C	TSR 0				
SN:469	HRS	3379.4		TSR 0				
	AFL	2209		TSR 0				
PROC. REF: GENERIC NO REF								
258011	COCKPIT CONTROL - AIRSHOW UNIT							Component ATA:25
PN:911010-2	MOS/MSC	20-Jun-03	O/C					
SN:152	HRS	273						
	AFL	190						
PROC. REF: GENERIC NO REF								
258012	AIRSHOW FLIGHT DECK CONTROLLER							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
258014	FORWARD AIRSHOW COLOR MONITOR-							Component ATA:25
PN:AI-LCD104-01-1	MOS/MSC	17-May-18	O/C					
SN:02001693	HRS	4350.8						
	AFL	2818						
PROC. REF: GENERIC NO REF								
258015	AFT AIRSHOW COLOR MONITOR-							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
258016	FORWARD 10.4 LCD COLOR, AIRSHOW 400 DISPLAY							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
258017	AFT 10.4 LCD COLOR, AIRSHOW 400 DISPLAY							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
258020	AIRSHOW 400 VIDEO SWITCH PANEL							Component ATA:25
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
25CUS1 ^U	FLIGHT DISPLAY DVD PLAYER							Component ATA:25
PN:PN	MOS/MSC	27-Nov-13	O/C					
SN:UNKNOWN	HRS	3381						
	AFL	2211						
25CUS1A ^U	INSPECT FLIGHT DISPLAY DVD PLAYER							Service ATA:25
PN:PN	MOS	11-Mar-22	12		11-Mar-23		59 d	ICA
SN:UNKNOWN	HRS	5539.1						
	AFL	3670						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
E2510010 ^S	INSPECT CREW SEATS AND SEAT BELTS FOR OPERATION, SECURITY OF MOUNTING, AND GENERAL CONDITION							Service ATA:25
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF							PKG:1	
N2571002 ^S	PERFORM FUNCTIONAL TEST OF NOSE AVIONICS COMPARTMENT EXHAUST BLOWERS AND THEIR RESPECTIVE CONTROL TEMPERATURE SWITCHES. (REFER TO 25-71-01.)							Service ATA:25
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 25-71-01							PKG:14	
P2520007 ^S	INSPECT CABIN SEATS AND SEAT BELTS FOR CONDITION; BAGGAGE COMPARTMENT, STOWAGE CABINETS, STOWAGE CABINET LATCHES, RUGS, HEADLINER, AND SIDE PANELS FOR SECURITY AND CONDITION.							Service ATA:25
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF							PKG:2	
U2510005 ^S	GENERAL VISUAL INSPECTION GLARESHIELD, HEADLINER, AND TRIM STRIPS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00)							Service ATA:25
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF							PKG:1	
U2540004 ^S	INSPECT ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.							Service ATA:25
	MOS	28-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:8	
ATA 26 - FIRE PROTECTION								
261001	NO. 1 FIRE DETECTION CONTROL UNIT							Component ATA:26
PN:377-02833	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0032-004	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261002	NO. 2 FIRE DETECTION CONTROL UNIT							Component ATA:26
PN:377-02833	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0032-008	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02								
261006	TAILCONE BLEED AIR OVERHEAT (E267) CONTROL BOX							Component ATA:26
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-13-02								
261007	TAILCONE BLEED AIR OVERHEAT (E268) CONTROL BOX							Component ATA:26
PN:35009-20	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D1472	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-13-02								
261008	TAILCONE BLEED AIR OVERHEAT (E269) CONTROL BOX							Component ATA:26
PN:PN	MOS/MSC	29-Dec-00	-	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-13-02								
261042-701 ^U	SMOKE DETECTOR							Component ATA:26
PN:FR2222	MOS/MSC	22-Apr-15	O/C	TSN 0				
SN:FX1079	HRS	3616.4		TSN 0				
	AFL	2379		TSN 0				
261051	NO. 1 TEE DOUBLE CHECK VALVE							Component ATA:26
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-05								
261052	NO. 2 TEE DOUBLE CHECK VALVE							Component ATA:26
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261207	BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY							Component ATA:26
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-12-01								
262013	FORWARD FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:32700004-1	MOS/MSC	23-Mar-21	O/C	TSR 0				
SN:24919C1	HRS	5214.4		TSR 0				
	AFL	3422		TSR 0				
PROC. REF: AMM 26-21-03								
262013A	CHECK FORWARD FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY (REF TO 05-10-00)							Service ATA:26
PN:32700004-1	MOS	12-Oct-22	6 (+14d/-14d)		12-Apr-23	26-Apr-23	91 d (+14)	
SN:24919C1	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 26-21-00								
262013C	HYDROSTATIC TEST FORWARD FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:32700004-1	MOS	24-Aug-20	60 (+14d/-14d)		24-Aug-25	07-Sep-25	956 d (+14)	
SN:24919C1	HRS	4968						
	AFL	3228						
PROC. REF: GENERIC NO REF								
262014	AFT FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:32700004-1	MOS/MSC	08-Jan-19	O/C	TSO 28				
SN:12928C1	HRS	4603.9		TSO 643.4				
	AFL	2964		TSO 349				
PROC. REF: AMM 26-21-03								
262014A	CHECK AFT FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 05-10-00)							Service ATA:26
PN:32700004-1	MOS	12-Oct-22	6 (+14d/-14d)		12-Apr-23	26-Apr-23	91 d (+14)	
SN:12928C1	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 26-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262014C	HYDROSTATIC TEST AFT FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:32700004-1	MOS	18-Mar-21	60 (+14d/-14d)		18-Mar-26	01-Apr-26	1162 d (+14)	
SN:12928C1	HRS							
	AFL							
PROC. REF: GENERIC NO REF								
262036	FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Component ATA:26
PN:30903823	MOS	23-Mar-21	72 (+14d/-14d)	TSN 2	23-Jan-27	06-Feb-27	1473 d (+14)	SERVICE LIFE LIMIT
SN:NSN	HRS	5214.4		TSN 0				
	AFL	3422		TSN 0				
PROC. REF: AMM 26-21-04								
262036A	REPLACE FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Service ATA:26
PN:30903823	MOS	21-Mar-21	108 (+14d/-14d)		21-Mar-30	04-Apr-30	2626 d (+14)	LIFE LIMIT
SN:NSN	HRS							
	AFL							
PROC. REF: AMM 26-21-04								
262037	AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Component ATA:26
PN:AE30903823	MOS	11-Mar-22	72 (+14d/-14d)	TSN 0	11-Mar-28	25-Mar-28	1886 d (+14)	SERVICE LIFE LIMIT
SN:UNKNOWN	HRS	5539.1		TSN 0				
	AFL	3670		TSN 0				
PROC. REF: AMM 26-21-04								
262037A	REPLACE AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Service ATA:26
PN:AE30903823	MOS	01-Nov-21	108 (+14d/-14d)		01-Nov-30	15-Nov-30	2851 d (+14)	LIFE LIMIT
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 26-21-04								
262038	FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB							Component ATA:26
PN:30903823	MOS	23-Mar-21	72 (+14d/-14d)	TSN 2	23-Jan-27	06-Feb-27	1473 d (+14)	SERVICE LIFE LIMIT
SN:NSN	HRS	5214.4		TSN 0				
	AFL	3422		TSN 0				
PROC. REF: AMM 26-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262038A	REPLACE FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB							Service ATA:26
PN:30903823	MOS	21-Mar-21	108 (+14d/-14d)		21-Mar-30	04-Apr-30	2626 d (+14)	LIFE LIMIT
SN:NSN	HRS							
	AFL							
PROC. REF: AMM 26-21-04								
262039	AFT ENGINE FIRE EXTINGUISHER AFT SQUIB							Component ATA:26
PN:A30903823	MOS	11-Mar-22	72 (+14d/-14d)	TSN 0	11-Mar-28	25-Mar-28	1886 d (+14)	SERVICE LIFE LIMIT
SN:UNKNOWN	HRS	5539.1		TSN 0				
	AFL	3670		TSN 0				
PROC. REF: AMM 26-21-04								
262039A	REPLACE AFT ENGINE FIRE EXTINGUISHER AFT SQUIB							Service ATA:26
PN:A30903823	MOS	01-Nov-21	108 (+14d/-14d)		01-Nov-30	15-Nov-30	2851 d (+14)	LIFE LIMIT
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 26-21-04								
262041	PILOT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:A344	MOS/MSC	13-Jan-17	O/C	TSN 0				
SN:B-74105458	HRS	3981		TSN 0				
	AFL	2629		TSN 0				
	APH	1032						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service ATA:26
PN:A344	MOS	13-Jan-17	144 (+14d/-14d)		13-Jan-29	27-Jan-29	2194 d (+14)	
SN:B-74105458	HRS	3981						
	AFL	2629						
	APH	1032						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262042	COPILOT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:A344	MOS/MSC	13-Jan-17	O/C	TSN 0				
SN:B-78359645	HRS	3981		TSN 0				
	AFL	2629		TSN 0				
	APH	1032						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
262042B	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service ATA:26
PN:A344	MOS	13-Jan-17	144 (+14d/-14d)		13-Jan-29	27-Jan-29	2194 d (+14)	
SN:B-78359645	HRS	3981						
	AFL	2629						
	APH	1032						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
262045	NO. 1 ENGINE FIRE - PULL SWITCH							Component ATA:26
PN:6608480-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:475	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-01								
262046	NO. 2 ENGINE FIRE - PULL SWITCH							Component ATA:26
PN:6608480-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:526	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-01								
262050	APU FIRE EXTINGUISHER							Component ATA:26
PN:50-1200	MOS/MSC	02-Jan-16	O/C	TSN 0				
SN:15-1017	HRS	3794.9		TSN 0				
	AFL	2502		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-61-01								
262050C	INSPECT APU FIRE EXTINGUISHER WEIGHT CHECK AND REPLACE AS NECESSARY							Service ATA:26
PN:50-1200	MOS	11-Mar-22	12		11-Mar-23		59 d	
SN:15-1017	HRS							
	AFL							
PROC. REF: GENERIC NO REF, SMM 49-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262051	CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:C352	MOS/MSC	13-Jan-17	O/C	TSN 0				
SN:C-32533459	HRS	3981		TSN 0				
	AFL	2629		TSN 0				
	APH	1032						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
262051B	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service ATA:26
PN:C352	MOS	13-Jan-17	144 (+14d/-14d)		13-Jan-29	27-Jan-29	2194 d (+14)	
SN:C-32533459	HRS	3981						
	AFL	2629						
	APH	1032						
	ACH	1195.9						
PROC. REF: GENERIC NO REF								
262057	APU FIRE BOTTLE SQUIB							Component ATA:26
PN:AE30900000M	MOS	23-Mar-21	60	TSN 0	23-Mar-26		1167 d	LIFE LIMIT
SN:998	HRS	5214.4		TSN 0				
	AFL	3422		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-61-04, SMM 49-11-03								
H2610010 ^S	INSPECT FIREWALL AND ACCESSORY GEARBOX FIRE DETECTOR ELEMENTS FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION.							Service ATA:26
	MOS	27-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
H2620020 ^S	DISCONNECT PLUMBING FROM THE FIRE EXTINGUISHER TWO-WAY CHECK VALVE ASSEMBLY. INSPECT FOR FREEDOM OF MOVEMENT OF THE TWO-WAY CHECK VALVE, EVIDENCE OF DEFECTS, WEAR, AND CORROSION. REPLACE VALVE CAP O-RING. (REFER TO 26-21-05.)							Service ATA:26
	MOS	15-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 26-21-05								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
P2620041 ^S	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:2
Q2620010 ^S	PERFORM WEIGHT CHECK OF FIRE EXTINGUISHER CONTAINERS. AFTER INSTALLATION OF CONTAINERS, PERFORM FUNCTIONAL TEST OF ENGINE FIRE EXTINGUISHER SYSTEM. (REFER TO 26-21-00).						Service	ATA:26
	MOS	24-Aug-20	24 (+14d/-14d)					
	HRS	4968	600 (+25/-25)					
	AFL	3228						
PROC. REF: AMM 26-21-00								PKG:9
T2614000 ^S	PERFORM FUNCTIONAL TEST OF BAGGAGE COMPARTMENT SMOKE DETECTOR SYSTEM. (REFER TO 26-12-00)						Service	ATA:26
	MOS	15-Mar-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 26-12-00								PKG:8
T2620045 ^S	INSPECT COPILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE						Service	ATA:26
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:1
T2620045 ^S	INSPECT PILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:1
U2610020A ^S	INSPECT NO. 1 ENGINE TAILCONE FIRE DETECTION ELEMENT						Service	ATA:26
	MOS	22-Apr-15						
	HRS	3616.4	3600 (+50)					
	AFL	2379						
PROC. REF: GENERIC NO REF								PKG:29

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
U2610020B ^S	INSPECT NO. 2 ENGINE TAILCONE FIRE DETECTION ELEMENT							Service ATA:26
	MOS	03-Jan-14						
	HRS	3401.1	3600 (+50)					
	AFL	2225						
PROC. REF: GENERIC NO REF							PKG:30	
ATA 27 - FLIGHT CONTROLS								
05-10-29-H2750044L	PERFORM DETAILED INSPECTION OF THE LEFT FLAP CAM FOLLOWER BEARING							Service ATA:27
	MOS	21-Feb-19						
	HRS	4647.4	1200 (+25/-25)		5847.4	5872.4	263.2 (+25)	
	AFL	2994						
PROC. REF: AMM 5-10-00								
05-10-29-H2750044R	PERFORM DETAILED INSPECTION OF THE RIGHT FLAP CAM FOLLOWER BEARING							Service ATA:27
	MOS	21-Feb-19						
	HRS	4647.4	1200 (+25/-25)		5847.4	5872.4	263.2 (+25)	
	AFL	2994						
PROC. REF: AMM 5-10-00								
05-11-00-E2710010L	REPLACE LEFT * AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)							Service ATA:27
	MOS	22-Apr-15						LIFE LIMIT
	HRS	3616.4	3600		7216.4		1632.2	
	AFL	2379						
PROC. REF: AMM 27-10-02								
05-11-00-E2710010R	REPLACE RIGHT * AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)							Service ATA:27
	MOS	22-Apr-15						LIFE LIMIT
	HRS	3616.4	3600		7216.4		1632.2	
	AFL	2379						
PROC. REF: AMM 27-10-02								
05-11-00-E2710013L	* REPLACE LEFT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)							Service ATA:27
	MOS	22-Apr-15						LIFE LIMIT
	HRS	3616.4	3600		7216.4		1632.2	
	AFL	2379						
PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2710013R	* REPLACE RIGHT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)							Service ATA:27
	MOS	22-Apr-15						LIFE LIMIT
	HRS	3616.4	3600		7216.4		1632.2	
	AFL	2379						
PROC. REF: AMM 27-10-02								
05-11-00-E2710020L	REPLACE LEFT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-E2710020R	REPLACE RIGHT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-E2710022L	* REPLACE LEFT AILERON SECTOR (5425105) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-10								
05-11-00-E2710022R	* REPLACE RIGHT AILERON SECTOR (5425105) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-10								
05-11-00-E2710024L	* REPLACE LEFT AILERON CLEVIS (2324517) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2710024R	* REPLACE RIGHT AILERON CLEVIS (2324517) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-E2710026L	REPLACE LEFT * AILERON YOKE ASSEMBLY (2324511) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-E2710026R	REPLACE RIGHT * AILERON YOKE ASSEMBLY (2324511) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-E2710028L	REPLACE LEFT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-E2710028R	REPLACE RIGHT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-E2710031L	REPLACE LEFT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2710031R	REPLACE RIGHT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: GENERIC NO REF								
05-11-00-E2720020	REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P5) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-20-01								
05-11-00-E2720022	REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-20-09								
05-11-00-E2720026	REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: GENERIC NO REF								
05-11-00-E2730021L	REPLACE LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-30-01								
05-11-00-E2730021R	REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2730022L	REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-30-01								
05-11-00-E2730022R	REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-30-01								
05-11-00-E2730024L	REPLACE LEFT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: GENERIC NO REF								
05-11-00-E2730024R	REPLACE RIGHT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: GENERIC NO REF								
05-11-00-E2740010	REPLACE * HORIZONTAL STABILIZER HINGE PIN (2331028) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-40-01								
05-11-00-E2750002L	REPLACE LEFT FLAP NOSE ROLLER BUSHINGS (NAS76A4)							Service ATA:27
	MOS	28-Apr-19						
	HRS	4647.4	1200 (+25/-25)		5847.4	5872.4	263.2 (+25)	
	AFL	2994						
PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2750002R	REPLACE RIGHT FLAP NOSE ROLLER BUSHINGS (NAS76A4)							Service ATA:27
	MOS	15-Apr-19						
	HRS	4647.4	1200 (+25/-25)		5847.4	5872.4	263.2 (+25)	
	AFL	2994						
	PROC. REF: AMM 27-50-01							
05-11-00-E2750035L	REPLACE LEFT * FLAP SECTOR (2625031) (AWL*)							Service ATA:27
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000		6000		2295	
	PROC. REF: AMM 27-50-01							
05-11-00-E2750035R	REPLACE RIGHT * FLAP SECTOR (2625031) (AWL*)							Service ATA:27
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000		6000		2295	
	PROC. REF: AMM 27-50-01							
05-11-00-E2760059L	REPLACE LEFT * SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14) (AWL*)							Service ATA:27
	MOS	25-Sep-18						LIFE LIMIT
	HRS	4478.3	4500		8978.3		3394.1	
	AFL	2886						
	PROC. REF: AMM 27-60-01							
05-11-00-E2760059R	REPLACE RIGHT * SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14) (AWL*)							Service ATA:27
	MOS	25-Sep-18						LIFE LIMIT
	HRS	4478.3	4500		8978.3		3394.1	
	AFL	2886						
	PROC. REF: AMM 27-60-01							
05-11-00-E2760061L	REPLACE LEFT * SPOILER ACTUATOR ARM (2422511) (AWL*)							Service ATA:27
	MOS	25-Sep-18						LIFE LIMIT
	HRS	4478.3	4500		8978.3		3394.1	
	AFL	2886						
	PROC. REF: AMM 27-60-04							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2760061R	REPLACE RIGHT * SPOILER ACTUATOR ARM (2422511) (AWL*)							Service ATA:27
	MOS	25-Sep-18						LIFE LIMIT
	HRS	4478.3	4500		8978.3		3394.1	
	AFL	2886						
PROC. REF: AMM 27-60-04								
05-11-00-E2760062L	REPLACE LEFT * SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	25-Sep-18						LIFE LIMIT
	HRS	4478.3	4500		8978.3		3394.1	
	AFL	2886						
PROC. REF: AMM 27-60-04								
05-11-00-E2760062R	REPLACE RIGHT * SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	25-Sep-18						LIFE LIMIT
	HRS	4478.3	4500		8978.3		3394.1	
	AFL	2886						
PROC. REF: AMM 27-60-04								
05-11-00-E2760063L	REPLACE LEFT * SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)							Service ATA:27
	MOS	25-Sep-18						LIFE LIMIT
	HRS	4478.3	4500		8978.3		3394.1	
	AFL	2886						
PROC. REF: AMM 27-60-04								
05-11-00-E2760063R	REPLACE RIGHT * SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)							Service ATA:27
	MOS	25-Sep-18						LIFE LIMIT
	HRS	4478.3	4500		8978.3		3394.1	
	AFL	2886						
PROC. REF: AMM 27-60-04								
05-11-00-E2760064LI	REPLACE LEFT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 27-60-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2760064LO	REPLACE LEFT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 27-60-04								
05-11-00-E2760064RI	REPLACE RIGHT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 27-60-04								
05-11-00-E2760064RO	REPLACE RIGHT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 27-60-04								
05-11-00-F2710036	REPLACE * PRIMARY AILERON CONTROL CABLES (AWL*)							Service ATA:27
	MOS	18-Apr-19					LIFE LIMIT	
	HRS	4647.4	2400		7047.4		1463.2	
	AFL	2994						
PROC. REF: AMM 27-10-07								
05-11-00-F2720029	REPLACE PRIMARY RUDDER CONTROL CABLES							Service ATA:27
	MOS	08-Mar-19						
	HRS	4647.4	2400 (+25/-25)		7047.4	7072.4	1463.2 (+25)	
	AFL	2994						
PROC. REF: AMM 27-20-10								
05-11-00-F2730030	REPLACE * PRIMARY ELEVATOR CONTROL SYSTEM CABLES (AWL*)							Service ATA:27
	MOS	08-Mar-19					LIFE LIMIT	
	HRS	4647.4	2400		7047.4		1463.2	
	AFL	2994						
PROC. REF: AMM 27-30-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-G2740011	REPLACE * HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS (NAS464P6) (AWL*)							Service ATA:27
	MOS	03-Aug-12	144		03-Aug-24		570 d	LIFE LIMIT
	HRS	3178.5						
	AFL	2065	6000		8065		4360	
PROC. REF: AMM 27-40-02								
05-11-00-G2750034L	REPLACE LEFT WING FLAP SECTOR MOUNTING BOLT							Service ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)		03-Aug-24	17-Aug-24	570 d (+14)	
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)		8065	8090	4360 (+25)	
PROC. REF: AMM 27-50-01								
05-11-00-G2750034R	REPLACE RIGHT WING FLAP SECTOR MOUNTING BOLT							Service ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)		03-Aug-24	17-Aug-24	570 d (+14)	
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)		8065	8090	4360 (+25)	
PROC. REF: AMM 27-50-01								
05-11-00-L2750027LI	REPLACE LEFT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-L2750027LO	REPLACE LEFT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-L2750027RI	REPLACE RIGHT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-L2750027RO	REPLACE RIGHT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-L2750028	REPLACE * INBOARD NOSE ROLLER TRACK (2322511) (AWL*)							Service ATA:27
	MOS	28-Apr-19						LIFE LIMIT
	HRS	4647.4						
	AFL	2994	20000		22994		19289	
PROC. REF: AMM 27-50-01								
05-11-00-L2750029	REPLACE * OUTBOARD NOSE ROLLER TRACK (2322512) (AWL*)							Service ATA:27
	MOS	15-Apr-19						LIFE LIMIT
	HRS	4647.4						
	AFL	2994	20000		22994		19289	
PROC. REF: AMM 27-50-01								
05-11-00-L2750033L	REPLACE LEFT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)							Service ATA:27
PN:PN	MOS	29-Dec-00						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	AFL	0	10000		10000		6295	
PROC. REF: AMM 27-50-01								
05-11-00-L2750033R	REPLACE RIGHT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)							Service ATA:27
PN:PN	MOS	29-Dec-00						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	AFL	0	10000		10000		6295	
PROC. REF: AMM 27-50-01								
05-11-00-M2710021	REPLACE * AILERON INBD & OUTBD HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-M2710021LI	REPLACE LEFT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-M2710021LO	REPLACE LEFT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-M2710021RI	REPLACE RIGHT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-M2710021RO	REPLACE RIGHT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-10-02								
05-11-00-M2730031	REPLACE * HINGE ASSEMBLIES (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 INBOARD)(LOCATED ON HORIZONTAL STABILIZER ASSEMBLY) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 27-30-01								
05-11-00-M2750049LI	REPLACE LEFT INBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-M2750049LO	REPLACE LEFT OUTBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-M2750049RI	REPLACE RIGHT INBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-M2750049RO	REPLACE RIGHT OUTBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-N2750025	REPLACE * INBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625023) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		2295	
PROC. REF: AMM 27-50-01								
05-11-00-N2750026	REPLACE * OUTBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625024) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		2295	
PROC. REF: AMM 27-50-01								
05-11-00-N2750031	REPLACE * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-1 THRU-8) (AWL*)							Service ATA:27
	MOS/MSC	29-Dec-00	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-N2750032	REPLACE * UPPER FLAP SECTOR BRACKET ASSEMBLY (6022511-1, -2, -801, AND -802) (AWL*)							Service ATA:27
	MOS	01-Mar-19						LIFE LIMIT
	HRS	4647.4						
	AFL	2994	3000		5994		2289	
PROC. REF: AMM 27-50-01								
05-11-00-N2750051	REPLACE * INBOARD FLAP HINGE FITTING (P/N 6025022) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-N2750051L	REPLACE * LEFT INBOARD FLAP HINGE FITTING (P/N 6025022) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-N2750051R	REPLACE * RIGHT INBOARD FLAP HINGE FITTING (P/N 6025022) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-N2750052	REPLACE * OUTBOARD FLAP HINGE FITTING (P/N 6025021) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-N2750052L	REPLACE * LEFT OUTBOARD FLAP HINGE FITTING (P/N 6025021) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-N2750052R	REPLACE * RIGHT OUTBOARD FLAP HINGE FITTING (P/N 6025021) (AWL*)							Service ATA:27
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-R2750050L	REPLACE LEFT UPPER * UPPER FLAP SECTOR BRACKET (AWL*)							Service ATA:27
PN:PN	MOS	29-Dec-00						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-R2750050R	REPLACE RIGHT UPPER * UPPER FLAP SECTOR BRACKET (AWL*)							Service ATA:27
PN:PN	MOS	29-Dec-00						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 27-50-01								
05-11-00-R2760079L	REPLACE LEFT LEFT * SPOILER ACTUATOR ATTACH FITTING AND BOLT (AWL*)							Service ATA:27
PN:PN	MOS	29-Dec-00						LIFE LIMIT
SN:UNKNOWN	HRS	0	10000		10000		4415.8	
	AFL	0						
PROC. REF: AMM 27-60-04								
05-11-00-R2760079R	REPLACE RIGHT RIGHT * SPOILER ACTUATOR ATTACH FITTING AND BOLT (AWL*)							Service ATA:27
PN:PN	MOS	29-Dec-00						LIFE LIMIT
SN:UNKNOWN	HRS	0	10000		10000		4415.8	
	AFL	0						
PROC. REF: AMM 27-60-04								
27-51-06-082	LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-06-082	LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01								
27-51-06-082	RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01								
27-51-06-082	RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01								
27-51-06-085	LEFT FLAP LEADING EDGE RIB							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01								
27-51-06-085	RIGHT FLAP LEADING EDGE RIB							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01								
270505	TRIM SWITCH PANEL ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-00-01								
271013	AILERON TRIM TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271015	LEFT AILERON BALANCE TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-03								
271016	RIGHT AILERON BALANCE TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-03								
271019	AILERON TRIM ACTUATOR							Component ATA:27
PN:6600156-034	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:B0057	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-11								
271025	PILOT CONTROL WHEEL							Component ATA:27
PN:2415151-017	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2560	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-01								
271026	COPILOT CONTROL WHEEL							Component ATA:27
PN:2415151-018	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2510	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-01								
271027	PILOT CONTROL COLUMN							Component ATA:27
PN:5415150-18-622	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:MRP477427	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-06								
271028	COPILOT CONTROL COLUMN							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271031	AILERON TRIM TAB ACTUATOR POTENTIOMETER							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-12								
271126	AILERON TRIM POSITION INDICATOR							Component ATA:27
PN:6608217-21	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:226	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-05								
271131	LEFT AILERON POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6435	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-06								
271132	RIGHT AILERON POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6439	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-06								
271701	* LEFT AILERON ASSEMBLY (AWL*)							Component ATA:27
PN:2424000-295	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:W606	HRS	0	20000	TSN 0	20000		14415.8	
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02								
271702	* RIGHT AILERON ASSEMBLY (AWL*)							Component ATA:27
PN:2424000-308	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:W587	HRS	0	20000	TSN 0	20000		14415.8	
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272001	* RUDDER ASSEMBLY (AWL*)							Component ATA:27
PN:5433000-20	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:W425	HRS	0	20000	TSN 0	20000		14415.8	
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-01								
272005	AFT RUDDER SECTOR							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-09								
272007	RUDDER TRIM TAB							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-02								
272013	RUDDER TRIM TAB ACTUATOR							Component ATA:27
PN:6600156-033	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5641	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-03								
272020	RUDDER TRIM TAB POTENTIOMETER							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-04								
272026	RUDDER TRIM INDICATOR							Component ATA:27
PN:6608217-20	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:241	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-06								
272031	PILOT RUDDER PEDAL ACTUATOR							Component ATA:27
PN:EM423-4	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:595	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272032	COPILOT RUDDER PEDAL ACTUATOR							Component ATA:27
PN:EM423-4	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:602	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-07								
273001	* LEFT ELEVATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2434000-177	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:W562	HRS	0	20000	TSN 0	20000		14415.8	
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01								
273002	* RIGHT ELEVATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2434000-178	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:W594	HRS	0	20000	TSN 0	20000		14415.8	
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01								
2730036	ELEVATOR BELLCRANKS - PERFORM EDDY CURRENT INSPECTION							Service ATA:27
	MOS	26-Apr-19	96		26-Apr-27		1566 d	
	HRS	4647.4	2400		7047.4		1463.2	
	AFL	2994						
PROC. REF: NDT 27-30-01								
273013	STALL WARNING COMPUTER							Component ATA:27
PN:6608263-18	MOS/MSC	01-Oct-21	O/C					
SN:1013	HRS	5471.4						
	AFL	3620						
PROC. REF: AMM 27-31-02								
273017	PILOT STICK SHAKER							Component ATA:27
PN:6608289-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:815A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273018	COPILOT STICK SHAKER							Component ATA:27
PN:6608289-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:814A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03								
273101	PILOT STALL WARNING TRANSDUCER							Component ATA:27
PN:25147A-12	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:GST03516	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01								
273102	COPILOT STALL WARNING TRANSDUCER							Component ATA:27
PN:25147A-12	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:GST03515	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01								
273105	PILOT ANGLE-OF-ATTACK (AOA) INDICATOR							Component ATA:27
PN:6608515-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:430	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-04								
273106	COPILOT ANGLE-OF-ATTACK (AOA) INDICATOR							Component ATA:27
PN:6608515-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:479	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-04								
273107	LEFT ANGLE OF ATTACK TRANSDUCER							Component ATA:27
PN:6608263-18	MOS/MSC	01-Oct-21	O/C					
SN:1013	HRS	5471.4						
	AFL	3620						
PROC. REF: AMM 27-31-01								
273108	RIGHT ANGLE OF ATTACK TRANSDUCER							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273110	ANGLE-OF-ATTACK (AOA) VANE							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-05								
274001	HORIZONTAL STABILIZER							Component ATA:27
PN:2332000-60	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:W318	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-01								
274003	HORIZONTAL STABILIZER ACTUATOR CONTROLLER							Component ATA:27
PN:6608444-2	MOS/MSC	10-May-19	O/C	TSN 0				
SN:1419A	HRS	4649.8		TSN 0				
	AFL	2998		TSN 0				
PROC. REF: AMM 27-40-03								
274010	TRIM-IN-MOTION DETECTOR							Component ATA:27
PN:6608326-004	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0047178	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-41-01								
274013	HORIZONTAL STABILIZER ACTUATOR							Component ATA:27
PN:5435005-028	MOS	04-Aug-21		TSO 1				OVERHAUL
SN:142	HRS	5402.6	600 (+25/-25)	TSO 0	6002.6	6027.6	418.4 (+25)	
	AFL	3560		TSO 0				
PROC. REF: AMM 27-40-02								
274062	PITCH TRIM INDICATOR							Component ATA:27
PN:6608514-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:228	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-04								
274070	STABILIZER POSITION SWITCH							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
274072	STABILIZER POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6454	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275001	* LEFT FLAP ASSEMBLY (AWL*)							Component ATA:27
PN:6025010-029	MOS	18-Apr-19						LIFE LIMIT
SN:W636	HRS	4647.4						
	AFL	2994	10000	TSN 2994, TSR 0	10000		6295	
PROC. REF: AMM 27-50-01								
275002	* RIGHT FLAP ASSEMBLY (AWL*)							Component ATA:27
PN:6025010-030	MOS	21-Mar-18						LIFE LIMIT
SN:W358	HRS	4310.5		TSN 4253.5				
	AFL	2793	10000	TSN 2767	10026		6321	
PROC. REF: AMM 27-50-01								
275005	LEFT LOWER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275005	LEFT UPPER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275005	RIGHT LOWER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275005	RIGHT UPPER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
2750058	* LEFT FLAP LEADING EDGE RIB - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	29-Dec-00	N/A					NOT APPLICABLE
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01								
2750058	* LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	29-Dec-00	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01								
2750058	* LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	29-Dec-00	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01								
2750058	* RIGHT FLAP LEADING EDGE RIB - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	29-Dec-00	N/A					NOT APPLICABLE
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01								
2750058	* RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	29-Dec-00	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01								
2750058	* RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	29-Dec-00	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01								
275010	FLAP & ENGINE SYNCHRONIZER RELAY BOX ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275012	FLAP POSITION POTENTIOMETER							Component ATA:27
PN:PN-UNKNOWN	MOS/MSC	16-Feb-21	O/C	TSN 0				
SN:UNKNOWN	HRS	5198		TSN 0				
	AFL	3399		TSN 0				
PROC. REF: AMM 27-50-09								
275019	LEFT LIMIT, INBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-05								
275020	RIGHT LIMIT, INBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-05								
275021	LEFT POSITION, OUTBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-04								
275022	RIGHT POSITION, OUTBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-04								
275031	FLAP CONTROL (FLAP/SPOILER) VALVE							Component ATA:27
PN:6600362-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:994A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-07								
275036	FLAP RESTRICTOR VALVE							Component ATA:27
PN:2R1047-0312	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2105	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275037	LEFT FLAP ACTUATOR							Component ATA:27
PN:6600493-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0320	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-08								
275038	RIGHT FLAP ACTUATOR							Component ATA:27
PN:6600493-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0318	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-08								
275200	FLAP POSITION INDICATOR							Component ATA:27
PN:6608475-004	MOS/MSC	06-Jan-21	O/C	TSO 0				
SN:115	HRS	5158.9		TSO 0				
	AFL	3375		TSO 0				
PROC. REF: AMM 27-50-10								
275213	FLAP PRESSURE RELIEF VALVE							Component ATA:27
PN:AN6245A4	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:18798	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-13								
275217	FLAP ACTUATION CHECK VALVE							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-12								
275407	FLAP SELECT SWITCH							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-03								
276001	* LEFT SPOILER ASSEMBLY (AWL*)							Component ATA:27
PN:2422510-137	MOS	25-Sep-18		TSN 0				LIFE LIMIT
SN:301	HRS	4478.3	4500	TSN 0	8978.3		3394.1	
	AFL	2886		TSN 0				
PROC. REF: AMM 27-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276002	* RIGHT SPOILER ASSEMBLY (AWL*)							Component ATA:27
PN:2422510-136	MOS	25-Sep-18		TSN 0				LIFE LIMIT
SN:315	HRS	4478.3	4500	TSN 0	8978.3		3394.1	
	AFL	2886		TSN 0				
PROC. REF: AMM 27-60-01								
276005	LEFT SPOILER FLOW CONTROL SERVO VALVE							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03								
276006	RIGHT SPOILER FLOW CONTROL SERVO VALVE							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03								
276007	LEFT SPOILER ACTUATOR ATTACH FITTING AND BOLT REMOVAL AND INSTALLATION							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-04								
276007	RIGHT SPOILER ACTUATOR ATTACH FITTING AND BOLT REMOVAL AND INSTALLATION							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-04								
276010	SPOILER COMPUTER							Component ATA:27
PN:6608454-3	MOS/MSC	18-Nov-03	O/C	TSN 0				
SN:1448	HRS	448		TSN 0				
	AFL	303		TSN 0				
PROC. REF: AMM 27-60-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276013	* LEFT SPOILER ACTUATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2417015-5	MOS	26-Apr-19		TSR 9				LIFE LIMIT
SN:1946	HRS	4647.4	10000	TSN 5823.5	8823.9		3239.7	
	AFL	2994						
	APH							
	ACH							
PROC. REF: AMM 27-60-04								
276014	* RIGHT SPOILER ACTUATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2417015-5	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:1990	HRS	0	10000	TSN 0	10000		4415.8	
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-04								
276037	LEFT SPOILER POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6413	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-07								
276038	RIGHT SPOILER POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6387	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-07								
276043	SPOILER POTENTIOMETER							Component ATA:27
PN:P30LS0GJS102KAG222	MOS/MSC	07-May-19	O/C	TSN 0				
SN:N/A	HRS	4649		TSN 0				
	AFL	2997		TSN 0				
PROC. REF: AMM 27-60-09								
276049	SPOILER POSITION INDICATOR							Component ATA:27
PN:6608476-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:236	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276110-701 ^U	#1 SPOILER COMPUTER							Component ATA:27
PN:6608454-3	MOS/MSC	18-Nov-03	O/C	TSN 0				
SN:1448.	HRS	448						
	AFL	303						
276128	SPOILER MANIFOLD VALVE							Component ATA:27
PN:2627023-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1025	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03								
276265	WHEEL SPEED DETECTION BOX							Component ATA:27
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-12								
AB2700049 ^S	REMOVE ALL PANELS REQUIRED TO GAIN ACCESS TO CABLES, PULLEYS, SECTORS, AND ASSOCIATED EQUIPMENT. VISUALLY INSPECT ACCESSIBLE PORTIONS OF FLIGHT CONTROLS FOR PROPER CONDITION, CABLE CLEARANCE, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO FLIGHT CONTROL CABLE CLEARANCES AT FUEL CROSSOVER TUBES.							Service ATA:27
	MOS	19-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:11
B2760050 ^S	PERFORM FUNCTIONAL TEST OF SPOILER (UP LIMIT) SWITCH. (REFER TO 27-60-05.)							Service ATA:27
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: AMM 27-60-05								PKG:28
C2700011 ^S	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.							Service ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
C2700013 ^S	WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (FLAPS,AILERONS, AND SPOILERS), INSPECT ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE						Service	ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
C2700019 ^S	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						Service	ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
C2700020 ^S	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						Service	ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
C2700022 ^S	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						Service	ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
C2700023 ^S	WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (RUDDER AND ELEVATORS), INSPECT ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERF						Service	ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
E2700031 ^S	CHECK ELEVATOR AND RUDDER CONTROL CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEY, PULLEY BRACKETS, AND GUARDS FOR SECURITY AND GENERAL CONDITION.							Service ATA:27
	MOS	19-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
E2700032 ^S	INSPECT CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION.							Service ATA:27
	MOS	18-Mar-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:8
E2710005 ^S	HOLD CONTROL WHEEL INA FIXED POSITION AND APPLY UP AND DOWN LOADS ON THE AILERON TRAILING EDGE. OBSERVE AILERON DRIVE ASSEMBLY AREA FOR WEAR IN SHAFT KEYWAYS, FAILURE OF BEARINGS, AND AILERON YOKE SLIPPAGE.							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:16
E2730025 ^S	INSPECT CONTROL COLUMNS (INCLUDING CONTROL WHEELS AND BOOTS) FOR CONDITION, PROPER OPERATION, AND CLEARANCES.							Service ATA:27
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:1
F2740020 ^S	REMOVE STABILIZER ACTUATOR. INSPECT UPPER AND LOWER ATTACHMENT STRUCTURE FOR FATIGUE CRACKS, DISTORTION, WEAR, CORROSION, AND GENERAL SECURITY.							Service ATA:27
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: AMM 27-40-02								PKG:27
H2700018 ^S	VISUALLY INSPECT SPOILER, FLAP, AILERON, AND AILERON TRIM TAB ELECTRICAL BONDING JMPERS FRO SECURITY AND GENERAL CONDITION.							Service ATA:27
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H2700021 ^S	INSPECT THE RUDDER AND ELEVATOR BALANCE WEIGHT INSTALLATIONS AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUC							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:18
H2700024 ^S	INSPECT THE AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUCTURE.							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:16
H2710032 ^S	CHECK AILERON, RUDDER, AND ELEVATOR CONTROL SYSTEM CABLE TENSIONS. (REFER TO 27-10-00, 27-20-00 AND 27-30-00.)							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 27-10-00, AMM 27-20-00, AMM 27-30-00								PKG:14
H2731000 ^S	PERFORM STALL WARNING SYSTEM FUNCTIONAL TEST. (REFER TO 27-31-00)							Service ATA:27
	MOS	23-Jun-21	24 (+14d/-14d)					
	HRS	5353.2	600 (+25/-25)					
	AFL	3523						
PROC. REF: AMM 27-31-00								PKG:7
P2700050 ^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.							Service ATA:27
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:1
P2700055 ^S	VISUALLY INSPECT ELEVATOR, RUDDER, AND RUDDER TRIM TAB ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION.							Service ATA:27
	MOS	18-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
P2700057 ^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.							Service ATA:27
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF							PKG:4	
P2710044 ^S	CHECK AILERON AND FLAP SYSTEM CONTROL CABLE TENSIONS. (REFER TO 27-10-00 AND 27-50-00.)							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 27-10-00, AMM 27-50-00							PKG:16	
P2710045 ^S	REMOVE CONTROL WHEEL SECTOR AND TURNBUCKLE COVERPLATE FROM CONTROL COLUMN. MOVE CONTROL WHEEL TO BOTH EXTREME RIGHT AND LEFT WHILE INSPECTING FOR FRAYED OR DAMAGED CABLES.							Service ATA:27
	MOS	19-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:8	
P2710046 ^S	DISASSEMBLE CONTROL COLUMN AS REQUIRED TO INSPECT PULLEYS, BEARINGS, ELECTRICAL WIRING FOR PROPER ROUTING AND CHAFING, AND CONTROL COLUMNS FOR GENERAL CONDITION.							Service ATA:27
	MOS	19-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:19	
P2760003 ^S	INSPECT SPOILER ACTUATOR INSTALLATION FOR SECURITY, SUPPORT STRUCTURE CRACKS, AND GENERAL CONDITION.							Service ATA:27
	MOS	19-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:10	
Q2700051 ^S	INSPECT RUDDER AND ELEVATOR CONTROLS (INCLUDING DOWNSPRING INSTALLATION WHEN INSTALLED AND PUSH-PULL TUBES) FOR PROPER OPERATION, GENERAL CONDITION AND SECURITY.							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:18	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2700017 ^S	INSPECT STRUCTURE, PULLEY BRACKETS, AND CONTROLS UNDER FLOORBOARDS FROM PEDESTAL AND CONTROL COLUMN AFT TO FRAME 24 FOR OPERATION, CLEARANCES, CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO THE ELEVATOR PULLEY BRACKET CUTOUT AREA RADIUS FOR CRACKS. (S							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:14	
T2700052 ^S	USING THE PROPER COCKPIT CONTROLS, CHECK FLAPS, SPOILERS, HORIZONTAL STABILIZER, AND TRIM TABS FOR PROPER OPERATION AND ACCURATE INDICATION.							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 27-40-00, AMM 27-50-00, AMM 27-60-00							PKG:13	
T2700056 ^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.							Service ATA:27
	MOS	25-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:12	
T2700058 ^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.							Service ATA:27
	MOS	21-Mar-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:20	
T2700059 ^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.							Service ATA:27
	MOS	22-Mar-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:24	
T2700060 ^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.							Service ATA:27
	MOS	22-Mar-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:22	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2710042 ^S	INSPECT AILERON AND AILERON TABS AND DRIVE MECHANISM FOR SECURITY, OPERATION, AND GENERAL CONDITION.							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 27-10-04							PKG:16	
T2720027 ^S	INSPECT RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS FOR SECURITY, PROPER OPERATION, AND CLEARANCES.							Service ATA:27
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:20	
T2730029 ^S	CHECK CONTROL COLUMN ASSEMBLY FREE PLAY. (REFER TO 27-30-06.)							Service ATA:27
	MOS	21-Mar-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 27-30-06							PKG:20	
T2731075 ^S	FUNCTIONAL TEST OF STALL WARNING ALTITUDE SWITCHES. (REFER TO 27-31-00.)							Service ATA:27
	MOS	18-Apr-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 27-31-00							PKG:19	
T2760030 ^S	INSPECT SPOILER AND HINGE INSTALLATION FOR SECURITY, CRACKS, AND GENERAL CONDITION.							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:16	
T2760031 ^S	INSPECT SPOILER CENTER ANGLE BRACKET RIVETS, LOWER SKIN CENTER RIB AND SUBSPAR RIVETS FOR EVIDENCE OF WORKING. WITH SPOILERS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO SPOILER TRAILING EDGE. CHECK MOTION AT CENTER HINGE. INSPECT SPOILER ACTUATOR MECHANISM AND							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:16	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2760040 ^S	FUNCTIONAL TEST OF SPOILER RESTRICTOR BYPASS VALVE COMPUTER CIRCUITRY AND WIRING. (REFER TO 27-60-03.)							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 27-60-03							PKG:16	
T2760084 ^S	VISUAL INSPECTION SPOILER CENTER ANGLE BRACKET RIVETS AND UPPER AND LOWER SKIN CENTER RIB AREA. (REFER TO 5-10-00.)							Service ATA:27
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF							PKG:4	
U2700033 ^S	INSPECT ALL CABLES, PULLEYS, SECTORS, AND PULLEY GUARD FOR PROPER OPERATION AND GENERAL CONDITION. PARTICULAR ATTENTION SHOULD BE GIVEN TO THOSE AREAS OF CABLES THAT PASS OVER PULLEYS, SECTORS, OR THROUGH FAIRLEADS.							Service ATA:27
	MOS	19-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:10	
U2710006 ^S	RUDDER TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK. (REFER TO 27-20-02.)							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 27-20-02							PKG:18	
U2710033 ^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK.							Service ATA:27
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 27-10-04							PKG:16	
U2710034 ^S	GENERAL VISUAL INSPECTION AILERON TRIM TAB INSTALLATION. (REFER TO 5-10-00.)							Service ATA:27
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF							PKG:4	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
U2710035 ^S	GENERAL VISUAL INSPECTION RUDDER TRIM TAB INSTALLATION. (REFER TO 5-10-00)							Service ATA:27
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:6
U2731050 ^S	VISUAL INSPECTION ANGLE-OF-ATTACK VANES. (REFER TO 5-10-00)							Service ATA:27
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:2
W2700062 ^S	CHECK CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION. (REFER TO 5-10-00.)							Service ATA:27
	MOS	19-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:8
ATA 28 - FUEL								
05-10-29-L2812002	INSPECT INNER WING STRUCTURE OUTBOARD OF WS 213.602							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								
05-10-29-L2812002L	INSPECT LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								
05-10-29-L2812002R	INSPECT RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
05-10-29-L2812010	INSPECT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								
05-10-29-L2812010L	INSPECT LEFT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								
05-10-29-L2812010R	INSPECT RIGHT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								
05-10-29-L2812020	INSPECT L/R INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								
05-10-29-L2812020L	INSPECT LEFT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								
05-10-29-L2812020R	INSPECT RIGHT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION							Service ATA:28
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
05-10-29-T2820012	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS							Service ATA:28
	MOS/MSC	23-Oct-02	-					
	HRS	21						
	AFL	20						
PROC. REF: AMM 28-20-04								
05-11-00-G2820003	REPLACE ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AIRCRAFT (PRESSURE)							Service ATA:28
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 28-00-00								
280002	FUEL CONTROL SWITCH PANEL ASEMBLY							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-02								
280003	LEFT WING DEFUEL VALVE							Component ATA:28
PN:6600145-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-03								
280004	RIGHT WING DEFUEL VALVE							Component ATA:28
PN:6600145-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3613	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-03								
280105	FUEL CONTROL OVERLAY ASSEMBLY							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281007	LEFT CHECK, CROSSFLOW VALVE							Component ATA:28
PN:7600004-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0042572	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281008	RIGHT CHECK, CROSSFLOW VALVE							Component ATA:28
PN:7600004-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00619135	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05								
281201	AFT FUSELAGE FUEL CELL							Component ATA:28
PN:6600501-003	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:83472	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01								
281202	FORWARD FUSELAGE FUEL CELL							Component ATA:28
PN:6600500-005	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:83471	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-02								
281283	FUSELAGE DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281301	LEFT WING FUEL VENT FLOAT VALVE							Component ATA:28
PN:6600346-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3659	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-01								
281302	RIGHT WING FUEL VENT FLOAT VALVE							Component ATA:28
PN:6600346-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3467	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-01								
281303	FUSELAGE FUEL VENT FLOAT VALVE							Component ATA:28
PN:6600346-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3661	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281305	LEFT WING FLAME ARRESTOR							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-03								
281306	RIGHT WING FLAME ARRESTOR							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-03								
281307	LEFT FUEL CELL PRESSURE RELIEF VALVE							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-07								
281308	RIGHT FUEL CELL PRESSURE RELIEF VALVE							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-07								
281309	FUSELAGE FLAME ARRESTOR							Component ATA:28
PN:9909018-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:418	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-09								
281401	LEFT FUSELAGE CELL TRANSFER PUMP							Component ATA:28
PN:2380060-43	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:C3312	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-01								
281402	RIGHT FUSELAGE CELL TRANSFER PUMP							Component ATA:28
PN:2380060-43	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:C3319	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281403	LEFT INBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02								
281404	RIGHT INBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02								
281405	LEFT CENTER WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02								
281406	RIGHT CENTER WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02								
281407	LEFT OUTBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02								
281408	RIGHT OUTBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02								
281409	LEFT SCAVENGE PUMP							Component ATA:28
PN:2380060-42	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:C3335	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281410	RIGHT SCAVENGE PUMP							Component ATA:28
PN:2380060-42	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:C3367	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-03								
281411	LEFT FUEL TRANSFER VALVE							Component ATA:28
PN:6600355-005	MOS/MSC	24-Oct-17	O/C	TSN 0				
SN:259644	HRS	4171.3		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: AMM 28-14-04								
281412	RIGHT FUEL TRANSFER VALVE							Component ATA:28
PN:6600355-4	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00811127	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-04								
281413	CROSSFLOW VALVE							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05								
281414	FUSELAGE HIGH-LEVEL FLOAT SWITCH							Component ATA:28
PN:L14F-94	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:207	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-07								
281415	LEFT FUEL TRANSFER PRESSURE INDICATING SWITCH							Component ATA:28
PN:7600002-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1053	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-06								
281416	RIGHT FUEL TRANSFER PRESSURE INDICATING SWITCH							Component ATA:28
PN:7600002-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1060	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281417	LEFT WING HIGH-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-8	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:11061	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-08								
281418	RIGHT WING HIGH-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-8	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:11120	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-08								
281419	LEFT WING LOW-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-8	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:11004	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-09								
281420	RIGHT WING LOW-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-8	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:11045	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-09								
281421	FUEL FILL AND TRANSFER BOX							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-10								
282001	LEFT INBOARD JET PUMP							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01								
282002	RIGHT INBOARD JET PUMP							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
2820021	WHEEL WELL AND KEEL BEAM AREA - PERFORM DETAILED VISUAL INSPECTION OF FUEL TUBE FERRULE ENDS (UNDERNEATH COUPLING ASSEMBLIES) BETWEEN FS 346 AND FS 421 (FRAMES 24 AND 31) FOR EVIDENCE OF FATIGUE CRACKS, CORROSION OR OTHER DEGRADATION							Service ATA:28
	MOS	EFF	36 (+14d/-14d)		18-Oct-24 *	01-Nov-24	646 d (+14)	
	HRS							
	AFL							
PROC. REF: AMM 28-20-00								
282003	LEFT STANDBY PUMP							Component ATA:28
PN:2380060-49	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:C3355	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-02								
282004	RIGHT STANDBY PUMP							Component ATA:28
PN:2380060-49	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3360	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-02								
282005	LEFT FUEL FILTER ASSEMBLY							Component ATA:28
PN:6600488-4	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1633	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-04								
282006	RIGHT FUEL FILTER ASSEMBLY							Component ATA:28
PN:6600488-4	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1631	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-04								
282007	LEFT ENGINE FUEL SHUTOFF VALVE							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282008	RIGHT ENGINE FUEL SHUTOFF VALVE							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05								
282009	LEFT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE							Component ATA:28
PN:6600354-4	MOS/MSC	15-Aug-04	O/C	TSN 0				
SN:00107528	HRS	726		TSN 0				
	AFL	479		TSN 0				
PROC. REF: AMM 28-20-06								
282010	RIGHT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE							Component ATA:28
PN:6600354-4	MOS/MSC	12-Dec-03	O/C	TSN 0				
SN:7073183	HRS	487		TSN 0				
	AFL	325		TSN 0				
PROC. REF: AMM 28-20-06								
282011	LEFT ENGINE RELIEF VALVE							Component ATA:28
PN:7600005-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00404316	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-07								
282012	RIGHT ENGINE RELIEF VALVE							Component ATA:28
PN:7600005-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00622171	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-07								
282013	FUEL CONTROL RELAY PANEL							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-08								
282015	LEFT WING PILOT VALVE							Component ATA:28
PN:2780610-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1855	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282016	RIGHT WING PILOT VALVE							Component ATA:28
PN:2780610-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1845	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-09								
282017	LEFT WING REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780614-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1188	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-10								
282018	RIGHT WING REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780614-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1186	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-10								
282019	FUSELAGE PILOT VALVE							Component ATA:28
PN:2780610-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1796	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-11								
282020	FUSELAGE VENT VALVE							Component ATA:28
PN:2780612-103	MOS/MSC	07-Nov-08	O/C	TSO 0				
SN:504	HRS	2094.5		TSO 0				
	AFL	1376		TSO 0				
PROC. REF: AMM 28-20-12								
282021	REFUELING CHECK VALVE							Component ATA:28
PN:2780623-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:596	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-13								
282022	FUSELAGE REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780624-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:714	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282023	FUEL SOLENOID VALVE							Component ATA:28
PN:2780613-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0648	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-15								
282024	PRESSURE REFUELING ADAPTER							Component ATA:28
PN:2780609-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:717	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-16								
282025	LEFT PRECHECK VALVE							Component ATA:28
PN:2780615-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1283	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-17								
282026	RIGHT PRECHECK VALVE							Component ATA:28
PN:2780615-102	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1310	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-17								
282027	PRESSURE REFUELING CONTROL PANEL							Component ATA:28
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-18								
282049 ^U	LEFT MOTIVE FLOW VALVE							Component ATA:28
PN:6600354-4	MOS/MSC	15-Aug-04	O/C	TSN 0				
SN:00107528	HRS	726		TSN 0, TSO 0				
	AFL	479		TSO 0				
282050 ^U	RIGHT MOTIVE FLOW VALVE							Component ATA:28
PN:6600354-4	MOS/MSC	12-Dec-03	O/C	TSN 0				
SN:7073183	HRS	487		TSN 0				
	AFL	325						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284001	LEFT INBOARD WING (MT5) FUEL PROBE							Component ATA:28
PN:2326014-016	MOS/MSC	22-Apr-15	O/C					
SN:13061354A	HRS	3616.4						
	AFL	2379						
PROC. REF: AMM 28-40-01								
284002	RIGHT INBOARD WING (MT6) FUEL PROBE							Component ATA:28
PN:2326014-12	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00030543	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01								
284003	LEFT OUTBOARD WING (MT7) FUEL PROBE							Component ATA:28
PN:2326014-9	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00071874	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01								
284004	RIGHT OUTBOARD WING (MT8) FUEL PROBE							Component ATA:28
PN:2326014-9	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00071869	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01								
284005	LEFT INBOARD WING EXTENSION STA 189 (MT9) FUEL PROBE							Component ATA:28
PN:2826003-6	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00071131	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01								
284006	RIGHT INBOARD WING EXTENSION STA 189 (MT10) FUEL PROBE							Component ATA:28
PN:2826003-6	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00071123	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01								
284007	LEFT OUTBOARD WING EXTENSION STA 244 (MT11) FUEL PROBE							Component ATA:28
PN:2826003-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00051096	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284008	RIGHT OUTBOARD WING EXTENSION STA 244 (MT12) FUEL PROBE							Component ATA:28
PN:2826003-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00041059	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01								
284009	FUSELAGE (MT18) FUEL PROBE							Component ATA:28
PN:0118KTU01	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:008360	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01								
284011	LEFT ENGINE LOW FUEL PRESSURE SWITCH							Component ATA:28
PN:7600002-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3932	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02								
284012	RIGHT ENGINE LOW FUEL PRESSURE SWITCH							Component ATA:28
PN:7600002-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3941	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02								
284013	FUEL QUANTITY INDICATOR							Component ATA:28
PN:6608529-001	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:121	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 28-40-03								
B2813011 ^S	DEFUEL FUSELAGE FUEL CELL AND PERFORM FUEL CELL STATIC ELECTRICAL BONDING RESISTANCE CHECK. CHECK FUSELAGE FUEL CELL FOR CLEANLINESS. (REFER TO 28-12-00.)							Service ATA:28
	MOS	07-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
PROC. REF: AMM 28-12-00								
PKG:25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
C2820030 ^S	INSPECT FUEL SUPPLY LINE CHECK VALVE ORIFICES FOR CONDITION AND CLEANLINESS. (REFER TO 28-20-03.)							Service ATA:28
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
	PROC. REF: AMM 28-20-03							PKG:27
D2812030 ^S	WITH LOWER SURFACE ACCESS PLATES REMOVED, INSPECT INTERIOR AND EXTERIOR WING STRUCTURE FOR EVIDENCE OF FUEL LEAKAGE, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, BACTERIAL GROWTH, FILIFORM CORROSION, AND GENERAL CONDITION. INSPECT WING FLAPPER VALVES FOR F							Service ATA:28
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
	PROC. REF: GENERIC NO REF							PKG:27
E2820010 ^S	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS. ON AIRCRAFT EQUIPPED WITH PAPER FILTERS, REMOVE AND REPLACE FILTERS. (REFER TO 28-20-04)							Service ATA:28
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 28-20-04							PKG:3
H2812060 ^S	OPERATIONAL CHECK OF WING LOW FUEL WARNING SYSTEM. (REFER TO 28-14-00.)							Service ATA:28
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: AMM 28-14-00							PKG:16
H2820020 ^S	PERFORM OPERATIONAL CHECK OF FUEL SUPPLY SHUTOFF VALVE AND HYDRAULIC SUPPLY SHUTOFF VALVES. (REFER TO 28-20-05 AND 29-10-01)							Service ATA:28
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 28-20-05, AMM 29-10-01							PKG:7
T2812070 ^S	OPERATIONAL CHECK OF FUEL CROSSFLOW VALVE AND MOTIVE FLOW CONTROL VALVES. (REFER TO 28-14-00 AND 28-20-00.)							Service ATA:28
	MOS	26-Apr-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 28-20-00, AMM 28-14-00							PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
T2814021 ^S	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES. (REFER TO 28-13-07.)							Service ATA:28
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: AMM 28-13-07				PKG:14
T2814039 ^S	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK VACUUM RELIEF VALVES. (REFER TO 28-13-06.)							Service ATA:28
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: AMM 28-13-06				PKG:14
T2820001 ^S	VISUALLY INSPECT FUEL PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.) CHECK FUEL DRAINS FOR OPERATION.							Service ATA:28
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: GENERIC NO REF				PKG:15
T2820004 ^S	INSPECT LOWER INBOARD GEAR DOORS AND CHECK ENTIRE KEELBEAM AND WHEEL WELL AREA FOR FUEL OR HYDRAULIC LEAKS, PLUMBING FOR ROUTING, CLEARANCES, SECURITY OF CLAMPS, AND GENERAL CONDITION.							Service ATA:28
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: GENERIC NO REF				PKG:17
Y2814041 ^S	PERFORM BENCH CHECK OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES.							Service ATA:28
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
				PROC. REF: AMM 28-13-07				PKG:27
ATA 29 - HYDRAULIC POWER								
05-11-00-G2900001	REPLACE HYDRAULIC HOSE ASSEMBLIES(EXCLUDING HOSES FOR THE LANDING GEAR AND THE HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA)							Service ATA:29
	MOS/MSC		N/A					
	HRS							
	AFL							
				PROC. REF: GENERIC NO REF				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
05-11-00-L2910020	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS							Service ATA:29
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 29-10-03								
290002	HYDRAULIC PRESSURE REGULATOR							Component ATA:29
PN:2702-13	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0510	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-02								
290003	HYDRAULIC RESERVOIR							Component ATA:29
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-03								
290005	PRESSURE REGULATOR CHECK VALVE							Component ATA:29
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-05								
291001	LEFT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE							Component ATA:29
PN:6600355-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0080322	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-01								
291002	RIGHT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE							Component ATA:29
PN:6600355-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0080319	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-01								
291003	LEFT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:6607066-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:K0445AB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291004	RIGHT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:6607066-1	MOS/MSC	02-Jan-16	O/C	TSO 0				
SN:K0871AB	HRS	3794.9		TSO 0				
	AFL	2502		TSO 0				
PROC. REF: AMM 29-10-02								
291005	HYDRAULIC PRESSURE FILTER ASSEMBLY							Component ATA:29
PN:M8815/2A-10	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0227	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-03								
291006	HYDRAULIC RETURN FILTER ASSEMBLY							Component ATA:29
PN:M8815/1A-10	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0232	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-03								
291007	HYDRAULIC SYSTEM ACCUMULATOR							Component ATA:29
PN:MS28700-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:8423-10672	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-04								
291008	HYDRAULIC THRUST REVERSER ACCUMULATOR							Component ATA:29
PN:MS28700-4	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:8424-15142	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-04								
291010	HYDRAULIC GROUND SERVICE PANEL							Component ATA:29
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
291015	HYDRAULIC RELIEF VENT VALVE							Component ATA:29
PN:2380103-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00815131	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291020	HYDRAULIC RESERVOIR RELIEF VALVE							Component ATA:29
PN:5120T-8TT-20	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00619439	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-08								
291220	THRUST REVERSER ISOLATION VALVE							Component ATA:29
PN:6607070-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:223	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-27								
291225	HYDRAULIC PRESSURE RELIEF VALVE							Component ATA:29
PN:1280	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:221	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-08								
292001	AUXILIARY HYDRAULIC PUMP							Component ATA:29
PN:6600248-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1760	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-20-01								
293001	HYDRAULIC PRESSURE MT15 TRANSDUCER							Component ATA:29
PN:124058-3000	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:40429	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-01								
293002	AUXILIARY HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730626	MOS/MSC	11-Nov-21	O/C	TSN 0				
SN:H1914	HRS	5529.6		TSN 0				
	AFL	3657		TSN 0				
PROC. REF: AMM 29-30-02								
293003	HYDRAULIC PRESSURE INDICATOR							Component ATA:29
PN:6608401-13	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:372	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
293005	LEFT HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730635	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:A444	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-04								
293006	RIGHT HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730635	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:A440	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-04								
293010	HYDRAULIC SYSTEM PRESSURE GAUGE							Component ATA:29
PN:S-218-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:961	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-05								
293015	THRUST REVERSER HYDRAULIC PRESSURE GAUGE							Component ATA:29
PN:S-218-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:962	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-05								
H2910009 ^S	REMOVE AND CLEAN OR REPLACE AUXILIARY HYDRAULIC PUMP FILTER. (REFER TO 29-20-02.)							Service ATA:29
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 29-20-02								PKG:15
N2920000 ^S	FUNCTIONAL TEST THRUST REVERSER HYDRAULIC RETURN LINE CHECK VALVE. (REFER TO 78-30-03.)							Service ATA:29
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: AMM 29-10-05								PKG:27
P2910023 ^S	INSPECT HYDRAULIC RESERVOIR FILLER FILTER ELEMENT AND REPLACE IF REQUIRED. (REFER TO 29-00-04.)							Service ATA:29
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
Q2910019 ^S	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS. (REFER TO 29-10-03).							Service ATA:29
	MOS	23-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: AMM 29-10-03				PKG:9
S2900004 ^S	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR PRESSURE RELIEF VALVE. (REFER TO 29-00-08.)							Service ATA:29
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: AMM 29-00-08				PKG:15
S2900005 ^S	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR VACUUM RELIEF VALVE. (REFER TO 29-00-08.)							Service ATA:29
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: AMM 29-00-08				PKG:15
S2910008 ^S	REMOVE HYDRAULIC RESERVOIR REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02.)							Service ATA:29
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: AMM 29-00-01				PKG:15
S2910025 ^S	REMOVE HYDRAULIC RESERVOIR PRESSURE REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02)							Service ATA:29
	MOS	01-Mar-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: AMM 29-00-01, AMM 29-00-02				PKG:9
T2900000 ^S	VISUALLY INSPECT HYDRAULIC PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:29
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: GENERIC NO REF				PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
W2910024 ^S		INSPECT HYDRAULIC FILTERS (PRESSURE AND RETURN) DIFFERENTIAL PRESSURE INDICATORS FOR BYPASS INDICATION.						Service ATA:29
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
				PROC. REF: AMM 29-10-03				PKG:3
ATA 30 - ICE AND RAIN PROTECTION								
300001		COPILOT ELECTRICAL EQUIPMENT BOX						Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-00-01				
301001		WING ANTI-ICE SHUTOFF AND PRESSURE REGULATING VALVE						Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-10-01				
301002		WING RT10 ANTI-ICE TEMPERATURE SENSOR						Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-10-02				
301003		WING (SPARE 2RT10) ANTI-ICE TEMPERATURE SENSOR						Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-10-02				
301004		WING (SPARE 3RT10) ANTI-ICE TEMPERATURE SENSOR						Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-10-02				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301005	WING OVERHEAT WARNING THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03								
301006	WING TEMPERATURE INDICATOR							Component ATA:30
PN:6608210-32	MOS/MSC	07-May-19	O/C	TSN 0				
SN:799	HRS	4649		TSN 0				
	AFL	2997		TSN 0				
PROC. REF: AMM 30-10-04								
301007	LEFT WING ANTI-ICE BYPASS VALVE							Component ATA:30
PN:27441482-13	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:9AT61	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05								
301008	RIGHT WING ANTI-ICE BYPASS VALVE							Component ATA:30
PN:27441482-13	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:9AT54	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05, AMM 30-10-06								
301009	LEFT WING BLEED AIR OVERHEAT SWITCH							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-06								
301010	RIGHT WING BLEED AIR OVERHEAT SWITCH							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-06								
301011	WING UNDERHEAT WARNING SWITCH							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301014	WING ANTI-ICE VALVE							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05, AMM 30-10-08								
301015	LEFT WING ANTI-ICE CHECK VALVE							Component ATA:30
PN:1H95-8	MOS/MSC	28-Apr-19	O/C	TSN 0				
SN:2BR1	HRS	4647.4		TSN 0				
	AFL	2994		TSN 0				
PROC. REF: AMM 30-10-08								
301016	RIGHT WING ANTI-ICE CHECK VALVE							Component ATA:30
PN:1H95-8	MOS/MSC	28-Apr-19	O/C	TSN 0				
SN:2BR2	HRS	4647.4		TSN 0				
	AFL	2994		TSN 0				
PROC. REF: AMM 30-10-08								
301101	HORIZONTAL STABILIZER ANTI-ICE CONTROLLER							Component ATA:30
PN:6608485-1	MOS/MSC	24-Jul-03	O/C	TSN 0				
SN:41061	HRS	318		TSN 0				
	AFL	216		TSN 0				
PROC. REF: AMM 30-11-01								
301103	LEFT HORIZONTAL STABILIZER HEAT BLANKET (BOOT)							Component ATA:30
PN:4065-3481	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00.06723	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-02								
301104	RIGHT HORIZONTAL STABILIZER HEAT BLANKET (BOOT)							Component ATA:30
PN:4065-3481	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:00.06683	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-02								
301109	CBR9 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:60475	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301110	CBR10 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:60462	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03								
301111	CBR11 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:60460	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03								
302101	LEFT NACELLE ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:27441482-09	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1AN8	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-01								
302102	RIGHT NACELLE ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:27441482-09	MOS/MSC	20-Sep-19	O/C					
SN:12AN112	HRS	4708.6						
	AFL	3044						
PROC. REF: AMM 30-21-01								
302103	LEFT NACELLE ANTI-ICE PRESSURE SWITCH							Component ATA:30
PN:7600020-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2925TW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02								
302104	RIGHT NACELLE ANTI-ICE PRESSURE SWITCH							Component ATA:30
PN:7600020-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:3042TW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02								
303001	LEFT PITOT HEAT MONITOR-							Component ATA:30
PN:6608317-7	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2942	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
303002	RIGHT PITOT HEAT MONITOR-							Component ATA:30
PN:6608317-7	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2946	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01								
303003	STANDBY PITOT HEAT MONITOR-							Component ATA:30
PN:6608317-7	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2957	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01								
304001	WINDSHIELD ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:6600201-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2681	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-01								
304002	WINDSHIELD ANTI-ICE MODULATING VALVE							Component ATA:30
PN:27241287-12	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:7AT22	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-02								
304003	WINDSHIELD ANTI-ICE RAM AIR MODULATING VALVE							Component ATA:30
PN:6600203-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:10AT46	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-03								
304004	WINDSHIELD ANTI-ICE HEAT EXCHANGER							Component ATA:30
PN:6600351-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1016	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-04								
304005	WINDSHIELD ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:6600203-7	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:9AT28	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304007	LEFT WINDSHIELD ANTI-ICE LOW-LIMIT (S83) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07								
304008	RIGHT WINDSHIELD ANTI-ICE LOW-LIMIT (S82) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07								
304009	LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07								
304010	RIGHT WINDSHIELD ANTI-ICE HIGH-LIMIT (S84) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07								
304101	ALCOHOL SUPPLY TANK ASSEMBLY							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-01								
304102	ALCOHOL ANTI-ICE FLOAT SWITCH							Component ATA:30
PN:L14F-74	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:565	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-02								
304104	ALCOHOL PRESSURE RELIEF VALVE							Component ATA:30
PN:6608260-3	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:1403	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 30-41-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304105	ANTI-ICE THREE-WAY SHUTOFF VALVE							Component ATA:30
PN:6608258-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-05								
304106	ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE							Component ATA:30
PN:6608257-1	MOS/MSC	22-Apr-15	O/C	TSN 0				
SN:2002A	HRS	3616.4		TSN 0				
	AFL	2379		TSN 0				
PROC. REF: AMM 30-41-06								
304203	WINDSHIELD DEFOG RELAY BOX							Component ATA:30
PN:6018505-002	MOS/MSC	27-Apr-20	O/C	TSR 0				
SN:987137	HRS	4827.6		TSR 0				
	AFL	3129		TSR 0				
PROC. REF: AMM 30-42-03								
308001	LEFT ICE DETECT LAMP							Component ATA:30
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-80-01								
308002	RIGHT ICE DETECT LAMP							Component ATA:30
PN:6839	MOS/MSC	29-Nov-18	O/C	TSN 0				
SN:N/A	HRS	4557.1		TSN 0				
	AFL	2931		TSN 0				
PROC. REF: AMM 30-80-01								
G3010001 ^S	OPERATIONAL CHECK WING ANTI-ICE CHECK VALVE. (REFER TO 30-10-08).							Service ATA:30
	MOS	28-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 30-10-08								
PKG:9								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
H3020002 ^S	REMOVE INLET COWL ACCESS PANEL. VISUALLY INSPECT ANTI-ICE PLUMBING CONNECTOR FOR CONDITION, SECURITY, AND EVIDENCE OF LEAKAGE. (REFER TO 5-10-00)							Service ATA:30
	MOS	23-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:9	
H3020003 ^S	REMOVE UPPER ENGINE ACCESS COWL AND PERFORM A VISUAL INSPECTION OF NACELLE ANTI-ICE PLUMBING AND ALOCHOL PRESSURE LINE. (REFER TO 5-10-00)							Service ATA:30
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:9	
T3040004 ^S	INSPECT WINDSHIELD DEFOG DUCTS AND EXTERNAL OUTLETS FOR SECURITY, CONTOUR, AND INTEGRITY OF SEALANT TO WINDSHIELD. CHECK THAT THE EXTERNAL ANTI-ICE NOZZLES ARE CLEAR OF OBSTRUCTIONS.							Service ATA:30
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:14	
T3040008 ^S	FUNCTIONAL TEST OF WINDSHIELD ANTI-ICE SYSTEM TIMER CIRCUIT. (REFER TO 30-40-00.)							Service ATA:30
	MOS	11-Apr-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 30-40-00							PKG:19	
T3050003 ^S	OPERATIONAL CHECK OF ALCOHOL ANTI-ICE SYSTEM. (REFER TO 30-41-00.)							Service ATA:30
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 30-41-00							PKG:14	
T3050009 ^S	CLEAN ALCOHOL ANTI-ICE FILTER ELEMENT. REPLACE FILTER ELEMENT IF MADE OF PAPER. (REFER TO 30-41-03.)							Service ATA:30
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 30-41-03							PKG:14	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
U3020001A ^S	INSPECT NO. 1 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION							Service ATA:30
	MOS	22-Apr-15						
	HRS	3616.4	3600 (+50)					
	AFL	2379						
PROC. REF: GENERIC NO REF							PKG:29	
U3020001B ^S	INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION							Service ATA:30
	MOS	03-Jan-14						
	HRS	3401.1	3600 (+50)					
	AFL	2225						
PROC. REF: GENERIC NO REF							PKG:30	
ATA 31 - INDICATING/RECORDING SYSTEMS								
311006	TEST SWITCH PANEL ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-06								
311007	PILOT DISPLAY CONTROL (DCP) PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-07								
311008	COPILOT DISPLAY CONTROL (DCP) PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-07								
311009	LEFT CURSOR CONTROL (CCP) PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
311010	RIGHT CURSOR CONTROL (CCP) PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-09								
312001	PILOT CREW CLOCK							Component ATA:31
PN:M877	MOS/MSC	02-Jan-16	O/C	TSN 0				
SN:23361	HRS	3794.9		TSN 0				
	AFL	2502		TSN 0				
PROC. REF: AMM 31-21-01								
312002	COPILOT CREW CLOCK							Component ATA:31
PN:M877	MOS/MSC	05-Sep-13	O/C	TSN 0				
SN:UNKNOWN	HRS	3374.5		TSN 0				
	AFL	2205		TSN 0				
PROC. REF: AMM 31-21-01								
312011	REPLACE PILOT DIGITAL CLOCK BATTERY							Component ATA:31
PN:LR06	MOS	23-Mar-21	24	TSN 0	23-Mar-23		71 d	
SN:NSN	HRS	5214.4		TSN 0				
	AFL	3422		TSN 0				
PROC. REF: GENERIC NO REF, CMM STANDARD AND OPTIONAL FEATURES								
312012	REPLACE COPILOT DIGITAL CLOCK BATTERY							Component ATA:31
PN:LR06	MOS	23-Mar-21	24	TSN 0	23-Mar-23		71 d	
SN:NSN	HRS	5214.4		TSN 0				
	AFL	3422		TSN 0				
PROC. REF: GENERIC NO REF, CMM STANDARD AND OPTIONAL FEATURES								
313001	FLIGHT DATA (FDR) RECORDER							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
313018	FDR INERTIA SWITCH							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
313103	MULTI-AXIAL ACCELEROMETER							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
314002	IAPS CARD CAGE							Component ATA:31
PN:822-0269-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5MRC	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-02								
314004	IAPS ENVIRONMENTAL (IEC) CONTROLLER							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-04								
314007	NO. 1 OPTIONS CONTROL MODULE							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-08								
314008	NO. 2 OPTIONS CONTROL MODULE							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-08								
314011	1A PWR-851A POWER SUPPLY CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01								
314012	2A PWR-851A POWER SUPPLY CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314013	1B PWR-851A POWER SUPPLY CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01								
314014	2B PWR-851A POWER SUPPLY CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01								
314021	1A FLIGHT CONTROL CARD							Component ATA:31
PN:822-0592-407	MOS/MSC	04-Aug-21	O/C	TSO 0				
SN:4CRH	HRS	5402.6		TSO 0				
	AFL	3560		TSO 0				
PROC. REF: AMM 31-40-01								
314022	2A FLIGHT CONTROL CARD							Component ATA:31
PN:822-0592-407	MOS/MSC	15-Dec-15	O/C	TSN 0				
SN:949	HRS	3785.3		TSN 0				
	AFL	2495		TSN 0				
PROC. REF: AMM 31-40-01								
314031	1B FLIGHT MANAGEMENT - FMC 851C CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01								
314032	2B FLIGHT MANAGEMENT - FMC 851C CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01								
314033	1B FLIGHT MANAGEMENT - FMC 852C CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314034	2B FLIGHT MANAGEMENT - FMC 852C CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01								
314041	1A INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02								
314042	2A INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02								
314043	1B INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02								
314044	2B INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02								
314047	NO. 1 CONFIGURATION STRAPPING (CSU) UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-05								
314048	NO. 2 CONFIGURATION STRAPPING (CSU) UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314101	DATA ACQUISITION UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01								
314110	MINI-FLIGHT DATA ACQUISITION (MFDAU) UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01								
315101	AURAL WARNING CONTROL UNIT							Component ATA:31
PN:6608108-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2104	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-01								
315102	TONE GENERATOR							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-02								
315103	AURAL WARNING MIXER							Component ATA:31
PN:1882-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-03								
315201	GLARESHIELD ANNUNCIATOR PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-52-01								
315203	MASTER CAUTION/WARNING TRIGGER UNIT ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-52-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316001	PILOT EFD-871 ELECTRONIC FLIGHT DISPLAY							Component ATA:31
PN:622-9345-026	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5DTR	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
316002	COPILOT EFD-871 ELECTRONIC FLIGHT DISPLAY							Component ATA:31
PN:622-9345-026	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5NFB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
316003	MULTIFUNCTION DISPLAY							Component ATA:31
PN:622-9434-026	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5N1B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-01								
316004	MULTIFUNCTION DISPLAY							Component ATA:31
PN:622-9434-026	MOS/MSC	11-Jun-21	O/C	TSO 0				
SN:3JKT	HRS	5333.9		TSO 0				
	AFL	3511		TSO 0				
PROC. REF: AMM 31-60-01								
316005	PILOT EFIS CONTROL PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-02								
316006	COPILOT EFIS CONTROL PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-02								
316007	LEFT OUTBOARD ADAPTIVE FLIGHT DISPLAY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316008	LEFT INBOARD ADAPTIVE FLIGHT DISPLAY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-04								
316009	RIGHT INBOARD ADAPTIVE FLIGHT DISPLAY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-04								
316010	RIGHT OUTBOARD ADAPTIVE FLIGHT DISPLAY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-04								
316011	NO. 1 DISPLAY IMT-871 TRAY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
316012	NO. 2 DISPLAY IMT-871 TRAY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
316013	NO. 3 DISPLAY IMT-871 TRAY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
316014	NO. 4 DISPLAY IMT-871 TRAY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316101	SENSOR DISPLAY UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01								
316102	SENSOR DISPLAY DRIVER UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-02								
316201	NO. 1 FILE SERVER (FSU) UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-01								
316202	NO. 2 FILE SERVER (FSU) UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-01								
316203	NO. 1 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-03								
316204	NO. 2 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-03								
316301	MAINTENANCE WARNING PANEL ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-63-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
P3151001 ^S	PERFORM OPERATIONAL CHECK OF THE AUTOPILOT AURAL WARNING. (REFER TO 31-51-00) (EFFECTIVE ON AIRCRAFT 60-307, 60-319 AND SUBSEQUENT)							Service ATA:31
	MOS/MSC	19-Oct-22	N/A					NOT APPLICABLE
	HRS	5563.7						
	AFL	3693						
				PROC. REF: AMM 31-51-00				PKG:1
P3160001 ^S	PERFORM OPERATIONAL CHECK OF THE ELECTRONIC FLIGHT INSTRUCMENT SYSTEM (EFIS). (REFER TO 31-60-03)							Service ATA:31
	MOS/MSC	18-Apr-17	N/A					
	HRS	4053.4						
	AFL	2668						
	APH	1090						
	ACH	1195.9						
				PROC. REF: AMM 31-60-03				PKG:7
T3110000 ^S	INSPECT EQUIPMENT INSTALLATIONS BETWEEN FORWARD PRESSURE BULKHEAD AND INSTRUMENT PANEL FOR SECURITY OF MOUNTING, WIRE ROUTING, AND CLEARANCES OF WIRING AND PLUMBING.							Service ATA:31
	MOS	26-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
				PROC. REF: GENERIC NO REF				PKG:19
U3100001 ^S	GENERAL VISUAL INSPECTION INSTRUMENT PANEL (REFER TO 5-10-00.)							Service ATA:31
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
				PROC. REF: GENERIC NO REF				PKG:1
ATA 32 - LANDING GEAR								
05-11-00-E3211066	REPLACE NOSE LANDING GEAR ACTUATOR BOLT (6042007-4)							Service ATA:32
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)		6000	6025	2295 (+25)	
				PROC. REF: AMM 32-32-01				
05-11-00-E3211074L	REPLACE LEFT * MLG UPPER BEARINGS (6041104) (AWL*)							Service ATA:32
	MOS	01-Mar-19						LIFE LIMIT
	HRS	4647.4						
	AFL	2994	3000		5994		2289	
				PROC. REF: AMM 32-11-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
05-11-00-E3211074R ^S	REPLACE RIGHT * MLG UPPER BEARINGS (6041104) (AWL*)							Service ATA:32
	MOS	30-May-19						LIFE LIMIT
	HRS	4651.3						
	AFL	3003	3000					
PROC. REF: AMM 32-11-00								
05-11-00-E3211084L	REPLACE LEFT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)							Service ATA:32
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 32-11-00								
05-11-00-E3211084R	REPLACE RIGHT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)							Service ATA:32
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		16295	
PROC. REF: AMM 32-11-00								
05-11-00-E3211090L	REPLACE LEFT * MLG UPPER BEARING RETENTION PIN (6041110-1) (AWL*)							Service ATA:32
	MOS	01-Mar-19						LIFE LIMIT
	HRS	4647.4						
	AFL	2994	3000		5994		2289	
PROC. REF: AMM 32-11-00								
05-11-00-E3211090R ^S	REPLACE RIGHT * MLG UPPER BEARING RETENTION PIN (6041110-1) (AWL*)							Service ATA:32
	MOS	30-May-19						LIFE LIMIT
	HRS	4651.3						
	AFL	3003	3000					
PROC. REF: AMM 32-11-00								
05-11-00-E3211092L	REPLACE LEFT * MLG UPPER BEARING (7600839) (AWL*)							Service ATA:32
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		2295	
PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
05-11-00-E3211092R	REPLACE RIGHT * MLG UPPER BEARING (7600839) (AWL*)							Service ATA:32
	MOS	30-May-19						LIFE LIMIT
	HRS	4651.3						
	AFL	3003	6000		9003		5298	
PROC. REF: AMM 32-11-00								
05-11-00-E3211093L	REPLACE LEFT * MLG LOWER BEARING (6041105) (AWL*)							Service ATA:32
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		2295	
PROC. REF: AMM 32-11-00								
05-11-00-E3211093R	REPLACE RIGHT * MLG LOWER BEARING (6041105) (AWL*)							Service ATA:32
	MOS	30-May-19						LIFE LIMIT
	HRS	4651.3						
	AFL	3003	6000		9003		5298	
PROC. REF: AMM 32-11-00								
05-11-00-G3210003	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN AND NOSE GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR							Service ATA:32
	MOS/MSC	25-Aug-15	O/C					TEFLON
	HRS	3702.6						
	AFL	2436						
PROC. REF: GENERIC NO REF								
05-11-00-G3233007	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY FREEFALL EXTENSION, LANDING GEAR EMERGENCY BLOWDOWN, AND EMERGENCY BRAKING SYSTEMS							Service ATA:32
	MOS/MSC	03-Aug-12	O/C					TEFLON
	HRS	3178.5						
	AFL	2065						
PROC. REF: GENERIC NO REF								
05-11-00-G3243040	REPLACE HYDRAULIC BRAKE HOSE ASSEMBLIES LOCATED ON THE STRUT AND IN WHEEL WELL AREA							Service ATA:32
	MOS/MSC	25-Aug-15	O/C					TEFLON
	HRS	3702.6						
	AFL	2436						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
05-11-00-U3211091L	REPLACE LEFT * MLG UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)							Service ATA:32
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		2295	
PROC. REF: AMM 32-11-00								
05-11-00-U3211091R	REPLACE RIGHT * MLG UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)							Service ATA:32
	MOS	30-May-19						LIFE LIMIT
	HRS	4651.3						
	AFL	3003	6000		9003		5298	
PROC. REF: AMM 32-11-00								
321001	* LEFT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*)							Component ATA:32
PN:6041100-035	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:056	HRS	0		TSN 0				
	AFL	0	16500	TSN 0	16500		12795	
PROC. REF: AMM 32-11-00								
321002	* RIGHT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*)							Component ATA:32
PN:6041100-036	MOS	30-May-19		TSR 0				LIFE LIMIT
SN:058	HRS	4651.3		TSR 0				
	AFL	3003	16500	TSN 2994, TSR 0	16509		12804	
	APH							
	ACH							
PROC. REF: AMM 32-11-00								
321003	* LEFT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*)							Component ATA:32
PN:PN	MOS	29-Dec-00		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		2295	
PROC. REF: AMM 32-11-01								
321004	* RIGHT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*)							Component ATA:32
PN:PN	MOS	29-Dec-00		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		2295	
PROC. REF: AMM 32-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321005	* LEFT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)							Component ATA:32
PN:2341123-023	MOS	29-Dec-00		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		2295	
PROC. REF: AMM 32-11-01								
321006	* RIGHT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)							Component ATA:32
PN:2341123-023	MOS	29-Dec-00		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		2295	
PROC. REF: AMM 32-11-01								
321011	LEFT MAIN LANDING GEAR PISTON ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-00								
321012	RIGHT MAIN LANDING GEAR PISTON ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-00								
321013	LEFT MAIN LANDING GEAR AXLE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-00								
321014	RIGHT MAIN LANDING GEAR AXLE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-00								
321501	LEFT HYDRAULIC, GEAR RETRACTION RESTRICTOR							Component ATA:32
PN:1R3665-035	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D6798	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321502	RIGHT HYDRAULIC, GEAR RETRACTION RESTRICTOR							Component ATA:32
PN:1R3665-035	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D6806	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04								
321511	LEFT HYDRAULIC, GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:1R3665-051	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D3462	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04								
321512	RIGHT HYDRAULIC, GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:1R3665-051	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D3432	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04								
321515	LEFT HYDRAULIC RESTRICTOR							Component ATA:32
PN:1R3665-035	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D6689	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
321516	RIGHT HYDRAULIC RESTRICTOR							Component ATA:32
PN:1R3665-059	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D2075	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
322001	* NOSE GEAR STRUT ASSEMBLY (AWL*)							Component ATA:32
PN:2342100-028	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:017	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		6295	
PROC. REF: AMM 32-21-00								
322002	NOSE LANDING GEAR & STEERING ASSEMBLY STRUT							Component ATA:32
PN:2342003-085	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:017	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		6295	
PROC. REF: AMM 32-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323019	LEFT MAIN LANDING GEAR SQUAT SWITCH							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-03								
323020	RIGHT MAIN LANDING GEAR SQUAT SWITCH							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-03								
323031	* LEFT MAIN LANDING GEAR ACTUATOR (AWL*)							Component ATA:32
PN:6027100-001	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:KL0082	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		16295	
PROC. REF: AMM 32-31-01								
323032	* RIGHT MAIN LANDING GEAR ACTUATOR (AWL*)							Component ATA:32
PN:6027100-001	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:KL0092	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		16295	
PROC. REF: AMM 32-31-01								
323043	LEFT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR							Component ATA:32
PN:6600085-9	MOS/MSC	20-Jan-03	O/C	TSN 0				
SN:0271	HRS	110		TSN 0, TSO 0				
	AFL	86		TSO 0				
PROC. REF: AMM 32-31-03								
323044	RIGHT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR							Component ATA:32
PN:95919-4	MOS/MSC	11-Mar-22	O/C	TSO 0				
SN:0359	HRS	5539.1		TSO 0				
	AFL	3670		TSO 0				
PROC. REF: AMM 32-31-03								
323052	LANDING GEAR CONTROL PANEL ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323055	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	12-Jul-18	O/C	TSO 0				
SN:401	HRS	4424.1		TSO 0				
	AFL	2855		TSO 0				
PROC. REF: AMM 32-31-02								
323056	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5135	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-02								
323057	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5166	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-04								
323058	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5161	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-04								
323073	* NOSE LANDING GEAR ACTUATOR (AWL*)							Component ATA:32
PN:2317100-016	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:KL-0173	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		6295	
PROC. REF: AMM 32-32-01								
323079	NOSE LANDING GEAR UPLOCK ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	20-Jan-03	O/C	TSN 0				
SN:4517	HRS	110		TSN 0, TSO 0				
	AFL	86		TSO 0				
PROC. REF: AMM 32-32-02								
323080	UPLOCK, NOSE LANDING GEAR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5159	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323098	GEAR DOOR CONTROL VALVE							Component ATA:32
PN:6600361-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1243	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-08								
323099	SELECT, LANDING GEAR VALVE							Component ATA:32
PN:48C48641	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-05								
323105	NOSE LANDING GEAR SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323110	NOSE LANDING GEAR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323205	LEFT MAIN LANDING GEAR EXTEND SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
323210	RIGHT MAIN LANDING GEAR EXTEND SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
323222	* LEFT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*)							Component ATA:32
PN:2341123-023	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		16295	
PROC. REF: AMM 32-31-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323223	* RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*)							Component ATA:32
PN:2341123-023	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		16295	
PROC. REF: AMM 32-31-05								
323305	LEFT MAIN LANDING GEAR DOOR SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
323310	RIGHT MAIN LANDING GEAR DOOR SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
323315	LEFT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
323320	RIGHT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
323401	AFT EMERGENCY GEAR BLOWDOWN EXTENSION VALVE							Component ATA:32
PN:6600078-6	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2148	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-02								
323402	FORWARD EMERGENCY GEAR FREEFALL EXTENSION VALVE							Component ATA:32
PN:6600078-6	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2147	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323405	LEFT CHECK, FREEFALL VALVE							Component ATA:32
PN:7600833-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0171	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-01								
323406	RIGHT CHECK, FREEFALL VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-01								
323409	UPPER EMERGENCY GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:6R7742S-0135	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4572	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323410	LOWER EMERGENCY GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:6R7742S-0135	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4584	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323430	NO. 1 EMERGENCY AIR BLOWDOWN SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
324001	NOSE TIRE							Component ATA:32
PN:184F10-2	MOS/MSC	11-Aug-21	O/C	TSN 0				
SN:03360619	HRS	5412.7		TSN 0				
	AFL	3568		TSN 0				
PROC. REF: AMM 32-40-01								
324007	ASSEMBLY, NOSE WHEEL							Component ATA:32
PN:9544207-4	MOS/MSC	11-Aug-21	O/C	TSR 0				
SN:MAR07-10350	HRS	5412.7		TSR 0				
	AFL	3568		TSR 0				
PROC. REF: AMM 32-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324013	NO. 1 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	11-Aug-21	O/C	TSN 0				
SN:93162490	HRS	5412.7		TSN 0				
	AFL	3568		TSN 0				
PROC. REF: AMM 32-40-02								
324014	NO. 2 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	11-Aug-21	O/C	TSN 0				
SN:10580130	HRS	5412.7		TSN 0				
	AFL	3568		TSN 0				
PROC. REF: AMM 32-40-02								
324015	NO. 3 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	11-Mar-22	O/C	TSN 0				
SN:13220776	HRS	5539.1		TSN 0				
	AFL	3670		TSN 0				
PROC. REF: AMM 32-40-02								
324016	NO. 4 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	11-Aug-21	O/C	TSN 0				
SN:10520219	HRS	5412.7		TSN 0				
	AFL	3568		TSN 0				
PROC. REF: AMM 32-40-02								
324020	NOSE TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324021	NO. 1 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324022	NO. 2 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324023	NO. 3 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324024	NO. 4 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324037	NO. 1 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	11-Aug-21	O/C	TSO 0				
SN:MAY10-3121	HRS	5412.7		TSO 0				
	AFL	3568		TSO 0				
PROC. REF: AMM 32-40-02								
324037A	NDT INSPECT NO. 1 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC	11-Aug-21	O/C					
SN:MAY10-3121	HRS	5412.7						
	AFL	3568						
PROC. REF: NDT 32-40-01								
324038	NO. 2 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	11-Aug-21	O/C	TSO 0				
SN:NOV06-2354	HRS	5412.7		TSO 0				
	AFL	3568		TSO 0				
PROC. REF: AMM 32-40-02								
324038A	NDT INSPECT NO. 2 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC	11-Aug-21	O/C					
SN:NOV06-2354	HRS	5412.7						
	AFL	3568						
PROC. REF: NDT 32-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
324039	NO. 3 MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:5011740	MOS/MSC	11-Mar-22	O/C	TSO 7, TSR 0					
SN:JUN04-2044/JUL94-330	HRS	5539.1	TSO 126.4, TSR 0						
	AFL	3670	TSO 102, TSR 0						
PROC. REF: AMM 32-40-02									
324039A	NDT INSPECT NO. 3 MAIN LANDING GEAR WHEEL							Service	ATA:32
PN:5011740	MOS/MSC	11-Aug-21	O/C						
SN:JUN04-2044/JUL94-330	HRS	5412.7							
	AFL	3568							
PROC. REF: NDT 32-40-01									
324040	NO. 4 MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:5011740	MOS/MSC	11-Aug-21	O/C	TSO 0					
SN:JUL99-1142/SEP04-2063	HRS	5412.7	TSO 0						
	AFL	3568	TSO 0						
PROC. REF: AMM 32-40-02									
324040A	NDT INSPECT NO. 4 MAIN LANDING GEAR WHEEL							Service	ATA:32
PN:5011740	MOS/MSC	11-Aug-21	O/C						
SN:JUL99-1142/SEP04-2063	HRS	5412.7							
	AFL	3568							
PROC. REF: NDT 32-40-01									
324048	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component	ATA:32
PN:5003096-7	MOS/MSC	11-Mar-22	O/C						
SN:JUL90-2880	HRS	5539.1							
	AFL	3670							
PROC. REF: AMM 32-41-01									
324049	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component	ATA:32
PN:5003096-7	MOS/MSC	11-Mar-22	O/C	TSO 7					
SN:OCT99-5296	HRS	5539.1	TSO 105.9						
	AFL	3670	TSO 86						
PROC. REF: AMM 32-41-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324050	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:5003096-7	MOS/MSC	11-Mar-22	O/C	TSO 0				
SN:JUL99-2864	HRS	5539.1		TSO 0				
	AFL	3670		TSO 0				
PROC. REF: AMM 32-41-01								
324051	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:5003096-7	MOS/MSC	11-Aug-21	O/C	TSO 6				
SN:DEC93-3720	HRS	5412.7		TSO 0				
	AFL	3568		TSO 0				
PROC. REF: AMM 32-41-01								
324061	NO. 1 POWER BRAKE, PILOTS VALVE							Component ATA:32
PN:3321200-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1554	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02								
324062	NO. 2 POWER BRAKE, PILOTS VALVE							Component ATA:32
PN:3321200-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1547	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02								
324063	NO. 1 POWER BRAKE, COPILOTS VALVE							Component ATA:32
PN:3321200-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1551	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02								
324064	NO. 2 POWER BRAKE, COPILOTS VALVE							Component ATA:32
PN:3321200-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02								
324085	NO. 1 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:2380114-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6617	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324086	NO. 2 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:2380114-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6606	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03								
324109	NO. 3 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:2380114-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6604	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03								
324110	NO. 4 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:2380114-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6608	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03								
324133	AFT PARKING BRAKE VALVE							Component ATA:32
PN:6600392-2	MOS/MSC	02-Aug-13	O/C	TSN 0				
SN:0451	HRS	3374.45		TSN 0				
	AFL	2205		TSN 0				
PROC. REF: AMM 32-41-04								
324134	FWD PARKING BRAKE VALVE							Component ATA:32
PN:6600392-2	MOS/MSC	02-Aug-13	O/C	TSN 0				
SN:0456	HRS	3374.45		TSN 0				
	AFL	2205		TSN 0				
PROC. REF: AMM 32-41-04								
324145	NO. 1 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:7052	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02								
324146	NO. 2 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:7050	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324147	NO. 3 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:7065	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02								
324148	NO. 4 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:7045	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02								
324169	LEFT ANTI-SKID VALVE							Component ATA:32
PN:39-309-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2353	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-01								
324170	RIGHT ANTI-SKID VALVE							Component ATA:32
PN:39-309-2	MOS/MSC	16-Jun-11	O/C					
SN:2679A	HRS	2903.7						
	AFL	1876						
PROC. REF: AMM 32-42-01								
324175	ANTI-SKID CONTROL							Component ATA:32
PN:42-379-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1766B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-03								
3243012 EMP ^S	CHECK BRAKE ASSEMBLIES FOR WEAR, CRACKS, HYDRAULIC LEAKS AND RELEASE. (AIRCRAFT EQUIPPED WITH 3-ROTOR BRAKE SYSTEM).							Service ATA:32
	MOS	29-Dec-00	72 (+14d/-14d)					
	HRS	0	1200 (+25/-25)					
	AFL	0						
PROC. REF: AMM 32-41-01								
PKG:42								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324413	PARK BRAKE ANNUNCIATOR BOX ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-06								
324501	EMERGENCY BRAKE CONTROL VALVE							Component ATA:32
PN:63500-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:422A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-01								
324505	LEFT MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
324510	RIGHT MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
324601	NO. 1 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
324602	NO. 2 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
324603	NO. 3 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324604	NO. 4 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01								
325001	NOSE WHEEL STEERING ACTUATOR							Component ATA:32
PN:501-1711-02	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1195	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-05								
325005	NOSE WHEEL STEERING COMPUTER							Component ATA:32
PN:6608468-8	MOS/MSC	07-Jul-20	O/C	TSN 0				
SN:80204	HRS	4896.1		TSN 0				
	AFL	3179		TSN 0				
PROC. REF: AMM 32-50-04								
325015	LEFT RUDDER POSITION SENSOR							Component ATA:32
PN:501-1123-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6411	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-03								
325016	RIGHT RUDDER POSITION SENSOR							Component ATA:32
PN:501-1123-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6405	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-03								
325019	NOSE WHEEL STEERING ACTUATOR GEARBOX							Component ATA:32
PN:3142020-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:214	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-02								
325020	NOSE WHEEL STEERING FOLLOW UP ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
325024	RIGHT NOSE WHEEL STEERING FOLLOWUP							Component ATA:32
PN:6608288-003	MOS/MSC	19-Jan-18	O/C	TSN 0				
SN:5636	HRS	4258.7		TSN 0				
	AFL	2769		TSN 0				
	APH	1201						
	ACH	1324						
PROC. REF: AMM 32-50-01								
325025	LEFT NOSE WHEEL STEERING FOLLOWUP							Component ATA:32
PN:6608288-003	MOS/MSC	19-Jan-18	O/C	TSN 0				
SN:5655	HRS	4258.7		TSN 0				
	AFL	2769		TSN 0				
	APH	1201						
	ACH	1324						
PROC. REF: AMM 32-50-01								
325628	AFT EMERGENCY GEAR CONTROL VALVE							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
326011	SQUAT SWITCH RELAY BOX							Component ATA:32
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-07								
AA3211058 ^S	COMPLETELY DISASSEMBLE MAIN LANDING GEAR STRUTS AND ACTUATORS. REMOVE AXLES AND PISTONS FROM HUBS. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. CONDUCT FLUORESCENT PENETRANT OR MAGNETIC PARTICLE INSPECTION OF ALL COMPONENTS. PAY PARTICULAR ATTENTION TO THE MAIN GEAR UPPER TRUNNION AREAS AND LOWER GLAND NUT OF THE CYLINDER FORGING FOR CRACKS.							Service ATA:32
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: NDT 32-13-01								
PKG:26								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
C3211040 ^S	CLEAN AND EDDY CURRENT INSPECT UPPER CYLINDER. (SEE FIGURE 1.) (REFER TO NDI MANUAL [NDI-2], PART 3, 32-40-02.)							Service ATA:32
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)					
	PROC. REF: NDT 32-40-02							PKG:26
C3211050 ^S	DEFLATE STRUTS AND STROKE FROM FULLY EXTENDED TO FULLY COMPRESSED POSITIONS. NOTE BINDING TENDENCIES DURING STROKING, PARTICULARLY NEAR THE FULLY COMPRESSED POSITION.							Service ATA:32
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)					
	PROC. REF: GENERIC NO REF							PKG:26
C3231030 ^S	INSPECT INBOARD ATTACHMENT OF MAIN GEAR ACTUATOR FOR SECURITY, LOOSENESS, OVERLOAD INDICATIONS, AND FATIGUE CRACKS. THE PILLAR ATTACHMENTS TO SPARS 7 AND 8 ARE TO BE SPECIFICALLY INSPECTED FOR DISCREPANT CONDITIONS. PILLAR REMOVAL IS REQUIRED TO FACILITATE DEFINI							Service ATA:32
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)					
	PROC. REF: GENERIC NO REF							PKG:26
C3233010 ^S	FUNCTIONAL TEST OF LANDING GEAR EMERGENCY BLOWDOWN EXTENSION SYSTEM. (REFER TO 32-33-00.)							Service ATA:32
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
	PROC. REF: AMM 32-33-00							PKG:27
C3233011 ^S	FUNCTIONAL TEST OF LANDING GEAR EMERGENCY FREEFALL SYSTEM. (REFER TO 32-33-00.)							Service ATA:32
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
	PROC. REF: AMM 32-33-00							PKG:27
D3211060 ^S	COMPLETELY DISASSEMBLE NOSE LANDING GEAR STRUT AND ACTUATOR. REMOVE AXLE AND PISTON FROM HUB. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. (REFER TO 32-21-00 AND 32-32-01.) CONDUCT FLUORE							Service ATA:32
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)					
	PROC. REF: AMM 32-32-01							PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
D3211061 ^S	VISUALLY INSPECT NOSE GEAR TRUNNION AXLE AND INSTALLATION AREA OF TRUNNION FOR CRACKS, CORROSION, AND DAMAGE. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION I							Service ATA:32
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)					
				PROC. REF: AMM 32-21-00				PKG:26
E3230020 ^S	INSPECT LANDING GEAR SQUAT SWITCHES FOR CONDITION.							Service ATA:32
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
				PROC. REF: GENERIC NO REF				PKG:5
E3242000 ^S	INSPECT NOSE AND MAIN TIRES FOR WEAR, CUTS, ABRASIONS, AND FLAT SPOTS. CHECK CHINE CONDITION ON CHINED TIRE. (REFER TO 32-40-00)							Service ATA:32
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
				PROC. REF: AMM 32-40-00				PKG:5
E3243010 ^S	INSPECT BRAKE ASSEMBLIES FO RWEAR, CRACKS, HYDRAULIC LEAKS, AND RELEASE.							Service ATA:32
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
				PROC. REF: AMM 32-41-01				PKG:5
E3244020 ^S	REMOVE AND CLEAN ANTI-SKID VALVE FILTERS. (REFER TO 32-42-01).							Service ATA:32
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: AMM 32-42-01				PKG:11
F3233020 ^S	FUNCTIONAL TEST OF EMERGENCY BRAKE SYSTEM. (REFER TO 34-43-00.)							Service ATA:32
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
				PROC. REF: AMM 32-43-00				PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
G3200000 ^S	PERFORM VISUAL INSPECTION OF LANDING GEAR SHOCK STRUTS FOR LEAKS AND GENERAL CONDITION. VISUALLY INSPECT LANDING GEAR SHOCK STRUTS AND LANDING GEAR ACTUATOR ATTACH POINTS FOR SECURITY AND GERNAL CONDITION. (REFER TO 5-10-00)							Service ATA:32
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:5
H3210000 ^S	VISUALLY INSPECT MAIN AND NOSE LANDING GEAR STRUT ASSEMBLIES, ACTUATORS, FASTENERS, AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT NOSE GEAR ACTUATOR ATTACH BRACKET IN THE AREA AROUND THE GREASE FITTING. INSPECT FOR CRACKS EM							Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:17
H3211010 ^S	INSPECT MAIN LANDING GEAR TORQUE LINKS FOR LOOSENESS.							Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:17
H3211020 ^S	INSPECT INTERIOR AND EXTERIOR OF MAIN LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-11-00.)							Service ATA:32
	MOS	13-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 32-11-00								PKG:23
H3221000 ^S	INSPECT NOSE GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION.							Service ATA:32
	MOS	20-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:23
H3221010 ^S	INSPECT INTERIOR AND EXTERIOR OF NOSE LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-21-00.)							Service ATA:32
	MOS	20-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 32-21-00								PKG:23

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H3230000 ^S		INSPECT LANDING GEAR ELECTRICAL WIRING FOR ROUTING AND GENERAL CONDITION.						Service ATA:32
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: GENERIC NO REF				PKG:11
H3230010 ^S		PERFORM LANDING GEAR RETRACTION AND EXTENSION CHECK. CHECK AUTOMATIC BRAKE SNUBBING AND LANDING LIGHTS FOR RETRACT CUTOFF. (REFER TO 32-30-00.)						Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: AMM 32-30-00				PKG:17
H3230021 ^S		INSPECT LANDING GEAR SQUAT SWITCHES FOR PROPER OPERATION AND CONDITION. (REFER TO 32-30-03.)						Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: GENERIC NO REF				PKG:17
H3231014 ^S		INSPECT MAIN GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FASTEMER CONDITION, AND PERMANENT DEFORMATION.						Service ATA:32
	MOS	13-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
				PROC. REF: GENERIC NO REF				PKG:23
H3232002 ^S		INSPECT NOSE GEAR ACTUATOR BOOT AND HYDRAULIC PLUMBING FOR SECURITY AND GENERAL CONDITION.						Service ATA:32
	MOS	19-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: GENERIC NO REF				PKG:8
H3233000 ^S		VISUALLY INSPECT GEAR FREE FALL, GEAR BLOW DOWN, AND EMERGENCY BRAKE VALVES AND FITTINGS FOR SECURITY OF ATTACHMENT. (REFER TO 5-10-00.)						Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: GENERIC NO REF				PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H3233012 ^S	PERFORM EMERGENCY AIR EXTENSION SYSTEM AND EMERGENCY BRAKE SYSTEM PLUMBING LEAKAGE CHECK. (REFER TO 32-33-00 AND 32-43-00.)							Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 32-33-00, AMM 32-43-00								PKG:17
H3243000 ^S	INSPECT BRAKE LINES FOR ROUTING AND LEAKS, MLG AND DOOR ACTUATOR ATTACH POINTS FOR SECURITY, AND STRUT HINGE POINTS FOR GENERAL CONDITION.							Service ATA:32
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:11
H3243023 ^S	INSPECT POWER BRAKE VALVES FOR SECURITY, OPERATION, AND LEAKS. ENSURE POWER BRAKE VALVE LEVER CONTACTS MECHANICAL STOP. (REFER TO 32-41-02.)							Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 32-41-02								PKG:14
H3243030 ^S	FUNCTIONAL TEST OF HYDRAULIC BRAKE FUSES. (REFER TO 32-41-03.)							Service ATA:32
	MOS	24-Apr-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 32-41-03								PKG:23
N3243024 ^S	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.							Service ATA:32
	MOS/MSC	18-Apr-17	N/A					
	HRS	4053.4						
	AFL	2668						
	APH	1090						
	ACH	1195.9						
PROC. REF: AMM 32-41-02								PKG:8
N3243050 ^S	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.							Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 32-41-02								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
Q3242001 ^S		OPERATIONAL CHECK ANTI-SKID VALVES (REFER TO 32-42-00)						Service ATA:32
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: AMM 32-42-00								PKG:5
T3211030 ^S		REMOVE AND REPLACE RETAINER RING LOCKSCREW FROM NOSE LANDING GEAR STRUT (P/N AN500A6-10).						Service ATA:32
	MOS	28-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 32-21-00								PKG:11
T3231040 ^S		INSPECT MAIN LANDING GEAR DOOR ACTUATORS AND HINGES FOR SECURITY AND GENERAL CONDITION.						Service ATA:32
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:11
W3232003 ^S		NOSE LANDING GEAR FREE FALL UPLATCH ACTUATOR - PERFORM DETAILED CHECK. (REFER TO 32-33-05.)						Service ATA:32
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 32-33-05								PKG:17
ATA 33 - LIGHTS								
331201		LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY						Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02								
331202		RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY						Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331303	QUAD EL (ELECTROLUMINESCENT) POWER SUPPLY							Component ATA:33
PN:SDA 16	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:342	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-13-03								
331311	PILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
331312	COPILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
331313	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
331314	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
331401	PILOT DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1166	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01								
331402	COPILOT DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1236	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331403	CENTER INSTRUMENT AND PEDESTAL DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1183	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01								
331404	PEDESTAL DIMMING CONTROL BOX							Component ATA:33
PN:LT-48E	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2464	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01								
331405	FUEL QUANTITY INDICATOR DIMMING CONTROL BOX							Component ATA:33
PN:LT-48E	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2440	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01								
331406	CDU LAMP DIMMING CONTROL BOX							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01								
331407	INSTRUMENT BACKLIGHTING FUSE BOX							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-02								
331601	LEFT ACS DIMMER CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1207	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
331602	RIGHT ACS DIMMER CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1212	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331701	LEFT AFT LIGHT DIMMING (E215) CONTROL BOX							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-17-01								
331801	LEFT FORWARD LIGHT DIMMING (AE9) CONTROL BOX							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-18-01								
331802	RIGHT LIGHT DIMMING (2AE9) CONTROL BOX							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-18-01								
332001	OVERHEAD INDIRECT LIGHTING (PS2) INVERTER							Component ATA:33
PN:6608477-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4505	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08								
332002	OVERHEAD INDIRECT LIGHTING (2PS2) INVERTER							Component ATA:33
PN:6608477-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4504	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08								
332003	OVERHEAD INDIRECT LIGHTING (3PS2) INVERTER							Component ATA:33
PN:6608477-1	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:3602	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 33-20-08								
332004	OVERHEAD INDIRECT LIGHTING (4PS2) INVERTER							Component ATA:33
PN:6608477-1	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:3606	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 33-20-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
332005	OVERHEAD INDIRECT LIGHTING (5PS2) INVERTER							Component ATA:33
PN:6608477-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4503	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08								
332006	OVERHEAD INDIRECT LIGHTING (6PS2) INVERTER							Component ATA:33
PN:6608477-1	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:3691	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 33-20-08								
332007	OVERHEAD INDIRECT LIGHTING (7PS2) INVERTER							Component ATA:33
PN:6608477-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4515	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08								
332009	INDIRECT LIGHTING CONTROL							Component ATA:33
PN:MS1836	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0156	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-09								
332010	ALTERNATE/MOMENTARY SWITCHING MODULE							Component ATA:33
PN:MS1881	MOS/MSC	02-Sep-16	O/C	TSO 0				
SN:0113	HRS	3960.5		TSO 0				
	AFL	2615		TSO 0				
PROC. REF: AMM 33-20-10								
332014	ZONE BACK LIGHTING CONTROL							Component ATA:33
PN:MS1839-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0436	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-14								
332028 ^U	NO. 8 POWER, LIGHTING INVERTER SUPPLY							Component ATA:33
PN:6608477-1	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:3650	HRS	21		TSN 0				
	AFL	20		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334101	LEFT LANDING AND TAXI LIGHT							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-01								
334102	RIGHT LANDING AND TAXI LIGHT							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-01								
334201	LEFT NAVIGATION LIGHT							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-01								
334202	RIGHT NAVIGATION LIGHT							Component ATA:33
PN:1683	MOS/MSC	01-Oct-21	O/C	TSN 0				
SN:UNKNOWN	HRS	5471.4		TSN 0				
	AFL	3620		TSN 0				
PROC. REF: AMM 33-42-01								
334203	TAIL NAVIGATION LIGHT							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-02								
334301	UPPER STROBE/BEACON LIGHT							Component ATA:33
PN:GE16386-9-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:AA0242	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01								
334302	LOWER STROBE/BEACON LIGHT							Component ATA:33
PN:GE16386-9-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:AA0315	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334401	WING ICE INSPECTION LIGHT							Component ATA:33
PN:GLJ-140	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:12329	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-44-01								
334501	RECOGNITION LIGHT							Component ATA:33
PN:Q4681	MOS/MSC	29-Nov-18	O/C	TSN 0				
SN:N/A	HRS	4557.1		TSN 0				
	AFL	2931		TSN 0				
PROC. REF: AMM 33-45-01								
334502	RECOGNITION LIGHT PULSE CONTROL UNIT							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-45-02								
335001	EMERGENCY EXIT LIGHTING PANEL							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
335505	PILOT FLASHLIGHT							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
335505A	REPLACE PILOT FLASHLIGHT BATTERIES							Service ATA:33
PN:PN	MOS/MSC	29-Dec-00	A/R					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
335506	COPILOT FLASHLIGHT							Component ATA:33
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
335506A	REPLACE COPILOT FLASHLIGHT BATTERIES							Service ATA:33
PN:PN	MOS/MSC	29-Dec-00	A/R					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
33CUS1 ^U	AIRCRAFT LIGHTING LED LIGHTING							Component ATA:33
PN:PN	MOS/MSC	27-Nov-16	O/C					
SN:UNKNOWN	HRS	3381						
	AFL	2211						
33CUS1A ^U	INSPECT AIRCRAFT LED LIGHTING							Service ATA:33
PN:PN	MOS/MSC	18-Dec-20	A/R					ICA
SN:UNKNOWN	HRS	5128.4						
	AFL	3357						
P3310004 ^S	CHECK OPERATION OF INTERIOR LIGHTING SYSTEMS							Service ATA:33
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:1
P3340012 ^S	CHECK OPERATION OF EXTERIOR LIGHTING SYSTEMS							Service ATA:33
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:1
ATA 34 - NAVIGATION								
05-10-29-W3411025	FUNCTIONAL TEST AIR DATA SYSTEM							Service ATA:34
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 34-17-00								
05-10-30-RVSM-W3411015	PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (RVSM) (REFER TO 34-17-00)							Service ATA:34
	MOS	11-Mar-22	12 (+14d/-14d)		11-Mar-23	25-Mar-23	59 d (+14)	
	HRS	5539.1						
	AFL	3670						
PROC. REF: AMM 34-17-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
239501A ^U	UPGRADE ATG 5000 UNIT UPDATE GOGO SOFTWARE FOR ATG 4000/5000 TO 2.8 SOFTWARE							Service ATA:34
PN:P15864-001	MOS/MSC	20-Apr-21	-					
SN:1586418363	HRS	5252.7						
	AFL	3454						
34-00-FAR-91.171	CHECK VOR FAR 91.171							Service ATA:34
	MOS/MSC	29-Dec-00	O/C					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF, FAR FAR 91.171								
34-00-FAR-91.217	PERFORM ALTITUDE DATA TRANSMISSION TEST							Service ATA:34
	MOS/MSC	29-Dec-00	A/R					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF, FAR FAR 91.217								
34-00-FAR-91.411	RECERTIFY PITOT-STATIC SYSTEM							Service ATA:34
	MOS	23-Mar-21	24		23-Mar-23		71 d	
	HRS	5214.4						
	AFL	3422						
PROC. REF: GENERIC NO REF, FAR FAR 91.411								
340001-RVSM	CHECK RVSM HEIGHT MONITORING							Service ATA:34
	MOS	07-Jun-21	24		07-Jun-23		147 d	
	HRS	5329.7	1000		6329.7		745.5	
	AFL	3508						
PROC. REF: GENERIC NO REF								
341020	LEFT PITOT/STATIC PROBE							Component ATA:34
PN:856KR7	MOS	29-Dec-00		TSN 0			LIFE LIMIT	
SN:201510	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	9415.8 (+25)	
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-02								
341020A	VERIFY LEFT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016							Service ATA:34
PN:856KR7	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
SN:201510	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 34-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341020B	DETAILED VISUAL INSPECTION LEFT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064							Service ATA:34
PN:856KR7	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
SN:201510	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 34-11-02								
341025	RIGHT PITOT/STATIC PROBE							Component ATA:34
PN:856KR8	MOS	29-Dec-00		TSN 0				LIFE LIMIT
SN:199261	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	9415.8 (+25)	
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-02								
341025A	VERIFY RIGHT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016							Service ATA:34
PN:856KR8	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
SN:199261	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 34-11-02								
341025B	DETAILED VISUAL INSPECTION RIGHT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064							Service ATA:34
PN:856KR8	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
SN:199261	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 34-11-02								
341026	PITOT/STATIC PROBE							Component ATA:34
PN:856KR8 (STDBY)	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:201228	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-02								
341049 ^U	RADIO (ALT-4000) ALTIMETER							Component ATA:34
PN:822-0615-001	MOS/MSC	28-Oct-02	O/C	TSN 0				
SN:100CM	HRS	26		TSN 0				
	AFL	24		TSN 0				
341105	PILOT RIGHT STATIC SHUTOFF VALVE							Component ATA:34
PN:6600473-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1630	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341106	COPILOT RIGHT STATIC SHUTOFF VALVE							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03								
341107	PILOT LEFT STATIC SHUTOFF VALVE							Component ATA:34
PN:6600473-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1715	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03								
341108	COPILOT LEFT STATIC SHUTOFF VALVE							Component ATA:34
PN:6600473-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1628	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03								
341111	STANDBY ALTIMETER							Component ATA:34
PN:8047-700-53	MOS/MSC	11-Mar-22	O/C	TSO 0				
SN:10433	HRS	5539.1		TSO 0				
	AFL	3670		TSO 0				
PROC. REF: AMM 34-15-01								
341111A	RECERTIFY STANDBY ALTIMETER							Service ATA:34
PN:8047-700-53	MOS	11-Mar-22	24		11-Mar-24		425 d	
SN:10433	HRS							
	AFL							
PROC. REF: FAR FAR 91.411, AMM 34-15-01								
341133	NO. 1 LOWER (ADC) AIR DATA COMPUTER							Component ATA:34
PN:822-0389-429	MOS/MSC	02-Sep-16	O/C	TSR 0				
SN:1W33M	HRS	3960.5		TSR 0				
	AFL	2615		TSR 0				
PROC. REF: AMM 34-17-01								
341133A	RECERTIFY NO. 1 LOWER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM							Service ATA:34
PN:822-0389-429	MOS	23-Mar-21	24		23-Mar-23		71 d	
SN:1W33M	HRS	5214.4						
	AFL	3422						
PROC. REF: FAR FAR 91.411, AMM 34-17-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341134	NO. 2 UPPER (ADC) AIR DATA COMPUTER							Component ATA:34
PN:822-0389-429	MOS/MSC	10-Sep-14	O/C					
SN:4103	HRS	3532.9						
	AFL	2315						
PROC. REF: AMM 34-17-01								
341134A	RECERTIFY NO. 2 UPPER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM							Service ATA:34
PN:822-0389-429	MOS	23-Mar-21	24		23-Mar-23		71 d	
SN:4103	HRS	5214.4						
	AFL	3422						
PROC. REF: FAR FAR 91.411, AMM 34-17-00								
341222	ESIS CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341225	STANDBY AIRSPEED INDICATOR							Component ATA:34
PN:2C131 (02B7C9)	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:592	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-18-01								
341401	RADIO ALTIMETER TRANSCEIVER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-01								
341402	RADIO ALTIMETER CONVERTER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-02								
341403	AFT RADIO ALTIMETER ANTENNA							Component ATA:34
PN:622-0954-002	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:554H	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341404	FORWARD RADIO ALTIMETER ANTENNA							Component ATA:34
PN:622-0954-002	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:554J	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-03								
341703	FORWARD SIGNAL INTERFACE ADAPTER							Component ATA:34
PN:622-9732-003	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5CUF	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-02								
341704	AFT SIGNAL INTERFACE ADAPTER							Component ATA:34
PN:622-9732-003	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5K8Y	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-02								
341705	PILOT AIR DATA REFERENCE PANEL							Component ATA:34
PN:622-9500-002	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5CMH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-03								
341706	COPILOT AIR DATA REFERENCE PANEL							Component ATA:34
PN:622-9500-002	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5CMG	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-03								
341707	TAT SENSOR PROBE							Component ATA:34
PN:102AU1AG	MOS/MSC	08-Sep-03	O/C	TSN 0				
SN:A40616	HRS	378		TSN 0				
	AFL	249		TSN 0				
PROC. REF: AMM 34-17-04								
341709	PRIMARY ADC SWITCHING UNIT							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341710	SECONDARY ADC SWITCHING UNIT							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-06								
341801	STANDBY MACH/AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-18-01								
342001	MAGNETIC COMPASS MAGNETOMETER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342015 ^U	DISPLAY UNIT SENSOR							Component ATA:34
PN:622-9735-002	MOS/MSC	23-Oct-02	O/C	TSN 0				
SN:D01W	HRS	21		TSN 0				
	AFL	20		TSN 0				
342025	AHRs COOLING FAN							Component ATA:34
PN:011035	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:100342341	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342055	NO. 1 FLUX DETECTOR UNIT							Component ATA:34
PN:622-5812-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:21445	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-02								
342056	NO. 2 FLUX DETECTOR UNIT							Component ATA:34
PN:622-5812-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:21446	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342057	NO. 1 INTERNAL COMPENSATOR (ICU-85) UNIT							Component ATA:34
PN:622-6189-002	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:58HB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-04								
342058	NO. 2 INTERNAL COMPENSATOR (ICU-85) UNIT							Component ATA:34
PN:622-6189-002	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:58HA	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-04								
342301	STANDBY GYRO							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	N/A	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-23-01								
342401	MAGNETIC COMPASS							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-24-01								
342401A ^U	CALIBRATION MAGNETIC COMPASS MAGNETIC COMPASS							Service ATA:34
PN:PN	MOS/MSC	28-Aug-18	A/R					
SN:UNKNOWN	HRS	4461.3						
	AFL	2875						
342410	NO. 1 ATTITUDE/HEADING (AHC-85E) COMPUTER							Component ATA:34
PN:622-9336-400	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:5RRJ	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 34-26-01								
342411	NO. 2 ATTITUDE/HEADING (AHC-85E) COMPUTER							Component ATA:34
PN:622-9336-400	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:5FDC	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 34-26-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342412	NO. 1 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-06								
342413	NO. 2 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-06								
342501	STANDBY ATTITUDE DIRECTIONAL (ADI) INDICATOR							Component ATA:34
PN:501-1567-02	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1857	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-25-01								
343007	MARKER BEACON (37X-2) ANTENNA							Component ATA:34
PN:522-0854-069	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:52752	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-04								
344007	NO. 1 GPS							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-54-01								
344008	NO. 2 GPS							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
344111	LOWER TCAS DIRECTIONAL (TRE-920) ANTENNA							Component ATA:34
PN:622-8973-001	MOS/MSC	10-Feb-17	O/C	TSO 0				
SN:10284	HRS	3994.6		TSO 0				
	AFL	2638		TSO 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
344112	UPPER TCAS DIRECTIONAL (TRE-920) ANTENNA							Component ATA:34
PN:622-8973-001	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:8FAP	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								
344142	TCAS (TTR-920) PROCESSOR							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-01								
344143	TCAS (TTR-4000) PROCESSOR							Component ATA:34
PN:822-1294-002	MOS/MSC	10-May-19	O/C	TSO 0				
SN:141238	HRS	4649.8		TSO 0				
	AFL	2998		TSO 0				
PROC. REF: AMM 34-43-01								
344151	STORMSCOPE PROCESSOR							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344153	STORMSCOPE DISPLAY							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344155	STORMSCOPE ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344171	NO. 1 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
344176	NO. 2 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02								
344201	EFIS RADAR (ERP) PANEL							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-07								
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01								
344220	AV200 WSI ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344225	AV200 WSI SATELLITE RECEIVER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344226	WSI RECEIVER MOUNT TRAY							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344501	EGPWS BOX ASSEMBLY							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-45-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
344513	TAWS COMPUTER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344515	TAWS CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344520	TERRAIN AWARENESS ISOLATION BOX							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344806	WEATHER RADAR INDICATOR							Component ATA:34
PN:622-9302-003	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5K1F	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344807	PILOT EFIS RADAR CONTROL PANEL							Component ATA:34
PN:1015-1-11	MOS/MSC	23-Oct-02	O/C	TSN 0				
SN:563	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 34-61-07								
344808	COPILOT EFIS RADAR CONTROL PANEL							Component ATA:34
PN:1015-1-11	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:520	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-07								
345001	NO. 1 ADF (ADF-462) RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4X5T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345002	NO. 2 ADF (ADF-462) RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:5FAW	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 34-57-01								
345005	ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER							Component ATA:34
PN:965-0976-040-206-206	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:8180	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 34-45-01								
345010	AUX GPWS/WINDSHEAR INDICATOR							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345011	NO. 1 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	10-Sep-14	O/C					
SN:5FPK	HRS	3532.9						
	AFL	2315						
PROC. REF: AMM 34-55-01								
345012	NO. 2 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	10-Sep-14	O/C	TSR 0				
SN:3HG7T	HRS	3532.9		TSR 0				
	AFL	2315		TSR 0				
PROC. REF: AMM 34-55-01								
345013	ADF, DUAL (ANT-462B) ANTENNA							Component ATA:34
PN:622-7384-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5GGY	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345021	NO. 1 VHF (VIR 432) RECEIVER							Component ATA:34
PN:622-7194-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5P5C	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01								
345022	NO. 2 VHF (VIR 432) RECEIVER							Component ATA:34
PN:622-7194-101	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:44DJ	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01								
345031	NO. 1 NAVIGATION COMPUTER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-06								
345032	NO. 2 NAVIGATION COMPUTER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-06								
345043	LEFT NAVIGATION (BLADE) ANTENNA							Component ATA:34
PN:DMN4-45	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:8394	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02								
345044	RIGHT NAVIGATION (BLADE) ANTENNA							Component ATA:34
PN:DMN4-45	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:8308	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02								
345045	NO. 1 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345046	NO. 2 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02								
345079	#1 TDR-940 TRANSPONDER							Component ATA:34
PN:622-9210-501	MOS/MSC	20-Oct-20	O/C					
SN:4V330	HRS	5063.5						
	AFL	3303						
PROC. REF: AMM 34-56-01								
345079A	RECERTIFY #1 TDR-940 TRANSPONDER							Service ATA:34
PN:622-9210-501	MOS	13-Oct-22	24 (+10d/-10d)	13-Oct-24	23-Oct-24	641 d (+10)		
SN:4V330	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 34-56-00, FAR FAR 91.413								
345080	#2 TDR-940 TRANSPONDER							Component ATA:34
PN:622-9210-501	MOS/MSC	20-Oct-20	O/C					
SN:4V331	HRS	5063.5						
	AFL	3303						
PROC. REF: AMM 34-56-01								
345080A	RECERTIFY #2 TDR-940 TRANSPONDER							Service ATA:34
PN:622-9210-501	MOS	13-Oct-22	24 (+10d/-10d)	13-Oct-24	23-Oct-24	641 d (+10)		
SN:4V331	HRS	5563.7						
	AFL	3693						
PROC. REF: AMM 34-56-00, FAR FAR 91.413								
345085	NO. 1 ATC TRANSPONDER CONTROL ADAPTER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-03								
345086	NO. 2 ATC TRANSPONDER CONTROL ADAPTER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345091	NO. 1 TRANSPONDER ANTENNA							Component ATA:34
PN:CI100-2	MOS/MSC	20-Sep-19	O/C	TSR 2				
SN:447510	HRS	4708.32		TSR 0				
	AFL	3044		TSR 0				
PROC. REF: AMM 34-56-02								
345092	NO. 2 TRANSPONDER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-02								
345108	ADF PRIMARY ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-02								
345316	VLF ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345603	#1 MODE (S) TRANSPONDER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-02								
345604	#2 MODE (S) TRANSPONDER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-02								
345605	NO. 1 DME ANTENNA							Component ATA:34
PN:CI100-2	MOS/MSC	25-Jun-14	O/C					
SN:00091427	HRS	3522.3						
	AFL	2300						
PROC. REF: AMM 34-55-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345606	NO. 2 DME ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-02								
346004	DATA BASE - DBU-4000 UNIT							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-04								
346005	HEADING SPEED ALTITUDE (HSA) CONTROL PANEL							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-05								
346007	DATA LOAD (DLP) PANEL							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-07								
346011	NO. 1 FLIGHT MANAGEMENT COMPUTER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-09								
346012	NO. 2 FLIGHT MANAGEMENT COMPUTER							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-09								
346015	NO. 1 FLIGHT MANAGEMENT SYSTEM CDU							Component ATA:34
PN:1017-41-221	MOS/MSC	26-Apr-19	O/C					
SN:2396	HRS	4647.4						
	AFL	2994						
PROC. REF: AMM 34-60-01, AMM 34-61-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346016	NO. 2 FLIGHT MANAGEMENT SYSTEM CDU							Component ATA:34
PN:1017-41-221	MOS/MSC	11-Mar-22	O/C	TSR 0				
SN:2396	HRS	5539.1		TSR 0				
	AFL	3670		TSR 0				
PROC. REF: AMM 34-60-01, AMM 34-61-01								
346017	NO. 3 FLIGHT MANAGEMENT SYSTEM CDU							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-01, AMM 34-61-01								
346021	PRIMARY FMS DATA TRANSFER (DTU) UNIT							Component ATA:34
PN:1406-01-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:325	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-04								
346022	SECONDARY FMS DATA TRANSFER (DTU) UNIT							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-04								
346025	NO. 1 FMS CONFIGURATION MODULE							Component ATA:34
PN:10171	MOS/MSC	26-Aug-15	O/C	TSN 0				
SN:6480	HRS	3702.6		TSN 0				
	AFL	2436		TSN 0				
PROC. REF: GENERIC NO REF								
346026	NO. 2 FMS CONFIGURATION MODULE							Component ATA:34
PN:10171	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:2375	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
346031	PILOT ALTITUDE AWARENESS PANEL							Component ATA:34
PN:822-0328-004	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5JBV	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-03, AMM 34-61-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346032	COPILOT ALTITUDE AWARENESS PANEL							Component ATA:34
PN:822-0328-004	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5J8W	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-03, AMM 34-61-03								
346041	COURSE HEADING PANEL							Component ATA:34
PN:622-7397-006	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:5LCH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-02, AMM 34-61-02								
346055	CONFIGURATION, AFIS MODULE							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
346071	UNILINK CONFIGURATION MODULE							Component ATA:34
PN:10651	MOS/MSC	23-Oct-02	O/C	TSN 0				
SN:1062	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								
346090	AFIS DATA MANAGEMENT UNIT							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
346091	DATA TRANSFER, AFIS UNIT							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
346092	AFIS ANTENNA							Component ATA:34
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
347510	FORWARD GPS ANTENNA							Component ATA:34
PN:10706	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6131	HRS	0		TSN 0				
	AFL	0		TSN 0				
347511	AFT GPS ANTENNA							Component ATA:34
PN:10706	MOS/MSC	06-Feb-21	O/C	TSN 0				
SN:17437	HRS	5182.4		TSN 0				
	AFL	3394		TSN 0				
34CUS1 ^U	GENERAL VISUAL INSPECTION OF ALLIED SIGNAL EGPWS PER STC							Service ATA:34
	MOS	11-Mar-22	12		11-Mar-23		59 d	ICA
	HRS	5539.1						
	AFL	3670						
34CUS2 ^U	ADS-B FLIGHT 1D ADAPTER							Component ATA:34
PN:833613-00	MOS/MSC	22-Oct-18	O/C					
SN:715	HRS	4496.3						
	AFL	2900						
34CUS3 ^U	FREEFLIGHT GPS SENSOR							Component ATA:34
PN:84327-50-XXXX	MOS/MSC	22-Oct-18	O/C					
SN:1820K132	HRS	4496.3						
	AFL	2900						
34CUS4 ^U	GPS/WAAS ANTENNA							Component ATA:34
PN:S67-1575-L45	MOS	22-Oct-18						
SN:824-5	HRS	4496.3						
	AFL	2900	20000	TSN 0	22900		19195	
34CUS4A ^U	INSPECT GPS/WAAS ANTENNA PER HFEC INSPECTION REQUIREMENT							Service ATA:34
PN:S67-1575-L45	MOS	22-Oct-18						ICA
SN:824-5	HRS	4496.3						
	AFL	2900	T:15000		17900		14195	
34CUS5 ^U	GENERAL VISUAL INSPECTION OF THE NEWLY INSTALLED WIRES, DIGITAL DISCRETE ADAPTER OR AIRCRAFT FLIGHT ID ADAPTER, AND ADS-B ANNUNCIATOR FOR CONDITION AND SECURITY AFTER STC ST03424CH INSTALLATION							Service ATA:34
	MOS	22-Oct-18	60		22-Oct-23		284 d	
	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34CUS6 ^U	PREFORM A VISUAL INSPECTION OF THE FREEFLIGHT 1203C GPS SENSOR P/N 84327-50-XXXX AND THE GPS/WAAS/LPV ANTENNAPIN S67-1575-145 AFTER THE INSTALLATION OF STC ST03424CH.							Service ATA:34
	MOS	10-May-21						
	HRS	5275.8	800		6075.8		491.6	
	AFL	3466						
H3411010 ^S	INSPECT PITOT TUBES, STATIC AND PITOT LINES, DRAIN LINES, AND WIRING FOR CONDITION AND SECURITY. CHECK STATIC PORTS AND PITOT/STAIC PROBES FOR DISTORTION. CHECK OPERATION OF DRAIN VALVES. (REFER TO 34-11-02)							Service ATA:34
	MOS	20-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 34-11-02							PKG:8
H3411012 ^S	INSPECT AIR TEMPERATURE SENSOR OR AIR DATA COMPUTER STATIC, PITOT, AND DRAIN LINES FOR CONDITION AND SECURITY. CHECK OPERATION OF DRAIN VALVES.							Service ATA:34
	MOS	20-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: GENERIC NO REF							PKG:8
H3411031 ^S	PERFORM FUNCTIONAL TEST OF STATIC SHUTOFF (ISOLATION) VALVES. (REFER TO 34-11-00)							Service ATA:34
	MOS	18-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: AMM 34-11-00							PKG:7
K3411061 ^S	PITOT-STATIC PROBE HEATING CURRENT SENSING RELAY - PERFORM FUNCTIONAL TEST. (REFER TO 30-30-01)							Service ATA:34
	MOS/MSC	18-Apr-17	N/A					
	HRS	4053.4						
	AFL	2668						
	APH	1090						
	ACH	1195.9						
	PROC. REF: AMM 30-30-01							PKG:7
P3400004 ^S	INSPECT NOSE COMPARTMENT FROM THE FORWARD SIDE OF THE FORWARD PRESSURE BULKHEAD, FORWARD, FOR CLEANLINESS. ELECTRONIC AND ELECTRICAL EQUIPMENT AND ANTENNA INSTALLATIONS FOR SECURITY OF MOUNTING AND GENERAL CONDITION. WIRE BUNDLE AND PLUMBING ROUTING FOR SECURIT							Service ATA:34
	MOS	20-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: GENERIC NO REF							PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
T3453003 ^S INSPECT ANTENNA INSTALLATIONS FOR SECURITY, CORROSION, AND PROPER TENSION OF HF ANTENNA WIRE. (REFER TO 23-12-03.) Service ATA:34								
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:18
U3411014 ^S INSPECT PITOT STATIC PROBES - PERFORM PITOT-STATIC PROBE DRAIN HOLE CHECK. (REFER TO 34-11-02) Service ATA:34								
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: AMM 34-11-02								PKG:2
ATA 35 - OXYGEN								
350003 NOSE OXYGEN SYSTEM PRESSURE TRANSDUCER Component ATA:35								
PN:124058-2000	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:40461	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: AMM 35-00-02								
350004 DORSAL OXYGEN SYSTEM PRESSURE TRANSDUCER Component ATA:35								
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-02								
350005 NOSE OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY Component ATA:35								
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-03								
350006 DORSAL OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY Component ATA:35								
PN:172180-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0507	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350007	NOSE OXYGEN PRESSURE INDICATOR							Component ATA:35
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-04								
350008	DORSAL OXYGEN PRESSURE INDICATOR							Component ATA:35
PN:6608401-20	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:255	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-04								
351001	PILOT OXYGEN MASK							Component ATA:35
PN:MC10-15-176	MOS/MSC	30-Mar-19	O/C	TSO 0				
SN:94225	HRS	4647.4		TSO 0				
	AFL	2994		TSO 0				
PROC. REF: AMM 35-10-01								
351001A	OVERHAUL PILOT OXYGEN MASK							Service ATA:35
PN:MC10-15-176	MOS	30-Mar-19	72 (+14d/-14d)		30-Mar-25	13-Apr-25	809 d (+14)	
SN:94225	HRS	4647.4						
	AFL	2994						
PROC. REF: GENERIC NO REF								
351002	COPILOT OXYGEN MASK							Component ATA:35
PN:MC10-15-176	MOS/MSC	08-Mar-20	O/C	TSO 0				
SN:89990	HRS	4808.4		TSO 0				
	AFL	3112		TSO 0				
PROC. REF: AMM 35-10-01								
351002A	OVERHAUL COPILOT OXYGEN MASK							Service ATA:35
PN:MC10-15-176	MOS	08-Mar-20	72 (+14d/-14d)		08-Mar-26	22-Mar-26	1152 d (+14)	
SN:89990	HRS	4808.4						
	AFL	3112						
PROC. REF: GENERIC NO REF								
351025	OXYGEN SYSTEM PRESSURE SWITCH							Component ATA:35
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
351071	PILOT CREW OXYGEN MASK BOX							Component ATA:35
PN: MXP302	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN: 22271	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-10-01								
351072	COPILOT CREW OXYGEN MASK BOX							Component ATA:35
PN: MXP302	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN: 22272	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-10-01								
352006	NOSE OXYGEN CYLINDER							Component ATA:35
PN: PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN: UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-01								
352007	DORSAL OXYGEN CYLINDER							Component ATA:35
PN: 176194-76	MOS	27-Apr-20	288 (+14d/-14d)	TSN 0	01-Jul-31	15-Jul-31	3093 d (+14)	LIFE LIMIT
SN: 0852-K888341	HRS	4827.6						
	AFL	3129						
Manufacture Date:: 01-Jul-07 PROC. REF: AMM 35-00-01								
352007A	HYDROSTATIC TEST DORSAL OXYGEN CYLINDER							Service ATA:35
PN: 176194-76	MOS	27-Apr-20	60 (+14d/-14d)		27-Apr-25	11-May-25	837 d (+14)	
SN: 0852-K888341	HRS	4827.6						
	AFL	3129						
PROC. REF: GENERIC NO REF								
352027	PASSENGER OXYGEN CONTROL VALVE							Component ATA:35
PN: P21004-3	MOS/MSC	21-Nov-03	O/C	TSN 0				
SN: 0180	HRS	457		TSN 0				
	AFL	307		TSN 0				
PROC. REF: AMM 35-20-03								
352031	FORWARD SELECTOR, OXYGEN VALVE							Component ATA:35
PN: PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN: UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
352032	AFT SELECTOR, OXYGEN VALVE							Component ATA:35
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05								
352033	RIGHT AFT SELECTOR, OXYGEN VALVE							Component ATA:35
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-06								
352040	PROTECTIVE BREATHING (PBE) EQUIPMENT							Component ATA:35
PN:802300-14	MOS	23-Oct-20	120 (+14d/-14d)	TSN 18	01-Dec-28 (M)	15-Dec-28	2151 d (+14)	LIFE LIMIT
SN:E18120277	HRS	5063.5		TSN 0				
	AFL	3303		TSN 0				
PROC. REF: GENERIC NO REF								
353001	L1 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-766-01	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:0294	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								
353002	R1 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-766-02	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:0282	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								
353003	L2 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-766-01	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:0284	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								
353004	R3 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-766-02	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:0281	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
353005	L3 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-766-01	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:0288	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								
353006	R4 OXYGEN MASK DROP BOX							Component ATA:35
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
353007	R2 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-766-01	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:0296	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF								
353013	PORTABLE O2 BOTTLE							Component ATA:35
PN:5500-C1W-BF23A	MOS/MSC	22-Nov-19	O/C	TSN 0				
SN:P19071836	HRS	4718.5		TSN 0				
	AFL	3054		TSN 0				
PROC. REF: GENERIC NO REF								
353013A	VISUAL INSPECTION PORTABLE O2 BOTTLE							Service ATA:35
PN:5500-C1W-BF23A	MOS	02-May-22	12 (+14d/-14d)		02-May-23	16-May-23	111 d (+14)	
SN:P19071836	HRS	5542.1						
	AFL	3671						
PROC. REF: GENERIC NO REF								
353013B	PERFORM PORTABLE O2 BOTTLE ICC HYDROSTATIC TEST ON PORTABLE OXYGEN CYLINDER (STEEL, DOT3AA1800) (IF INSTALLED)							Service ATA:35
PN:5500-C1W-BF23A	MOS	01-Jul-19	60 (+14d/-14d)		01-Jul-24	15-Jul-24	537 d (+14)	
SN:P19071836	HRS							
	AFL							
PROC. REF: GENERIC NO REF								
H3500020 ^S	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY.							Service ATA:35
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								
								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
P3510020 ^S	ON AIRCRAFT EQUIPPED WITH E.R.O.S. AVIATION CREW MASKS, PERFORM FUNCTIONAL TEST OF OXYGEN MASK. (REFER TO 35-10-01.)							Service ATA:35
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: AMM 35-10-01							PKG:13
T3500000 ^S	FUNCTIONAL TEST OF OXYGEN SYSTEM. (REFER TO 35-00-00.)							Service ATA:35
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: AMM 35-00-00							PKG:14
T3500010 ^S	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY.							Service ATA:35
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: GENERIC NO REF							PKG:14
T3500040 ^S	CHECK CREW MEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) FOIL POUCH FOR VACUUM SEAL INTEGRITY. IF VACUUM SEAL IS BROKEN, REPLACE EQUIPMENT.							Service ATA:35
	MOS	15-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: GENERIC NO REF							PKG:7
ATA 36 - PNEUMATIC								
05-11-00-W3610011	REPLACE ENGINE BLEED AIR CHECK VALVES							Service ATA:36
	MOS	18-Mar-19						
	HRS	4647.4	2400 (+25/-25)		7047.4	7072.4	1463.2 (+25)	
	AFL	2994						
	PROC. REF: AMM 36-10-06							
360001	REPLACE LEFT ENGINE PYLON BLEED AIR SEALS							Service ATA:36
	MOS/MSC	02-Sep-16	O/C					
	HRS	3960.5						
	AFL	2615						
	PROC. REF: AMM 36-10-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
360002	REPLACE RIGHT ENGINE PYLON BLEED AIR SEALS							Service ATA:36
	MOS/MSC	02-Sep-16	O/C					
	HRS	3960.5						
	AFL	2615						
PROC. REF: AMM 36-10-01								
360003	REPLACE TAILCONE BLEED AIR SEALS (LOCATED BETWEEN THE FORWARD BLEED AIR MANIFOLD AND AFT BLEED AIR MANIFOLD) (REFER TO 36-10-01)							Service ATA:36
	MOS	18-Mar-19						
	HRS	4647.4	1200 (+25/-25)		5847.4	5872.4	263.2 (+25)	
	AFL	2994						
PROC. REF: AMM 36-10-01								
361001	NO. 1 BLEED AIR REGULATING/SHUTOFF VALVE							Component ATA:36
PN:895B/10E87-1	MOS/MSC	20-Sep-19	O/C					
SN:221	HRS	4708.32						
	AFL	3044						
PROC. REF: AMM 36-10-04								
361002	NO. 2 BLEED AIR REGULATING/SHUTOFF VALVE							Component ATA:36
PN:895B/10E87-1	MOS/MSC	20-Sep-19	O/C					
SN:219	HRS	4708.32						
	AFL	3044						
PROC. REF: AMM 36-10-04								
361011	LEFT BLEED AIR MIXING VALVE							Component ATA:36
PN:1H106-8	MOS/MSC	29-Apr-19	O/C					
SN:1AR1	HRS	4647.4						
	AFL	2994						
PROC. REF: AMM 36-10-02								
361012	RIGHT BLEED AIR MIXING VALVE							Component ATA:36
PN:1H106-8	MOS/MSC	29-Apr-19	O/C					
SN:4AK20	HRS	4647.4						
	AFL	2994						
PROC. REF: AMM 36-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361013	NO. 1 BLEED AIR CHECK VALVE							Component ATA:36
PN:6608295-3	MOS/MSC	18-Mar-19	O/C	TSN 0				
SN:4764	HRS	4647.4		TSN 0				
	AFL	2994		TSN 0				
PROC. REF: AMM 36-10-06								
361014	NO. 2 BLEED AIR CHECK VALVE							Component ATA:36
PN:6608295-3	MOS/MSC	18-Mar-19	O/C	TSN 0				
SN:4761	HRS	4647.4		TSN 0				
	AFL	2994		TSN 0				
PROC. REF: AMM 36-10-06								
361017	NO. 1 BLEED AIR (1 1/4) CHECK VALVE							Component ATA:36
PN:6600210-10	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:7037	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03								
361018	NO. 2 BLEED AIR (1 1/4) CHECK VALVE							Component ATA:36
PN:6600210-10	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:7032	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03								
361037	* NO. 1 EMERGENCY AIR BOTTLE (AWL*)							Component ATA:36
PN:23111425	MOS	08-Jun-18	180		26-Apr-24		471 d	SCRAP
SN:1187	HRS	4376.2						
	AFL	2832						
Manufacture Date:: 26-Apr-09 PROC. REF: AMM 36-15-01								
361037A	PERFORM * NO. 1 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST							Service ATA:36
PN:23111425	MOS	23-Mar-21	36 (+14d/-14d)		11-Mar-24 (M)	25-Mar-24	425 d (+14)	
SN:1187	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 36-15-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361037B	X-RAY INSPECT * NO. 1 EMERGENCY AIR BOTTLE							Service ATA:36
PN:23111425	MOS	23-Mar-21	36 (+14d/-14d)		23-Mar-24	06-Apr-24	437 d (+14)	
SN:1187	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 36-15-01								
361038	* NO. 2 EMERGENCY AIR BOTTLE (AWL*)							Component ATA:36
PN:6600194-008	MOS	08-Jun-18	180		14-Oct-30		2833 d	SCRAP
SN:00546	HRS	4376.2		TSN 0				
	AFL	2832		TSN 0				
Manufacture Date:: 14-Oct-15 PROC. REF: AMM 36-15-01								
361038A	PERFORM * NO. 2 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST							Service ATA:36
PN:6600194-008	MOS	11-Mar-21	36 (+14d/-14d)		11-Mar-24	25-Mar-24	425 d (+14)	
SN:00546	HRS							
	AFL							
PROC. REF: AMM 36-15-01								
361038B	PERFORM * NO. 2 EMERGENCY AIR BOTTLE X-RAY INSPECTION							Service ATA:36
PN:6600194-008	MOS	23-Mar-21	36 (+14d/-14d)		23-Mar-24	06-Apr-24	437 d (+14)	
SN:00546	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 36-15-01								
361125	LEFT TAILCONE BLEED AIR CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03								
361126	RIGHT TAILCONE BLEED AIR CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
362001	LANDING GEAR/BRAKE AIR PRESSURE INDICATOR							Component ATA:36
PN:6608401-12	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:412	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-01								
362003	PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER							Component ATA:36
PN:124058-5000	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:42054	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02								
362004	SECONDARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER							Component ATA:36
PN:124058-5000	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:42060	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02								
362011	NO. 1 ENGINE HI-LIMIT BLEED AIR THERMOSTAT							Component ATA:36
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-03								
362012	NO. 2 ENGINE HI-LIMIT BLEED AIR THERMOSTAT							Component ATA:36
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-03								
362019	NO. 1 INBOARD OVERHEAT SWITCH							Component ATA:36
PN:6600213-5	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:163401	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
362020	NO. 2 INBOARD OVERHEAT SWITCH							Component ATA:36
PN:6600213-5	MOS/MSC	23-Dec-02	O/C	TSN 0				
SN:177947	HRS	79		TSN 0				
	AFL	66		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
H3620001 ^S	FUNCTIONAL TEST OF PYLON OVERHEAT THERMOSTAT, DUCT TEMPERATURE SENSOR, AND ELECTRICAL SYSTEM. (REFER TO 36-20-03 AND 36-20-04.)							Service ATA:36
	MOS	11-Apr-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
				PROC. REF: AMM 36-20-03, AMM 36-20-04				PKG:21
J3610037 ^S	VISUALLY INSPECT HIGH PRESSURE BLEED AIR CHECK VALVES							Service ATA:36
	MOS	22-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
				PROC. REF: AMM 36-10-06				PKG:21
L3610039 ^S	PERFORM OPERATIONAL CHECK OF BLLED AIR CHECK VALVES. (REFER TO 36-10-03).							Service ATA:36
	MOS	25-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: AMM 36-10-03				PKG:9
U3610044 ^S	GENERAL VISUAL INSPECTION BLEED AIR DUCTING (INCLUDING CLAMPS AND VALVES). (REFER TO 5-10-00)							Service ATA:36
	MOS	20-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: GENERIC NO REF				PKG:9
ATA 38 - WATER/WASTE								
381008	LAVATORY SINK FAUCET							Component ATA:38
PN:HV1C-016	MOS/MSC	23-Jul-20	O/C					
SN:N/A	HRS	4919.4						
	AFL	3196						
				PROC. REF: GENERIC NO REF				
381009	FORWARD TOILET DRAIN, HEATED MAST							Component ATA:38
PN:116393-101C	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:971	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 38-32-01				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
381010	AFT TOILET DRAIN, HEATED MAST							Component ATA:38
PN:116393-101C	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:980	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-32-01								
381020	TOILET WATER PUMP							Component ATA:38
PN:5250-10	MOS/MSC	10-Sep-14	O/C	TSN 0				
SN:P7941	HRS	3532.9		TSN 0				
	AFL	2315		TSN 0				
PROC. REF: GENERIC NO REF								
381030	TOILET TIMER							Component ATA:38
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
381050	TOILET MACERATOR							Component ATA:38
PN:5300-1	MOS/MSC	30-Oct-18	O/C	TSN 0				
SN:M6175	HRS	4509.4		TSN 0				
	AFL	2905		TSN 0				
PROC. REF: GENERIC NO REF								
381060	LAVATORY ON-DEMAND WATER SYSTEM VOLTAGE REGULATOR							Component ATA:38
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
381070	LAVATORY SINK PUMP							Component ATA:38
PN:42510-0000	MOS/MSC	23-Jul-20	O/C	TSN 0				
SN:N/A	HRS	4919.4		TSN 0				
	AFL	3196		TSN 0				
PROC. REF: GENERIC NO REF								
382015	NO. 1 HOT WATER TANK							Component ATA:38
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
382016	NO. 2 HOT WATER TANK							Component ATA:38
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
383101	LAVATORY TOILET ASSEMBLY							Component ATA:38
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-31-01								
ATA 44 - CABIN SYSTEMS								
442401	XM RADIO RECEIVER							Component ATA:44
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-54-01								
442403	GPS/XM ANTENNA							Component ATA:44
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
ATA 45 - CENTRAL MAINT SYSTEM								
451001	MAINTENANCE DIAGNOSTIC (MDC) COMPUTER							Component ATA:45
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 45-10-00								
ATA 49 - AIRBORNE AUXILIARY POWER								
490020	APU - ESU - ELECTRONIC SENSOR UNIT							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
490030	APU - SEAL PLATE							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
490101	COCKPIT APU CONTROL PANEL							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-01								
490102	APU RELAY BOX							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-02								
490103	(ESU / DESU) ELECTRONIC SEQUENCE UNIT							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-03, SMM 49-01-04								
490105	APU (GCU) GENERATOR CONTROL UNIT							Component ATA:49
PN:GCSG505-16G	MOS/MSC	11-Mar-22	O/C	TSR 0				
SN:1019C	HRS	5539.1		TSR 0				
	AFL	3670		TSR 0				
PROC. REF: GENERIC NO REF, SMM 49-01-05								
490106	BITE ANNUNCIATOR BOX							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-06								
490109	UPPER CURRENT TRANSFORMER							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
490110	LOWER CURRENT TRANSFORMER							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
490111	CURRENT SENSOR							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-10								
492000	APU - PRESERVATION AND STORAGE OF APU							Service ATA:49
	MOS/MSC	29-Sep-06	A/R					
	HRS	0						
	APUS	0						
492001	APU - COMBUSTOR HOUSING ASSEMBLY							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	1.73		TSN 0				
	APUS	16		TSN 0				
492002	APU - APU EXHAUST THERMOCOUPLE							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	1.73		TSN 0				
	APUS	16		TSN 0				
492010	APU - TURBINE NOZZLE							Component ATA:49
PN:160912-200	MOS/MSC	13-Aug-17	O/C	TSN 0				
SN:0225	HRS	1676		TSN 0				
	APUS	3500		TSN 0				
492020	APU - IGNITER							Component ATA:49
PN:160544-1	MOS/MSC	18-Dec-20	O/C	TSN 0				
SN:NSN	HRS	2324		TSN 0				
	APUS	4592		TSN 0				
492030	APU - OUTPUT GEAR							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
492040	APU - BITE BOX							Component ATA:49
PN:161212-100	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:0623-0817	HRS	1.73		TSN 0				
	APUS	16		TSN 0				
492050	APU - SHAFT							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492201	APU - ROTOR BEARING							Component ATA:49
PN:161623-1	MOS/MSC	13-Aug-17	O/C	TSN 0				
SN:R022	HRS	1676		TSN 0				
	APUS	3500		TSN 0				
492202	APU - ROTOR BEARING							Component ATA:49
PN:161623-1	MOS/MSC	13-Aug-17	O/C	TSN 0				
SN:R020	HRS	1676		TSN 0				
	APUS	3500		TSN 0				
492207	APU - HOUSING BEARING SUPPORT							Component ATA:49
PN:161617-100	MOS/MSC	13-Aug-17	O/C	TSN 0				
SN:UNKNOWN	HRS	1676		TSN 0				
	APUS	3500		TSN 0				
492208	APU - BEARING HOUSING ADAPTER							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492300	APU - PRESSURE (LOW OIL) SWITCH							Component ATA:49
PN:4951600	MOS/MSC	09-May-07	O/C	TSN 0				
SN:325	HRS	14		TSN 0				
	APUS	68		TSN 0				
492320	APU - SPEED (MAGNETIC PICK-UP) SENSOR							Component ATA:49
PN:169080-1	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:B332	HRS	1.73		TSN 0				
	APUS	16		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
493001	APU - FUEL CONTROL							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	1.73		TSN 0				
	APUS	16		TSN 0				
493003	APU - PUMP ASSEMBLY, FUEL CONTROL							Component ATA:49
PN:4502863C	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:08-06-24	HRS	1.73		TSN 0				
	APUS	16		TSN 0				
493005	APU - FUEL ATOMIZER INTERCONNECT HARNESS							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	1.73		TSN 0				
	APUS	16		TSN 0				
493007	APU - ASSEMBLY, FUEL ATOMIZER							Component ATA:49
PN:4504283A	MOS/MSC	04-Jan-16	O/C	TSR 0				
SN:09-04-25	HRS	1521		TSR 0				
	APUS	3217		TSR 0				
493010	APU - HARNESS							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
493055	APU - ATOMIZER CUP MOTOR							Component ATA:49
PN:4953094	MOS/MSC	13-Aug-17	O/C	TSR 0				
SN:M755	HRS	1676		TSR 0				
	APUS	3500		TSR 0				
493101	APU FUEL SHUTOFF VALVE							Component ATA:49
PN:EM91-41	MOS/MSC	04-Jun-01	O/C	TSN 0				
SN:00524309	HRS	21		TSN 0				
	AFL	20		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-31-01								
493102	APU - FUEL PUMP							Component ATA:49
PN:161627-2	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:V60T0423	HRS	1.73		TSN 0				
	APUS	16		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
493102	APU FUEL BOOST PUMP							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-31-02								
494001	APU - IGNITION EXCITER							Component ATA:49
PN:4951302	MOS/MSC	29-Nov-18	O/C	TSN 0				
SN:NNA14110061	HRS	1919		TSN 0				
	APUS	3885		TSN 0				
495001	APU - TURBINE WHEEL							Component ATA:49
PN:164253-3	MOS	13-Aug-17		TSN 1				LIFE LIMIT
SN:HB147	HRS	1676		TSN 0				
	APUS	3500	3500	TSN 0	7000		1903	
495005	APU - COMPRESSOR WHEEL							Component ATA:49
PN:160915-4	MOS	13-Aug-17		TSN 49				LIFE LIMIT
SN:H424B	HRS	1676		TSN 0				
	APUS	3500	7000	TSN 0	10500		5403	
495010	APU - AIR INLET HOUSING							Component ATA:49
PN:160909-2	MOS/MSC	13-Aug-17	O/C	TSN 0				
SN:13L0001	HRS	1676		TSN 0				
	APUS	3500		TSN 0				
496103	APU FIRE HORN							Component ATA:49
PN:430-M1	MOS/MSC	16-Jul-03	O/C					
SN:20519	HRS	298						
	AFL	204						
PROC. REF: GENERIC NO REF, SMM 49-61-03								
497010	APU - HOURMETER/EVENT COUNTER INDICATOR							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	1.73		TSN 0				
	APUS	16		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
498010	EXHAUST (APU) DUCT							Component ATA:49
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
499010	APU - OIL PUMP GEAR							Component ATA:49
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
49APU1	APU							Component ATA:49
PN:4503135	MOS/MSC	16-Dec-21	E/C					
SN:SP-E060449	HRS	5539.1		TSN 2623				
WC#: 49.APU1	AFL	3670						
PROC. REF: GENERIC NO REF								
49CUS1 ^U	APU - APU FUEL BOOST PUMP							Component ATA:49
PN:1500-00-22	MOS/MSC	06-Aug-18	O/C	TSO 0				
SN:2123	HRS	1866		TSO 0				
	APUS	3774		TSO 0				
ATA 52 - DOORS								
05-10-29-L5210025	VISUAL INSPECTION EXTERIOR LWR DOOR STRUCTURE/HINGE FOR CORROSION							Service ATA:52
	MOS	11-Mar-22	24 (+14d/-14d)		11-Mar-24	25-Mar-24	425 d (+14)	
	HRS	5539.1						
	AFL	3670						
PROC. REF: GENERIC NO REF								
521001	UPPER PASSENGER/CREW DOOR							Component ATA:52
PN:5410501-115	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:W-152	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00								
521002	LOWER PASSENGER/CREW DOOR							Component ATA:52
PN:5410536-032	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:W260	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
521003	UPPER PASSENGER/CREW DOOR HANDLE							Component ATA:52
PN:6600480-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:270	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-02								
521004	UPPER PASSENGER/CREW DOOR LOCK ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-03								
5210054	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE - REPLACE							Service ATA:52
	MOS	20-Apr-21	144 (+14d/-14d)		20-Apr-33	04-May-33	3752 d (+14)	
	HRS	5252.7						
	AFL	3454	6000 (+25/-25)		9454	9479	5749 (+25)	
PROC. REF: AMM 52-10-02, AMM 52-20-02								
521006	UPPER PASSENGER/CREW DOOR DAMPER							Component ATA:52
PN:7600838-002	MOS/MSC	20-Jan-21	O/C					
SN:UNKNOWN	HRS	5171.2						
	AFL	3384						
PROC. REF: AMM 52-10-06								
521008	LOWER PASSENGER/CREW DOOR HANDLE							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-08								
521010	FORWARD PASSENGER/CREW LOWER DOOR CABLE							Component ATA:52
PN:6015550-003	MOS/MSC	14-Jul-21	O/C	TSN 0				
SN:NSN	HRS	5372.3		TSN 0				
	AFL	3539		TSN 0				
PROC. REF: AMM 52-10-10								
521011	AFT PASSENGER/CREW LOWER DOOR CABLE							Component ATA:52
PN:6015550-002	MOS/MSC	23-Dec-19	O/C					
SN:N/A	HRS	4745						
	AFL	3074						
PROC. REF: AMM 52-10-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
521012	LOWER PASSENGER/CREW DOOR DAMPER							Component ATA:52
PN:6600425-2	MOS/MSC	03-Jan-14	O/C	TSN 0				
SN:1454	HRS	3430		TSN 0				
	AFL	2225		TSN 0				
PROC. REF: AMM 52-10-11								
522000	EMERGENCY EXIT / BAGGAGE DOOR							Component ATA:52
PN:6011501-12	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:W222	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00								
522002	EMERGENCY EXIT / BAGGAGE DOOR HANDLE							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-02								
522005	PASSENGER DOOR FORWARD SNUBBER							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-15								
522006	PASSENGER DOOR AFT SNUBBER							Component ATA:52
PN:7600838-002	MOS/MSC	20-Jan-21	O/C					
SN:UNKNOWN	HRS	5171.2						
	AFL	3384						
PROC. REF: AMM 52-10-15								
522007	EMERGENCY EXIT DOOR FORWARD SNUBBER							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-07								
522008	EMERGENCY EXIT DOOR AFT SNUBBER							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
522025	EMERGENCY EXIT/BAGGAGE DAMPER							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00								
522032	EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY							Component ATA:52
PN:LA6600405-30	MOS/MSC	26-Apr-19	O/C	TSN 0				
SN:1051	HRS	4647.4		TSN 0				
	AFL	2994		TSN 0				
PROC. REF: AMM 52-20-06								
522032A	PRISM CHECK EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY 05-10-29-M5600008							Service ATA:52
PN:LA6600405-30	MOS/MSC	26-Apr-19	C/C					
SN:1051	HRS	4647.4						
	AFL	2994						
PROC. REF: NDT 56-30-01								
523101	TAILCONE BAGGAGE DOOR							Component ATA:52
PN:6011552-17	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:220/2656	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-01								
523102	TAILCONE BAGGAGE HANDLE							Component ATA:52
PN:6600480-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:249	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-01								
524001	PERFORM AFT AVIONICS DOOR GAP AND MISMATCH INSPECTION (RVSM) (REFER TO 52-40-01)							Service ATA:52
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 52-40-01								
524003	LEFT FORWARD NOSE AVIONICS DOOR							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
524004	RIGHT FORWARD NOSE AVIONICS DOOR							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01								
524005	LEFT AFT NOSE AVIONICS DOOR							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01								
524006	RIGHT AFT NOSE AVIONICS DOOR							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01								
524007	TAILCONE AVIONICS DOOR							Component ATA:52
PN:5412500-21	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0113	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-02								
527005	CREW DOOR WARNING BOX ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-70-05								
527006	EMERGENCY EXIT DOOR WARNING BOX ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-70-05								
528001	LEFT INBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:6022161-807	MOS/MSC	10-Sep-14	O/C	TSN 0				
SN:UNKNOWN	HRS	3532.9		TSN 0				
	AFL	2315		TSN 0				
PROC. REF: AMM 52-80-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
528002	RIGHT INBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:6022161-808	MOS/MSC	10-Sep-14	O/C	TSN 0				
SN:UNKNOWN	HRS	3532.9		TSN 0				
	AFL	2315		TSN 0				
PROC. REF: AMM 52-80-01								
528003	LEFT OUTBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01								
528004	RIGHT OUTBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:6022151-802	MOS/MSC	20-Sep-19	O/C	TSR 0				
SN:NSN	HRS	4708.32		TSR 0				
	AFL	3044		TSR 0				
PROC. REF: AMM 52-80-01								
528101	LEFT NOSE LANDING GEAR DOOR							Component ATA:52
PN:5410450-19	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:60-210	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-81-01								
528102	RIGHT NOSE LANDING GEAR DOOR							Component ATA:52
PN:5410450-20	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:60-210	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-81-01								
52CUS1 ^U	PAX DOOR LOCK/UNLOCK SWITCH.							Component ATA:52
PN:311SM7-T	MOS/MSC	28-Nov-17	O/C					
SN:UNKNOWN	HRS	4222.4						
	AFL	2747						
A5210030 ^S	REMOVE TENSION FITTINGS AND PLATES FROM PASSENGER/CREW DOORS (SIX [6] IN EACH DOOR). MAGNETIC PARTICLE INSPECT FOR EVIDENCE OF CRACKS. (REFER TO NDI MANUAL [NDI-2], PART 6, 52-10-01 AND 53-10-01.)							Service ATA:52
	MOS	12-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
PROC. REF: NDT 52-10-01, NDT 53-10-01, AMM 52-10-17								
PKG:25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
AA5210056 ^S		CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION						Service ATA:52
	MOS	29-Dec-00	48 (+14d/-14d)					
	HRS	0	1200 (+25/-25)					
	AFL	0						
PROC. REF: AMM 12-21-03								PKG:18
C5210052 ^S		UPPER AND LOWER DOOR HANDLE MECHANISM: GAIN ACCESS TO UPPER AND LOWER DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION.						Service ATA:52
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF								PKG:27
C5220021 ^S		EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM; GAIN ACCESS TO EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION.						Service ATA:52
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: NDT 52-60-01								PKG:27
E5220010 ^S		EMERGENCY EXIT/BAGGAGE DOOR HINGE INSTALLATION FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT HINGE INSTALLATIONS WHILE RACKING THE DOOR WITH ALTERNATING LOADS.						Service ATA:52
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 52-20-00								PKG:18
E5220020 ^S		EMERGENCY EXIT/BAGGAGE DOOR HANDLE AND CONTROL ASSEMBLY FREE PLAY CHECK. OPEN DOOR AND REMOVE UPHOLSETRY TO GAIN ACCESS TO ROD CONTROL ASSEMBLY. RESTRAIN THE DOOR PINS AND MOVE THE EMERGENCY EXIT/BAGGAGE DOOR HANDLE TOWARD THE CLOSED POSITION AND THEN TO						Service ATA:52
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 52-20-00								PKG:18
E5280002 ^S		VISUALLY INSPECT TAILCONE AVIONICS AND BAGGAGE DOOR ELECTRICAL BONDING JUMPERS, WHEN INSTALLED, FOR SECURITY AND GENERAL CONDITION						Service ATA:52
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
H5210020 ^S	UPPER AND LOWER DOOR HINGE INSTALLATIONS FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT EDGES OF HINGE INSTALLATION WHILE RACKING THE DOORS WITH ALTERNATING LOADS. IF HINGE INSTALLATION CONDITION REQUIRES A MORE THO							Service ATA:52
	MOS	20-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:24	
H5210040 ^S	CLEAN ARM GUIDES OF PASSENGER/CREW UPPER DOOR AND VISUALLY CHECK FOR CRACKS. (SEE FIGURE 1.)							Service ATA:52
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:18	
H5210060 ^S	INSPECT ENTIRE LENGTH OF LOWER DOOR CABLES FOR EVIDENCE OF FRAYING OR OTHER DAMAGE. DOOR ACCESS PANELS MUST BE REMOVED. (REFER TO 52-10-10)							Service ATA:52
	MOS	21-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 52-10-10							PKG:12	
H5210065 ^S	CLEAN LATCH ARM OF PASSENGER/CREW LOWER DOOR AND VISUALLY INSPECT FOR CRACKS. (SEE FIGURE 1.)							Service ATA:52
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:18	
H5210086 ^S	CHECK LOWER CABIN DOOR MECHANISM. OPEN UPPER AND LOWER CABIN DOORS. MOVE LOWER DOOR HANLE TOWARD THE DOOR PIN MOVEMENT. CHECK FOR SECURITY AND FREE PLAY IN MECHANISM. EXCESSIVE FREE PLAY MAY BE DUE TO MECHANISM FAILURE, EXCESSIVE WEAR, OR DEFORMATION. CHECK DOO							Service ATA:52
	MOS	20-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:24	
H5280001 ^S	VISUALLY INSPECT INBOARD AND OUTBOARD MAIN LANDING GEAR DOOR BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00)							Service ATA:52
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
K5210070 ^S	EDDY CURRENT INSPECT AROUND LOWER CABIN DOOR LATCH ARM FASTENERS AND PERIPHERY OF ARM PIN EYES FOR CRACKS. (REFER TO NDI MANUAL [NDI-2], PART 3, 52-10-01.)							Service ATA:52
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: NDT 52-10-01					PKG:27
P5210042 ^S	INSPECT CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR SEALS FOR ADHESIONS, CUTS, AND ABRASION; LATCH FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY.							Service ATA:52
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:12
T5230011 ^S	VISUALLY INSPECT AVIONICS DOORS, HINGES, AND FASTENERS FOR GENERAL CONDITION, PROPER FIT, SEALS, ELECTRICAL BONDING, AND GENERAL CONDITION.							Service ATA:52
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
			PROC. REF: GENERIC NO REF					PKG:14
T5240002 ^S	VISUAL INSPECTION SINGLE POINT REFUELING DOOR. (REFER TO 5-10-00)							Service ATA:52
	MOS	21-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:8
T5280000 ^S	VISUALLY INSPECT EMERGENCY EXIT/BAGGAGE DOOR ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00).							Service ATA:52
	MOS	01-Mar-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:12
T5280003 ^S	VISUALLY INSPECT NOSE AVIONICS DOOR AND NOSE LANDING GEAR DOOR ELECTRICAL BONDING JUMPERS FRO SECURITY AND GENERAL CONDITION.							Service ATA:52
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
			PROC. REF: GENERIC NO REF					PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
05-10-29-Y5331017	INSPECTION OF UPPER FUSELAGE SKIN UNDER THE AFT OXYGEN LINE FAIRING							Service ATA:53
	MOS	02-Sep-16	144 (+14d/-14d)		02-Sep-28	16-Sep-28	2061 d (+14)	
	HRS	3960.5						
	AFL	2615						
PROC. REF: AMM 53-50-06								
05-10-30-RVSM-N5313000	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (RVSM) (REFER TO 53-11-01)							Service ATA:53
	MOS	23-Mar-21	24 (+14d/-14d)		23-Mar-23	06-Apr-23	71 d (+14)	
	HRS	5214.4						
	AFL	3422						
PROC. REF: AMM 53-11-01								
05-11-00-T5322000	REPLACE KEELBEAM ATTACHMENT BOLTS							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)		03-Aug-24	17-Aug-24	570 d (+14)	
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)		8065	8090	4360 (+25)	
PROC. REF: AMM 53-10-02								
531001	AFT PRESSURE BULKHEAD							Component ATA:53
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-10-01								
534001	NO. 1 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02								
534002	NO. 2 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
534003	NO. 1 ENGINE AFT ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02								
534004	NO. 2 ENGINE AFT ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02								
535001	RADOME							Component ATA:53
PN:5410420-26	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:211	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-50-01								
535089	LEFT DELTA FIN ASSEMBLY							Component ATA:53
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-50-04								
535090	RIGHT DELTA FIN ASSEMBLY							Component ATA:53
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-50-04								
A5321060 ^S	WING/FUSELAGE FITTINGS: CLEAN AND VISUALLY INSPECT ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE). USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, VISUALLY INSPECT FITTINGS AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHE							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
AA5323107 ^S	CIRCUMFERENTIAL SKIN SPLICES - CONDUCT AN X-RAY INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW: A. FRAMES 17, 20, 25, 26 AND 30. B. ON AIRCRAFT 60-002, FRAME 12. C. ON AIRCRAFT 60-003 AND SUBSEQUENT, FRAME 13. D. ON AIRCRAFT 60-002 THRU 60-093, FRAME 20B. CONDUCT SPECIFIC X-RAY INSPECTIONS OF THE CIRCUMFERENTIAL SKIN SPLICES IN THE PRESSURE CABIN ACROSS THE TOP OF THE FUSELAGE FROM STRINGER 8L TO 8R.							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 53-20-02, NDT 53-20-03, NDT 53-20-04								PKG:28
B5331030 ^S	TAILCONE STRUCTURE (REFER TO 5-10-00.): CONDUCT A VISUAL INSPECTION OF THE TAILCONE STRUCTURE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. FROM THE TAILCONE ACCESS DOOR OPENING, VISUALLY INSPECT ACCESSIBLE AREAS							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:28
C5314011 ^S	BELOW FLOORBOARD INSPECTION INSPECT FOR CORROSION, GENERAL CONDITION, AND FATIGUE CRACKS.							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF								PKG:27
C5314040 ^S	EMERGENCY EXIT/BAGGAGE DOOR FUSELAGE FRAMING STRUCTURE: CONDUCT X-RAY INSPECTION OF FUSELAGE DOOR FRAMING STRUCTURE IN AREA OF BORDERING INNER SKIN. PAY PARTICULAR ATTENTION TO HINGES, HINGE ATTACHMENTS, CORNER DOUBLERS, AND THE LATCH PIN AND RECEPTACLE S							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: NDT 52-60-01								PKG:27
C5321000 ^S	FUSELAGE FRAMES AND STRINGERS: GAIN ACCESS TO ALL FUSELAGE FRAMES AND STRINGERS FROM FRAME 6 TO AFT PRESSURE BULKHEAD. CONDUCT AN INTERIOR VISUAL INSPECTION OF ALL FUSELAGE FRAMES AND STRINGERS. PARTICULAR ATTENTION SHOULD BE GIVEN TO ALL FRAME SPLICES. I							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
C5321040 ^S	WITH WING/FUSELAGE FAIRINGS REMOVED, USE FLASHLIGHT AND MIRROR TO VISUALLY INSPECT THE HONEYCOMB SUPPORT ANGLE SEGMENTS AT THE OUTBOARD ENDS OF THE FORWARD BAGGAGE FLOOR FOR FATIGUE CRACKS, CORROSION, FASTENER SECURITY, AND GENERAL CONDITION							Service ATA:53
	MOS	19-Feb-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
				PROC. REF: GENERIC NO REF				PKG:25
C5321055 ^S	WING-TO-FUSELAGE ATTACHMENT FITTINGS: CLEAN AND VISUALLY INSPECT WITH THE AID OF 10X MAGNIFICATION, FLASHLIGHT, AND MIRROR, ALL EIGHT WING-TO-FUSELAGE ATTACHMENT FITTINGS. INSPECT FITTINGS AND SUPPORT STRUCTURE FOR CRACKS, CORROSION, MARKS, SCRATCHES, FAS							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
				PROC. REF: GENERIC NO REF				PKG:27
D5321020 ^S	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. TAP-TEST FLOOR PANEL, WHICH SUPPORTS THE ELECTRICAL EQUIPMENT, TO CHECK FOR UNBONDING OF UPPER SURFACE PLATE FROM THE HONEYCOMB CORE STRUCTURE. VISUALLY INSPECT FOR CORROSION, PARTICULARLY IN THE							Service ATA:53
	MOS	21-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
				PROC. REF: GENERIC NO REF				PKG:25
D5350020 ^S	INSPECT UNDER WING KEELBEAM AND ATTACHMENTS FOR SECURITY, CORROSION, FASTENER CONDITION, FATIGUE CRACKS, AND PERMANENT DEFORMATION. ALSO INSPECT ATTACHING FITTINGS, FORWARD OF FRAME 24 AND AFT OF FRAME 31, FOR SIMILAR EFFECTS.							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
				PROC. REF: GENERIC NO REF				PKG:27
D5350051 ^S	UNDERWING KEEL BEAM: VISUALLY INSPECT REMOVED ASSEMBLY FOR CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO END FITTINGS COMMON TO BEAM ASSEMBLY AS WELL AS THOSE MATING FITTINGS FORWARD OF FRAME 24 AND AFT OF FRAME 31. (REFER							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
				PROC. REF: GENERIC NO REF				PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
F5350010 ^S		VISUALLY INSPECT KEELBEAM, FORWARD AND AFT ATTACH FITTINGS ON KEELBEAM AND ON AIRCRAFT, FOR CRACKS AND GENERAL CONDITION. (REFER TO 5-10-00.)						Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
G5321021 ^S		REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. VISUALLY INSPECT FLOOR PANEL WHICH SUPPORTS THE ELECTRICAL EQUIPMENT AND FRAMES 25, 26, AND 26A FOR CORROSION AND ANY OTHER DAMAGE.						Service ATA:53
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:8
G5321079 ^S		AFT PRESSURE BULKHEAD REMOVE FUEL BLADDER AND VISUALLY INSPECT BULKHEAD FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, OR OTHER DAMAGE. VISUALLY INSPECT SUPPORTING STRUCTURE ALONG FLOOR, FRAME PERIPHERY, AND CENTERLINE BEAM FOR FATIGUE CRACKS, FASTENER SECURI						Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
H5230020 ^S		INSPECT TAILCONE EQUIPMENT ACCESS AND TAILCONE BAGGAGE COMPARTMENT DOOR SEALS FOR CUTS, ADHESION, AND ABRASION; LOCKING MECHANISM FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY.						Service ATA:53
	MOS	21-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:12
H5311000 ^S		INSPECT NOSE GEAR SUPPORT INSTALLATION FOR SECURITY, FASTENER CONDITION, PANEL FATIGUE CRACKS, PERMANENT DEFORMATION AT TRUNNION FITTINGS, ACTUATOR ATTACHMENT SUPPORT STRUCTURE AREAS, AND GENERAL CONDITION.						Service ATA:53
	MOS	20-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:23
H5314031 ^S		FRAMING MEMBERS OF PASSENGER/CREW AND EMERGENCY EXIT/BAGGAGE DOORS AND SURROUNDING FUSELAGESTRUCTURE FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION.						Service ATA:53
	MOS	20-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H5321014 ^S	IF INSTALLED, INSPECT ACCESSIBLE AREAS AROUND THE GALLEY, POTTY, AND LAVATORY FOR EVIDENCE OF SPILLAGE. INVESTIGATE FURTHER IF EVIDENCE OF SPILLAGE IS FOUND.							Service ATA:53
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:8	
H5321039 ^S	VISUALLY INSPECT LOWER LONGERON IN REGION OF WING FOR FATIGUE CRACKS, PERMANENT DEFORMATION, AND GENERAL CONDITION.							Service ATA:53
	MOS	22-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:27	
H5321042 ^S	BAGGAGE FLOOR/OVER WING AREA: A. INSPECT ENTIRE AREA FOR CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT THE SEGMENTED HONEYCOMB FLOOR SUPPORT ANGLES AT THE OUTBOARD EDGES FOR FATIGUE CRACKS, FASTENER SECURITY, AND GENERAL CONDITION. B. INSPECT FRAME							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF							PKG:27	
H5321048 ^S	BAGGAGE FLOOR/OVER WING AREA (REFER TO 5-10-00.) A. SUPPORT STRUCTURE FOR WING-TO-FUSELAGE FITTINGS. AT EACH LOCATION (SPAR/FRAME) 2/25, 5/27, 7/29, AND 8/30)8 LOCATIONS TOTAL) INSPECT FUSELAGE FRAME STRUCTURE FOR CRACKS, CORROSION, FASTENER CONDITION, P							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF							PKG:28	
H5321049 ^S	VISUALLY INSPECT OVERWING CUTOUT RADIUS AT FS 346 AND FS 421 (FRAMES 24 AND 31 FUSELAGE SKIN PANELS). (REFER TO 5-10-00.)							Service ATA:53
	MOS	22-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:20	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H5321050 ^S	INSPECT ACCESSIBLE PORTIONS OF LOWER CAP OF THE FRAME 26A AREA, AND ADJACENT FLOOR STRUCTURE, FRAME 24-26A. VISUALLY INSPECT FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:53
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:17
H5323011 ^S	INSPECT CORNER OF DOORS FOR FASTENER SECURITY AND GENERAL CONDITION.							Service ATA:53
	MOS	12-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:12
H5331010 ^S	INSPECT BULKHEADS, FRAMES, AND STIFFENERS IN THE TAILCONE FOR FASTENER SECURITY, CRACKS, AND GENERAL CONDITION.							Service ATA:53
	MOS	22-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:21
H5331020 ^S	INSPECT CANTED BULKHEADS AND LOWER VERTICAL STABILIZER ATTACHMENTS IN THE AFT TAILCONE FOR FASTENER SECURITY AND PERMANENT DEFORMATION AT BULKHEADS AND SPAR ASSEMBLIES.							Service ATA:53
	MOS	22-Jan-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:21
J5340001 ^S	EDDY CURRENT FORWARD BEAM SUPPORT FITTING. (REFER TO NDI MANUAL [NDI-2], PART 3, 53-40-01.)							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 53-40-01								PKG:28
J5340002 ^S	VISUAL INSPECTION FORWARD ENGINE BEAM ASSEMBLY. (REFER TO 5-10-00.)							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
J5340003 ^S	VISUAL INSPECTION FORWARD ENGINE BEAM STABILIZER STRUCTURE. (REFER TO 5-10-00.)							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
	PROC. REF: GENERIC NO REF							PKG:28
J5340004 ^S	EDDY CURRENT AFT BEAM SUPPORT FITTING - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 53-40-02.)							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
	PROC. REF: NDT 53-40-02							PKG:28
J5340005 ^S	VISUAL INSPECTION AFT ENGINE BEAM - PERFORM VISUAL INSPECTION. (REFER TO 5-10-00.)							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
	PROC. REF: GENERIC NO REF							PKG:28
J5340006 ^S	VISUAL INSPECTION AFT ENGINE BEAM AND FRAME STRUCTURE - PERFORM VISUAL INSPECTION. (REFER TO 5-10-00.)							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
	PROC. REF: GENERIC NO REF							PKG:28
K5321081 ^S	VISUALLY INSPECT FORWARD PRESSURE BULKHEAD FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION.							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
	PROC. REF: GENERIC NO REF							PKG:27
L5321085 ^S	FORWARD PRESURE BULKHEAD: VISUALLY INSPECT FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION. GAIN ACCESS TO THE FORWARD SIDE OF THE FORWARD PRESSURE B							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
	PROC. REF: GENERIC NO REF							PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
M5323065 ^S	CIRCUMFERENTIAL SKIN SPLICES: CONDUCT A GENERAL VISUAL INTERNAL AND EXTERNAL INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW: A. FRAMES 8, 17, 20, 25, AND 26. B. ON AIRCRAFT 60-002, FRAME 12. C. ON AIRCRAFT 60-003 AND SUBSEQUENT,							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
M5323106 ^S	LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) : A. CONDUCT AN INTERNAL AND EXTERNAL VISUAL INSPECTION OF THE LONGITUDINAL SKIN SPLICES ALONG THE MAIN "T" STRINGERS AT STRINGERS 4L, 6L, 7AL, 18L, 23L, 2R, 6R, 8R, AND 18R. (REFER TO 5-10-00.)							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
M5323108 ^S	LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) - PERFORM AN X-RAY INSPECTION OF THE LONGITUDIAL SKIN SPLICES ALONG THE "T" STRINGERS AT STRINGERS 4L, 6L, 18L, 23L, 2R, 6R, AND 18R. (REFER TO NDI MANUAL [NDI-2], PART 2, CHAPTER 53-20-05, 53-20-06, 53-20-07, 53							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
			PROC. REF: NDT 53-20-05, NDT 53-20-06, NDT 53-20-07, NDT 53-20-08, NDT 53-20-09, NDT 53-20-10					PKG:28
N5323010 ^S	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00)							Service ATA:53
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
			PROC. REF: GENERIC NO REF					PKG:2
N5323012 ^S	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00)							Service ATA:53
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
			PROC. REF: GENERIC NO REF					PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
O5331035 ^S	REMOVE TAIL CONE ACCESS PLATES AND USE A FLASHLIGHT AND MIRROR TO INSPECT INTERNAL TAIL CONE STRUCTURE IN AREA WHERE THE VERTICAL STABILIZER SPARS ATTACH TO THE CANTED FUSELAGE FRAMES. CHECK FOR ATTACHMENT SECURITY, FRAME CRIPPLING, CORROSION, AND FATIGUE CRACKS							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:28
P5311006 ^S	REMOVE NOSE GEAR TRUNNION FITTINGS AND VISUALLY INSPECT NOSE GEAR TRUNNION FITTING AREA IN FORWARD FUSELAGE FOR CRACKS, CORROSION, AND PERMANENT DEFORMATION. EDDY CURRENT INSPECT NOSE GEAR TRUNNION FITTING ATTACH HOLES AND TRUNNION AXLE BOSS. (REFER TO NDI MANUA							Service ATA:53
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: NDT 53-61-02								PKG:26
P5311007 ^S	EDDY CURRENT INSPECT UPPER ATTACHEMNET AREA OF NOSE GEAR ACTUATOR FOR CRACKS, CORROSION, PERMANENT DEFORMATION, AND ATTACHMENY FITTING SECURITY. (REFER TO NDI MANUAL [NDI-2], PART 3, 56-60-01.)							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: NDT 53-60-01								PKG:27
P5320008 ^S	INSPECT CENTER PEDESTAL AND EQUIPMENT FOR SECURITY AND GENERAL CONDITION. SPOILER, THROTTLE, AND FLAP CONTROLS FOR GENERAL CONDITION AND SERVICEABILITY.							Service ATA:53
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:1
P5321087 ^S	AFT PRESSURE BULKHEAD A. GAIN ACCESS TO AND REMOVE AFT PRESSURE BULKHEAD. B. EDDY CURRENT INSPECT THE FORWARD FRAME FLANGE OF FRAM 26A AFT PRESSURE BULKHEAD. (REFER TO NDI MANUAL [NDI-2], PART 3, CHAPTER 53-20-01 AND 53-20-05.) C. EDDY CURRENT INSPECT SUP							Service ATA:53
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 53-20-01, NDT 53-20-02, NDT 53-20-03, NDT 53-20-04, NDT 53-20-05								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
P5323162 ^S	VISUALLY INSPECT EXTERNAL LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR EVIDENCE OF FATIGUE CRACKS, WORKING RIVETS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:53	
	MOS	21-Mar-19							
	HRS	4647.4							
	AFL	2994	3000 (+25/-25)						
			PROC. REF: GENERIC NO REF						PKG:25
S5230021 ^S	OPERATIONAL CHECK OF TAILCONE BAGGAGE AND TAILCONE ACCESS DOOR WARNING SYSTEMS. (REFER TO 52-70-00).							Service ATA:53	
	MOS	15-Apr-19	24 (+14d/-14d)						
	HRS	4647.4	600 (+25/-25)						
	AFL	2994							
			PROC. REF: AMM 52-70-00						PKG:12
S5314070 ^S	UPPER AND LOWER CABIN DOOR HINGES AND FUSELAGE FRAMING STRUCTURE: A. VISUALLY INSPECT ACCESSIBLESTRUCTURE FOR SECURITY, GENERAL CONDITION, EXCESSIVE WEAR OR LOOSENESS, AND FATIGUE CRACKS. (REFER TO 5-10-00.) B. CONDUCT X-RAY INSPECTION OF UPPER AND LOWER							Service ATA:53	
	MOS	03-Aug-12	144 (+14d/-14d)						
	HRS	3178.5							
	AFL	2065	6000 (+25/-25)						
			PROC. REF: NDT 52-20-01						PKG:27
S5323158 ^S	INSPECT EXTERIOR OF THE SKIN, GIVING PARTICULAR ATTENTION TO LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR FASTENER CONDITION, FATIGUE CRACKS, AND GENERAL SPLICE CONDITION.							Service ATA:53	
	MOS	21-Feb-19	96 (+14d/-14d)						
	HRS	4647.4	2400 (+25/-25)						
	AFL	2994							
			PROC. REF: GENERIC NO REF						PKG:20
T5321013 ^S	INSPECT ACCESSIBLE PORTION OF FRAME 26A AREA VISIBLE THROUGH WHEEL WELLS FOR FATIGUE CRACKS, PERMANENT DEFORMATION, SECURITY, AND GENERAL CONDITION.							Service ATA:53	
	MOS	22-Feb-19	24 (+14d/-14d)						
	HRS	4647.4	600 (+25/-25)						
	AFL	2994							
			PROC. REF: GENERIC NO REF						PKG:11
T5321093 ^S	INSPECT TAILCONE BAGGAGE COMPARTMENT UPHOLSTERY FOR CUTS, TEARS , AND GENERAL CONDITION.							Service ATA:53	
	MOS	05-Sep-17	48 (+14d/-14d)						
	HRS	4170.4	1200 (+25/-25)						
	AFL	2721							
			PROC. REF: GENERIC NO REF						PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
U5323146 ^S	SKIN CUTOUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT SKIN PENETRATIONS AND CUTOUTS FOR ANTENNAS AND ELECTRICAL COMPONENTS. (REFER TO 5-10-00.)							Service ATA:53
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
	PROC. REF: GENERIC NO REF							PKG:27
U5331012	* REMOVE ACCESS PANELS (TOP OF FUSELAGE) AND PERFORM VISUAL INSPECTION OF ELECTRICAL BOXES FOR SECURITY OF ATTACHMENT, CORROSION, AND GENERAL CONDITION. INSPECT DOUBLERS, FUSELAGE SKIN, INTERIOR FRAMES, AND INTERCOSTALS FOR FATIGUE CRACKS AND GENERAL CONDITION. (AWL*)							Service ATA:53
	MOS	22-Sep-20	49		22-Oct-24		650 d	AIRWORTHINESS
	HRS	5022.3						
	AFL	3265						
	PROC. REF: GENERIC NO REF							
U5360005 ^S	GENERAL VISUAL INSPECTION RADOME AND LIGHTNING DIVERTER STRIPS. (REFER TO 5-10-00)							Service ATA:53
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: GENERIC NO REF							PKG:2
ATA 54 - NACELLES/PYLONS								
H5450000 ^S	CHECK PYLON FIREWALLS FOR CRACKS, CONDITION OF FIREWALL SEALANT, SECURITY OF HYDRAULIC AND FUEL CONNECTIONS, ELECTRICAL AND MECHANICAL FEED-THROUGHS, AND CONDITION OF BLEED AIR FLANGE GASKETS.							Service ATA:54
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
	PROC. REF: GENERIC NO REF							PKG:9
H5450002 ^S	VISUAL INSPECTION ENGINE SUPPORT STRUCTURE. (REFER TO 5-10-00.)							Service ATA:54
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
	PROC. REF: GENERIC NO REF							PKG:28
K5450010 ^S	INSPECT PYLON BEAMS FOR CRACKS, FASTENER CONDITION, ATTACHMENT TO FUSELGAE FRAMES, AND GENERAL CONDITION OF FITTINGS. REMOVE UPPER AND LOWER PYLON ACCESS COVERS FOR COMPLETE INSPECTION.							Service ATA:54
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: GENERIC NO REF							PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
5520020 ^S	ELEVATOR (REMOVED FROM HORIZONTAL STABILIZER) (REFER TO 5-10-00.): A. CLEAN HINGE LOCATIONS AND VISUALLY INSPECT LOCAL STRUCTURE USING PROPER LIGHTING AND 10X MAGNIFICATION. INSPECT HINGE SUPPORT STRUCTURE FOR DEFORMATION, CORROSION, LOOSE OR WORKING FAST							Service ATA:55
	MOS	29-Dec-00						
	HRS	0	T:12000 (+14/-14)					
	AFL	0						
PROC. REF: NDT 55-20-01							PKG:28	
553001	VERTICAL STABILIZER							Component ATA:55
PN:5431000-030	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:W409	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF							PKG:28	
A5510061 ^S	HORIZONTAL STABILIZER (DETACHED FROM VERTICAL STABILIZER): A. CONDUCT A GENERAL VISUAL INSPECTION OF THE STABILIZER ASSEMBLY INCLUDING UPPER AND LOWER SKIN SPLICES AT BL 4.5 RIB, ACCESSIBLE PORTIONS OF FRONT AND REAR SPAR INSTALLATIONS, ELEVATOR HINGE SUP							Service ATA:55
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF							PKG:28	
A5510062 ^S	CLEAN AND VISUALLY INSPECT THE HINGE PIN FOR WEAR AND CORROSION (INCLUDING THE INTERNAL SURFACE OF THE PIN). APPLY A COAT OF EPOXY PRIMER TO THE INTERNAL SURFACE OF THE PIN PRIOR TO REINSTALLATION. (REFER TO 5-10-00.) MAGNETIC PARTICLE INSPECT PIN FOR CRACKS.							Service ATA:55
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 55-30-01							PKG:28	
B5530010 ^S	VERTICAL STABILIZER (ATTACHE DTO FUSELAGE) (REFER TO 5-10-00.): A. CONDUCT A GENERAL VISUAL INSPECTION OF THE VERICAL STABILIZER ABOVE THE FUSELAGE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION. LOOSE OR WORKING FASTENERS, FATIGUE CRACKS, AND GENERAL C							Service ATA:55
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF							PKG:28	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
B5540020 ^S	RUDDER (REMOVED FROM VERTICAL STABILIZER) (REFER TO 5-10-00.) A. CLEAN HINGE LOCATIONS AND VISUALLY INSPECT LOCAL STRUCTURE USING PROPER LIGHTING AND 10X MAGNIFICATION. INSPECT HINGE SUPPORT STRUCTURE FOR DEFORMATION, CORROSION, AND FATIGUE CRACKS. (INCLU							Service ATA:55
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:28
C5510050 ^S	HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER) (REFER TO 5-10-00.) A. WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LB.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FIT							Service ATA:55
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF								PKG:27
E5510040 ^S	WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCTURE ATTACHING BOLTS, AND BOLT RETAINERS FOR WEAR, LOOSENE							Service ATA:55
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:18
E5520010 ^S	WITH CONTROL COLUMN FIXED, APPLY ALTERNATE UP AND DOWN LOADS TO THE ELEVATOR TRAILING EDGE. INSPECT EACH ELEVATOR HINGE LOCATION FOR LOOSENESS, FREE PLAY, FATIGUE CRACKS, AND GENERAL SECURITY.							Service ATA:55
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:18
E5540010 ^S	WITH RUDDER PEDALS RESTRAINED, APPLY ALTERNATING LEFT AND RIGHT LOADS TO THE RUDDER TRAILING EDGE. OBSERVE RUDDER HINGE FITTING ATTACHMENTS FOR LOOSENESS, FREE PLAY, AND GENERAL SECURITY.							Service ATA:55
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H5510031 ^S	REMOVE ACCESS PANELS AND INSPECT UPPER AND LOWER FLANGES OF HORIZONTAL STABILIZER RIBS AT RIGHT AND LEFT BUTT LINE 19.4 FOR CRACKS.							Service ATA:55
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:18	
H5510035 ^S	INSPECT HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS (INCLUDING ATTACH BOLTS), SUPPORT STRUCTURE, AND ATTACH BOLT RETAINING CLIPS (IF INSTALLED) FOR CRACKS, FASTENER CONDITION, SECURITY, WEAR, AND GENERAL CONDITION.							Service ATA:55
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:18	
H5520000 ^S	ELEVATOR: WITH PUSH-PULL TUBES DISCONNECTED FROM ELEVATOR BELLCRANKS, MOVE EACH ELEVATOR SURFACE THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR SMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, RUST OR CORROSION, TURNING ON BOLT RATHER THAN BEA							Service ATA:55
	MOS	15-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:24	
H5530001 ^S	VERTICAL STABILIZER FOR CRACKS, FASTENER CONDITION, AND SECURITY AT ATTACH POINTS, AND STRUCTURE IN AREA OF HORIZONTAL STABILIZER ATTACH FITTINGS.							Service ATA:55
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:18	
H5540011 ^S	RUDDER: WITH CABLES DISCONNECTED AT AFT BELLCRANK LOCATION, MOVE RUDDER THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR AMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, TURNING ON BOLT RATHER THAN BEARING, RUST OR CORROSION, AND GENERAL CONDITI							Service ATA:55
	MOS	18-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:24	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H5560001 ^S	VISUALLY INSPECT THE DELTA FIN SURFACES. REMOVE TAILCONE ACCESS COVERS AND VISUALLY INSPECT SUPPORT STRUCTURE FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, PERMANENT DEFORMATION, AND CORROSION. INSPECT UPPER AND LOWER SURFACES, PAYING PARTICULAR ATTENTION TO THE TAILCON							Service ATA:55
	MOS	20-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:21
M5530003 ^S	VERTICAL STABILZER (ATTACHED TO FUSELAGE) (REFER TO 5-10-00.) A. CONDUCT A VISUAL INSPECTION OF THE VERTICAL STABILIZER ABOVE THE FUSLEAGE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, LOSE OR WORKING FASTENERS, FATIGUE CRACKS, AND GENERAL CONDITION.							Service ATA:55
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF								PKG:27
O5510060 ^S	HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER): WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCT							Service ATA:55
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:28
P5510089 ^S	CONDUCT A THOROUGH EXTERNAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER FORWARD AND REAR SPAR CAPS (UPPER AND LOWER) FOR CORROSION, INTEGRITY OF PAINT, AND GENERAL CONDITION. (ELEVATOR REMOVAL NOT REQUIRED.) (REFER TO 5-10-00)							Service ATA:55
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:6
T5500002 ^S	INSPECT RUDDER, RUDDER TAB, AND ELEVATOR HINGE POINTS FOR EVIDENCE OF WEAR, SECURITY, AND GENERAL CONDITION. WHEN INSTALLING VERTICAL STABILIZER AFT FAIRING, ENSURE THAT ELEVATOR TO FAIRING CLEARANCE IS 0.31 (+0.12) INCH [7.9 (+3) MM].							Service ATA:55
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
U5500000 ^S		GENERAL VISUAL INSPECTION FILLETS, FAIRINGS, AND SKINS. (REFER TO 5-10-00)						Service ATA:55
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:6
U5560000 ^S		GENERAL VISUAL INSPECTION DELTA FINS. (REFER TO 5-10-00)						Service ATA:55
	MOS	20-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
ATA 56 - WINDOWS								
05-10-29-C5610022L		PRISM CHECK LEFT						Service ATA:56
PN:6600394-1	MOS/MSC	10-Apr-17	C/C					
SN:1419	HRS	4050.6						
	AFL	2666						
	APH	1088						
	ACH	1195.9						
PROC. REF: NDT 56-10-01								
05-10-29-C5610022R		PRISM CHECK RIGHT						Service ATA:56
PN:6600394-2	MOS/MSC	10-Apr-17	C/C					
SN:1440	HRS	4050.6						
	AFL	2666						
	APH	1088						
	ACH	1195.9						
PROC. REF: NDT 56-10-01								
561001		LEFT WINDSHIELD ASSY						Component ATA:56
PN:6600394-1	MOS/MSC	24-Jun-14	O/C	TSN 0				
SN:1419	HRS	3522.3		TSN 0				
	AFL	2300		TSN 0				
PROC. REF: AMM 56-10-01								
561002		RIGHT WINDSHIELD ASSY						Component ATA:56
PN:6600394-2	MOS/MSC	09-Sep-14	O/C	TSN 0				
SN:1440	HRS	3532.9		TSN 0				
	AFL	2315		TSN 0				
PROC. REF: AMM 56-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
561009	LEFT COCKPIT CREW WINDOW							Component ATA:56
PN:6600403-5	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:437	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02								
561010	RIGHT COCKPIT CREW WINDOW							Component ATA:56
PN:6600402-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:862	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02								
562011	LEFT NO. 1 CABIN WINDOW							Component ATA:56
PN:PAS6600405-10	MOS/MSC	13-Sep-13	O/C	TSN 0				
SN:9118	HRS	3379.4		TSN 0				
	AFL	2209		TSN 0				
PROC. REF: AMM 56-20-01								
562011A	PRISM CHECK LEFT NO. 1 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PAS6600405-10	MOS/MSC	17-Nov-16	C/C					
SN:9118	HRS	3980.4						
	AFL	2628						
PROC. REF: NDT 56-30-01								
562013	LEFT NO. 2 CABIN WINDOW							Component ATA:56
PN:PAS6600405-10	MOS/MSC	13-Sep-13	O/C	TSN 0				
SN:11309	HRS	3379.4		TSN 0				
	AFL	2209		TSN 0				
PROC. REF: AMM 56-20-01								
562013A	PRISM CHECK LEFT NO. 2 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PAS6600405-10	MOS/MSC	17-Nov-16	C/C					
SN:11309	HRS	3980.4						
	AFL	2628						
PROC. REF: NDT 56-30-01								
562015	LEFT NO. 3 CABIN WINDOW							Component ATA:56
PN:PAS6600405-10	MOS/MSC	13-Sep-13	O/C	TSN 0				
SN:11302	HRS	3379.4		TSN 0				
	AFL	2209		TSN 0				
PROC. REF: AMM 56-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562015A	PRISM CHECK LEFT NO. 3 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PAS6600405-10	MOS/MSC	17-Nov-16	C/C					
SN:11302	HRS	3980.4						
	AFL	2628						
PROC. REF: NDT 56-30-01								
562017	LEFT NO. 4 CABIN WINDOW							Component ATA:56
PN:LA6600405-32	MOS/MSC	22-Apr-15	O/C	TSN 0				
SN:1458	HRS	3616.4		TSN 0				
	AFL	2379		TSN 0				
PROC. REF: AMM 56-20-01								
562017A	PRISM CHECK LEFT NO. 4 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:LA6600405-32	MOS/MSC	17-Nov-16	C/C					
SN:1458	HRS	3980.4						
	AFL	2628						
PROC. REF: NDT 56-30-01								
562019	LEFT NO. 5 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	11-Mar-22	O/C	TSN 0				
SN:UNKNOWN	HRS	5539.1		TSN 0				
	AFL	3670		TSN 0				
PROC. REF: AMM 56-20-01								
562019A	PRISM CHECK LEFT NO. 5 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS	11-Mar-22						
SN:UNKNOWN	HRS	5539.1	T:600 (+25/-25)	6139.1	6164.1	554.9 (+25)		
	AFL	3670						
PROC. REF: NDT 56-30-01								
562022	RIGHT NO. 1 CABIN WINDOW							Component ATA:56
PN:PAS6600405-10	MOS/MSC	13-Sep-13	O/C	TSN 0				
SN:9116	HRS	3379.4		TSN 0				
	AFL	2209		TSN 0				
PROC. REF: AMM 56-20-01								
562022A	PRISM CHECK RIGHT NO. 1 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PAS6600405-10	MOS/MSC	17-Nov-16	C/C					
SN:9116	HRS	3980.4						
	AFL	2628						
PROC. REF: NDT 56-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562024	RIGHT NO. 2 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	11-Mar-22	O/C	TSN 0				
SN:UNKNOWN	HRS	5539.1		TSN 0				
	AFL	3670		TSN 0				
PROC. REF: AMM 56-20-01								
562024A	PRISM CHECK RIGHT NO. 2 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS	11-Mar-22						
SN:UNKNOWN	HRS	5539.1	T:600 (+25/-25)		6139.1	6164.1	554.9 (+25)	
	AFL	3670						
PROC. REF: NDT 56-30-01								
562026	RIGHT NO. 3 CABIN WINDOW							Component ATA:56
PN:PAS6600405-10	MOS/MSC	13-Sep-13	O/C	TSN 0				
SN:11327	HRS	3379.4		TSN 0				
	AFL	2209		TSN 0				
PROC. REF: AMM 56-20-01								
562026A	PRISM CHECK RIGHT NO. 3 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PAS6600405-10	MOS/MSC	17-Nov-16	C/C					
SN:11327	HRS	3980.4						
	AFL	2628						
PROC. REF: NDT 56-30-01								
562028	RIGHT NO. 4 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	11-Mar-22	O/C	TSN 0				
SN:UNKNOWN	HRS	5539.1		TSN 0				
	AFL	3670		TSN 0				
PROC. REF: AMM 56-20-01								
562028A	PRISM CHECK RIGHT NO. 4 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS	11-Mar-22						
SN:UNKNOWN	HRS	5539.1	T:600 (+25/-25)		6139.1	6164.1	554.9 (+25)	
	AFL	3670						
PROC. REF: NDT 56-30-01								
562030	RIGHT NO. 5 CABIN WINDOW							Component ATA:56
PN:PAS6600405-10	MOS/MSC	13-Sep-13	O/C	TSN 0				
SN:11295	HRS	3379.4		TSN 0				
	AFL	2209		TSN 0				
PROC. REF: AMM 56-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562030A	PRISM CHECK RIGHT NO. 5 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN: PAS6600405-10	MOS/MSC	17-Nov-16	C/C					
SN: 11295	HRS	3980.4						
	AFL	2628						
PROC. REF: NDT 56-30-01								
H5610024 ^S	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE) A. CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS. B. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS FOR DELAMINATION, CHIPPING,							Service ATA:56
	MOS	15-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:24
H5620000 ^S	PERFORM AN EXTERNAL VISUAL INSPECTION OF THE CABIN WINDOWS AND RETAINERS FOR GENERAL CONDITION, SECURITY, AND CLEANLINESS. INSPECT INTERNAL AND EXTERNAL SURFACES OF THE CABIN WINDOWS FOR SCRATCHES, PITS, OR OTHER DAMAGE. (REFER TO 56-20-01)							Service ATA:56
	MOS	20-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: AMM 56-20-01								PKG:8
M5610010 ^S	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE): (A.) CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS IN ACCORDANCE WITH CHAPTER 12. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS FOR DELAMINATION, CHIPPING, CRAZING, CRACKS, GOUGES, HEAT DAMAGE IN THE EXTERNAL DEFOG AREA, AND GENERAL CONDITION. (B.) CONDUCT AN X-RAY INSPECTION OF THE WINDSHIELD SUPPORTING STRUCTURE. REMOVAL NOT REQUIRED UNLESS X-RAY INDICATES POSSIBLE CRACKS. (C.) EDDY CURRENT INSPECT OUTER RETAINER.							Service ATA:56
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: NDT 56-20-01, NDT 56-20-01								PKG:27
M5620001 ^S	CABIN WINDOWS AND FRAMING MEMBERS: A. VISUALLY INSPECT ACCESSIBLE STRUCTURE FOR SECURITY, GENERAL CONDITION, AND FATIGUE CRACKS. (REFER TO 5-10-00.) B. CONDUCT X-RAY INSPECTION OF SUPPORT STRUCTURE. (REFER TO NDI MANUAL [NDI-2], PART 2, 56-50-01.)							Service ATA:56
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: NDT 56-50-01								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
T5610002 ^S	INSPECT INTERIOR AND EXTERIOR OF WINDSHIELD FOR CRAZING, INCLUDING VISIBLE PORTION UMDER RETAINERS FOR CRACKS, CLEANLINESS, SECURITY, AND GENERAL CONDITION. AREA UNDER ANTI-ICE DUCT SHALL BE INSPECTED BY VIEWING THE EPOXY-PRIMED OUTER SURFACE OF THE WINDSHIELD FR							Service ATA:56
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: AMM 12-24-00, AMM 12-25-00							PKG:14	
T5620007 ^S	CABIN WINDOWS: USING PRISM TECHNIQUES, INSPECT WINDOWS FOR CRACKS, CHIPS, DELAMINATION, OR OTHER DAMAGE. THIS INSPECTION IS ALSO CAPABLE OF VISUALLY ASSESSING THE CONDITION OF THE ATTACHING FASTENERS. BROWN DISCOLORATIONS IN THE AREA OF THE FASTENERS MAY							Service ATA:56
	MOS	15-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
							PKG:24	
ATA 57 - WINGS								
05-10-29-L5720012L	PERFORM LEFT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	T:10000 (+25/-25)	10000	10025	6295 (+25)		
PROC. REF: NDT 57-40-03								
05-10-29-L5720012R	PERFORM RIGHT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	T:10000 (+25/-25)	10000	10025	6295 (+25)		
PROC. REF: NDT 57-40-03								
570001	LEFT WING							Component ATA:57
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-00-01								
570002	RIGHT WING							Component ATA:57
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
572001	LEFT WINGLET ASSEMBLY							Component ATA:57
PN:2822650-43	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:270	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-01								
572002	RIGHT WINGLET ASSEMBLY							Component ATA:57
PN:2822650-44	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:277	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-01								
572003	LEFT WING LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-02								
572004	RIGHT WING LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-02								
572025	LEFT FRONT WINGLET SPAR FITTING							Component ATA:57
PN:6022621-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:R-229	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
572026	RIGHT FRONT WINGLET SPAR FITTING							Component ATA:57
PN:6022621-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:R-265	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
572027	LEFT AFT WINGLET SPAR FITTING							Component ATA:57
PN:6022622-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:R-296	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
572028	RIGHT AFT WINGLET SPAR FITTING							Component ATA:57
PN:6022622-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:R-318	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
A5710045 ^S	REMOVE LOWER SURFACE ACCESS PLATES FROM WS 92 INBOARD TO BL 0.0 INCLUDING FUEL PUMPS AT WS 6.0 AND 11.0. VISUALLY INSPECT THE PERIPHERY OF THESE CUTOUTS FOR FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.) CONDUCT EDDY CURRRENT INSPECTIONS A							Service ATA:57
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 57-10-01								PKG:28
A5710070 ^S	CLEAN UPPER AND LOWER CENTERLINE SPLICE PLATE (SPAR 2 TO 5 AND 7 TO 8) ADJACENT TO BL 0.0 RIB CAP. VISUALLY INSPECT THESE AREAS FOR CORROSION, FATIGUE CRACKS, WORKING FASTENERS, AND GENERAL SECURITY. (REFER TO 5-10-00)							Service ATA:57
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:28
A5760010 ^S	AILERON (REMOVED FROM WING) (REFER TO 5-10-00.)							Service ATA:57
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:28
B5710050 ^S	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER AND LOWER STRUCTURE IN THE CENTERLINE DOUBLER AREA. INSPECT FOR FATIGUE CRACKS, CORROSION, LOOSE OR MISSING FASTENERS, AND GENERAL SECURITY. (REFER TO NDI MANUAL [NDI-2], PART 2, 57-20-01 AND 57-21-01.)							Service ATA:57
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 57-20-01, NDT 57-21-01								PKG:28
C5710040 ^S	CLEAN AND CONDUCT A GENERAL EXTERNAL AND INTERNAL VISUAL INSPECTION OF THE WING CENTER SECTION, PAYING PARTICULAR ATTENTION TO THE LOWER SKIN AT THE FUEL PUMP LOCATIONS AND THE SPLICE DETAILS AT BL 0.0, AS ACCESSIBLE. INSPECT FOR EVIDENCE OF AFTIGUE CRACKS, COR							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
C5710055 ^S	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER STRUCTURE INBOARD OF THE WING-TO-FUSELAGE FITTINGS AND FORWARD OF SPAR 5. INSPECT FOR CORROSION, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. IF CORROSION IS FOUND, WING REMOVAL FROM FUSELAGE MAY							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: NDT 57-12-01					PKG:27
C5710060 ^S	CONDUCT AN EDDY CURRENT INSPECTION FOR THE FOLLOWING WING STRUCTURAL AREAS: SURFACE OF ACCESSIBLE AREAS OF LOWER DOUBLER FROM BL 0.0 TO OUTBOARD END OF DOUBLER ALONG SPARS 4, 5, AND 7, AND LOWER SKIN ADJACENT TO THE OUTBOARD 2 INCHES OF DOUBLER FINGERS. SKIN ADJA							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: NDT 57-12-01					PKG:27
C5710062 ^S	REMOVE THE ACCESS COVER AT WS 73.0 BETWEEN SPARS 4/5 AND 6/7. INSPECT ALL HOLES AT THIS LOCATION IN THE SPAR AND SKIN USING AN EDDY CURRENT HOLE PROBE. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-12-01.)							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: NDT 57-12-01					PKG:27
C5710065 ^S	EDDY CURRENT AREA AROUND FASTENERS COMMON TO TRUNNION FITTINGS. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-12-01, AREAS E AND D.)							Service ATA:57
	MOS	22-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
			PROC. REF: NDT 57-12-01					PKG:25
C5720020 ^S	VISUALLY INSPECT INTERNAL AND EXTERNAL AREA OF WING WHEEL WELL STRUCTURE, PAYING PARTICULAR ATTENTION TO THE MAIN LANDING GEAR ACTUATOR UPPER ATTACHMENT AND LANDING GEAR RIB STRUCTURE AT WS 53.04. (REFER TO 5-10-00.)							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
C5720025 ^S	X-RAY INSPECT THE OUTBOARD LOWER WING SKIN FROM WS 31 TO WS 61. (REFER TO NDI MANUAL [NDI-2], PART 2, 57-30-01.)							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: NDT 57-30-01					PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
C5720040 ^S	INSPECT THE JOINT AT WS 181 THAT SPLICES THE WING TO THE OUTER WING EXTENSION. VISUALLY INSPECT FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, AND GENERAL SECURITY. (REFER TO 5-10-00.)							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
C5740001 ^S	WITH LEADING EDGE ASSEMBLIES REMOVED, INSPECT FORWARD SIDE OF SPAR 1 FOR EVIDENCE OF FATIGUE CRACKS, OVERHEAT (DISCOLORED PRIMER), GENERAL CORROSION, LOOSE OR MISSING FASTENERS, FIFLIFORM CORROSION, AND GENERAL CONDITION.							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
C5740002 ^S	WITH LEADING EDGE LOWER CUFF FAIRING ASSEMBLIES REMOVED, INSPECT LOWER WING SKIN COVERED BY CUFF FAIRING AND INNER SURFACE OF CUFF FOR EVIDENCE OF FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, CORROSION, AND GENERAL CONDITION.							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: GENERIC NO REF					PKG:27
E5710066 ^S	CONDUCT A VISUAL AND EDDY CURRENT INSPECTION OF THE FOLLOWING LOWER WING STRUCTURAL AREAS							Service ATA:57
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
			PROC. REF: NDT 57-10-01, NDT 57-12-01					PKG:28
E5710071 ^S	CONDUCT AN EDDY CURRENT INSPECTION OF THE LOWER SPLICE PLATE ALONG THE CENTERLINE FASTENER ROWS. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-10-01)							Service ATA:57
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
			PROC. REF: NDT 57-10-01					PKG:28
E5720010 ^S	INSPECT FLAP SECTOR SUPPORT BRACKETS AND FLAP ACTUATOR SUPPORT FLAP BRACKET FOR CRACKS, DISTORTION, INTERFERENCE, AND FASTENER CONDITION. (REFER TO 57-40-03).							Service ATA:57
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: AMM 57-40-03					PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
E5750020 ^S	WITH FLAPS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO FLAP TRAILING EDGE. INSPECT INBOARD AND OUTBOARD FLAP TRACKS AND NOSE ROLLER SUPPORT STRUCTURE CRACKS, DISTORTION, FASTENER CONDITION, EVIDENCE OF CHAFING OR INTERFERENCE, AND GENERAL SECURITY.							Service ATA:57
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:16
E5750030 ^S	INSPECT FLAP NOSE ROLLER BUSHINGS. REPLACE FLAP NOSE ROLLER IF WORN TO A DIAMETER LESS THAN 0.744 INCH. REPLACE FLAP NOSE ROLLER TRACK IF SLOT EXCEEDS 0.775 INCH AT ANY POINT WITH FLAPS FULLY EXTENDED. ENSURE THAT A POSITIVE CLEARANCE EXISTS BETWEEN NOSE ROLLERS							Service ATA:57
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:16
E5750060 ^S	CLEAN AND VISUALLY INSPECT FLAP ATTACH FITTING (CASTINGS ATTACHED TO FLAP SPAR) FOR CRACKS. (REFER TO 5-10-00.) (SEE FIGURE 3.)							Service ATA:57
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF								PKG:16
E5770010 ^S	INSPECT SPOILER CENTER HINGE BRACKETS (ATTACHED TO WING SPAR 8) FOR CRACKS EMANATING FROM THE BOLT HOLE AND/OR BRACKET BEND RELIEF. INSPECT BOLT HOLE FOR ELONGATION OR DISTORTION.							Service ATA:57
	MOS	22-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:10
G5720021 ^S	VISUALLY INSPECT INTERNAL AND EXTERNAL AREAS OF WING STRUCTURE ADJACENT TO LANDING GEAR RIB WS 53.04 (BETWEEN SPARS 4 AND 8). INSPECT TRUNNION FITTINGS FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, ELONGATION OF TRUNNION PIN HOLES, AND GENERAL SECURITY. CHECK							Service ATA:57
	MOS	29-Dec-00						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: GENERIC NO REF								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
H5750000 ^S	INSPECT TRAILING EDGE REGION OF WING FOR LOCAL DEFORMATION AFFECTING NORMAL USAGE OF FLAP AND AILERON.							Service ATA:57
	MOS	22-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
	PROC. REF: GENERIC NO REF							PKG:22
H5750047 ^S	FLAP (REMOVED FROM WING) VISUALLY INSPECT THE FOLLOWING (REFER TO 5-10-00): A. FLAP SUPPRT FOR SECURITY, CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERFERENCE, AND GENERAL CONDITION. INSPECT THE FLAP SECTOR AND SUPPORTIN BRACKERTY FOR EVIDENCE OF OVER							Service ATA:57
	MOS	22-Mar-19						
	HRS	4647.4						
	AFL	2994	3000 (+25/-25)					
	PROC. REF: GENERIC NO REF							PKG:25
J5720011 ^S	FLAP SUPPORT FITTING (ALUMINUM, P/N 6022521-1 THRU 6022521-8) - OERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-40-02.)							Service ATA:57
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
	PROC. REF: NDT 57-40-02							PKG:16
K5730012 ^S	DETAILED INSPECTION AILERON BRUSH SEALS. (REFER TO 57-30-07)							Service ATA:57
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: AMM 57-30-07							PKG:4
N5700004 ^S	VISUAL INSPECTION WING SURFACE, WING TO FUSELAGE FAIRING AND WINGLET EXTERIOR. (REFER TO 5-10-00)							Service ATA:57
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
	PROC. REF: GENERIC NO REF							PKG:4
P5710140 ^S	REMOVE UPPER WING-TO-FUSELAGE FAIRINGS AND INSPECT WING SKINS, WING TO FUSELAGE ATTACH FITTINGS, AND ADJACENT STRUCTURE FOR CORROSION, FASTENER SECURITY, CRACKS, PERMANENT DEFORMATION, PROTECTIVE COATING, AND GENERAL CONDITION. EXAMINE EXPOSED EDGE OF HONEYCOMB							Service ATA:57
	MOS	19-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
	PROC. REF: GENERIC NO REF							PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5710141 ^S	INSPECT WING-TO-FUSELAGE ATTACH POINTS FOR SECURITY (THAT PORTION VISIBLE THROUGH WHEEL WELLS).							Service ATA:57
	MOS	22-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:23	
P5710142 ^S	WITH WING-TO-FUSELAGE FAIRING REMOVED, CLEAN AND VISUALLY INSPECT ALL EIGHT WING-TO-FUSELAGE FITTINGS (FOUR PER SIDE). USING A 10X MAGNIFYING GLASS, ADEQUATE LIGHTING, AND MIRROR, INSPECT FITTINGS AND SUPPORT STRUCTURES FOR FATIGUE CRACKS, DEFORMATION, CO							Service ATA:57
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
PROC. REF: GENERIC NO REF							PKG:27	
P5710143 ^S	CLEAN CLEAN AND VISUALLY INSPECT, USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE) AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHES, FASTENER WORKING, AND GENERAL SECURITY. (REFER TO 5-10-00.)							Service ATA:57
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 57-13-01							PKG:28	
P5710144 ^S	INSPECT WHEEL WELL AND CENTER SECTION OF WING FOR GENERAL CONDITION OF SKIN, SPARS, ATTACH FITTINGS AND SUPPORTING STRUCTURE, LANDING GEAR RIB, AND TRUNNION FITTINGS. CHECK FOR DEFORMATION, FATIGUE CRACKS, PROTECTIVE FINISH CONDITION, AND GENERAL SECURITY.							Service ATA:57
	MOS	22-Feb-19	96 (+14d/-14d)					
	HRS	4647.4	2400 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:23	
P5710146 ^S	INSPECT UPPER PORTION OF BL 0.0 RIB CAP, JUST FORWARD OF SPAR 7. INSPECT FOR ANY EVIDENCE OF CORROSION, PRIMER BLISTERING, AND CONDITION OF PRIMER SURFACE. (SEE FIGURE 2.)							Service ATA:57
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:16	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5750050 ^S	INSPECT FLAP UPPER AND LOWER SURFACES FOR SKIN CRACKS, LOOSE RIVETS, AND OTHER DAMAGE. CHECK NOSE ROLLERS FOR FREEDOM OF ROTATION. PAY PARTICULAR ATTENTION TO NOSE ROLLER SUPPORT STRUCTURE FOR CRACKS.							Service ATA:57
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF							PKG:4	
U5720071 ^S	GENERAL VISUAL INSPECTION STALL FENCES, STALL STRIPS, WING STALL TRIANGLES, AND BOUNDARY LAYER ENERGIZERS. (REFER TO 5-10-00.)							Service ATA:57
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF							PKG:4	
ATA 70 - STANDARD PRACTICES - ENGINES								
700010	LEFT ENGINE INSPECTION-AIRFRAME ITEMS							Package ATA:70
	MOS	22-Apr-15						
	HRS	3616.4	3600 (+50)		7216.4	7266.4	1632.2 (+50)	
	AFL	2379						
PROC. REF: GENERIC NO REF							PKG:29	
700020	RIGHT ENGINE INSPECTION-AIRFRAME ITEMS							Package ATA:70
	MOS	03-Jan-14						
	HRS	3401.1	3600 (+50)		7001.1	7051.1	1416.9 (+50)	
	AFL	2225						
PROC. REF: GENERIC NO REF							PKG:30	
ATA 71 - POWER PLANT								
05-11-00-E7120049L	REPLACE * NO. 1 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)							Service ATA:71
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 71-20-10								
05-11-00-E7120049R	REPLACE * NO. 2 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)							Service ATA:71
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
PROC. REF: AMM 71-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-11-00-G7110021L	REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA							Service ATA:71
	MOS/MSC	25-Aug-15	N/A					
	HRS	3702.6						
	AFL	2436						
	PROC. REF: AMM 28-00-00							
05-11-00-G7110021R	REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA							Service ATA:71
	MOS/MSC	25-Aug-15	N/A					
	HRS	3702.6						
	AFL	2436						
	PROC. REF: AMM 28-00-00							
05-11-00-G7110022L	REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)							Service ATA:71
	MOS/MSC	25-Aug-15	N/A					
	HRS	3702.6						
	AFL	2436						
	PROC. REF: GENERIC NO REF							
05-11-00-G7110022R	REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)							Service ATA:71
	MOS/MSC	25-Aug-15	N/A					
	HRS	3702.6						
	AFL	2436						
	PROC. REF: GENERIC NO REF							
05-11-00-M7120048L	REPLACE NO. 1 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)							Service ATA:71
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
	PROC. REF: AMM 71-20-05							
05-11-00-M7120048R	REPLACE NO. 2 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)							Service ATA:71
	MOS	29-Dec-00						LIFE LIMIT
	HRS	0	20000		20000		14415.8	
	AFL	0						
	PROC. REF: AMM 71-20-05							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-P&W-710001	NO. 1 ENGINE - PERFORM OVERHAUL ENGINE							Service ATA:71
	MOS	11-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
05-P&W-710001	NO. 2 ENGINE - PERFORM OVERHAUL ENGINE							Service ATA:71
	MOS	10-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
05-P&W-710006	NO. 1 ENGINE - PERFORM HOT SECTION INSPECTION							Service ATA:71
	MOS	15-Apr-15						INSPECT
	HRS	3616.4	3600 (+50)		(7216.4) 7216.4	7266.4	1632.2 (+50)	
	ENC	2379						
PROC. REF: GENERIC NO REF								
05-P&W-710006	NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION							Service ATA:71
	MOS	14-Nov-13						INSPECT
	HRS	3379.4	3600 (+50)		(6979.4) 6976.9	7029.4	1392.7 (+50)	
	ENC	2209						
PROC. REF: GENERIC NO REF								
05-P&W-710015	NO. 1 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS							Service ATA:71
	MOS	29-Apr-19						
	HRS	4625.7	1200 (+25/-25)		(5825.7) 5825.7	5850.7	241.5 (+25)	
	ENC	2994						
PROC. REF: GENERIC NO REF								
05-P&W-710015	NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS							Service ATA:71
	MOS	12-Mar-19						
	HRS	4625.7	1200 (+25/-25)		(5825.7) 5823.2	5850.7	239 (+25)	
	ENC	2977						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-P&W-710017	NO. 1 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR							Service ATA:71
	MOS	12-Oct-22						
	HRS	5563.7	600 (+25/-25)		(6163.7) 6163.7	6188.7	579.5 (+25)	
	ENC	3693						
PROC. REF: GENERIC NO REF								
05-P&W-710017	NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR							Service ATA:71
	MOS	03-Nov-22						
	HRS	5566.2	600 (+25/-25)		(6166.2) 6163.7	6191.2	579.5 (+25)	
	ENC	3696						
PROC. REF: GENERIC NO REF								
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEED OFF VALVE SOLENOID							Service ATA:71
PN:30B7178-02	MOS	12-Mar-21						
SN:AGJA000A794	HRS	5214.4	3600 (+400)		(8814.4) 8814.4	9214.4	3230.2 (+400)	
	ENC	3423	3600		(7023) 7023		3318	
PROC. REF: EMM 75-30-02								
05-P&W-710019	NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID							Service ATA:71
PN:30B7178-02	MOS	12-Mar-21						
SN:AGJ12430805	HRS	5165.7	3600 (+400)		(8765.7) 8763.2	9165.7	3179 (+400)	
	ENC	3406	3600		(7006) 7003		3298	
PROC. REF: EMM 75-30-02								
05-P&W-710020	NO. 1 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESSSES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR							Service ATA:71
	MOS	03-Nov-17						
	HRS	4179	3600 (+50)		(7779) 7779	7829	2194.8 (+50)	
	ENC	2725						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-P&W-710020	NO. 2 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESSSES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR							Service ATA:71
	MOS	14-Nov-13						
	HRS	3379.4	3600 (+50)		(6979.4) 6976.9	7029.4	1392.7 (+50)	
	ENC	2209						
			PROC. REF: GENERIC NO REF					
710000	NO. 1 ENGINE - COMPRESSOR WASH							Service ATA:71
	MOS/MSC	11-Nov-00	A/R					
	HRS	0						
	ENC	0						
			PROC. REF: EMM 71-00-00					
710000	NO. 2 ENGINE - COMPRESSOR WASH							Service ATA:71
	MOS/MSC	10-Nov-00	A/R					
	HRS	0						
	ENC	0						
			PROC. REF: EMM 71-00-00					
710050	NO. 1 ENGINE - RUN ENGINES							Service ATA:71
	MOS/MSC		A/R					
	HRS							
	ENC							
			PROC. REF: EMM 72-00-00					
710050	NO. 2 ENGINE - RUN ENGINES							Service ATA:71
	MOS/MSC	05-Jul-19	A/R					
	HRS	4670.3						
	ENC	3015						
			PROC. REF: EMM 72-00-00					
711005	LEFT ENGINE INLET COWL							Component ATA:71
PN:282-0211-505	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:548	HRS	0		TSN 0				
	AFL	0		TSN 0				
			PROC. REF: AMM 71-10-05					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711006	RIGHT ENGINE INLET COWL							Component ATA:71
PN:282-0211-507	MOS/MSC	20-Sep-19	O/C					
SN:549	HRS	4708.6						
	AFL	3044						
PROC. REF: AMM 71-10-05								
711011	LEFT ENGINE UPPER ACCESS COWL							Component ATA:71
PN:266-0212-519	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10								
711012	RIGHT ENGINE UPPER ACCESS COWL							Component ATA:71
PN:266-0212-521	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:549	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10								
711013	LEFT ENGINE LOWER ACCESS COWL							Component ATA:71
PN:266-0211-533	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10								
711014	RIGHT ENGINE LOWER ACCESS COWL							Component ATA:71
PN:266-0211-535	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:551	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10								
711015	LEFT ENGINE PYLON APRON ASSEMBLY							Component ATA:71
PN:6080001-009	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-15								
711016	RIGHT ENGINE PYLON APRON ASSEMBLY							Component ATA:71
PN:6080001-010	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:549	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711021	LEFT ENGINE OUTER FAN DUCT							Component ATA:71
PN:266-0075-517	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:CFND0145	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-20								
711022	RIGHT ENGINE OUTER FAN DUCT							Component ATA:71
PN:266-0075-519	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:CFNR0123	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-20								
711023	LEFT ENGINE LEFT FORWARD CORE COWL							Component ATA:71
PN:266-0261-501	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25								
711024	RIGHT ENGINE LEFT FORWARD CORE COWL							Component ATA:71
PN:266-0261-501	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:549	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25								
711025	LEFT ENGINE RIGHT FORWARD CORE COWL							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25								
711026	RIGHT ENGINE RIGHT FORWARD CORE COWL							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25								
711027	LEFT ENGINE UPPER AFT CORE COWL							Component ATA:71
PN:266-0263-511	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711028	RIGHT ENGINE UPPER AFT CORE COWL							Component ATA:71
PN:266-0263-511	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:549	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25								
711029	LEFT ENGINE LOWER AFT CORE COWL							Component ATA:71
PN:266-0263-509	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25								
711030	RIGHT ENGINE LOWER AFT CORE COWL							Component ATA:71
PN:266-0263-509	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:549	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25								
712001	LEFT ENGINE FORWARD INTERMEDIATE FITTING							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-01								
712002	RIGHT ENGINE FORWARD INTERMEDIATE FITTING							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-01								
712005	LEFT ENGINE FORWARD UPPER VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-501	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:LK0774	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05								
712006	RIGHT ENGINE FORWARD UPPER VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-505	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:LK0802	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712007	LEFT ENGINE FORWARD LOWER VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-505	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:LK0789	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05								
712008	RIGHT ENGINE FORWARD LOWER VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-501	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:LK0758	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05								
712009	LEFT ENGINE FORWARD MOUNT YOKE							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05								
712010	RIGHT ENGINE FORWARD MOUNT YOKE							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05								
712011	LEFT ENGINE AFT VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-503	MOS/MSC	22-Apr-15	O/C	TSN 0				
SN:LK1156	HRS	3616.4		TSN 0				
	AFL	2379		TSN 0				
PROC. REF: AMM 71-20-10								
712012	RIGHT ENGINE AFT VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-503	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:LK0707	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10								
712013	LEFT ENGINE UPPER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712014	RIGHT ENGINE UPPER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10								
712015	LEFT ENGINE LOWER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10								
712016	RIGHT ENGINE LOWER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10								
715020	NO. 1 ENGINE - ENGINE WIRE HARNESS							Component ATA:71
PN:30B3089-03	MOS/MSC	15-Apr-15	O/C	TSN 0				
SN:EMA3D93351	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
PROC. REF: EMM 73-20-03								
715020	NO. 2 ENGINE - ENGINE WIRE HARNESS							Component ATA:71
PN:30B3089-01	MOS/MSC	14-Nov-13	O/C					
SN:AA15944	HRS	3379.4						
	ENC	2209						
PROC. REF: EMM 73-20-03								
715025	NO. 1 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR							Component ATA:71
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01								
715025	NO. 2 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR							Component ATA:71
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:31B4067-04	MOS/MSC	22-Apr-15	E/C					
SN:PCE-CA0260	HRS	3616.4		TSN 3615.6				
WC#: 71.EN1	AFL	2379						
PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:31B4067-04	MOS/MSC	14-Nov-13	E/C					
SN:PCE-CA0259	HRS	3379.4		TSN 3379.4				
WC#: 71.EN2	AFL	2209						
PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00								
E7100004 ^S	VISUAL INSPECTION OF ALL BLEED AIR DUCTS, LINES, HOSES, AND ELECTRICAL WIRING IN THE ENGINE NACELLE. INSPECT FOR SECURITY, CLAMPING, ROUTING, CLEARANCE, EVIDENCE OF LEAKS, AND GENERAL CONDITION. (REFER TO 5-10-00)							Service ATA:71
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:3
E7100016 ^S	INSPECT HOLD OPEN RODS FOR SECURITY OF INSTALLATION AND EVIDENCE OF DAMAGE.							Service ATA:71
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:3
E7100020 ^S	REMOVE IGNITER ACCESS PANEL AND INSPECT CORE COWL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE.							Service ATA:71
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:3
E7100022 ^S	INSPECT IGNITER ACCESS PANEL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE.							Service ATA:71
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
E7100030 ^S	INSPECT FUEL, HYDRAULIC, FIRE EXTINGUISHER, AND DRAIN LINES, CONTROLS CONNECTIONS, COUPLINGS, AND ACCESSORIES FOR LOOSE OR FAILED FASTENERS, CHAFING WEAR, ROUTING, PROPER SAFETY, SECURITY OF MOUNTING, AND EVIDENCE OF DAMAGE. INSPECT SHIELDED FADEC ELECTRICAL HAR							Service ATA:71
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:3
J7120051 ^S	FORWARD ENGINE BEAM INTERMEDIATE FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-01.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-01								PKG:28
J7120052 ^S	FORWARD ENGINE MOUNT YOKE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-02.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-02								PKG:28
J7120053 ^S	BOLT/FORWARD INTERMEDIATE FITTING TO FORWARD BEAM SUPPORT FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-03.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-03								PKG:28
J7120054 ^S	BOLT/FORWARD YOKE TO INTERMEDIATE FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-04.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-04								PKG:28
J7120055 ^S	BOLT/FORWARD YOKE TO ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-05.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-05								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
J7120056 ^S	BOLT/FORWARD ENGINE ISOLATOR TO ENGINE CASE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-06.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
				PROC. REF: NDT 71-20-06				PKG:28
J7120057 ^S	FORWARD TO ENGINE ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-07.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
				PROC. REF: NDT 71-20-07				PKG:28
J7120058 ^S	AFT ENGINE ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-08.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
				PROC. REF: NDT 71-20-08				PKG:28
J7120059 ^S	AFT MOUNT LINKS - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-09.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
				PROC. REF: NDT 71-20-09				PKG:28
J7120060 ^S	BOLT/AFT ISOLATOR TO SUPPORT FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-10.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
				PROC. REF: NDT 71-20-10				PKG:28
J7120061 ^S	BOLT/AFT ISOLATOR TO MOUNT LINKS - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-11.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
				PROC. REF: NDT 71-20-11				PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
J7120062 ^S	BOLT/MOUNT LINKS TO ENGINE CASE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-12.)							Service ATA:71
	MOS	29-Dec-00						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-12							PKG:28	
M7120068A	INSPECT NO. 1 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS							Service ATA:71
	MOS	22-Apr-15						
	HRS	3616.4	3600 (+25/-25)		7216.4	7241.4	1632.2 (+25)	
	AFL	2379						
PROC. REF: AMM 71-20-05, AMM 71-20-10								
M7120068B	INSPECT NO. 2 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS							Service ATA:71
	MOS	22-Apr-15						
	HRS	3616.4	3600 (+25/-25)		7216.4	7241.4	1632.2 (+25)	
	AFL	2379						
PROC. REF: AMM 71-20-05, AMM 71-20-10								
T7100010 ^S	INSPECT UPPER COWL DOOR AND APRON FOR FAILED FASTENERS, SECURITY, AND EVIDENCES OF DAMAGE. INSPECT BONDING JUMPERS ACROSS COWLING HINGES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR AND APRON FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY							Service ATA:71
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:15	
T7100012 ^S	INSPECT LOWER COWL DOOR INNER AND OUTER SKINS AND SEALS FOR EVIDENCE OF DAMAGE. INSPECT LATCH ASSEMBLIES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY AROUND THE HEADS OF FASTENERS AND ALONG							Service ATA:71
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
PROC. REF: GENERIC NO REF							PKG:15	
T7100018 ^S	GENERAL VISUAL INSPECTION FAN DUCT OUTER SKIN AND ATTACHMENT. (REFER TO 5-10-00)							Service ATA:71
	MOS	23-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF							PKG:9	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
U7100014 ^S	GENERAL VISUAL INSPECTION OIL FILLER DOOR. (REFER TO 5-10-00)							Service ATA:71
	MOS	23-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
U7110032 ^S	GENERAL VISUAL INSPECTION GENERATOR INLET DUCT SEAL. (REFER TO 5-10-00)							Service ATA:71
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: GENERIC NO REF								PKG:3
U7110041 ^S	GENERAL VISUAL INSPECTION NACELLE OUTER SKIN ATTACHMENT. (REFER TO 5-10-00)							Service ATA:71
	MOS	23-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
U7110042 ^S	GENERAL VISUAL INSPECTION NACELLE LIP ASSEMBLY AND INNER BARREL. (REFER TO 5-10-00)							Service ATA:71
	MOS	24-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
ATA 72 - ENGINE								
496010	APU - H.O.T. SWITCH							Component ATA:72
PN:PN	MOS/MSC	29-Sep-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
720000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION							Service ATA:72
	MOS	15-Apr-15	T:180 (+12m)	15-Apr-30	15-Apr-31	2651 d (+365)		
	HRS	3616.4						
	ENC	2379						
PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION							Service ATA:72
	MOS	15-Nov-13	T:180 (+12m)		15-Nov-28	15-Nov-29	2135 d (+365)	
	HRS	3379.4						
	ENC	2204						
PROC. REF: EMM 72-00-00								
720001	NO. 1 ENGINE - ENGINE PRESERVATION - 1 TO 14 DAYS							Service ATA:72
	MOS/MSC	11-Nov-00	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720001	NO. 2 ENGINE - ENGINE PRESERVATION - 1 TO 14 DAYS							Service ATA:72
	MOS/MSC	10-Nov-00	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720002	NO. 1 ENGINE - ENGINE PRESERVATION - 15 TO 28 DAYS							Service ATA:72
	MOS/MSC	11-Nov-00	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720002	NO. 2 ENGINE - ENGINE PRESERVATION - 15 TO 28 DAYS							Service ATA:72
	MOS/MSC	10-Nov-00	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720003	NO. 1 ENGINE - ENGINE PRESERVATION - 1 TO 28 DAYS							Service ATA:72
	MOS/MSC	11-Nov-00	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720003	NO. 2 ENGINE - ENGINE PRESERVATION - 1 TO 28 DAYS							Service ATA:72
	MOS/MSC	10-Nov-00	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720004	NO. 1 ENGINE - ENGINE PRESERVATION - 29 TO 90 DAYS							Service ATA:72
	MOS/MSC	11-Nov-00	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-00-00							
720004	NO. 2 ENGINE - ENGINE PRESERVATION - 29 TO 90 DAYS							Service ATA:72
	MOS/MSC	10-Nov-00	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-00-00							
720005	NO. 1 ENGINE - ENGINE PRESERVATION - 91 DAYS AND OVER							Service ATA:72
	MOS/MSC	11-Nov-00	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-00-00							
720005	NO. 2 ENGINE - ENGINE PRESERVATION - 91 DAYS AND OVER							Service ATA:72
	MOS/MSC	10-Nov-00	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-00-00							
720006	NO. 1 ENGINE - ENGINE DEPRESERVATION							Service ATA:72
	MOS/MSC	11-Nov-00	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-00-00							
720006	NO. 2 ENGINE - ENGINE DEPRESERVATION							Service ATA:72
	MOS/MSC	10-Nov-00	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-00-00							
720007	NO. 1 ENGINE - ENGINE ALTERNATIVE PRESERVATION							Service ATA:72
	MOS/MSC	11-Nov-00	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-00-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720007	NO. 2 ENGINE - ENGINE ALTERNATIVE PRESERVATION							Service ATA:72
	MOS/MSC	10-Nov-00	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720010 ^S	NO. 1 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES							Service ATA:72
	MOS	23-Mar-21	24					
	HRS	5214.4	600					
	ENC	3424						
PROC. REF: EMM 05-20-00								PKG:1
720010 ^S	NO. 2 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1
720015 ^S	NO. 1 ENGINE - EEC - REMOVE, CHECK CONDITION, CLEAN THE CONNECTORS AND REINSTALL							Service ATA:72
	MOS	11-Nov-00	24					
	HRS	0	600					
	ENC	0						
PROC. REF: EMM 70-00-00								PKG:1
720015 ^S	NO. 2 ENGINE - EEC - REMOVE, CHECK CONDITION, CLEAN THE CONNECTORS AND REINSTALL							Service ATA:72
	MOS	10-Nov-00	24					
	HRS	0	600					
	ENC	0						
PROC. REF: EMM 70-00-00								PKG:1
720020 ^S	NO. 1 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720020 ^S	NO. 2 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720030 ^S	NO. 1 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720030 ^S	NO. 2 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1
720040 ^S	NO. 1 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720040 ^S	NO. 2 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1
720050 ^S	NO. 1 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720050 ^S	NO. 2 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720060 ^S	NO. 1 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720060 ^S	NO. 2 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720070 ^S	NO. 1 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720070 ^S	NO. 2 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720080 ^S	NO. 1 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720080 ^S	NO. 2 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720090 ^S	NO. 1 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640)							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720090 ^S	NO. 2 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640)							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720095	NO. 1 ENGINE - DISCARD LP COMPRESSOR FAN BLADES							Service ATA:72
PN:PN	MOS	11-Nov-00						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	ENC	0	15000		(15000) 15000		11295	
PROC. REF: GENERIC NO REF								
720095	NO. 2 ENGINE - DISCARD LP COMPRESSOR FAN BLADES							Service ATA:72
PN:PN	MOS	10-Nov-00						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	ENC	0	15000		(15000) 14997		11292	
PROC. REF: GENERIC NO REF								
720100 ^S	NO. 1 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720100 ^S	NO. 2 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720110 ^S	NO. 1 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720110 ^S	NO. 2 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1
720120 ^S	NO. 1 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720120 ^S	NO. 2 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1
720130 ^S	NO. 1 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720130 ^S	NO. 2 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1
720140 ^S	NO. 1 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720140 ^S	NO. 2 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720150 ^S	NO. 1 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720150 ^S	NO. 2 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720160 ^S	NO. 1 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720160 ^S	NO. 2 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720170 ^S	NO. 1 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 79-20-01							PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720170 ^S	NO. 2 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 79-20-01								PKG:1
720180 ^S	NO. 1 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720180 ^S	NO. 2 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1
720190 ^S	NO. 1 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1
720190 ^S	NO. 2 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00								PKG:1
720200 ^S	NO. 1 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720200 ^S	NO. 2 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720210 ^S	NO. 1 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720210 ^S	NO. 2 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720220 ^S	NO. 1 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND.							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720220 ^S	NO. 2 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND.							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720230 ^S	NO. 1 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720230 ^S	NO. 2 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720240 ^S	NO. 1 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720240 ^S	NO. 2 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720250 ^S	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE.							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720250 ^S	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE.							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720260 ^S	NO. 1 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720260 ^S	NO. 2 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720270 ^S	NO. 1 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 77-20-02, EMM 75-30-03							PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720270 ^S	NO. 2 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 77-20-02, EMM 75-30-03							PKG:1	
720280 ^S	NO. 1 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720280 ^S	NO. 2 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720290 ^S	NO. 1 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY.							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720290 ^S	NO. 2 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY.							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
720300 ^S	NO. 1 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720300 ^S	NO. 2 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720310 ^S	NO. 1 ENGINE - SPARK IGNITERS, OPERATIONAL TEST							Service ATA:72
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 05-20-00							PKG:1	
720310 ^S	NO. 2 ENGINE - SPARK IGNITERS, OPERATIONAL TEST							Service ATA:72
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 05-20-00							PKG:1	
723001	NO. 1 ENGINE - FAN HUB							Component ATA:72
PN:30B2256	MOS	11-Nov-00		TSN 0				LIFE LIMIT
SN:A000FE6K	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	12000	TSN 0			8295	
PROC. REF: EMM 72-30-01								
723001	NO. 2 ENGINE - FAN HUB							Component ATA:72
PN:30B2256	MOS	10-Nov-00		TSN 0				LIFE LIMIT
SN:A000FR29	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	12000	TSN 0			8292	
PROC. REF: EMM 72-30-01								
723002	NO. 1 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01								
723002	NO. 2 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723003	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:30B4565-01	MOS	11-Nov-00		TSN 0				LIFE LIMIT
SN:A000F2DR	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	7000	TSN 0			3295	
PROC. REF: EMM 72-30-01								
723003	NO. 2 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:30B4565-01	MOS	10-Nov-00		TSN 0				LIFE LIMIT
SN:A000H83R	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	7000	TSN 0			3292	
PROC. REF: EMM 72-30-01								
723004	NO. 1 ENGINE - PRESSURE CHECK IMPELLER SHROUD							Service ATA:72
	MOS/MSC	11-Nov-00	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
723004	NO. 2 ENGINE - PRESSURE CHECK IMPELLER SHROUD							Service ATA:72
	MOS/MSC	10-Nov-00	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
723005	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR							Component ATA:72
PN:30B6551-01	MOS	15-Apr-15		TSN 0				LIFE LIMIT
SN:TXA1D3966	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
	ACCCYC	0	12000	TSN 0			10674	
PROC. REF: EMM 72-30-01								
723005	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR							Component ATA:72
PN:30B6551-01	MOS	14-Nov-13		TSN 0				LIFE LIMIT
SN:TXA1C9436	HRS	3379.4		TSN 0				
	ENC	2209		TSN 0				
	ACCCYC	0	12000	TSN 0			10501	
PROC. REF: EMM 72-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723005A	NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR)							Service ATA:72
PN:30B6551-01	MOS/MSC	15-Apr-15	N/A					NOT APPLICABLE
SN:TXA1D3966	HRS	3616.4						
	ENC	2379						
PROC. REF: EMM 72-00-00								
723005A	NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR)							Service ATA:72
PN:30B6551-01	MOS/MSC	14-Nov-13	N/A					NOT APPLICABLE
SN:TXA1C9436	HRS	3379.4						
	ENC	2209						
PROC. REF: EMM 72-00-00								
723008	NO. 1 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR							Component ATA:72
PN:30B4745-01	MOS	11-Nov-00		TSN 0				LIFE LIMIT
SN:43B503	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	8500	TSN 0			4795	
PROC. REF: GENERIC NO REF								
723008	NO. 2 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR							Component ATA:72
PN:30B4745-01	MOS	10-Nov-00		TSN 0				LIFE LIMIT
SN:43B501	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	8500	TSN 0			4792	
PROC. REF: GENERIC NO REF								
723008A	NO. 1 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM							Service ATA:72
	MOS/MSC		N/A					
	HRS							
	ENC							
PROC. REF: GENERIC NO REF								
723008A	NO. 2 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM							Service ATA:72
	MOS/MSC		N/A					
	HRS							
	ENC							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723040	NO. 1 ENGINE - LP COMPRESSOR BLADES							Component ATA:72
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723040	NO. 2 ENGINE - LP COMPRESSOR BLADES							Component ATA:72
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724010	NO. 1 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)							Service ATA:72
	MOS/MSC	11-Nov-00	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
724010	NO. 2 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)							Service ATA:72
	MOS/MSC	10-Nov-00	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
725001	NO. 1 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING							Component ATA:72
PN:30B3012CL01	MOS/MSC	15-Apr-15	O/C	TSN 0				
SN:HLAC206	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
PROC. REF: EMM 72-50-01								
725001	NO. 2 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING							Component ATA:72
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-01								
725003	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725003	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-03								
725101	NO. 1 ENGINE - STAGE 1 TURBINE DISC							Component ATA:72
PN:30B2981-01	MOS	15-Apr-15		TSN 0				LIFE LIMIT
SN:A003K6N8	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
	ACCCYC	0	3100	TSN 0			1774	
PROC. REF: EMM 72-50-01								
725101	NO. 2 ENGINE - STAGE 1 TURBINE DISC							Component ATA:72
PN:30B2981-01	MOS	14-Nov-13		TSN 0				LIFE LIMIT
SN:A003BADN	HRS	3379.4		TSN 0				
	ENC	2209		TSN 0				
	ACCCYC	0	3100	TSN 0			1601	
PROC. REF: EMM 72-50-01								
725102	NO. 1 ENGINE - STAGE 2 TURBINE DISC							Component ATA:72
PN:30B2912-01	MOS	15-Apr-15		TSN 0				LIFE LIMIT
SN:A003KL5D	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
	ACCCYC	0	3300	TSN 0			1974	
PROC. REF: EMM 72-50-01								
725102	NO. 2 ENGINE - STAGE 2 TURBINE DISC							Component ATA:72
PN:30B2912-01	MOS	14-Nov-13		TSN 0				LIFE LIMIT
SN:A003B885	HRS	3379.4		TSN 0				
	ENC	2209		TSN 0				
	ACCCYC	0	3300	TSN 0			1801	
PROC. REF: EMM 72-50-01								
725103	NO. 1 ENGINE - STAGE 3 TURBINE DISC							Component ATA:72
PN:30A1833	MOS	11-Nov-00		TSN 0				LIFE LIMIT
SN:59B535	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	10000	TSN 0			6295	
PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725103	NO. 2 ENGINE - STAGE 3 TURBINE DISC							Component ATA:72
PN:30A1833	MOS	10-Nov-00		TSN 0				LIFE LIMIT
SN:59B534	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	10000	TSN 0			6292	
PROC. REF: EMM 72-50-01								
725104	NO. 1 ENGINE - STAGE 4 TURBINE DISC							Component ATA:72
PN:30A1834	MOS	11-Nov-00		TSN 0				LIFE LIMIT
SN:32B283	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	10000	TSN 0			6295	
PROC. REF: EMM 72-50-01								
725104	NO. 2 ENGINE - STAGE 4 TURBINE DISC							Component ATA:72
PN:30A1834	MOS	10-Nov-00		TSN 0				LIFE LIMIT
SN:62B288	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	10000	TSN 0			6292	
PROC. REF: EMM 72-50-01								
725105	NO. 1 ENGINE - STAGE 5 TURBINE DISC							Component ATA:72
PN:30A1835	MOS	11-Nov-00		TSN 0				LIFE LIMIT
SN:59B915	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	10000	TSN 0			6295	
PROC. REF: EMM 72-50-01								
725105	NO. 2 ENGINE - STAGE 5 TURBINE DISC							Component ATA:72
PN:30A1835	MOS	10-Nov-00		TSN 0				LIFE LIMIT
SN:59B902	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	10000	TSN 0			6292	
PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725107	NO. 1 ENGINE - FRONT HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B2748-01	MOS	11-Nov-00		TSN 0				LIFE LIMIT
SN:A000H2H1	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	4800	TSN 0			1095	
PROC. REF: EMM 72-50-01								
725107	NO. 2 ENGINE - FRONT HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B2748-01	MOS	10-Nov-00		TSN 0				LIFE LIMIT
SN:A000H2FP	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	4800	TSN 0			1092	
PROC. REF: EMM 72-50-01								
725109	NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B6726-01	MOS	15-Apr-15		TSN 0				LIFE LIMIT
SN:A003C9AL	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
	ACCCYC	0	4400	TSN 0			2544	
PROC. REF: EMM 72-50-01								
725109	NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B6726-01	MOS	14-Nov-13		TSN 0				LIFE LIMIT
SN:A003CNK5	HRS	3379.4		TSN 0				
	ENC	2209		TSN 0				
	ACCCYC	0	4400	TSN 0			2301	
PROC. REF: EMM 72-50-01								
725111	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL							Component ATA:72
PN:30B2793-01	MOS	15-Apr-15		TSN 0				LIFE LIMIT
SN:PKAAA543145	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
	ACCCYC	0	4000	TSN 0			2674	
PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725111	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL							Component ATA:72
PN:30B2793-01	MOS	14-Nov-13		TSN 0				LIFE LIMIT
SN:PKAAA522182	HRS	3379.4		TSN 0				
	ENC	2209		TSN 0				
	ACCCYC	0	4000	TSN 0			2501	
PROC. REF: EMM 72-50-01								
726001	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING							Component ATA:72
PN:31B5064-01	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:A000KKPD	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01								
726001	NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING							Component ATA:72
PN:31B5064-01	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:A000KKPB	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01								
726011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)							Service ATA:72
	MOS	11-Nov-00						
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
726011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)							Service ATA:72
	MOS	10-Nov-00						
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
727001	NO. 1 ENGINE - COMBUSTION CHAMBER LINER							Component ATA:72
PN:30B4008-01	MOS/MSC	15-Apr-15	O/C					
SN:A000X8Y2	HRS	3616.4						
	ENC	2379						
PROC. REF: EMM 72-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
727001	NO. 2 ENGINE - COMBUSTION CHAMBER LINER							Component ATA:72
PN:30B4008-01	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:A000HF7P	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01								
727001A	NO. 1 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER							Service ATA:72
PN:30B4008-01	MOS	22-Apr-15						
SN:A000X8Y2	HRS	3616.4	3600 (+50)		(7216.4) 7216.4	7266.4	1632.2 (+50)	
	ENC	2379						
PROC. REF: EMM 72-40-01								
727001A	NO. 2 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER							Service ATA:72
	MOS	14-Nov-13						
	HRS	3379.4	3600 (+50)		(6979.4) 6976.9	7029.4	1392.7 (+50)	
	ENC	2209						
PROC. REF: EMM 72-40-01								
727002	NO. 1 ENGINE - INNER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01								
727002	NO. 2 ENGINE - INNER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01								
727003	NO. 1 ENGINE - OUTER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
727003	NO. 2 ENGINE - OUTER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01								
727004	NO. 1 ENGINE - EXAMINE FOR CRACKS AROUND IGNITER BOSSES - COMBUSTION CHAMBER LINER							Service ATA:72
	MOS/MSC		N/A					
	HRS							
	ENC							
PROC. REF: EMM 72-00-00								
727004	NO. 2 ENGINE - EXAMINE FOR CRACKS AROUND IGNITER BOSSES - COMBUSTION CHAMBER LINER							Service ATA:72
	MOS/MSC		N/A					
	HRS							
	ENC							
PROC. REF: EMM 72-00-00								
ATA 73 - ENGINE FUEL AND CONTROL								
05-P&W-730001	NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT							Service ATA:73
	MOS	11-Mar-22	12		11-Mar-23		59 d	
	HRS	5539.1	1200 (+25/-25)		(6739.1) 6739.1	6764.1	1154.9 (+25)	
	ENC	3671						
PROC. REF: EMM 73-10-03								
05-P&W-730001	NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT							Service ATA:73
	MOS	11-Mar-22	12		11-Mar-23		59 d	
	HRS	5490.4	1200 (+25/-25)		(6690.4) 6687.9	6715.4	1103.7 (+25)	
	ENC	3654						
PROC. REF: EMM 73-10-03								
05-P&W-730005	NO. 1 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE							Service ATA:73
	MOS	13-Oct-22						
	HRS	5563.7	1800 (+600/-600)		(7363.7) 7363.7	7963.7	1779.5 (+600)	
	ENC	3693						
PROC. REF: EMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
05-P&W-730005	NO. 2 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE							Service ATA:73
	MOS	23-Sep-21						
	HRS	5417.1	1800 (+600/-600)		(7217.1) 7214.6	7817.1	1630.4 (+600)	
	ENC	3597						
PROC. REF: EMM 73-10-04								
731001	NO. 1 ENGINE - FUEL PUMP							Component ATA:73
PN:30B1910	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:MX631256A	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02								
731001	NO. 2 ENGINE - FUEL PUMP							Component ATA:73
PN:30B1910	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:MX631256A	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02								
731002	NO. 1 ENGINE - MOTIVE FLOW VALVE							Component ATA:73
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01								
731002	NO. 2 ENGINE - MOTIVE FLOW VALVE							Component ATA:73
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01								
731003	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH							Component ATA:73
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731003	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH							Component ATA:73
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03								
731004	NO. 1 ENGINE - UPPER PRIMARY FUEL NOZZLE							Component ATA:73
PN:31B5832-04	MOS/MSC	13-Oct-22	O/C	TSO 0				
SN:1TL04727	HRS	5563.7		TSO 0				
	ENC	3693		TSO 0				
PROC. REF: EMM 73-10-04								
731004	NO. 2 ENGINE - UPPER PRIMARY FUEL NOZZLE							Component ATA:73
PN:31B5832-04	MOS/MSC	14-Nov-13	O/C	TSN 0				
SN:AAA17861	HRS	3379.4		TSN 0				
	ENC	2209		TSN 0				
PROC. REF: EMM 73-10-04								
731005	NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE							Component ATA:73
PN:31B5832-04	MOS/MSC	13-Oct-22	O/C	TSO 0				
SN:1NM02349	HRS	5563.7		TSO 0				
	ENC	3693		TSO 0				
PROC. REF: EMM 73-10-04								
731005	NO. 2 ENGINE - LOWER PRIMARY FUEL NOZZLE							Component ATA:73
PN:31B5832-04	MOS/MSC	14-Nov-13	O/C	TSN 0				
SN:AAA17860	HRS	3379.4		TSN 0				
	ENC	2209		TSN 0				
PROC. REF: EMM 73-10-04								
731010	NO. 1 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY							Component ATA:73
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05								
731010	NO. 2 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY							Component ATA:73
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731011 ^S	NO. 1 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY							Service ATA:73
	MOS	28-Apr-19	24					
	HRS	4647.4	600					
	ENC	2994						
PROC. REF: EMM 73-10-05, EMM 73-10-04							PKG:1	
731011 ^S	NO. 2 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY							Service ATA:73
	MOS	29-Apr-19	24					
	HRS	4625.7	600					
	ENC	2977						
PROC. REF: EMM 73-10-05, EMM 73-10-04							PKG:1	
731012	NO. 1 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP							Service ATA:73
PN:30B1910	MOS	11-Nov-00						OVERHAUL
SN:MX631256A	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-02								
731012	NO. 2 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP							Service ATA:73
PN:30B1910	MOS	10-Nov-00						OVERHAUL
SN:MX631256A	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-02								
731013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH							Service ATA:73
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
731013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH							Service ATA:73
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731014	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY							Service ATA:73
	MOS	11-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04								
731014	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY							Service ATA:73
	MOS	10-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04								
731022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY)							Service ATA:73
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
731022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY)							Service ATA:73
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
731023	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK							Service ATA:73
PN:31B5132-01	MOS	11-Nov-00						
SN:0835	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
731023	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK							Service ATA:73
PN:31B5132-01	MOS	10-Nov-00						
SN:0815	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731024	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY							Service ATA:73
	MOS	11-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04								
731024	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY							Service ATA:73
	MOS	10-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04								
731025	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE							Service ATA:73
PN:31B5131-01	MOS	11-Nov-00						
SN:0687	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
731025	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE							Service ATA:73
PN:31B5131-01	MOS	10-Nov-00						
SN:0647	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
731026	NO. 1 ENGINE - FUEL WASTE EJECTOR							Component ATA:73
PN:31B5132-01	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:0835	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03								
731026	NO. 2 ENGINE - FUEL WASTE EJECTOR							Component ATA:73
PN:31B5132-01	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:0815	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731044	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - INLET							Service ATA:73
	MOS	11-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04								
731044	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - INLET							Service ATA:73
	MOS	10-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04								
731045	NO. 1 ENGINE - DISCARD - FUEL SHUT-OFF CABLE							Service ATA:73
	MOS	11-Nov-00						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05								
731045	NO. 2 ENGINE - DISCARD - FUEL SHUT-OFF CABLE							Service ATA:73
	MOS	10-Nov-00						DISCARD
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05								
731051	NO. 1 ENGINE - FUEL START & DUMP VALVE							Component ATA:73
PN:31B5131-01	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:0687	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05								
731051	NO. 2 ENGINE - FUEL START & DUMP VALVE							Component ATA:73
PN:31B5131-01	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:0647	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731055	NO. 1 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF							Service ATA:73
	MOS	11-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05								
731055	NO. 2 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF							Service ATA:73
	MOS	10-Nov-00						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05								
732001	NO. 1 ENGINE - HYDRO MECHANICAL FUEL CONTROL							Component ATA:73
PN:31B4469-06	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:1891626	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01								
732001	NO. 2 ENGINE - HYDRO MECHANICAL FUEL CONTROL							Component ATA:73
PN:31B4469-06	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:1891625	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01								
732002	NO. 1 ENGINE - REPLACE TRIM PLUG							Service ATA:73
	MOS	31-Mar-21	120		31-Mar-31		3001 d	
	HRS	5223.1						
	ENC	3430						
PROC. REF: EMM 73-20-02, EMM 70-00-00								
732002	NO. 2 ENGINE - REPLACE TRIM PLUG							Service ATA:73
	MOS	31-Mar-21	120		31-Mar-31		3001 d	
	HRS	5174.4						
	ENC	3413						
PROC. REF: EMM 73-20-02, EMM 70-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732003	NO. 1 ENGINE - ELECTRICAL FRONT HARNESS							Component ATA:73
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03, EMM 73-20-03								
732003	NO. 2 ENGINE - ELECTRICAL FRONT HARNESS							Component ATA:73
PN:31B3767-01	MOS/MSC	14-Nov-13	O/C					
SN:AA16486	HRS	3379.4		TSN 3379.4				
	ENC	2209						
PROC. REF: EMM 73-20-03, EMM 73-20-03								
732004	NO. 1 ENGINE - ELECTRICAL REAR HARNESS							Component ATA:73
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03								
732004	NO. 2 ENGINE - ELECTRICAL REAR HARNESS							Component ATA:73
PN:31B3766-01	MOS/MSC	14-Nov-13	O/C					
SN:AA16271	HRS	3379.4		TSN 3379.4				
	ENC	2209						
PROC. REF: EMM 73-20-03								
732005	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC							Component ATA:73
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-02								
732005	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL EEC							Component ATA:73
PN:622821-5-063-004	MOS/MSC	20-Sep-19	O/C					
SN:EEC400-1	HRS	4686.9						
	ENC	3027						
PROC. REF: EMM 73-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732011	NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU							Service ATA:73
PN:31B4469-06	MOS	11-Nov-00						
SN:1891626	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
732011	NO. 2 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU							Service ATA:73
PN:31B4469-06	MOS	10-Nov-00						
SN:1891625	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
732012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC							Service ATA:73
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
732012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC							Service ATA:73
PN:622821-5-063-004	MOS	10-Nov-20						
SN:EEC400-1	HRS	0	7200 (+50)		(7200) 7197.5 (M)	7250	1613.3 (+50)	
	ENC							
PROC. REF: GENERIC NO REF								
732013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR)							Service ATA:73
PN:30B3089-03	MOS	11-Nov-00						
SN:EMA3D93351	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
732013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR)							Service ATA:73
PN:30B3089-01	MOS	10-Nov-00						
SN:AA15944	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732021	NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU							Service ATA:73
PN:31B4469-06	MOS/MSC	11-Nov-00	N/A					
SN:1891626	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-01								
732021	NO. 2 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU							Service ATA:73
PN:31B4469-06	MOS/MSC	10-Nov-00	N/A					
SN:1891625	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-01								
732101	NO. 1 ENGINE - ENGINE FADEC							Component ATA:73
PN:822821-5-004	MOS/MSC	05-Jul-19	O/C					
SN:00024036	HRS	4693.1						
	ENC	3034						
PROC. REF: EMM 73-20-03								
732101	NO. 2 ENGINE - ENGINE FADEC							Component ATA:73
PN:822821-5-004	MOS/MSC	05-Jul-19	O/C					
SN:00058365	HRS	4671.4						
	ENC	3017						
PROC. REF: EMM 73-20-03								
733010	DUAL FUEL FLOW CONVERTER							Component ATA:73
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-03								
733101	LEFT ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:7600021-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:515040	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-01								
733102	RIGHT ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:7600021-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:515044	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
733103	LEFT ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:6608488-001	MOS/MSC	03-Aug-12	O/C	TSN 0				
SN:4470	HRS	3178.5		TSN 0				
	AFL	2065		TSN 0				
PROC. REF: AMM 73-31-02								
733104	RIGHT ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:6608488-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4518	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-02								
ATA 74 - IGNITION								
741001	NO. 1 ENGINE - NO. 1 IGNITION EXCITER							Component ATA:74
PN:31B4636-02	MOS/MSC	22-Apr-15	O/C	TSR 0				
SN:NNA12290056	HRS	3616.4		TSR 0				
	ENC	2379		TSR 0				
PROC. REF: EMM 74-10-01								
741001	NO. 2 ENGINE - NO. 1 IGNITION EXCITER							Component ATA:74
PN:31B4636-02	MOS/MSC	05-May-18	O/C	TSO 0				
SN:NN97100250	HRS	4325.3		TSO 0				
	ENC	2798		TSO 0				
PROC. REF: EMM 74-10-01								
741002	NO. 1 ENGINE - NO. 2 IGNITION EXCITER							Component ATA:74
PN:31B4636-02	MOS/MSC	22-Apr-15	O/C					
SN:NN00292721	HRS	3616.4						
	ENC	2379						
PROC. REF: EMM 74-10-01								
741002	NO. 2 ENGINE - NO. 2 IGNITION EXCITER							Component ATA:74
PN:31B4636-02	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:NN00292721	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741003	NO. 1 ENGINE - NO. 1 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01								
741003	NO. 2 ENGINE - NO. 1 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01								
741004	NO. 1 ENGINE - NO. 2 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01								
741004	NO. 2 ENGINE - NO. 2 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01								
741011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX							Service ATA:74
PN:31B4636-02	MOS	11-Nov-00						
SN:NNA12290056	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
741011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX							Service ATA:74
PN:31B4636-02	MOS	10-Nov-00						
SN:NN97100250	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX							Service ATA:74
PN:31B4636-02	MOS	11-Nov-00						
SN:NN00292721	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
741012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX							Service ATA:74
PN:31B4636-02	MOS	10-Nov-00						
SN:NN00292721	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
741021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES							Service ATA:74
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
741021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES							Service ATA:74
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
741022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES							Service ATA:74
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
741022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES							Service ATA:74
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741031	NO. 1 ENGINE - REPLACE - NO. 1 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	11-Nov-00						REPLACE
SN:N/A	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 74-10-01								
741031	NO. 2 ENGINE - REPLACE - NO. 1 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	10-Nov-00						REPLACE
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 74-10-01								
741032	NO. 1 ENGINE - REPLACE - NO. 2 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	11-Nov-00						REPLACE
SN:N/A	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 74-10-01								
741032	NO. 2 ENGINE - REPLACE - NO. 2 IGNITER PLUGS							Service ATA:74
PN:31B3168-01	MOS	10-Nov-00						REPLACE
SN:N/A	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 74-10-01								
742025	NO. 1 ENGINE - NO. 1 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	15-Apr-15	O/C	TSN 0				
SN:N/A	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
PROC. REF: EMM 74-10-01								
742025	NO. 2 ENGINE - NO. 1 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	25-Aug-15	O/C	TSN 0				
SN:UNKNOWN	HRS	3680.9		TSN 0				
	ENC	2420		TSN 0				
PROC. REF: EMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742026	NO. 1 ENGINE - NO. 2 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	15-Apr-15	O/C	TSN 0				
SN:N/A	HRS	3616.4		TSN 0				
	ENC	2379		TSN 0				
PROC. REF: EMM 74-10-01								
742026	NO. 2 ENGINE - NO. 2 IGNITER PLUG							Component ATA:74
PN:31B3168-01	MOS/MSC	05-Sep-17	O/C	TSN 0				
SN:N/A	HRS	4148.4		TSN 0				
	ENC	2704		TSN 0				
PROC. REF: EMM 74-10-01								
743003	ENGINE WARNING LIGHT BOX							Component ATA:74
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 74-30-03								
ATA 75 - AIR								
751001	NO. 1 ENGINE - ANTI-ICING SOLENOID VALVE							Component ATA:75
PN:31B5108-03	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:AL487	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-10-01								
751001	NO. 2 ENGINE - ANTI-ICING SOLENOID VALVE							Component ATA:75
PN:31B5108-03	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:AL486	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-10-01								
751011	NO. 1 ENGINE - OVERHAUL - ANTI-ICING VALVE							Service ATA:75
PN:31B5108-03	MOS	11-Nov-00						OVERHAUL
SN:AL487	HRS	0	7200 (+50)	(7200) 7200	7250	1615.8 (+50)		
	ENC	0						
PROC. REF: EMM 75-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
751011	NO. 2 ENGINE - OVERHAUL - ANTI-ICING VALVE							Service ATA:75
PN:31B5108-03	MOS	10-Nov-00						OVERHAUL
SN:AL486	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 75-10-01								
753001	NO. 1 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES							Service ATA:75
	MOS	12-Mar-21						OVERHAUL
	HRS	5214.4	7200 (+50)		(12414.4) 12414.4	12464.4	6830.2 (+50)	
	ENC	3423						
PROC. REF: EMM 75-30-01								
753001	NO. 2 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES							Service ATA:75
	MOS	12-Mar-21						OVERHAUL
	HRS	5165.7	7200 (+50)		(12365.7) 12363.2	12415.7	6779 (+50)	
	ENC	3406						
PROC. REF: EMM 75-30-01								
753002	NO. 1 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS	12-Mar-21						DISCARD
	HRS	5214.4	7200 (+50)		(12414.4) 12414.4	12464.4	6830.2 (+50)	
	ENC	3423						
PROC. REF: GENERIC NO REF								
753002	NO. 2 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS	12-Mar-21						DISCARD
	HRS	5165.7	7200 (+50)		(12365.7) 12363.2	12415.7	6779 (+50)	
	ENC	3406						
PROC. REF: GENERIC NO REF								
753003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER							Service ATA:75
	MOS	11-Nov-00						
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER							Service ATA:75
	MOS	10-Nov-00						
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
753004	NO. 1 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04								
753004	NO. 2 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR							Component ATA:75
PN:31B5255-01	MOS/MSC	14-Nov-13	O/C					
SN:2600576	HRS	3379.4		TSN 3379.4				
	ENC	2209						
PROC. REF: EMM 75-30-04								
753005	NO. 1 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04								
753005	NO. 2 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04								
753012	NO. 1 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS/MSC	12-Mar-21	N/A					DISCARD
	HRS	5214.4						
	ENC	3423						
PROC. REF: EMM 75-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753012	NO. 2 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS/MSC	12-Mar-21	N/A					DISCARD
	HRS	5165.7						
	ENC	3406						
PROC. REF: EMM 75-30-02								
753014	NO. 1 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR							Service ATA:75
PN:PN	MOS/MSC	11-Nov-00	N/A					DISCARD
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
753014	NO. 2 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR							Service ATA:75
PN:PN	MOS/MSC	10-Nov-00	N/A					DISCARD
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
753024	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR							Service ATA:75
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
753024	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR							Service ATA:75
PN:31B5255-01	MOS	10-Nov-00						
SN:2600576	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
753081	NO. 1 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID							Component ATA:75
PN:30B7178-02	MOS/MSC	12-Mar-21	O/C	TSN 0				
SN:AGJA000A794	HRS	5214.4		TSN 0				
	ENC	3423		TSN 0				
PROC. REF: EMM 75-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753081	NO. 2 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID							Component ATA:75
PN:30B7178-02	MOS/MSC	12-Mar-21	O/C	TSN 0				
SN:AGJ12430805	HRS	5165.7		TSN 0				
	ENC	3406		TSN 0				
PROC. REF: EMM 75-30-02								
753082	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT							Component ATA:75
PN:PN-UNKNOWN	MOS/MSC	12-Mar-21	O/C					
SN:UNKNOWN	HRS	5214.4						
	ENC	3423						
PROC. REF: GENERIC NO REF								
753082	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT							Component ATA:75
PN:PN-UNKNOWN	MOS/MSC	12-Mar-21	O/C					
SN:UNKNOWN	HRS	5165.7						
	ENC	3406						
PROC. REF: GENERIC NO REF								
753083	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE							Service ATA:75
PN:PN-UNKNOWN	MOS/MSC	12-Mar-21	N/A					
SN:UNKNOWN	HRS	5214.4						
	ENC	3423						
PROC. REF: EMM 75-30-02								
753083	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE							Service ATA:75
PN:PN-UNKNOWN	MOS/MSC	12-Mar-21	N/A					
SN:UNKNOWN	HRS	5165.7						
	ENC	3406						
PROC. REF: EMM 75-30-02								
753101	NO. 1 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5759-01	MOS	12-Mar-21		TSO 0				REPLACE
SN:AHX017832	HRS	5214.4	3600 (+50)	TSO 0	(8814.4) 8814.4	8864.4	3230.2 (+50)	
	ENC	3423		TSO 0				
PROC. REF: EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753101	NO. 2 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5759-01	MOS	12-Mar-21						REPLACE
SN:AHX3500075	HRS	5165.7	3600 (+50)	TSN 0	(8765.7) 8763.2	8815.7	3179 (+50)	
	ENC	3406						
PROC. REF: EMM 75-30-01								
753102	NO. 1 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5759-01	MOS	12-Mar-21						REPLACE
SN:GF000114	HRS	5214.4	3600 (+50)	TSN 0	(8814.4) 8814.4	8864.4	3230.2 (+50)	
	ENC	3423						
PROC. REF: EMM 75-30-01								
753102	NO. 2 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5759-01	MOS	12-Mar-21		TSO 0				REPLACE
SN:AHX017891	HRS	5165.7	3600 (+50)	TSO 0	(8765.7) 8763.2	8815.7	3179 (+50)	
	ENC	3406		TSO 0				
PROC. REF: EMM 75-30-01								
753105	NO. 1 ENGINE - COMPRESSOR BLEED - P2.8 VALVE							Component ATA:75
PN:31B5756-01	MOS	12-Mar-21		TSO 0				REPLACE
SN:AHX005525	HRS	5214.4	3600 (+50)	TSO 0	(8814.4) 8814.4	8864.4	3230.2 (+50)	
	ENC	3423		TSO 0				
PROC. REF: EMM 75-30-01								
753105	NO. 2 ENGINE - COMPRESSOR BLEED - P2.8 VALVE							Component ATA:75
PN:31B5756-01	MOS	12-Mar-21		TSO 0				REPLACE
SN:AHX007920	HRS	5165.7	3600 (+50)	TSO 0	(8765.7) 8763.2	8815.7	3179 (+50)	
	ENC	3406		TSO 0				
PROC. REF: EMM 75-30-01								
753111	NO. 1 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5759-01	MOS/MSC	12-Mar-21	N/A					
SN:AHX017832	HRS	5214.4						
	ENC	3423						
PROC. REF: EMM 75-30-01, EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753111	NO. 2 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5759-01	MOS/MSC	12-Mar-21	N/A					
SN:AHX3500075	HRS	5165.7						
	ENC	3406						
PROC. REF: EMM 75-30-01, EMM 75-30-01								
753112	NO. 1 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5759-01	MOS/MSC	12-Mar-21	N/A					
SN:GF000114	HRS	5214.4						
	ENC	3423						
PROC. REF: EMM 75-30-01, EMM 75-30-01								
753112	NO. 2 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5759-01	MOS/MSC	12-Mar-21	N/A					
SN:AHX017891	HRS	5165.7						
	ENC	3406						
PROC. REF: EMM 75-30-01, EMM 75-30-01								
753115	NO. 1 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE							Service ATA:75
PN:31B5756-01	MOS/MSC	23-Mar-21	N/A					
SN:AHX005525	HRS	5214.4						
	ENC	3423						
PROC. REF: EMM 75-30-01, EMM 75-30-01								
753115	NO. 2 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE							Service ATA:75
PN:31B5756-01	MOS/MSC	23-Mar-21	N/A					
SN:AHX007920	HRS	5165.7						
	ENC	3406						
PROC. REF: EMM 75-30-01, EMM 75-30-01								
754001	NO. 1 ENGINE - PRESSURE P3 TRANSDUCER							Component ATA:75
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-03								
754001	NO. 2 ENGINE - PRESSURE P3 TRANSDUCER							Component ATA:75
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
761001	THROTTLE/THRUST REVERSER QUADRANT ASSEMBLY							Component ATA:76
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-01								
761003	LEFT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER							Component ATA:76
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-02								
761004	RIGHT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER							Component ATA:76
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-02								
761101	NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS							Component ATA:76
PN:6008016-027	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:080	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: EMM 73-20-03								
761101	NO. 2 ENGINE - FADEC, ENGINE TAILCONE HARNESS							Component ATA:76
PN:6008016-028	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:076	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: EMM 73-20-03								
761103	NO. 1 ENGINE - FADEC, ENGINE HARNESS							Component ATA:76
PN:6008016-029	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:078	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: EMM 73-20-03								
761103	NO. 2 ENGINE - FADEC, ENGINE HARNESS							Component ATA:76
PN:6008016-030	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:080	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: EMM 73-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
761105	NO. 1 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:6008408-033	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:095	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: EMM 73-20-03								
761105	NO. 2 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03								
761107	NO. 1 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:6008408-037	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:086	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: EMM 73-20-03								
761107	NO. 2 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:6008408-032	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:092	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: EMM 73-20-03								
761201	ENGINE FADEC SLAVE/MASTER SWITCH							Component ATA:76
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-12-01								
E7614000 ^S	FUNCTIONAL TEST OF APR (AUTOMATIC PERFORMANCE RESERVE) SYSTEM. (REFER TO 76-14-00)							Service ATA:76
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
PROC. REF: AMM 76-14-00								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
H7611007 ^S		VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS FOR SECURITY AND GENERAL CONDITION. REMOVAL OF UPPER COWLING IS REQUIRED FOR THIS INSPECTION. (REFER TO 5-10-00)						Service ATA:76
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: GENERIC NO REF				PKG:9
J7611006 ^S		VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS FOR SECURITY AND GENERAL CONDITION, INCLUDING THE SHIELDED HARNESSES ROUTED TO THE FADEC MAINTENANCE PANEL. PAY PARTICULAR ATTENTION TO SIGNS OF CHAFING AGAINST STRUCTURE ADJACENT TO ELECTRICAL BONDING CLAMP LOCATIONS. (						Service ATA:76
	MOS	27-Feb-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
				PROC. REF: GENERIC NO REF				PKG:9
ATA 77 - ENGINE INDICATING								
771001		LEFT ENGINE N1 INDICATOR						Component ATA:77
PN:6608496-001	MOS/MSC	06-Jul-18	O/C					
SN:8993L	HRS	4424.1						
	AFL	2855						
				PROC. REF: AMM 77-10-01				
771001		NO. 1 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS						Service ATA:77
	MOS	11-Nov-00						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
				PROC. REF: GENERIC NO REF				
771001		NO. 2 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS						Service ATA:77
	MOS	10-Nov-00						DISCARD
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
				PROC. REF: GENERIC NO REF				
771002		RIGHT ENGINE N1 INDICATOR						Component ATA:77
PN:64500-002	MOS/MSC	30-Jan-21	O/C					
SN:5781L	HRS	5180.5						
	AFL	3393						
				PROC. REF: AMM 77-10-01				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771003	LEFT ENGINE N2 INDICATOR							Component ATA:77
PN:6608508-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4711	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-10-02								
771004	RIGHT ENGINE N2 INDICATOR							Component ATA:77
PN:6608508-001	MOS/MSC	04-Aug-20	O/C					
SN:1453	HRS	4944						
	AFL	3213						
PROC. REF: AMM 77-10-02								
771011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS							Service ATA:77
	MOS	11-Nov-00						
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 77-10-01								
771011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS							Service ATA:77
	MOS	10-Nov-00						
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 77-10-01								
771012	LEFT DATA CONCENTRATOR (DCU) UNIT							Component ATA:77
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
771012	RIGHT DATA CONCENTRATOR (DCU) UNIT							Component ATA:77
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771014	LEFT ENGINE DATA CONCENTRATOR (EDC) UNIT							Component ATA:77
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
771014	RIGHT ENGINE DATA CONCENTRATOR (EDC) UNIT							Component ATA:77
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
771021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7200	7250	1615.8 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REF								
771021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7197.5	7250	1613.3 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REF								
771022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7200	7250	1615.8 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REF								
771022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7197.5	7250	1613.3 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771027	NO. 1 ENGINE - CHANNEL A N1 SPEED SENSOR							Component ATA:77
PN:30B6152-06	MOS	03-Nov-17		TSN 0				
SN:CH3784	HRS	4179	3600 (+50)	TSN 0	(7779) 7779	7829	2194.8 (+50)	
	ENC	2725		TSN 0				
PROC. REF: EMM 77-10-01								
771027	NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR							Component ATA:77
PN:30B6152-06	MOS	14-Nov-13		TSN 0				
SN:CH3649	HRS	3379.4	3600 (+50)	TSN 0	(6979.4) 6976.9	7029.4	1392.7 (+50)	
	ENC	2209		TSN 0				
PROC. REF: EMM 77-10-01								
771028	NO. 1 ENGINE - CHANNEL B N1 SPEED SENSOR							Component ATA:77
PN:30B6150-06	MOS	03-Nov-17		TSN 0				
SN:CH3401	HRS	4179	3600 (+50)	TSN 0	(7779) 7779	7829	2194.8 (+50)	
	ENC	2725		TSN 0				
PROC. REF: EMM 77-10-01								
771028	NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR							Component ATA:77
PN:30B6150-06	MOS	14-Nov-13		TSN 0				
SN:CH3283	HRS	3379.4	3600 (+50)	TSN 0	(6979.4) 6976.9	7029.4	1392.7 (+50)	
	ENC	2209		TSN 0				
PROC. REF: EMM 77-10-01								
771040	NO. 1 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01								
771040	NO. 2 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771041	NO. 1 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01								
771041	NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01								
772001	LEFT ENGINE ITT INDICATOR							Component ATA:77
PN:6608505-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4816	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-20-01								
772002	RIGHT ENGINE ITT INDICATOR							Component ATA:77
PN:6608505-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4815	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-20-01								
772010	NO. 1 ENGINE - T4.5 THERMOCOUPLE HARNESS							Component ATA:77
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01								
772010	NO. 2 ENGINE - T4.5 THERMOCOUPLE HARNESS							Component ATA:77
PN:30B2749-02	MOS/MSC	14-Nov-13	O/C	TSN 0				
SN:EM177314	HRS	3379.4		TSN 0				
	ENC	2209		TSN 0				
PROC. REF: EMM 77-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS							Service ATA:77
PN:31B5840-01	MOS	11-Nov-00						
SN:RTJ5853	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
772013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS							Service ATA:77
PN:31B5840-01	MOS	10-Nov-00						
SN:RTJ5854	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
772014	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-02								
772014	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-02								
772015	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:31B5840-01	MOS/MSC	16-Jul-03	O/C	TSN 0				
SN:RTJ5853	HRS	298		TSN 0				
	ENC	204		TSN 0				
PROC. REF: EMM 77-20-02								
772015	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:31B5840-01	MOS/MSC	16-Jul-03	O/C	TSN 0				
SN:RTJ5854	HRS	298		TSN 0				
	ENC	204		TSN 0				
PROC. REF: EMM 77-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772021	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX							Service ATA:77
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 77-20-01								
772021	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX							Service ATA:77
PN:30B2749-02	MOS	10-Nov-00						
SN:EM177314	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 77-20-01								
772022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS							Service ATA:77
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
772022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS							Service ATA:77
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
773000 ^U	DOWNLOAD BOTH ENGINE EDU'S/ INTERROGATE EVENTS IN EDU							Service ATA:77
	DAYS	14-Dec-22	30 (+10/-10)		13-Jan-23	23-Jan-23	2 d (+10)	
	HRS	5584.2						
	AFL	3705						
774001	ENGINE DIAGNOSTIC UNIT							Component ATA:77
PN:9-361-06	MOS/MSC	30-Jul-21	O/C	TSR 0				
SN:F213	HRS	5392.9		TSR 0				
	AFL	3555		TSR 0				
PROC. REF: AMM 77-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
774001A ^U	REPLACE ENGINE DIAGNOSTIC UNIT INTERNAL BATTERY							Service ATA:77
PN:9-361-06	MOS	30-Jul-21	36		30-Jul-24		566 d	
SN:F213	HRS	5392.9						
	AFL	3555						
774002	CONTROL AND DISPLAY (CDU) UNIT							Component ATA:77
PN:9-362-03	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:C87	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-02								
774003	LEFT ENGINE ISOLATION INTERFACE UNIT							Component ATA:77
PN:9-343-04	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:C121	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-03								
774004	RIGHT ENGINE ISOLATION INTERFACE UNIT							Component ATA:77
PN:9-343-04	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:C153	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-03								
774101	SIGNAL CONDITIONING BOX							Component ATA:77
PN:6600504-5	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0295	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-01								
774103	LEFT ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:6600504-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0777	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02								
774104	RIGHT ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:6600504-2	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0785	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
05-10-29-D7830036L	VISUAL INSPECTION THRUST REVERSER GUIDE ROD BUSHINGS (REFER TO 78-30-00)							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 78-30-00								
05-10-29-D7830036R	VISUAL INSPECTION THRUST REVERSER GUIDE ROD BUSHINGS (REFER TO 78-30-00)							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 78-30-00								
780001	LEFT THRUST REVERSER							Component ATA:78
PN:282-0052-519	MOS/MSC	22-Apr-15	O/C	TSR 0				
SN:0548	HRS	3616.4		TSR 0				
	AFL	2379		TSR 0				
PROC. REF: AMM 78-30-05								
780001A	REPLACE LEFT THRUST REVERSER * LEFT THRUST REVERSER DOOR DRIVER LINK BOLTS (NAS6305U18D) (AWL*)							Service ATA:78
PN:282-0052-519	MOS/MSC		N/A					
SN:0548	HRS							
	AFL							
PROC. REF: AMM 78-30-10								
780001B	REPLACE LEFT THRUST REVERSER * LEFT THRUST REVERSER SUPPORT BEAM DRIVER LINK BOLTS (122450-8A49) (ALT P/N PBF1344-8-49D) (AWL*)							Service ATA:78
PN:282-0052-519	MOS/MSC		N/A					
SN:0548	HRS							
	AFL							
PROC. REF: AMM 78-30-20								
780001C	REPLACE LEFT THRUST REVERSER * LEFT THRUST REVERSER OVERCENTER LINK DRIVER LINK BOLTS (NAS6304U20D) (AWL*)							Service ATA:78
PN:282-0052-519	MOS/MSC		N/A					
SN:0548	HRS							
	AFL							
PROC. REF: AMM 78-30-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
780001D	REPLACE LEFT THRUST REVERSER * LEFT THRUST REVERSER CARRIAGE ASSEMBLY OVERCENTER LINK BOLTS (NAS6307U15D) (AWL*)							Service ATA:78
PN:282-0052-519	MOS/MSC		N/A					
SN:0548	HRS							
	AFL							
PROC. REF: AMM 78-30-20								
780002	RIGHT THRUST REVERSER							Component ATA:78
PN:282-0052-521	MOS/MSC	22-Apr-15	O/C	TSR 0				
SN:0549	HRS	3616.4		TSR 0				
	AFL	2379		TSR 0				
PROC. REF: AMM 78-30-05								
780002A	REPLACE RIGHT THRUST REVERSER DOOR DRIVER LINK BOLTS (NAS6305U18D) * (AWL*)							Service ATA:78
PN:282-0052-521	MOS/MSC		N/A					
SN:0549	HRS							
	AFL							
PROC. REF: AMM 78-30-10								
780002B	REPLACE RIGHT THRUST REVERSER * SUPPORT BEAM DRIVER LINK BOLTS (122450-8A49) (ALT PBF1344-8-49D) (AWL*)							Service ATA:78
PN:282-0052-521	MOS/MSC		N/A					
SN:0549	HRS							
	AFL							
PROC. REF: AMM 78-30-20								
780002C	REPLACE RIGHT THRUST REVERSER * OVER-CENTER LINK DRIVER LINK BOLTS (NAS6304U20D) (AWL*)							Service ATA:78
PN:282-0052-521	MOS/MSC		N/A					
SN:0549	HRS							
	AFL							
PROC. REF: AMM 78-30-20								
780002D	REPLACE RIGHT THRUST REVERSER * CARRIAGE ASSEMBLY OVER-CENTER LINK BOLTS (NAS6307U15D) (AWL*)							Service ATA:78
PN:282-0052-521	MOS/MSC		N/A					
SN:0549	HRS							
	AFL							
PROC. REF: AMM 78-30-20								
783001	LEFT THRUST REVERSER RELAY BOX							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783002	RIGHT THRUST REVERSER RELAY BOX							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-01								
783005	LEFT THRUST REVERSER HYDRAULIC CONTROL UNIT							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-03								
783006	RIGHT THRUST REVERSER HYDRAULIC CONTROL UNIT							Component ATA:78
PN:282D0007-507	MOS/MSC	02-Aug-13	O/C	TSO 0				
SN:0598	HRS	3374.5		TSO 0				
	AFL	2205		TSO 0				
PROC. REF: AMM 78-30-03								
783008	HYDRAULIC CONTROL RELAY BOX							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-06								
783009	THRUST REVERSER INTERFACE BOX							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-07								
783013	LEFT ENGINE THRUST REVERSER UPPER DOOR							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10								
783014	RIGHT ENGINE THRUST REVERSER UPPER DOOR							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783015	LEFT ENGINE THRUST REVERSER LOWER DOOR							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10								
783016	RIGHT ENGINE THRUST REVERSER LOWER DOOR							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10								
783021	LEFT PRIMARY LATCH WIRE HARNESS ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-25								
783022	RIGHT PRIMARY LATCH WIRE HARNESS ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-25								
783025	LEFT ENGINE THRUST REVERSER SWITCH CABLE							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-25								
783026	RIGHT ENGINE THRUST REVERSER SWITCH CABLE							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-25								
783105	LEFT OUTBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:282D0006-501	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0924R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783106	LEFT INBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:282D0006-501	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0928R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05								
783107	RIGHT INBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:282D0006-501	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0919R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05								
783108	RIGHT OUTBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:282D0006-501	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:0927R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05								
783115	LEFT UPPER SECONDARY LOCK ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15								
783116	RIGHT UPPER SECONDARY LOCK ACTUATOR							Component ATA:78
PN:266D0486-503	MOS/MSC	29-Oct-21	O/C					
SN:02438	HRS	5523.1						
	AFL	3652						
PROC. REF: AMM 78-31-15								
783117	LEFT LOWER SECONDARY LOCK ACTUATOR							Component ATA:78
PN:266D0486-507	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:1121	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15								
783118	RIGHT LOWER SECONDARY LOCK ACTUATOR							Component ATA:78
PN:266D0486-503	MOS/MSC	29-Oct-21	O/C					
SN:UNKNOWN	HRS	5523.1						
	AFL	3652						
PROC. REF: AMM 78-31-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783132	LEFT OUTBOARD STANG FAIRING ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15								
783136	RIGHT OUTBOARD STANG FAIRING ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15								
783142	LEFT INBOARD STANG FAIRING ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15								
783146	RIGHT INBOARD STANG FAIRING ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15								
C7830027A	VISUAL INSPECTION THRUST REVERSER DRIVER LINKS (EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 78-30-00)							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: GENERIC NO REF								PKG:31
C7830027B	VISUAL INSPECTION THRUST REVERSER DRIVER LINKS (EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 78-30-00)							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: GENERIC NO REF								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
C7830029A	VISUAL INSPECTION THRUST REVERSER OVER-CENTER LINK (EIGHT PER AIRCRAFT) AND OVER-CENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: GENERIC NO REF								PKG:31
C7830029B	VISUAL INSPECTION THRUST REVERSER OVER-CENTER LINK (EIGHT PER AIRCRAFT) AND OVER-CENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: GENERIC NO REF								PKG:32
C7830031A	VISUAL INSPECTION THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: GENERIC NO REF								PKG:31
C7830031B	VISUAL INSPECTION THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: GENERIC NO REF								PKG:32
C7830033A	VISUAL INSPECTION THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: GENERIC NO REF								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
C7830033B	VISUAL INSPECTION THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
				PROC. REF: GENERIC NO REF				PKG:32
C7830035A	VISUAL INSPECTION THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
				PROC. REF: GENERIC NO REF				PKG:31
C7830035B	VISUAL INSPECTION THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
				PROC. REF: GENERIC NO REF				PKG:32
D7830015A	CHECK THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
				PROC. REF: GENERIC NO REF				PKG:31
D7830015B	CHECK THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION							Service ATA:78
	MOS/MSC		N/A					
	HRS							
	AFL							
				PROC. REF: GENERIC NO REF				PKG:32
E7830038 ^S	DETAILED INSPECTION THRUST REVERSERS FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 78-30-00.)							Service ATA:78
	MOS	05-Sep-17	48 (+14d/-14d)					
	HRS	4170.4	1200 (+25/-25)					
	AFL	2721						
				PROC. REF: AMM 78-30-00				PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
M7830084 ^S	INSPECT THRUST REVERSER SECONDARY LATCH - LUBRICATE LATCH SWITCH PLUNGERS, ROLLER ASSEMBLY, AND ACTUATOR PINS. (REFER TO 12-21-04)							Service ATA:78
	MOS	19-Oct-22	12 (+14d/-14d)					
	HRS	5563.7	300 (+25/-25)					
	AFL	3693						
			PROC. REF: AMM 12-21-04					PKG:3
P7830022 ^S	FUNCTIONAL TEST OF THRUST REVERSER HYDRAULIC CONTROL VALVE ASSEMBLY CHECK VALVES. (REFER TO 78-30-03.)							Service ATA:78
	MOS	03-Aug-12	144 (+14d/-14d)					
	HRS	3178.5						
	AFL	2065	6000 (+25/-25)					
			PROC. REF: AMM 78-30-03					PKG:27
T7830014 ^S	VISUAL INSPECTION OF THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:9
T7830016 ^S	VISUAL INSPECTION OF THRUST REVERSER ACTUATOR FOR HYDRAULIC LEAKS, DAMAGED PUSHROD, DAMAGED FLEXIBLE HOSES, AND SECURITY OF INSTALLATION. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:9
T7830018 ^S	VISUAL INSPECTION OF HYDRAULIC CONTROL UNITS, PRESSURE SWITCH, CHECK VALVES, AND HYDRAULIC LINES FOR LEAKAGE, CLEANLINESS, SECURITY OF INSTALLATION, AND CONDITION OF ECLECTRICAL COMPONENTS. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:9
T7830020 ^S	VISUAL INSPECTION OF STOW AND DEPLOY SWITCHES FOR SECURITY OF INSTALLATION AND CONDITION OF ELECTRICAL COMPONENTS. VISUALLY INSPECT SHIELDED ELECTRICAL THRUST REVERSER HARNESS FOR CONDITION. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
			PROC. REF: GENERIC NO REF					PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
T7830026 ^S	VISUAL INSPECTION OF THRUST REVERSER DRIVER LINKS(EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT.) INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
T7830028 ^S	VISUAL INSPECTION OF THRUST REVERSER OVERCENTER LINK (EIGHT PER AIRCRAFT) AND OVERCENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
T7830030 ^S	VISUAL INSPECTION OF THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATI							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
T7830032 ^S	VISUAL INSPECTION OF THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
T7830034 ^S	VISUAL INSPECTION OF THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9
T7830039 ^S	VISUAL INSPECTION OF FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 5-10-00)							Service ATA:78
	MOS	11-Apr-19	24 (+14d/-14d)					
	HRS	4647.4	600 (+25/-25)					
	AFL	2994						
PROC. REF: GENERIC NO REF								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
T7830085 ^S	FUNCTIONAL TEST ** OF THE THRUST REVERSER WITH WHEEL SPEED DETECT INTERFACE. (REFER TO 78-30-00.) (AWL**)							Service ATA:78
	MOS	23-Mar-21	48 (+14d/-14d)					
	HRS	5214.4	1200 (+25/-25)					
	AFL	3422						
PROC. REF: AMM 78-30-00							PKG:15	
U7830010A ^S	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION							Service ATA:78
	MOS	22-Apr-15						
	HRS	3616.4	3600 (+50)					
	AFL	2379						
PROC. REF: GENERIC NO REF							PKG:29	
U7830010B ^S	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION							Service ATA:78
	MOS	03-Jan-14						
	HRS	3401.1	3600 (+50)					
	AFL	2225						
PROC. REF: GENERIC NO REF							PKG:30	
U7830012A ^S	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE							Service ATA:78
	MOS	22-Apr-15						
	HRS	3616.4	3600 (+50)					
	AFL	2379						
PROC. REF: GENERIC NO REF							PKG:29	
U7830012B ^S	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE							Service ATA:78
	MOS	03-Jan-14						
	HRS	3401.1	3600 (+50)					
	AFL	2225						
PROC. REF: GENERIC NO REF							PKG:30	
ATA 79 - OIL								
05-P&W-790001	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT							Service ATA:79
	MOS	11-Mar-22	12		11-Mar-23		59 d	
	HRS	5539.1	1200 (+25/-25)		(6739.1) 6739.1	6764.1	1154.9 (+25)	
	ENC	3671						
PROC. REF: EMM 79-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
05-P&W-790001	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT							Service ATA:79
	MOS	11-Mar-22	12		11-Mar-23		59 d	
	HRS	5490.4	1200 (+25/-25)		(6690.4) 6687.9	6715.4	1103.7 (+25)	
	ENC	3654						
PROC. REF: EMM 79-20-01								
05-P&W-790002	NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE							Service ATA:79
	MOS	11-Mar-22	12		11-Mar-23		59 d	
	HRS	5539.1	600 (+50/-50)		(6139.1) 6139.1	6189.1	554.9 (+50)	
	ENC	3671						
PROC. REF: EMM 72-00-00								
05-P&W-790002	NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE							Service ATA:79
	MOS	11-Mar-22	12	TAC 0	11-Mar-23		59 d	
	HRS	5490.4	600 (+50/-50)		(6090.4) 6087.9	6140.4	503.7 (+50)	
	ENC	3654						
PROC. REF: EMM 72-00-00								
792001	NO. 1 ENGINE - OIL PUMP							Component ATA:79
PN:31B6167-01	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:40A074	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05								
792001	NO. 2 ENGINE - OIL PUMP							Component ATA:79
PN:31B6167-01	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:40A071	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05								
792002	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER							Component ATA:79
PN:91020-000-4	MOS/MSC	15-Apr-15	O/C					
SN:0999	HRS	3616.4						
	ENC	2379						
PROC. REF: EMM 79-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792002	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER							Component ATA:79
PN:31B5790-02	MOS/MSC	14-Nov-13	O/C	TSO 0				
SN:0903	HRS	3379.4		TSO 0				
	ENC	2209		TSO 0				
PROC. REF: EMM 79-20-02								
792005	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH							Component ATA:79
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-01								
792005	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH							Component ATA:79
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-01								
792010	NO. 1 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH							Component ATA:79
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
792010	NO. 2 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH							Component ATA:79
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
792011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH							Service ATA:79
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7200	7250	1615.8 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH							Service ATA:79
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
792012	NO. 1 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER							Service ATA:79
PN:91020-000-4	MOS	11-Nov-00						
SN:0999	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
792012	NO. 2 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER							Service ATA:79
PN:31B5790-02	MOS	10-Nov-00						
SN:0903	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
792020	NO. 1 ENGINE - OIL PUMP HOUSING							Component ATA:79
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05								
792020	NO. 2 ENGINE - OIL PUMP HOUSING							Component ATA:79
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05								
792035	NO. 1 ENGINE - OIL FILTER BYPASS SWITCH							Component ATA:79
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792035	NO. 2 ENGINE - OIL FILTER BYPASS SWITCH							Component ATA:79
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793001	LEFT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR							Component ATA:79
PN:6608499-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4662	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-01								
793001	NO. 1 ENGINE - DISCARD - CHIP DETECTOR							Service ATA:79
	MOS	11-Nov-00						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-01								
793001	NO. 2 ENGINE - DISCARD - CHIP DETECTOR							Service ATA:79
	MOS	10-Nov-00						DISCARD
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-01								
793002	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH							Service ATA:79
	MOS	11-Nov-00						
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-02								
793002	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH							Service ATA:79
	MOS	10-Nov-00						
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793002	RIGHT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR							Component ATA:79
PN:6608499-001	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:4663	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-01								
793003	LEFT ENGINE OIL PRESSURE TRANSDUCER							Component ATA:79
PN:7600019-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6264-4-686	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-02								
793003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP							Service ATA:79
	MOS	11-Nov-00						
	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-03								
793003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP							Service ATA:79
	MOS	10-Nov-00						
	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-03								
793004	RIGHT ENGINE OIL PRESSURE TRANSDUCER							Component ATA:79
PN:7600019-1	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:6264-4-695	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-02								
793005	NO. 1 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				REPLACE
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793005	NO. 2 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				REPLACE
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-01								
793010	LEFT ENGINE OIL TEMPERATURE BULB							Component ATA:79
PN:MS28034-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D6920	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03								
793011	RIGHT ENGINE OIL TEMPERATURE BULB							Component ATA:79
PN:MS28034-3	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:D6921	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03								
793013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)							Service ATA:79
PN:PN	MOS	11-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	1615.8 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
793013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)							Service ATA:79
PN:PN	MOS	10-Nov-00						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7197.5	7250	1613.3 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REF								
793030	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR							Component ATA:79
PN:PN	MOS/MSC	11-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of: 14-Dec-2022

11-Jan-2023 11:26 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793030	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR							Component ATA:79
PN:PN	MOS/MSC	10-Nov-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-03								
ATA 80 - STARTING								
801001	CROSS START RELAY BOX							Component ATA:80
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 80-10-01								
801002	AIR START RELAY BOX							Component ATA:80
PN:PN	MOS/MSC	29-Dec-00	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 80-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task