



DueList Report

LEARJET 60

S/N 60 210 C-FONG

OWNER: FLIGHTPATH CHARTER AIRWAYS

OPERATOR: FLIGHTPATH CHARTER AIRWAYS

ADDRESS: 4A-4881 FOUNTAIN ST. N., HANGAR 33, BRESLAU ON NOB1M0

ADDRESS: HANGAR 17 BRESLAU ONTARIO NOB 1M0

OFFICE: FAX:

OFFICE: FAX:

ANALYST: BOUN EM
EMAIL: BEM@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
316-462-2442 (FAX)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PROJECTED: 2 MOS. to 11-MAR-23

AIRCRAFT SERIAL/REGNO: 60 210/C-FONG MODEL: LEARJET 60 MANUFACTURER: BOMBARDIER AVIATION

CERTIFICATION DATE: 29-DEC-2000

LAST ACTUALS:
5584.2 A/C HRS as of 14-DEC-2022
3705 AFL as of 14-DEC-2022
2079 APH as of 14-DEC-2022
1558.8 ACH as of 11-NOV-2021

PROJECTED:
5661.78
3802
2098
1578

APU SERIAL/PART: SP-E060449/4503135 MODEL: T-20G-10C3A (CIMMS) MANUFACTURER: HAMILTON SUNDSTRAND CORPORATION

INSTALLED ON: 16-DEC-2021
2623 APU HRS 5539.1 A/C HRS
5076 APUS

LAST ACTUALS:
2642 APU HRS as of 14-DEC-2022
5097 APUS as of 14-DEC-2022

PROJECTED:
2661.40
5136

ENGINE NO. 1 SERIAL/PART: PCE-CA0260/31B4067-04 MODEL: PW305A MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 22-APR-2015
3616.4 ENG. HRS 3616.4 A/C HRS
2379 ENC

LAST ACTUALS:
5584.2 ENG. HRS as of 14-DEC-2022
3705 ENC as of 14-DEC-2022

PROJECTED:
5661.78
3802

ENGINE NO. 2 SERIAL/PART: PCE-CA0259/31B4067-04 MODEL: PW305A MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 14-NOV-2013
3379.4 ENG. HRS 3379.4 A/C HRS
2209 ENC

LAST ACTUALS:
5586.7 ENG. HRS as of 14-DEC-2022
3708 ENC as of 14-DEC-2022

PROJECTED:
5664.28
3805



Due List Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of:
14-Dec-2022 Operator: FLIGHTPATH CHARTER AIRWAYS

Report Date: 11-Jan-2023

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-T20G-490001		APU - PERFORM OIL LEVEL CHECK							
	MOS	1	04-Dec-22		04-Jan-23		OVD		1.2
	HRS								
	APUS								
REF: MM 49-20-00									
773000 ^U		DOWNLOAD BOTH ENGINE EDU'S/ INTERROGATE EVENTS IN EDU							
	DAYS	30 (+10/-10)	14-Dec-22		13-Jan-23	23-Jan-23	2 d (+10)	13-Jan-2023(2)	28 d
	HRS		5584.2					13-Jan-2023(2)	0
	AFL		3705					13-Jan-2023(2)	0
REF:									
FAA 1998-16-18-3		RIGHT INBOARD DETECT AND REPAIR ABNORMAL BRAKE WEAR CONDITION							
	MOS		19-Oct-22					25-Jan-2023(3)	2.7
	HRS		5563.7					25-Jan-2023(3)	20.5
	AFL	35	3693		3728		23	25-Jan-2023(3)	12
REF: AD									
FAA 1998-16-18-1		LEFT OUTBOARD DETECT AND REPAIR ABNORMAL BRAKE WEAR CONDITION							
	MOS		19-Oct-22					07-Mar-2023	2.7
	HRS		5563.7					07-Mar-2023	20.5
	AFL	T:100	3693		3793		88	07-Mar-2023	12
REF: AD									
FAA 1998-16-18-2		LEFT INBOARD DETECT AND REPAIR ABNORMAL BRAKE WEAR CONDITION							
	MOS		19-Oct-22					07-Mar-2023	2.7
	HRS		5563.7					07-Mar-2023	20.5
	AFL	T:100	3693		3793		88	07-Mar-2023	12
REF: AD									
FAA 1998-16-18-4		RIGHT OUTBOARD DETECT AND REPAIR ABNORMAL BRAKE WEAR CONDITION							
	MOS		19-Oct-22					07-Mar-2023	2.7
	HRS		5563.7					07-Mar-2023	20.5
	AFL	T:100	3693		3793		88	07-Mar-2023	12
REF: AD									
05-10-30-RVSM-W3411015		PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (RVSM) (REFER TO 34-17-00)							
	MOS	12 (+14d/-14d)	11-Mar-22		11-Mar-23	25-Mar-23	59 d (+14)	11-Mar-2023	10
	HRS		5539.1					11-Mar-2023	45.1
	AFL		3670					11-Mar-2023	35
REF: AMM 34-17-00									



Due List Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of:
14-Dec-2022 Operator: FLIGHTPATH CHARTER AIRWAYS

Report Date: 11-Jan-2023

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
REF: EMM 73-10-03										
05-P&W-730001		NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT								Service ATA:73
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
	HRS	1200 (+25/-25)	5539.1		(6739.1)6739.1	6764.1	1154.9 (+25)	11-Mar-2023	45.1	
	ENC		3671					11-Mar-2023	34	
REF: EMM 73-10-03										
05-P&W-730001		NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT								Service ATA:73
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
	HRS	1200 (+25/-25)	5490.4		(6690.4)6687.9	6715.4	1103.7 (+25)	11-Mar-2023	96.3	
	ENC		3654					11-Mar-2023	54	
REF: EMM 79-20-01										
05-P&W-790001		NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT								Service ATA:79
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
	HRS	1200 (+25/-25)	5539.1		(6739.1)6739.1	6764.1	1154.9 (+25)	11-Mar-2023	45.1	
	ENC		3671					11-Mar-2023	34	
REF: EMM 79-20-01										
05-P&W-790001		NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT								Service ATA:79
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
	HRS	1200 (+25/-25)	5490.4		(6690.4)6687.9	6715.4	1103.7 (+25)	11-Mar-2023	96.3	
	ENC		3654					11-Mar-2023	54	
REF: EMM 72-00-00										
05-P&W-790002		NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE								Service ATA:79
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
	HRS	600 (+50/-50)	5539.1		(6139.1)6139.1	6189.1	554.9 (+50)	11-Mar-2023	45.1	
	ENC		3671					11-Mar-2023	34	
REF: EMM 72-00-00										
05-P&W-790002		NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE								Service ATA:79
	MOS	12	11-Mar-22	TAC:0	11-Mar-23		59 d	11-Mar-2023	10	
	HRS	600 (+50/-50)	5490.4		(6090.4)6087.9	6140.4	503.7 (+50)	11-Mar-2023	96.3	
	ENC		3654					11-Mar-2023	54	
REF: EMM 72-00-00										
05-P&W-490002		APU - ANNUAL INSPECTION OF APU MOUNTS FOR LOOSENESS & DAMAGE								Service ATA:05
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
	HRS		2623					11-Mar-2023	19	
	APUS		5076					11-Mar-2023	21	
REF: SMM 49-11-03										

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of:
14-Dec-2022 Operator: FLIGHTPATH CHARTER AIRWAYS

Report Date: 11-Jan-2023

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
232510 ^U INSPECT AND FUNCTIONAL CHECK OF THE ATG 5000 SYSTEM AND COMPONENTS Service ATA:23									
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10
	HRS		5539.1					11-Mar-2023	45.1
	AFL		3670					11-Mar-2023	35
Disposition: ICA REF:									
23CUS1 ^U GENERAL VISUAL INSPECTION COLLINS VHF-422C/D COMMUNICATION SYSTEM PER STC Service ATA:23									
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10
	HRS		5539.1					11-Mar-2023	45.1
	AFL		3670					11-Mar-2023	35
Disposition: ICA REF:									
23CUS3 ^U GENERAL VISUAL INSPECTION OF AVIONICS INSTRUMENT 1200 VA 115VAC/60HZ INVERTER PER STC Service ATA:23									
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10
	HRS		5539.1					11-Mar-2023	45.1
	AFL		3670					11-Mar-2023	35
Disposition: ICA REF:									
23CUS4 ^U GENERAL VISUAL INSPECTION OF COLLINS TCAS 4000 SYSTEM PER STC Service ATA:23									
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10
	HRS		5539.1					11-Mar-2023	45.1
	AFL		3670					11-Mar-2023	35
Disposition: ICA REF:									
243062B PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 1 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015 Service ATA:24									
PN:501-1712-02	MOS	12 (+14d/-14d)	11-Mar-22		11-Mar-23	25-Mar-23	59 d (+14)	11-Mar-2023	10
PN:501-1712-02	HRS		5539.1					11-Mar-2023	45.1
PN:501-1712-02	AFL		3670					11-Mar-2023	35
REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170									
243063B PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015 Service ATA:24									
PN:501-1712-02	MOS	12 (+14d/-14d)	11-Mar-22		11-Mar-23	25-Mar-23	59 d (+14)	11-Mar-2023	10
PN:501-1712-02	HRS		5539.1					11-Mar-2023	45.1
PN:501-1712-02	AFL		3670					11-Mar-2023	35
REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170									
243301A CHARGE NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030 Service ATA:24									
PN:M6088352-025	MOS	12 (+14d/-14d)	11-Mar-22		11-Mar-23	25-Mar-23	59 d (+14)	11-Mar-2023	10
PN:M6088352-025	HRS		5539.1					11-Mar-2023	45.1
PN:M6088352-025	AFL		3670					11-Mar-2023	35
REF: AMM 12-23-02									



Due List Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of:
14-Dec-2022 Operator: FLIGHTPATH CHARTER AIRWAYS

Report Date: 11-Jan-2023

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
243302A		CHARGE NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030								Service ATA:24
PN:M6088352-025	MOS	12 (+14d/-14d)	11-Mar-22		11-Mar-23	25-Mar-23	59 d (+14)	11-Mar-2023	10	
PN:M6088352-025	HRS		5539.1					11-Mar-2023	45.1	
PN:M6088352-025	AFL		3670					11-Mar-2023	35	
REF: AMM 12-23-02										
24CUS1A ^U		INSPECT FLIGHT DISPLAY USB CHARGERS								Service ATA:24
PN:UNKNOWN	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
PN:UNKNOWN	HRS		5539.1					11-Mar-2023	45.1	
PN:UNKNOWN	AFL		3670					11-Mar-2023	35	
Disposition: ICA REF:										
256001A		INSPECT/FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER								Service ATA:25
PN:453-5000-(366)	MOS	12 (+14d/-14d)	11-Mar-22		11-Mar-23	25-Mar-23	59 d (+14)	11-Mar-2023	10	
PN:453-5000-(366)	HRS		5539.1					11-Mar-2023	45.1	
PN:453-5000-(366)	AFL		3670					11-Mar-2023	35	
REF: AMM 25-62-00										
256060 ^U		PERFORM ANNUAL INSPECTION OF ALL LIFE VESTS								Service ATA:25
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
	HRS		5539.1					11-Mar-2023	45.1	
	AFL		3670					11-Mar-2023	35	
Disposition: CUSTOMER CODE REF: OMM 6.3										
256076A		CONDITION CHECK FIRST AID KIT INVENTORY & EXPIRATION DATES								Service ATA:25
PN:70001-00	MOS	12 (+10d/-10d)	11-Mar-22		11-Mar-23	21-Mar-23	59 d (+10)	11-Mar-2023	10	
PN:70001-00	HRS		5539.1					11-Mar-2023	45.1	
PN:70001-00	AFL		3670					11-Mar-2023	35	
REF: GENERIC NO REF										
256076B		INSPECT FIRST AID KIT CONTENTS								Service ATA:25
PN:70001-00	MOS	12 (+10d/-10d)	11-Mar-22		11-Mar-23	21-Mar-23	59 d (+10)	11-Mar-2023	10	
PN:70001-00	HRS		5539.1					11-Mar-2023	45.1	
PN:70001-00	AFL		3670					11-Mar-2023	35	
REF: GENERIC NO REF										
25CUS1A ^U		INSPECT FLIGHT DISPLAY DVD PLAYER								Service ATA:25
PN:PN	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10	
PN:PN	HRS		5539.1					11-Mar-2023	45.1	
PN:PN	AFL		3670					11-Mar-2023	35	
Disposition: ICA REF:										



Due List Report

Model: LEARJET 60 Serial: 60 210 RegNo: C-FONG HRS: 5584.2 AFL: 3705 As Of:
14-Dec-2022 Operator: FLIGHTPATH CHARTER AIRWAYS

Report Date: 11-Jan-2023

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
262050C		INSPECT APU FIRE EXTINGUISHER WEIGHT CHECK AND REPLACE AS NECESSARY							
PN:50-1200	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10
PN:50-1200	HRS							11-Mar-2023	
PN:50-1200	AFL							11-Mar-2023	
REF: GENERIC NO REF, SMM 49-11-03									
34CUS1 ^U		GENERAL VISUAL INSPECTION OF ALLIED SIGNAL EGPWS PER STC							
	MOS	12	11-Mar-22		11-Mar-23		59 d	11-Mar-2023	10
	HRS		5539.1					11-Mar-2023	45.1
	AFL		3670					11-Mar-2023	35

Disposition: ICA REF: